

TITLE: DRYER VENT
VERSION: VI.3
DATE PUBLISHED: 7/31/20

DEFINITION: A vent attached to a clothes dryer.
PURPOSE: Transport moisture, excess heat, lint, and, in some cases, carbon monoxide to a designated location.
NAME VARIANTS: Dryer exhaust vent; Air vent; Dryer lent trap box; Dryer lent trap box with water reservoir
COMMON MATERIALS: Metal; Vinyl; PVC; Aluminum; Plastic
COMMON COMPONENTS: Transition duct; Metal or aluminum ductwork; External louvered vent and cover; Water reservoir
LOCATION: Unit Laundry room, washer and dryer area
 Inside Laundry room, washer and dryer area
 Outside External louvered vent and cover
MORE INFORMATION: None

DEFICIENCY 1: Electric dryer vent is missing, detached, or has a hole
LOCATION: Unit Inside

DEFICIENCY 2: Gas dryer vent is missing, detached, or has a hole
LOCATION: Unit Inside

DEFICIENCY 3: Dryer vent has restricted airflow
LOCATION: Unit Inside

DEFICIENCY 4: Exterior dryer vent cover missing or damaged
LOCATION: Outside

DEFICIENCY 5: Gas dryer vent of unsuitable material has been installed
LOCATION: Unit Inside

DEFICIENCY 6: Exterior dryer vent cover is blocked
LOCATION: Outside

DEFICIENCY I — UNIT: ELECTRIC DRYER VENT IS MISSING, DETACHED, OR HAS A HOLE

DEFICIENCY CRITERIA: Dryer vent is missing, detached, or has a hole.

HEALTH AND SAFETY DETERMINATION: Standard This is a standard health and safety issue. A repair, correction, or act of abatement for this deficiency should occur within 30 days.

CORRECTION TIMEFRAME: Within 30 days

HCV — CORRECTION TIMEFRAME: Within 30 days

RATIONALE:

CODE	CATEGORY	TYPE	DESCRIPTION	EXPLANATION
R1	Health	Direct	Condition could affect resident's mental, or physical, or psychological state.	If dryer vent is missing, detached, or has a hole, then resident's air quality may be impacted.
R2	Safety	Direct	Resident could be injured because of this condition.	If dryer vent is missing, detached, or has a hole, then this could create a fire hazard.
R6	Usability and Operability of Fixtures	Direct	Because of this condition, the resident is unable to use certain fixtures, features, or appliances, which are reasonably assumed to be part of their rent.	If the dryer vent is missing, detached, or has a hole, then resident may not be able to use an appliance that is expected to be provided and maintained as part of their rent.
M1	Corrective Maintenance	Direct	It is reasonable to expect a tenant to report this deficiency, and for facilities management to prioritize a work order response to fix that deficiency.	If the dryer vent is missing, detached, or has a hole, then the resident will likely report this deficiency and its presence may indicate that complaint-based work orders are not being addressed.
M2	Routine Maintenance	Direct	It is reasonable to expect that this deficiency would be identified through routine daily observations and facilities management would prioritize work orders to fix this deficiency.	If the dryer vent is missing, detached, or has a hole, then this will likely be identified through routine maintenance activities and its presence may indicate that self-generated work orders are not being addressed.

INSPECTION PROCESS:

- OBSERVATION:**
- Look behind the clothes dryer and attempt to locate the dryer vent.
 - If unable to locate dryer vent, look behind the clothes dryer and observe if there is an accumulation of dryer lint, which indicates that a dryer vent may be missing or detached from the dryer or the wall.
 - Look for holes in the dryer vent
- REQUEST FOR HELP:** - None
- ACTION:** - None
- More Information:** - Use of a dryer vent lint trap box with water reservoir is allowed on electric dryers only.

- The reservoir must be filled with water.
- Listed and labeled condensing (ductless) dryers are exempt.

TOOLS OR EQUIPMENT:

- REQUIRED: - Flashlight
- USEFUL: - Inspection mirror

DEFICIENCY I — INSIDE: ELECTRIC DRYER VENT IS MISSING, DETACHED, OR HAS A HOLE

DEFICIENCY CRITERIA: Dryer vent is missing, detached, or has a hole.

HEALTH AND SAFETY DETERMINATION: Standard This is a standard health and safety issue. A repair, correction, or act of abatement for this deficiency should occur within 30 days.

CORRECTION TIMEFRAME: Within 30 days

HCV — CORRECTION TIMEFRAME: Within 30 days

RATIONALE:

CODE	CATEGORY	TYPE	DESCRIPTION	EXPLANATION
R1	Health	Direct	Condition could affect resident's mental, or physical, or psychological state.	If dryer vent is missing, detached, or has a hole, then resident's air quality may be impacted.
R2	Safety	Direct	Resident could be injured because of this condition.	If dryer vent is missing, detached, or has a hole, then this could create a fire hazard.
R6	Usability and Operability of Fixtures	Direct	Because of this condition, the resident is unable to use certain fixtures, features, or appliances, which are reasonably assumed to be part of their rent.	If the dryer vent is missing, detached, or has a hole, then resident may not be able to use an appliance that is expected to be provided and maintained as part of their rent.
M1	Corrective Maintenance	Direct	It is reasonable to expect a tenant to report this deficiency, and for facilities management to prioritize a work order response to fix that deficiency.	If the dryer vent is missing, detached, or has a hole, then the resident will likely report this deficiency and its presence may indicate that complaint-based work orders are not being addressed.
M2	Routine Maintenance	Direct	It is reasonable to expect that this deficiency would be identified through routine daily observations and facilities management would prioritize work orders to fix this deficiency.	If the dryer vent is missing, detached, or has a hole, then this will likely be identified through routine maintenance activities and its presence may indicate that self-generated work orders are not being addressed.

INSPECTION PROCESS:

- OBSERVATION:**
- Look behind the clothes dryer and attempt to locate the dryer vent.
 - If unable to locate dryer vent, look behind the clothes dryer and observe if there is an accumulation of dryer lint, which indicates that a dryer vent may be missing or detached from the dryer or the wall.
 - Look for holes in the dryer vent
- REQUEST FOR HELP:** - None
- ACTION:** - None
- More Information:** - Use of a dryer vent lint trap box with water reservoir is allowed on electric dryers only.

- The reservoir must be filled with water.
- Listed and labeled condensing (ductless) dryers are exempt.

TOOLS OR EQUIPMENT:

- REQUIRED: - Flashlight
- USEFUL: - Inspection mirror

DEFICIENCY 2 — UNIT: GAS DRYER VENT IS MISSING, DETACHED, OR HAS A HOLE

DEFICIENCY CRITERIA: Gas dryer vent is missing, detached, has a hole.

HEALTH AND SAFETY DETERMINATION: Life-Threatening This is a life-threatening issue requiring a 24-hour repair, correction, or act of abatement.

CORRECTION TIMEFRAME: 24 hours

HCV — CORRECTION TIMEFRAME: 24 hours

RATIONALE:

CODE	CATEGORY	TYPE	DESCRIPTION	EXPLANATION
R1	Health	Direct	Condition could affect resident's mental, or physical, or psychological state.	If dryer vent is missing, detached, or has a hole, then resident's air quality may be impacted.
R2	Safety	Direct	Resident could be injured because of this condition.	If dryer vent is missing, detached, or has a hole, then this could create a fire hazard.
R6	Usability and Operability of Fixtures	Direct	Because of this condition, the resident is unable to use certain fixtures, features, or appliances, which are reasonably assumed to be part of their rent.	If the dryer vent is missing, detached, or has a hole, then resident may not be able to use an appliance that is expected to be provided and maintained as part of their rent.
M1	Corrective Maintenance	Direct	It is reasonable to expect a tenant to report this deficiency, and for facilities management to prioritize a work order response to fix that deficiency.	If the dryer vent is missing, detached, or has a hole, then the resident will likely report this deficiency and its presence may indicate that complaint-based work orders are not being addressed.
M2	Routine Maintenance	Direct	It is reasonable to expect that this deficiency would be identified through routine daily observations and facilities management would prioritize work orders to fix this deficiency.	If the dryer vent is missing, detached, or has a hole, then this will likely be identified through routine maintenance activities and its presence may indicate that self-generated work orders are not being addressed.

INSPECTION PROCESS:

- OBSERVATION:
- Look behind the clothes dryer and attempt to locate the dryer vent.
 - If unable to locate dryer vent, look behind the clothes dryer and observe if there is an accumulation of dryer lint, which indicates that a dryer vent may be missing or detached from the dryer or the wall.
 - Verify gas dryer vent is of metal material suitable.
- REQUEST FOR HELP: - None
- ACTION: - None
- More Information:
- Use of a dryer vent lint trap box with water reservoir is not allowed on gas dryers.
 - If found connected to a gas dryer record a deficiency.

TOOLS OR EQUIPMENT:

REQUIRED: - Flashlight; Inspection mirror

USEFUL: - None

DEFICIENCY 2 — INSIDE: GAS DRYER VENT IS MISSING, DETACHED, OR HAS A HOLE

DEFICIENCY CRITERIA: Gas dryer vent is missing, detached, has a hole.

HEALTH AND SAFETY DETERMINATION: Life-Threatening This is a life-threatening issue requiring a 24-hour repair, correction, or act of abatement.

CORRECTION TIMEFRAME: 24 hours

HCV — CORRECTION TIMEFRAME: 24 hours

RATIONALE:

CODE	CATEGORY	TYPE	DESCRIPTION	EXPLANATION
R1	Health	Direct	Condition could affect resident's mental, or physical, or psychological state.	If dryer vent is missing, detached, or has a hole, then resident's air quality may be impacted.
R2	Safety	Direct	Resident could be injured because of this condition.	If dryer vent is missing, detached, or has a hole, then this could create a fire hazard.
R6	Usability and Operability of Fixtures	Direct	Because of this condition, the resident is unable to use certain fixtures, features, or appliances, which are reasonably assumed to be part of their rent.	If the dryer vent is missing, detached, or has a hole, then resident may not be able to use an appliance that is expected to be provided and maintained as part of their rent.
M1	Corrective Maintenance	Direct	It is reasonable to expect a tenant to report this deficiency, and for facilities management to prioritize a work order response to fix that deficiency.	If the dryer vent is missing, detached, or has a hole, then the resident will likely report this deficiency and its presence may indicate that complaint-based work orders are not being addressed.
M2	Routine Maintenance	Direct	It is reasonable to expect that this deficiency would be identified through routine daily observations and facilities management would prioritize work orders to fix this deficiency.	If the dryer vent is missing, detached, or has a hole, then this will likely be identified through routine maintenance activities and its presence may indicate that self-generated work orders are not being addressed.

INSPECTION PROCESS:

OBSERVATION:

- Look behind the clothes dryer and attempt to locate the dryer vent.
- If unable to locate dryer vent, look behind the clothes dryer and observe if there is an accumulation of dryer lint, which indicates that a dryer vent may be missing or detached from the dryer or the wall.
- Verify gas dryer vent is of metal material suitable.

REQUEST FOR HELP: - None

ACTION: - None

More Information:

- Use of a dryer vent lint trap box with water reservoir is not allowed on gas dryers.
- If found connected to a gas dryer record a deficiency.

TOOLS OR EQUIPMENT:

REQUIRED: - Flashlight; Inspection mirror

USEFUL: - None

DEFICIENCY 3 — UNIT: DRYER VENT HAS RESTRICTED AIRFLOW

DEFICIENCY CRITERIA: Dryer vent has restricted airflow.

HEALTH AND SAFETY DETERMINATION: Life-Threatening This is a life-threatening issue requiring a 24-hour repair, correction, or act of abatement.

CORRECTION TIMEFRAME: 24 hours

HCV — CORRECTION TIMEFRAME: 24 hours

RATIONALE:

CODE	CATEGORY	TYPE	DESCRIPTION	EXPLANATION
R1	Health	Direct	Condition could affect resident's mental, or physical, or psychological state.	If dryer vent has restricted airflow, then resident's air quality may be impacted.
R2	Safety	Indirect	Resident could be injured because of this condition.	If dryer vent has restricted airflow, and the vent achieves a high enough temperature, then this could create a fire hazard.
R6	Usability and Operability of Fixtures	Direct	Because of this condition, the resident is unable to use certain fixtures, features, or appliances, which are reasonably assumed to be part of their rent.	If dryer vent has restricted airflow, then resident may not be able to use an appliance that is expected to be provided and maintained as part of their rent.
M1	Corrective Maintenance	Direct	It is reasonable to expect a tenant to report this deficiency, and for facilities management to prioritize a work order response to fix that deficiency.	If dryer vent has restricted airflow, then the resident will likely report this deficiency and its presence may indicate that complaint-based work orders are not being addressed.
M2	Routine Maintenance	Direct	It is reasonable to expect that this deficiency would be identified through routine daily observations and facilities management would prioritize work orders to fix this deficiency.	If dryer vent has restricted airflow, then this will likely be identified through routine maintenance activities and its presence may indicate that self-generated work orders are not being addressed.

INSPECTION PROCESS:

- OBSERVATION:
- Look at the dryer vent and identify the flexible duct line.
 - Look at the entire duct line that runs from the back of the dryer into the wall.
 - Look for crushed pipe or any unintentionally designed kinks in the ductwork.
- REQUEST FOR HELP: - None
- ACTION:
- Ask the resident or POA if they smell a burning smell when dryer is active
 - Ask the resident or POA if there is an increased drying time.

- More Information:
- Improvised filter materials (e.g., stockings, t-shirts, etc.) attached at the end of a dryer vent pipe and terminated inside the unit is considered blocked or restricted air flow.
 - For the purpose of this inspection, vent elbows that are designed to direct air at a 90-degree angle should not be recorded as a deficiency.

TOOLS OR EQUIPMENT:

- REQUIRED:** - Flashlight
- USEFUL:** - Inspection mirror
-

DEFICIENCY 3 — INSIDE: DRYER VENT HAS RESTRICTED AIRFLOW

DEFICIENCY CRITERIA: Dryer vent has restricted airflow.

HEALTH AND SAFETY DETERMINATION: Life-Threatening This is a life-threatening issue requiring a 24-hour repair, correction, or act of abatement.

CORRECTION TIMEFRAME: 24 hours

HCV — CORRECTION TIMEFRAME: 24 hours

RATIONALE:

CODE	CATEGORY	TYPE	DESCRIPTION	EXPLANATION
R1	Health	Direct	Condition could affect resident's mental, or physical, or psychological state.	If dryer vent has restricted airflow, then resident's air quality may be impacted.
R2	Safety	Indirect	Resident could be injured because of this condition.	If dryer vent has restricted airflow, and the vent achieves a high enough temperature, then this could create a fire hazard.
R6	Usability and Operability of Fixtures	Direct	Because of this condition, the resident is unable to use certain fixtures, features, or appliances, which are reasonably assumed to be part of their rent.	If dryer vent has restricted airflow, then resident may not be able to use an appliance that is expected to be provided and maintained as part of their rent.
M1	Corrective Maintenance	Direct	It is reasonable to expect a tenant to report this deficiency, and for facilities management to prioritize a work order response to fix that deficiency.	If dryer vent has restricted airflow, then the resident will likely report this deficiency and its presence may indicate that complaint-based work orders are not being addressed.
M2	Routine Maintenance	Direct	It is reasonable to expect that this deficiency would be identified through routine daily observations and facilities management would prioritize work orders to fix this deficiency.	If dryer vent has restricted airflow, then this will likely be identified through routine maintenance activities and its presence may indicate that self-generated work orders are not being addressed.

INSPECTION PROCESS:

- OBSERVATION:
- Look at the dryer vent and identify the flexible duct line.
 - Look at the entire duct line that runs from the back of the dryer into the wall.
 - Look for crushed pipe or any unintentionally designed kinks in the ductwork.
- REQUEST FOR HELP: - None
- ACTION:
- Ask the resident or POA if they smell a burning smell when dryer is active
 - Ask the resident or POA if there is an increased drying time.

- More Information:
- Improvised filter materials (e.g., stockings, t-shirts, etc.) attached at the end of a dryer vent pipe and terminated inside the unit is considered blocked or restricted air flow.
 - For the purpose of this inspection, vent elbows that are designed to direct air at a 90-degree angle should not be recorded as a deficiency.

TOOLS OR EQUIPMENT:

- REQUIRED:** - Flashlight
- USEFUL:** - Inspection mirror
-

DEFICIENCY 4 — OUTSIDE: EXTERIOR DRYER VENT COVER MISSING OR DAMAGED

DEFICIENCY CRITERIA: Exterior dryer vent cover is missing (i.e. evidence of prior installation, but now not present or is incomplete).

OR

Exterior dryer vent cover is damaged (i.e. visibly defective; impacts functionality).

HEALTH AND SAFETY DETERMINATION: Standard This is a standard health and safety issue. A repair, correction, or act of abatement for this deficiency should occur within 30 days.

CORRECTION TIMEFRAME: Within 30 days

HCV — CORRECTION TIMEFRAME: Within 30 days

RATIONALE:

CODE	CATEGORY	TYPE	DESCRIPTION	EXPLANATION
R1	Health	Direct	Condition could affect resident's mental, or physical, or psychological state.	If exterior dryer vent cover is missing or damaged, then resident's air quality may be impacted.
R2	Safety	Direct	Resident could be injured because of this condition.	If exterior dryer vent cover is missing or damaged, then this could create an access point for pests.
M2	Routine Maintenance	Direct	It is reasonable to expect that this deficiency would be identified through routine daily observations and facilities management would prioritize work orders to fix this deficiency.	If exterior dryer vent cover is missing or damaged, then this will likely be identified through routine maintenance activities and its presence may indicate that self-generated work orders are not being addressed.

INSPECTION PROCESS:

OBSERVATION: - Look at vent covers on the exterior wall of the building.
 - Identify vent covers that are missing or damaged.
 - Identify vent covers that are missing rain covers or louvers.

REQUEST FOR HELP: - None

ACTION: - None

More Information: - None

TOOLS OR EQUIPMENT:

REQUIRED: - None

USEFUL: - Flashlight; Inspection mirror

DEFICIENCY 5 — UNIT: GAS DRYER VENT OF UNSUITABLE MATERIAL HAS BEEN INSTALLED

DEFICIENCY CRITERIA: Gas dryer vent is not constructed of metal.

HEALTH AND SAFETY DETERMINATION: Standard This is a standard health and safety issue. A repair, correction, or act of abatement for this deficiency should occur within 30 days.

CORRECTION TIMEFRAME: Within 30 days

HCV — CORRECTION TIMEFRAME: Within 30 days

RATIONALE:

CODE	CATEGORY	TYPE	DESCRIPTION	EXPLANATION
R2	Safety	Direct	Resident could be injured because of this condition.	If exhaust duct is constructed of unsuitable material, then it may cause a fire hazard.
M2	Routine Maintenance	Direct	It is reasonable to expect that this deficiency would be identified through routine daily observations and facilities management would prioritize work orders to fix this deficiency.	If exhaust duct is constructed of unsuitable material, then this will likely be identified through routine maintenance activities and its presence may indicate that self-generated work orders are not being addressed.

INSPECTION PROCESS:

OBSERVATION: - Look at the gas dryer vent and determine if the it is constructed of metal.

REQUEST FOR HELP: - None

ACTION: - None

More Information: - None

TOOLS OR EQUIPMENT:

REQUIRED: - None

USEFUL: - Flashlight

DEFICIENCY 5 — INSIDE: GAS DRYER VENT OF UNSUITABLE MATERIAL HAS BEEN INSTALLED

DEFICIENCY CRITERIA: Gas dryer vent is not constructed of metal.

HEALTH AND SAFETY DETERMINATION: Standard This is a standard health and safety issue. A repair, correction, or act of abatement for this deficiency should occur within 30 days.

CORRECTION TIMEFRAME: Within 30 days

HCV — CORRECTION TIMEFRAME: Within 30 days

RATIONALE:

CODE	CATEGORY	TYPE	DESCRIPTION	EXPLANATION
R2	Safety	Direct	Resident could be injured because of this condition.	If exhaust duct is constructed of unsuitable material, then it may cause a fire hazard.
M2	Routine Maintenance	Direct	It is reasonable to expect that this deficiency would be identified through routine daily observations and facilities management would prioritize work orders to fix this deficiency.	If exhaust duct is constructed of unsuitable material, then this will likely be identified through routine maintenance activities and its presence may indicate that self-generated work orders are not being addressed.

INSPECTION PROCESS:

OBSERVATION: - Look at the gas dryer vent and determine if the it is constructed of metal.

REQUEST FOR HELP: - None

ACTION: - None

More Information: - None

TOOLS OR EQUIPMENT:

REQUIRED: - None

USEFUL: - Flashlight

DEFICIENCY 6 — OUTSIDE: EXTERIOR DRYER VENT COVER IS BLOCKED

DEFICIENCY CRITERIA: Vent cover is blocked.

HEALTH AND SAFETY DETERMINATION: Life-Threatening This is a life-threatening issue requiring a 24-hour repair, correction, or act of abatement.

CORRECTION TIMEFRAME: 24 hours

HCV — CORRECTION TIMEFRAME: 24 hours

RATIONALE:

CODE	CATEGORY	TYPE	DESCRIPTION	EXPLANATION
R1	Health	Direct	Condition could affect resident's mental, or physical, or psychological state.	If exterior dryer vent cover is blocked, then resident's air quality may be impacted.
R2	Safety	Direct	Resident could be injured because of this condition.	If exterior dryer vent cover is blocked, then this could create a fire hazard.
R6	Usability and Operability of Fixtures	Direct	Because of this condition, the resident is unable to use certain fixtures, features, or appliances, which are reasonably assumed to be part of their rent.	If exterior dryer vent cover is blocked, then resident may not be able to use an appliance that is expected to be provided and maintained as part of their rent.
M1	Corrective Maintenance	Direct	It is reasonable to expect a tenant to report this deficiency, and for facilities management to prioritize a work order response to fix that deficiency.	If exterior dryer vent cover is blocked, then the resident will likely report this deficiency and its presence may indicate that complaint-based work orders are not being addressed.
M2	Routine Maintenance	Direct	It is reasonable to expect that this deficiency would be identified through routine daily observations and facilities management would prioritize work orders to fix this deficiency.	If exterior dryer vent cover is blocked, then this will likely be identified through routine maintenance activities and its presence may indicate that self-generated work orders are not being addressed.

INSPECTION PROCESS:

OBSERVATION: - Look for vent covers that are blocked or clogged with lint or any foreign material (e.g., bird's nest).

REQUEST FOR HELP: - None

ACTION: - None

More Information: - None



NATIONAL STANDARDS FOR THE PHYSICAL INSPECTION OF REAL ESTATE

TOOLS OR EQUIPMENT:

REQUIRED: - None

USEFUL: - None

SUMMARY OF CHANGES

TITLE: DRYER VENT
VERSION: VI.3
DATE PUBLISHED: 7/31/20

FIELD	CHANGE	VERSION	DATE
Overall Formatting	Complete rework of document format and layout	VI.3	2020-07-31
Definition	Revised definition	VI.3	2020-07-31
Purpose	Field added	VI.3	2020-07-31
Name Variants	Revised name variants	VI.3	2020-07-31
Common Materials	Revised common materials	VI.3	2020-07-31
Common Components	Revised common components	VI.3	2020-07-31
Location	Revised inspectable locations	VI.3	2020-07-31
More Information	Field added	VI.3	2020-07-31
Deficiency 1	Separated by inspectable locations — Unit and Inside	VI.3	2020-07-31
Title	Revised title; added inspectable locations		
Deficiency Criteria	Revised deficiency criteria		
Health and Safety Determination	Revised to “Standard” determination; added standardized description		
Correction Timeframe	Field added; response input as “Within 30 days”		
HCV — Correction Timeframe	Field added; response input as “Within 30 days”		
Rationale	Revised rationale categories, types, and explanations; added standardized codes and descriptions		
Inspection Process	Revised observation, request for help, action, and more information		
Tools or Equipment	Field added to deficiency; response revised		
Deficiency 2	Separated by inspectable locations — Unit and Inside	VI.3	2020-07-31
Title	Revised title; added inspectable locations		
Deficiency Criteria	Revised deficiency criteria		
Health and Safety Determination	Revised to “Life-Threatening” determination; added standardized description		

Correction Timeframe	Field added; response input as "24 hours"		
HCV – Correction Timeframe	Field added; response input as "24 hours"		
Rationale	Revised rationale categories, types, and explanations; added standardized codes and descriptions		
Inspection Process	Revised observation, request for help, action, and more information		
Tools or Equipment	Field added to deficiency; response revised		
Deficiency 3	Separated by inspectable locations – Unit and Inside	VI.3	2020-07-31
Title	Added inspectable locations		
Health and Safety Determination	Revised to "Life-Threatening" determination; added standardized description		
Correction Timeframe	Field added; response input as "24 hours"		
HCV – Correction Timeframe	Field added; response input as "24 hours"		
Rationale	Revised rationale categories, types, and explanations; added standardized codes and descriptions		
Inspection Process	Revised observation, request for help, action, and more information		
Tools or Equipment	Field added to deficiency; response revised		
Deficiency 4	Added by inspectable location – Outside	VI.3	2020-07-31
Title	Added title; added inspectable location		
Deficiency Criteria	Added deficiency criteria		
Health and Safety Determination	Added "Standard" determination; added standardized description		
Correction Timeframe	Field added; response input as "Within 30 days"		
HCV – Correction Timeframe	Field added; response input as "Within 30 days"		
Rationale	Added rationale categories, types, and explanations; added standardized codes and descriptions		
Inspection Process	Added observation, request for help, action, and more information		
Tools or Equipment	Field added to deficiency		
Deficiency 5	Added by inspectable locations – Unit and Inside	VI.3	2020-07-31
Title	Added title; added inspectable locations		
Deficiency Criteria	Added deficiency criteria		
Health and Safety Determination	Added "Standard" determination; added standardized description		
Correction Timeframe	Field added; response input as "Within 30 days"		

HCV – Correction Timeframe	Field added; response input as “Within 30 days”
Rationale	Added rationale categories, types, and explanations; added standardized codes and descriptions
Inspection Process	Added observation, request for help, action, and more information
Tools or Equipment	Field added to deficiency
Deficiency 6	Added by inspectable location — Outside
	VI.3
	2020-07-31
Title	Added title; added inspectable location
Deficiency Criteria	Added deficiency criteria
Health and Safety Determination	Revised to “Life-Threatening” determination; added standardized description
Correction Timeframe	Field added; response input as “24 hours”
HCV – Correction Timeframe	Field added; response input as “24 hours”
Rationale	Added rationale categories, types, and explanations; added standardized codes and descriptions
Inspection Process	Added observation, request for help, action, and more information
Tools or Equipment	Field added to deficiency