09/03/2020

TITLE V, FEDERAL SURPLUS PROPERTY PROGRAM FEDERAL REGISTER REPORT FOR 09/04/2020

SUITABLE / AVAILABLE PROPERTIES LAND INDIANA

New Albany Parking Lot See Directions New Albany IN 47150 Landholding Agency: GSA Property Number: 54202030003 Status: Excess GSA Number: 1-G-IN-629 Directions: Corner of W. Market Street Comments: 0.47 acres of land; contact GSA for more information.

UNSUITABLE PROPERTIES BUILDING ARKANSAS

Shower House 1700 Lock & Dam Road Barling AR 72923 Landholding Agency: USACE Property Number: 31202030012 Status: Excess Directions: Springhill Park-James W. Trimble Lock & Dam Project Comments: Not structurally sound for relocation, dilapidated and in a constant state of repair Reasons: Structural Damage - Extensive Deterioration

UNSUITABLE PROPERTIES BUILDING MISSOURI

40X48 Pole Barn 16123 Mount Olivet Road Smithville MO 64089 Landholding Agency: USACE Property Number: 31202030011 Status: Unutilized Directions: Smithville Lake #01006 SMTHVL -28275 Comments: Building is condemned and ready to fall. Reasons: Structural Damage - Extensive Deterioration

OREGON

Toilet, Aspen Cabin See Directions Lakeview OR 97630 Landholding Agency: USDA Property Number: 15202030085 Status: Excess Directions: 07658 00 (1484.004681) MP 7.4 on FSR 3615 Comments: Contains human waste, biohazard. Poor condition Reasons: Documented Deficiencies-Contamination. Structural Damage - Extensive Deterioration

UNSUITABLE PROPERTIES BUILDING WASHINGTON

D5 Sullivan Lk W CG Picnic She See Directions Pend Oreille WA 99153 Landholding Agency: USDA Property Number: 15202030086 Status: Excess Directions: (1555.005691) Sullivan Lake West Campground Comments: Structural supports rotten and hollow; building is falling down. Insect infestation. Floodway.

Reasons:

Environmental. Structural Damage - Extensive Deterioration. Floodway

ARKANSAS

Waterborne Restrooms 1700 Lock & Dam Road Barling AR 72923 Landholding Agency: USACE Property Number: 31202030010 Status: Underutilized Directions: Springhill Park-James W. Trimble Lock & Dam Project Comments: Not structurally sound for relocation, dilapidated and in a constant state of repair.

Reasons:

Other - Bldg. materials-concrete masonry. Structural Damage - Extensive Deterioration