03/09/2022

# TITLE V, FEDERAL SURPLUS PROPERTY PROGRAM FEDERAL REGISTER REPORT FOR 03/11/2022

# SUITABLE / AVAILABLE PROPERTIES BUILDING OKLAHOMA

Greenhouse 15 1301 North Western Road Stillwater OK 74075

Landholding Agency: USDA-ARS Property Number: 14202210004

Status: Excess Directions:

CPAIS-RP #621700B015 RPUID #3.50711. Latitude: 36.117393, Longitude -97.094431. Structure located on University/Agricultural Research Land. Structure only.

## Comments:

Offsite removal only. 43-yr-old, 2,976 SF greenhouse. Plumb, HVAC, and electrical need replaced/repaired as soon as possible. Estimated cost as of 2017 was \$30,000. Structurally sound. Contact Agency for more information.

Headhouse 16 1301 North Western Road Stillwater OK 74075

Landholding Agency: USDA-ARS Property Number: 14202210005

Status: Excess Directions:

CPAIS-RP #621700B016, RPUID # 3.50712 Latitude: 36.117395, Longitude: -97.094599. Located on University/Agricultural Research land, structure only. Requires permission to access the site.

## Comments:

Offsite removal only. 42-yr-old, 1,880 SF Headhouse. Interior finishes & electrical need repair as soon as possible. Estimated cost as of 2017 was \$26,000. Structurally sound. Contact Agency for more information.

# UNSUITABLE PROPERTIES BUILDING WEST VIRGINIA

Well Pump House See Directions Elkins WV 26241

Landholding Agency: USDA-FS Property Number: 13202210024

Status: Unutilized

Directions:

Located at Stuart Recreation Area, Monongahela National Forest. Area is open to the public May through September, sun-up to sun-down.

## Comments:

Offsite removal only. 5-yr-old, 16 SF wood framed abandoned water-well pump house. Structurally unsound floors, roof, exterior and interior walls. Roof leaks, and walls are delaminating. Utilities have been removed.

## Reasons:

Structural Damage - Extensive Deterioration