TITLE V, FEDERAL SURPLUS PROPERTY PROGRAM FEDERAL REGISTER REPORT FOR 01/12/2024

1

SUITABLE / AVAILABLE PROPERTIES

LAND

ALASKA

106.84 acres Glenn Hwy

Boniface Parkway and Muldoon Road

Anchorage AK 99506 Landholding Agency: GSA Property Number: 54202410001

Status: Excess

GSA Number: 9-D-AK-1309-AA

Directions:

Landholding Agency: Air Force; Disposal Agency: GSA

Comments:

The State was granted an indefinite easement for the entire 106.84 acres from Air

Force prior to the land being excessed. It is a public highway.

Summary for SUITABLE / AVAILABLE

Total number of = 1

UNSUITABLE PROPERTIES BUILDING COLORADO

Q-0105-H ESD 2-BDRM HOUSE;

Q-0100A&B-H Duplex

Ptarmingan Lane
Estes Park CO 80517

Landholding Agency: DOI-NPS Property Number: 61202410005

Status: Excess Directions:

RPUID:27365, 27372; PMIS:252926, 252926

Reasons:

Structural Damage - Extensive Deterioration Documented Deficiencies-Contamination

Comments:

Structure documented as below average including interior & exterior, strutures,

windows & doors. ACM and LBP throughout interior and exterior.

BUILDING

COLORADO

Q-0269-H ESD 1-BDRM HOUSE

Marmot Drive

Estes Park CO 80517

Landholding Agency: DOI-NPS Property Number: 61202410006

Status: Excess Directions:

RPUID:30317; PMIS#529312

Reasons:

Structural Damage - Extensive Deterioration Documented Deficiencies-Contamination

Comments:

Structure documented as below average including interior & exterior, strutures,

windows & doors. ACM and LBP throughout interior and exterior.

Q-0749-N ESD EFFICIENCY CABIN

Aspen Glen Campground Road

Estes Park CO 80517

Landholding Agency: DOI-NPS Property Number: 61202410007

Status: Excess Directions:

RPUID:24068; PMIS#252931

Reasons:

Structural Damage - Extensive Deterioration Documented Deficiencies-Contamination

Comments:

Structure documented as below average including interior & exterior, strutures,

windows & doors. ACM and LBP throughout interior and exterior.

UNSUITABLE PROPERTIES BUILDING FLORIDA

Storage Building J-1717 1002 Saddlebunch Road

Key West FL 33040

Landholding Agency: DoD-USN-USMC Property Number: 77202410006

Status: Unutilized

Reasons:

National Security Concerns

Comments:

Active Military Installation, no public access.

Transmitter Building J-1561 1000 Saddlebunch Road

Key West FL 33040

Landholding Agency: DoD-USN-USMC

Property Number: 77202410007

Status: Unutilized

Reasons:

National Security Concerns

Comments:

Active Military Installation, no public access.

Storage Building J-1700 1004 Saddlebunch Road

Key West FL 33040

Landholding Agency: DoD-USN-USMC

Property Number: 77202410008

Status: Unutilized

Reasons:

National Security Concerns

Comments:

Active Military Installation, no public access.

Building A-1036 994 Hawk Missle Road Key West FL 33040

Landholding Agency: DoD-USN-USMC

Property Number: 77202410009

Status: Unutilized

Reasons:

BUILDING

FLORIDA

National Security Concerns

Comments:

Active Military Installation, no public access.

Building A-332 Administrative 8220 Forrestal Street Key West FL 33040

Landholding Agency: DoD-USN-USMC

Property Number: 77202410010

Status: Unutilized

Reasons:

National Security Concerns

Comments:

Active Military Installation, no public access.

A-515, Training Facility 7850 Langley Avenue Key West FL 33040

Landholding Agency: DoD-USN-USMC

Property Number: 77202410011

Status: Underutilized

Reasons:

National Security Concerns

Comments:

Active Military Installation, no public access.

Building A-805 Small Arms Road Key West FL 33040

Landholding Agency: DoD-USN-USMC

Property Number: 77202410012

Status: Unutilized

Reasons:

Runway clear zone and military airfield clear zone Structural Damage - Extensive Deterioration

National Security Concerns

Comments:

Active Military Installation, no public access. Property located within an airport runway

and do to documented deficiencies it doesn't meet criteria.

BUILDING

FLORIDA

Building A-806 Small Arms Road Key West FL 33040

Landholding Agency: DoD-USN-USMC

Property Number: 77202410013

Status: Unutilized

Reasons:

National Security Concerns

Structural Damage - Extensive Deterioration Runway clear zone and military airfield clear zone

Comments:

Active Military Installation, no public access. Property located within an airport runway

and do to documented deficiencies it doesn't meet criteria.

Building A-807 Small Arms Road Key West FL 33040

Landholding Agency: DoD-USN-USMC Property Number: 77202410014

Status: Unutilized

Reasons:

National Security Concerns

Runway clear zone and military airfield clear zone Structural Damage - Extensive Deterioration

Comments:

Active Military Installation, no public access. Property located within an airport runway

and do to documented deficiencies it doesn't meet criteria.

Building A-808 Small Arms Road Key West FL 33040

Landholding Agency: DoD-USN-USMC

Property Number: 77202410015

Status: Unutilized

Reasons:

Structural Damage - Extensive Deterioration

National Security Concerns

Runway clear zone and military airfield clear zone

Comments:

Active Military Installation, no public access. Property located within an airport runway

and do to documented deficiencies it doesn't meet criteria.

BUILDING

FLORIDA

Shredder/Incinerator Building

A-1005

1321 East Side Road Key West FL 33040

Landholding Agency: DoD-USN-USMC Property Number: 77202410016

Status: Unutilized

Reasons:

Runway clear zone and military airfield clear zone Structural Damage - Extensive Deterioration

National Security Concerns

Comments:

Active Military Installation, no public access. Property located within an airport runway

and do to documented deficiencies it doesn't meet criteria.

Building A-1034 996 Hawk Missle Road

Key West FL 33040

Landholding Agency: DoD-USN-USMC Property Number: 77202410017

Status: Unutilized

Reasons:

Runway clear zone and military airfield clear zone Structural Damage - Extensive Deterioration

National Security Concerns

Comments:

Active Military Installation, no public access. Property located within an airport runway

and do to documented deficiencies it doesn't meet criteria.

Building A-1035 Hawk Missle Road Key West FL 33040

Landholding Agency: DoD-USN-USMC

Property Number: 77202410018

Status: Unutilized

Reasons:

Runway clear zone and military airfield clear zone Structural Damage - Extensive Deterioration

National Security Concerns

Comments:

Active Military Installation, no public access. Property located within an airport runway

and do to documented deficiencies it doesn't meet criteria.

BUILDING

FLORIDA

IDAHO

Crawford Guard Station 304 Warm Lake Road

Cascade ID

Landholding Agency: USDA-FS Property Number: 13202410005

Status: Unutilized

Reasons:

Documented Deficiencies-Contamination

National Security Concerns

Comments:

Nature of the contaminants is Asbestos. Poor condition of all features, requires maintenance exceeding the cost of full reconstruction influencing proposal to decommission and excessive maintenance.

MARYLAND

Katie Poffenberger House 5834 Dunker Church Rd. Sharpsburg MD 21782

Sharpsburg MD 21762

Landholding Agency: DOI-NPS Property Number: 61202410008

Status: Excess Directions:

RPUID:257841

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Water is infiltrating the interior, plaster is failing between the 1st & 2nd floor; floor is rotten, sagging & unstable. The chimney is crumbing where the water is infiltrating. Attic

inaccessible.

Katie Poffenberger Shed 5834 Dunker Church Rd. Sharpsburg MD 21872

Landholding Agency: DOI-NPS Property Number: 61202410009

Status: Excess Directions:

RPUID:25702

Reasons:

Structural Damage - Extensive Deterioration

Comments:

BUILDING

MARYLAND

Building is in poor condition; over grown with vegetation, most of the wooden walls have rotten boards, and the roof is collapsing in.

Katie Poffenberger Barn 5834 Dunker Church Rd. Sharpsburg MD 21782

Landholding Agency: DOI-NPS Property Number: 61202410010

Status: Excess Directions:

RPUID:257901

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Building is in poor condition; the barn is structurally unstable with extensive rot on the

rafters and some supports.

Katie Poffenberger Pole Barn 5834 Dunker Church Rd. Sharpsburg MD 21782

Landholding Agency: DOI-NPS Property Number: 61202410011

Status: Excess Directions:

RPUID:257903

Reasons:

Environmental

Comments:

The structure was already removed and there is no value in moving the remaining

concrete slab.

BUILDING

MICHIGAN

Stanford Crew Quarters

405 2nd Ave N

Stanford MI 59479

Landholding Agency: USDA-FS Property Number: 13202410002

Status: Excess Directions:

RPUID: 2832.000851; Asset ID: 1311

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Building is dilapidated and in poor condition.

MISSISSIPPI

Building 316 and related structures Marque @ Bldg 445 334 Marvin Shields Blvd

Gulfport MS

Landholding Agency: DoD-USN-USMC Property Number: 77202410019

Status: Excess Directions:

Bachelor Enlisted Quarters Bldg 316, Utility Pad/Screen, Break Shelter, In Memory of

Marker @ 316, Picnic Patio @ 316 (2 each) and a Marque at Building 445.

Reasons:

National Security Concerns

Comments:

Active Military Installation, no public access.

BUILDING

NEW YORK

Building 174

174 First Street East

Fort Drum NY 13602

Landholding Agency: DoD-Army Property Number: 21202410001

Status: Underutilized

Directions:

RPUID:314652

Reasons:

National Security Concerns

Comments:

Active Military Installation, no public access.

Building 370, Child Dev. Ctr.

B/370 East Street

Upton NY 11973

Landholding Agency: DOE Property Number: 41202410001

Status: Excess Directions:

Brookhaven National Laboratory

Reasons:

Structural Damage - Extensive Deterioration

National Security Concerns

Comments:

Located in a National Security Complex, no public access. Structural issuses; roof needs to be replaced; all major building systems are at the end of their useful life.

Bldgs. 513A, 513B, 513C, S251

10 South Street New York NY 10004

Landholding Agency: DOI-NPS Property Number: 61202410002

Status: Excess Directions:

RPUID:70156, 70158, 70160, 70164

Structural damage & extensive deterioration due to water penetration.

Reasons:

Documented Deficiencies-Contamination Structural Damage - Extensive Deterioration

Comments:

Roof partially collapsed. Interior ceilings & walls have partially collapsed.

BUILDING

NEW YORK

Bldg contaminated with mold, asbestos & LBP; only accessible by ferry/boat.

Building 513D 10 South Street 10004

New York NY

Landholding Agency: DOI-NPS Property Number: 61202410003

Status: Excess Directions:

RPUID:70145

Water & weather damage.

Reasons:

Documented Deficiencies-Contamination Structural Damage - Extensive Deterioration

Inaccessible

Comments:

Mechanical utilities are severely deteriorated from rust & lack of maintenance. Doors & frames are partially collapsing due to deteriorated condition. LBP & asbestos present;

accessible by ferry/boat.

Generator Storage Building

10 South Street New York NY 10004

Landholding Agency: DOI-NPS Property Number: 61202410004

Status: Excess Directions:

RPUID:257930

Reasons:

Inaccessible

Structural Damage - Extensive Deterioration

Comments:

Building deteriorated due to water penetration; only accessible by ferry/boat.

UNSUITABLE PROPERTIES BUILDING UTAH

Bear River A S White Trailer #19040617 CN 1067.003441

Hwy 150 MP 55 Kamas UT 84036

Landholding Agency: USDA-FS Property Number: 13202410001

Status: Excess

Structural Damage - Extensive Deterioration

Comments:

Reasons:

Foundation unsound, windows broken, possible roof leak.

Summary for UNSUITABLE PROPERTIES

Total number of = 29

SUMMARY OF ALL PROPERTIES

Suitable/Available = 1

Suitable/Unavailable = 0

Suitable/To Be = 0

** Suitable/ Undefined = 0

Total Suitable = 1

Total Unsuitable = 29

Total number of = 30

Properties = 0