

UNSUITABLE PROPERTIES

BUILDING

ARIZONA

Jones Water Vault Toilet #1

Globe AZ

Landholding Agency: USDA-FS

Property Number: 13202430001

Status: Excess

Directions:

Asset ID # 020403, Latitude: 33.59055555, Longitude: -110.64222222

Reasons:

Floodway

Structural Damage - Extensive Deterioration

Comments:

Concrete bldg. is attached to a concrete vault that holds sewage from the above-ground toilet & can not be removed without destroying it. Interior components are deteriorating. Located in a floodway.

Bermuda Flat Entry Station

Roosevelt AZ

Landholding Agency: USDA-FS

Property Number: 13202430002

Status: Excess

Directions:

Asset ID # 060501, Latitude: 33.57739167, Longitude: -111.22672223

Reasons:

Structural Damage - Extensive Deterioration

Comments:

All components (plumbing & electric, building finishes, doors, etc) are in poor, unusable condition. Most interior components have been removed.

Cholla CG Entry Station

Tonto Basin AZ

Landholding Agency: USDA-FS

Property Number: 13202430003

Status: Excess

Directions:

Asset ID # 061015, Latitude: 33.724736611, Longitude: -111.20505000

Reasons:

Structural Damage - Extensive Deterioration

Comments:

All components (plumbing and electric, building finishes, doors, etc) are in

UNSUITABLE PROPERTIES

BUILDING

ARIZONA

poor, unusable condition. Most interior components have been removed.

Schoolhouse CG Flush Toilet #6

Acacia Loop South

Roosevelt AZ

Landholding Agency: USDA-FS

Property Number: 13202430004

Status: Excess

Directions:

Asset ID # 062406, Latitude: 33.65430555, Longitude: -111.01866667

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Water system that serves loop has been abandoned & will be disconn. Toilet is being disposed of because of high costs of oper & maint & the lack of funding that is necessary comply with ADEQ and EPA.

Schoolhouse CG Flush Toilet #7

Acacia Loop North

Roosevelt AZ

Landholding Agency: USDA-FS

Property Number: 13202430005

Status: Excess

Directions:

Asset ID # 062407, Latitude: 33.65430555, Longitude: -111.01866667

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Water system that serves loop has been abandoned & will be disconn. Toilet is being disposed of because of high costs of oper & maint & the lack of funding that is necessary comply with ADEQ and EPA.

Schoolhouse CG Entry Station

Roosevelt AZ

Landholding Agency: USDA-FS

Property Number: 13202430006

Status: Excess

Directions:

Asset ID # 062413, Latitude: 33.64161666, Longitude: -111.0080000

Reasons:

Structural Damage - Extensive Deterioration

Comments:

UNSUITABLE PROPERTIES

BUILDING

ARIZONA

All components (plumbing & electric, building finishes, doors, etc) are in poor, unusable condition. Most interior components have been removed.

Windy Hill CG Compost Toilet
#2- Desert Bighorn Loop South
Roosevelt AZ
Landholding Agency: USDA-FS
Property Number: 13202430007
Status: Excess
Directions:

Asset ID # 062702, Latitude: 33.65649444, Longitude: -111.09358888

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Sewage treatment for this composting unit poses a serious health & safety threat to the employees who operate & maintain the system. System is in poor shape.

Windy Hill CG Compost Toilet
#3 - Desert Bighorn Loop North
Roosevelt AZ
Landholding Agency: USDA-FS
Property Number: 13202430008
Status: Excess
Directions:

Asset ID # 062703, Latitude: 33.65659167, Longitude: -111.09352777

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Sewage treatment for this composting unit poses a serious health & safety threat to the employees who operate & maintain the system. System is in poor shape.

Windy Hill CG Entry Station
Roosevelt AZ
Landholding Agency: USDA-FS
Property Number: 13202430009
Status: Excess
Directions:

Asset ID # 062721, Latitude: 33.65028611 Longitude: -111.08605000

Reasons:

National Security Concerns

UNSUITABLE PROPERTIES

BUILDING

ARIZONA

Comments:

All components (plumbing & electric, building finishes, doors, etc) are in poor, unusable condition. Most interior components have been removed.

Indian Point (IP) Vault Toilet

(Anasazi Loop)

Tonto Basin AZ

Landholding Agency: USDA-FS

Property Number: 13202430010

Status: Excess

Directions:

Asset ID # 063502, Latitude: 33.76669445, Longitude: -111.23959722

Reasons:

Floodway

Structural Damage - Extensive Deterioration

Comments:

Located in a floodway. Toilet is close to Roosevelt Lake and there is the potential of the toilet vault and building flooding and contaminating the lake violating the Safe Drinking Water Act.

Jones Water Vault Toilet #2

Globe AZ

Landholding Agency: USDA-FS

Property Number: 13202430011

Status: Excess

Directions:

Asset ID # 020402, Latitude: 33.59055555, Longitude: -110.64222222

Reasons:

Floodway

Structural Damage - Extensive Deterioration

Comments:

Located in a floodway. Building is attached to a concrete vault that holds sewage from the above-ground toilet and can not be removed without destroying it. Interior components are deteriorating.

UNSUITABLE PROPERTIES

BUILDING

MINNESOTA

Norway Beach Recreation Area

Wanaki Shower Bldg 1

15830 Norway Beach Rad NW

Cass Lake MN 56633

Landholding Agency: USDA-FS

Property Number: 13202420048

Status: Surplus

Reasons:

National Security Concerns

Comments:

Located in a National security complex, No public access.

SOUTH CAROLINA

BSNS6,

Charleston Training Del Point

North Charleston SC 29405

Landholding Agency: DHS

Property Number: 89202420001

Status: Unutilized

Reasons:

National Security Concerns

Comments:

Located in a National security complex, No public access.

UNSUITABLE PROPERTIES

BUILDING

TEXAS

1380

14657 Snieder Street

Houston TX 77034

Landholding Agency: DoD-USAF

Property Number: 18202430001

Status: Excess

Reasons:

National Security Concerns

Comments:

Located in a National security complex, No public access.

Fort Cavazos Bldg 25039

441 W Hell on Wheels

Fort Cavazos TX 76544

Landholding Agency: DoD-Army

Property Number: 21202420105

Status: Underutilized

Directions:

RPUID: 181943

Reasons:

National Security Concerns

Comments:

Active Military installation; No public access

Fort Cavazos Bldg 19038

301 Murphy Road

Fort Cavazos TX 76544

Landholding Agency: DoD-Army

Property Number: 21202420106

Status: Excess

Directions:

RPUID: 956445

Reasons:

National Security Concerns

Comments:

Active Military installation; No public access

UNSUITABLE PROPERTIES

BUILDING

TEXAS

Summary for UNSUITABLE PROPERTIES

Total number of = 16

SUMMARY OF ALL PROPERTIES

Suitable/Available = 0

Suitable/Unavailable = 0

Suitable/To Be = 0

**** Suitable/ Undefined** = 0

Total Suitable = 0

Total Unsuitable = 16

Total number of = 16

Properties = 0