# TITLE V, FEDERAL SURPLUS PROPERTY PROGRAM FEDERAL REGISTER REPORT FOR 07/12/2024

1

# UNSUITABLE PROPERTIES BUILDING

#### **CALIFORNIA**

Water Treatment Building #901 11895 Crystal Creek Road Whiskeytown CA 96095 Landholding Agency: DOI-NPS

Property Number: 61202430015 Status: Excess

Status: Exces
Directions:

RPUID:249340, PMIS #319078

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Building is significantly deteroriated due to wet climate, mold, mildew, heavy graffiti,

vandalism, trash and rodent infestation is prevalent.

Oil & Gas Station #902 11895 Crystal Creek Road Whiskeytown CA 96095

Landholding Agency: DOI-NPS Property Number: 61202430016

Status: Excess Directions:

RPUID:249322, PMIS #319078

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Building is significantly deteroriated due to wet climate, mold, mildew, heavy graffiti,

vandalism, trash and rodent infestation is prevalent.

Shop Storage Shed #904 11895 Crystal Creek Road Whiskeytown CA 96095

Landholding Agency: DOI-NPS Property Number: 61202430017

Status: Excess Directions:

RPUID:249329, PMIS #319078

Reasons:

Structural Damage - Extensive Deterioration

Comments:

#### **BUILDING**

#### CALIFORNIA

Building is significantly deteroriated due to wet climate, mold, mildew, heavy graffiti, vandalism, trash and rodent infestation is prevalent.

CDC Warehouse #905 11895 Crystal Creek Road Whiskeytown CA 96095 Landholding Agency: DOI-NPS

Landholding Agency: DOI-NPS Property Number: 61202430018

Status: Excess Directions:

RPUID:249332 PMIS #319078

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Building is significantly deteroriated due to wet climate, mold, mildew, heavy graffiti,

vandalism, trash and rodent infestation is prevalent.

Cinder Storage Shed #906 11895 Crystal Creek Road Whiskeytown CA 96095

Landholding Agency: DOI-NPS Property Number: 61202430019

Status: Excess Directions:

RPUID:249336, PMIS #319078

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Building is significantly deteroriated due to wet climate, mold, mildew, heavy graffiti,

vandalism, trash and rodent infestation is prevalent.

Equipment Building #908 11895 Crystal Creek Road

Whiskeytown CA 96095

Landholding Agency: DOI-NPS Property Number: 61202430020

Status: Excess Directions:

RPUID:249339, PMIS #319078

Reasons:

Structural Damage - Extensive Deterioration

#### BUILDING

#### **CALIFORNIA**

Comments:

Building is significantly deteroriated due to wet climate, mold, mildew, heavy graffiti, vandalism, trash and rodent infestation is prevalent.

CDC Office #914

11895 Crystal Creek Road

Whiskeytown CA 96095

Landholding Agency: DOI-NPS Property Number: 61202430021

Status: Excess Directions:

RPUID:249333, PMIS #319078

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Building is significantly deteroriated due to wet climate, mold, mildew, heavy graffiti,

vandalism, trash and rodent infestation is prevalent.

Hobby Shop #915

11895 Crystal Creek Road

Whiskeytown CA 96095

Landholding Agency: DOI-NPS Property Number: 61202430022

Status: Excess Directions:

RPUID:249334, PMIS #319078

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Building is significantly deteroriated due to wet climate, mold, mildew, heavy graffiti,

vandalism, trash and rodent infestation is prevalent.

WES Camp Cabin #704 10106 Paige Bar Road

Whiskeytown CA 96095

Landholding Agency: DOI-NPS Property Number: 61202430023

Status: Excess Directions:

RPUID:22974, PMIS #329647

Reasons:

#### BUILDING

#### **CALIFORNIA**

Structural Damage - Extensive Deterioration

Comments:

Cabin is significantly deteroriated due to wet climate, mold, mildew. Foundations are not sufficiently connected to the ground to provide any seismic reinforcing per CA Building code.

WES Camp Cabin #708 10106 Paige Bar Road Whiskeytown CA 96095

Landholding Agency: DOI-NPS Property Number: 61202430024

Status: Excess Directions:

RPUID:22978, PMIS #329647

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Cabin is significantly deteroriated due to wet climate, mold, mildew. Foundations are not sufficiently connected to the ground to provide any seismic reinforcing per CA Building

code.

WES Camp Cabin #709 10106 Paige Bar Road Whiskeytown CA 96095

Landholding Agency: DOI-NPS Property Number: 61202430025

Status: Excess Directions:

RPUID 22981, PMIS # 329647

Reasons:

**National Security Concerns** 

Comments:

Cabin is significantly deteroriated due to wet climate, mold, mildew. Foundations are not sufficiently connected to the ground to provide any seismic reinforcing per CA Building

code.

WES Camp Cabin #710 10106 Paige Bar Road Whiskeytown CA 96095

Landholding Agency: DOI-NPS Property Number: 61202430026

Status: Excess

#### BUILDING

#### **CALIFORNIA**

Directions:

RPUID:22983, PMIS #329647

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Cabin is significantly deteroriated due to wet climate, mold, mildew. Foundations are not sufficiently connected to the ground to provide any seismic reinforcing per CA Building code.

WES Camp Cabin #711 10106 Paige Bar Road Whiskeytown CA 96095

Landholding Agency: DOI-NPS Property Number: 61202430027

Status: Excess Directions:

RPUID:22985, PMIS #329647

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Cabin is significantly deteroriated due to wet climate, mold, mildew. Foundations are not sufficiently connected to the ground to provide any seismic reinforcing per CA Building

code.

WES Camp Cabin #713 10106 Paige Bar Road Whiskeytown CA 96095

Landholding Agency: DOI-NPS Property Number: 61202430028

Status: Excess Directions:

RPUID:22990, PMIS #329647

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Cabin is significantly deteroriated due to wet climate, mold, mildew. Foundations are not sufficiently connected to the ground to provide any seismic reinforcing per CA Building code.

WES Camp Cabin #714 10106 Paige Bar Road Whiskeytown CA 96095

#### BUILDING

#### **CALIFORNIA**

Landholding Agency: DOI-NPS Property Number: 61202430029

Status: Excess Directions:

RPUID:22992, PMIS #329647

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Cabin is significantly deteroriated due to wet climate, mold, mildew. Foundations are not sufficiently connected to the ground to provide any seismic reinforcing per CA Building

code.

WES Camp Cabin #715 10106 Paige Bar Road Whiskeytown CA 96095

Landholding Agency: DOI-NPS Property Number: 61202430030

Status: Excess Directions:

RPUID:22994, PMIS #329647

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Cabin is significantly deteroriated due to wet climate, mold, mildew. Foundations are not sufficiently connected to the ground to provide any seismic reinforcing per CA Building

code.

WES Camp Staff Cabin #717 10106 Paige Bar Road Whiskeytown CA 96095

Landholding Agency: DOI-NPS Property Number: 61202430031

Status: Excess Directions:

RUPID:22998, PMIS #329647

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Cabin is significantly deteroriated due to wet climate, mold, mildew. Foundations are not sufficiently connected to the ground to provide any seismic reinforcing per CA Building

code.

#### **BUILDING**

#### **CALIFORNIA**

WES Camp Bathhouse #718 10106 Paige Bar Road Whiskeytown CA 96095 Landholding Agency: DOI-NPS Property Number: 61202430032

Status: Excess Directions:

RPUID:22999, PMIS #329647

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Cabin is significantly deteroriated due to wet climate, mold, mildew. Foundations are not sufficiently connected to the ground to provide any seismic reinforcing per CA Building

code.

#### **MASSACHUSETTS**

Bartlett House 40 Ocean View Drive Eastham MA 02642

Landholding Agency: DOI-NPS Property Number: 61202430001

Status: Excess Directions:

RPUID:39609

Reasons:

Structural Damage - Extensive Deterioration

Floodway

Comments:

Located in a floodway. Due to erosion property no longer safe for occupancy.

#### **BUILDING**

#### **MONTANA**

Toilet Elk Lake #2 North

Lakeview MT 59739

Landholding Agency: USDA-FS Property Number: 13202430012

Status: Excess Directions:

RPUID:1824.000221; Asset ID: 5656, 111.63147223 x 44.66980556

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Foundation structually unsound.

#### **OREGON**

Hogback Prefab Building (1113.005651) Off Old Fort Road Lakeview OR

Landholding Agency: USDA-FS Property Number: 13202430013

Status: Excess Directions:

W3500, Lat 42.2426111 Long 121.706 13889

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Building in poor condition, has outlived it's life expectancy.

#### BUILDING

#### SOUTH DAKOTA

Huron Westland Mgt. Area - Sch

20721 392nd Avenue

Wolsey SD 57348

Landholding Agency: GSA Property Number: 54202430001

Status: Surplus

GSA Number: 7-I-SD-0543-AA

Reasons:

**Documented Deficiencies-Contamination** 

Comments:

The property has field mice intrusion from the adjacent field. Building will need to be

moved off of the foundation and disassembled and moved offsite.

#### WEST VIRGINIA

Harrah Coal Shed

Mill Creek Fishing Access Road

Beaver WV 25813

Landholding Agency: DOI-NPS Property Number: 61202430002

Status: Excess Directions:

RPUID:87581, Tract #124-05

Reasons:

Structural Damage - Extensive Deterioration

Floodway

Comments:

Poorly constructed structure in severe delapidation. Property located in a floodway.

Harrah Outbuilding #2

Mill Creek Fishing Access Road

Beaver WV 25813

Landholding Agency: DOI-NPS Property Number: 61202430003

Status: Excess Directions:

RPUID:87582, Tract #124-05

Reasons:

Floodway

Structural Damage - Extensive Deterioration

Comments:

Poorly constructed structure in severe delapidation. Property located in a

# UNSUITABLE PROPERTIES BUILDING

WEST VIRGINIA

floodway.

Harrah Shed #1

Mill Creek Fishing Access Road

Beaver WV 25813

Landholding Agency: DOI-NPS Property Number: 61202430004

Status: Excess Directions:

RPUID:87583, Tract #124-05

Reasons:

Floodway

Structural Damage - Extensive Deterioration

Comments:

Poorly constructed structure in severe delapidation. Property located in a floodway.

Harrah Hen House

Mill Creek Fishing Access Road

Beaver WV 25813

Landholding Agency: DOI-NPS Property Number: 61202430005

Status: Excess Directions:

RPUID:87584, Tract #124-05

Reasons:

Structural Damage - Extensive Deterioration

Floodway

Comments:

Poorly constructed structure in severe delapidation. Property located in a floodway.

Harrah Smokehouse

Mill Creek Fishing Access Road

Beaver WV 25813

Landholding Agency: DOI-NPS Property Number: 61202430006

Status: Excess Directions:

RPUID:87585, Tract #124-05

Reasons:

#### BUILDING

#### **WEST VIRGINIA**

Structural Damage - Extensive Deterioration

Floodway

Comments:

Poorly constructed structure in severe delapidation. Property located in a floodway.

Cochrane Farm Outbuilding

#1 Henhouse New River Road Hinton WV 25951

Landholding Agency: DOI-NPS Property Number: 61202430007

Status: Excess Directions:

RPUID:87598, Tract #104-29

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Poorly constructed structure in severe delapidation.

Cochrane Farm Outbuilding

#2 Stable/Corral New River Road Hinton WV 25951

Landholding Agency: DOI-NPS Property Number: 61202430008

Status: Excess Directions:

RPUID:87599; Tract #104-29

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Poorly constructed structure in severe delapidation.

Harrah Outhouse

Mill Creek Fishing Access Road

Beaver WV 25813

Landholding Agency: DOI-NPS Property Number: 61202430009

Status: Excess Directions:

#### BUILDING

#### **WEST VIRGINIA**

RPUID:87620, Tract #124-05

Reasons:

Floodway

Structural Damage - Extensive Deterioration

Comments:

Poorly constructed structure in severe delapidation. Property located in a floodway.

James Phillips Storage

Building #2 New River Road Hinton WV 25951

Landholding Agency: DOI-NPS Property Number: 61202430010

Status: Excess Directions:

RPUID:88103, Tract #103-04

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Poorly constructed structure in severe delapidation.

James Phillips Farm Shed

New River Road Hinton WV 25951

Landholding Agency: DOI-NPS Property Number: 61202430011

Status: Excess Directions:

RPUID:88104, Tract #103-04

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Shed has partially collapsed.

James Phillips Farm

Outbuilding #1 New River Road Hinton WV 25951

Landholding Agency: DOI-NPS Property Number: 61202430012

Status: Excess

#### BUILDING

#### **WEST VIRGINIA**

Directions:

RPUID:88105, Tract #103-04

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Poorly constructed structure in severe delapidation.

Thurmond Package Plant

River Crest Road

Thurmond WV 25936

Landholding Agency: DOI-NPS Property Number: 61202430013

Status: Excess Directions:

RPUID:88881, Tract #140-40

Reasons:

Floodway

Comments:

Property located in a floodway.

James K. Carper Barn

Heron Lane

Beaver WV 25813

Landholding Agency: DOI-NPS Property Number: 61202430014

Status: Excess Directions:

RPUID:237320, Tract #124-10

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Very large unutilized dilapidated barn in field in serious condition.

### Summary for UNSUITABLE PROPERTIES

Total number of = 35

## SUMMARY OF ALL PROPERTIES

Suitable/Available = 0

Suitable/Unavailable = 0

Suitable/To Be = 0

\*\* Suitable/ Undefined = 0

Total Suitable = 0

Total Unsuitable = 35

Total number of = 35

Properties = 0