10/01/2020

TITLE V, FEDERAL SURPLUS PROPERTY PROGRAM FEDERAL REGISTER REPORT FOR 10/02/2020

SUITABLE / AVAILABLE PROPERTIES BUILDING ARIZONA

Desert View Fee Collect Trailer Desert View Maintenance Road

See Directions

Desert View/Grand Can AZ 86023

Landholding Agency: DOI Property Number: 61202030015

Status: Excess Directions:

-111.827148 36.038168 Decimal Degrees

Comments:

Poor condition. General deterioration. Asbestos in flooring remediation required. No axels. Contact agency for more information.

UNSUITABLE PROPERTIES BUILDING GEORGIA

SL331 Olympic Park

See Directions

Gainesville GA 30506

Landholding Agency: USACE Property Number: 31202030020

Status: Unutilized

Directions:

Leased area to City of Gainesville, DACW01-1-19-0459, Structure # SL331

Comments:

Poor condition. Not suitable for offsite removal due to bldg. materials – concrete comfort station.

Reasons:

Documented Deficiencies-Contamination. Structural Damage - Extensive Deterioration

BUILDING

NORTH CAROLINA

Tract 105-20 See Directions

Harkers Island NC 28531 Landholding Agency: DOI Property Number: 61202030016

Status: Excess Directions:

Les and Sally's House PMIS# 254047. 34°36'45.09"N 76°31'50.49"W

By boat, travel 4.9 miles SSE from CALO Harkers Island HQ

Comments:

Poor condition. Mold throughout the structure. Offsite removal only. Structurally unsound for removal.

Reasons:

Documented Deficiencies-Contamination. Structural Damage - Extensive Deterioration. Other - National Historic Designation

MISSOURI

Stockton Comfort Station

See Directions Stockton MO

Landholding Agency: USACE Property Number: 31202030019

Status: Excess Directions:

NOTE: THIS SHOULD BE MISSOURI AND NOT CALIFORNIA.

POSTING DATE 9/25/20. Stockton Lake Project LAT: 37°41'0.41"N

LONG: 93°47'29.97"W. STCKTN-28936

Comments:

Aging plumbing and electrical systems issues, general deterioration due to age, open style allows vermin access creating possible public health hazards.

Reasons:

Structural Damage - Extensive Deterioration