

TITLE V, FEDERAL SURPLUS PROPERTY PROGRAM  
FEDERAL REGISTER REPORT FOR 02/09/2024

UNSUITABLE PROPERTIES

BUILDING

ARIZONA

Temple Bar Personal Property

Vacation Cabin #27

Temple Bar AZ 86443

Landholding Agency: DOI-NPS

Property Number: 61202410087

Status: Excess

Directions:

PMIS#238165E

Reasons:

Documented Deficiencies-Contamination

Structural Damage - Extensive Deterioration

Comments:

Poor condition; roof collapsed. Friable Regulated Asbestos Containing Material (RACM) transite paneling. EPA Category II Non-Friable ACM floor tiles with black mastic & wall & ceiling systems.

Temple Bar Personal Property

Vacation Cabin #33

Temple Bar AZ 86443

Landholding Agency: DOI-NPS

Property Number: 61202410088

Status: Excess

Directions:

PMIS#238165E

Reasons:

Structural Damage - Extensive Deterioration

Documented Deficiencies-Contamination

Comments:

HVAC units deteriorated beyond repair. Friable Regulated Asbestos Containing Material sheet flooring. EPA Category II Non-Friable non-ACM floor tiles with ACM black mastic & ceiling & wall systems.

## UNSUITABLE PROPERTIES

### BUILDING

#### HAWAII

QUARTERS 1, 3-8, 10,14 & 15 AT

LITTLE MAKALAPA, JBPHH

Pearl Harbor HI 96860

Landholding Agency: DoD-USN-USMC

Property Number: 77202410026

Status: Unutilized

Reasons:

Documented Deficiencies-Contamination

National Security Concerns

Structural Damage - Extensive Deterioration

Comments:

Active Military Installation; no public access. structurally un-sound and contains asbestos and dioxins.

#### MARYLAND

Facility 5010

5010 Eastern Blvd

Middle River MD 21220

Landholding Agency: DoD-USAF

Property Number: 18202410012

Status: Unutilized

Directions:

RPUID: 479078

Reasons:

National Security Concerns

Comments:

Active Military installation; No public access

Whites Ferry Sportsmans Club

Cabin 17-116-1

24801 Whites Ferry Road

Dickerson MD 20842

Landholding Agency: DOI-NPS

Property Number: 61202410051

Status: Excess

Directions:

RPUID:255774; PMIS:319030

Reasons:

Structural Damage - Extensive Deterioration

Documented Deficiencies-Contamination

Comments:

Rotting & broken foundation piles, broken windows & doors, severe leans,

## UNSUITABLE PROPERTIES

### BUILDING

#### MARYLAND

sagging floors, water damage from flooding & failed roofing. Lead-based paint; asbestos; land contains spilled diesel fuel.

Whites Ferry Sportsmans Club

Cabin 17-116-2

24802 Whites Ferry Road

Dickerson MD 20842

Landholding Agency: DOI-NPS

Property Number: 61202410052

Status: Excess

Directions:

RPUID:255776; PMIS#319030

Reasons:

Documented Deficiencies-Contamination

Structural Damage - Extensive Deterioration

Comments:

Rotting & broken foundation piles, broken windows & doors, severe leans, sagging floors, water damage from flooding & failed roofing. Lead-based paint; asbestos; land contains spilled diesel fuel.

Whites Ferry Sportsmans Club

Cabin 17-116-3

24803 Whites Ferry Road

Dickerson MD 20842

Landholding Agency: DOI-NPS

Property Number: 61202410053

Status: Excess

Directions:

RPUID:255777; PMIS#319030

Reasons:

Structural Damage - Extensive Deterioration

Documented Deficiencies-Contamination

Comments:

Rotting & broken foundation piles, broken windows & doors, severe leans, sagging floors, water damage from flooding & failed roofing. Lead-based paint; asbestos; land contains spilled diesel fuel.

Whites Ferry Sportsmans Club

Cabin 17-116-4

24804 Whites Ferry Road

Dickerson MD 20842

Landholding Agency: DOI-NPS

## UNSUITABLE PROPERTIES

### BUILDING

#### MARYLAND

Property Number: 61202410054

Status: Excess

Directions:

RPUID:255778; PMIS#319030

Reasons:

Structural Damage - Extensive Deterioration

Documented Deficiencies-Contamination

Comments:

Rotting & broken foundation piles, broken windows & doors, severe leans, sagging floors, water damage from flooding & failed roofing. Lead-based paint; asbestos; land contains spilled diesel fuel.

Whites Ferry Sportsmans Club

Cabin 17-116-5

24805 Whites Ferry Road

Dickerson MD 20842

Landholding Agency: DOI-NPS

Property Number: 61202410055

Status: Excess

Directions:

RPUID:255779; PMIS#319030

Reasons:

Structural Damage - Extensive Deterioration

Documented Deficiencies-Contamination

Comments:

Rotting & broken foundation piles, broken windows & doors, severe leans, sagging floors, water damage from flooding & failed roofing. Lead-based paint; asbestos; land contains spilled diesel fuel.

Whites Ferry Sportsmans Club

Cabin 17-116-6

24806 Whites Ferry Road

Dickerson MD 20842

Landholding Agency: DOI-NPS

Property Number: 61202410056

Status: Excess

Directions:

RPUID:255780; PMIS#319030

Reasons:

Documented Deficiencies-Contamination

Structural Damage - Extensive Deterioration

Comments:

Rotting & broken foundation piles, broken windows & doors, severe leans, sagging floors, water damage from flooding & failed roofing. Lead-based

## UNSUITABLE PROPERTIES

## BUILDING

## MARYLAND

paint; asbestos; land contains spilled diesel fuel.

## Whites Ferry Sportsmans Club

Cabin 17-116-7

24807 Whites Ferry Road

Dickerson MD 20842

Landholding Agency: DOI-NPS

Property Number: 61202410057

Status: Excess

Directions:

RPUID:255781; PMIS#319030

Reasons:

Structural Damage - Extensive Deterioration

Documented Deficiencies-Contamination

Comments:

Rotting & broken foundation piles, broken windows & doors, severe leans, sagging floors, water damage from flooding & failed roofing. Lead-based paint; asbestos; land contains spilled diesel fuel.

## Whites Ferry Sportsmans Club

Cabin 17-116-8

24808 Whites Ferry Road

Dickerson MD 20842

Landholding Agency: DOI-NPS

Property Number: 61202410058

Status: Excess

Directions:

RPUID:255782; PMIS#319030

Reasons:

Documented Deficiencies-Contamination

Structural Damage - Extensive Deterioration

Comments:

Rotting & broken foundation piles, broken windows & doors, severe leans, sagging floors, water damage from flooding & failed roofing. Lead-based paint; asbestos; land contains spilled diesel fuel.

## Whites Ferry Sportsmans Club

Cabin 17-116-9

24809 Whites Ferry Road

Dickerson MD 20842

Landholding Agency: DOI-NPS

Property Number: 61202410059

## UNSUITABLE PROPERTIES

### BUILDING

#### MARYLAND

Status: Excess

Directions:

RPUID:255783; PMIS#319030

Reasons:

Structural Damage - Extensive Deterioration  
Documented Deficiencies-Contamination

Comments:

Rotting & broken foundation piles, broken windows & doors, severe leans, sagging floors, water damage from flooding & failed roofing. Lead-based paint; asbestos; land contains spilled diesel fuel.

Whites Ferry Sportsmans Club

Cabin 17-116-10

24810 Whites Ferry Road

Dickerson MD 20842

Landholding Agency: DOI-NPS

Property Number: 61202410060

Status: Excess

Directions:

RPUID:255784; PMIS#319030

Reasons:

Documented Deficiencies-Contamination

Comments:

Rotting & broken foundation piles, broken windows & doors, severe leans, sagging floors, water damage from flooding & failed roofing. Lead-based paint; asbestos; land contains spilled diesel fuel.

Whites Ferry Sportsmans Club

Cabin 17-116-11

24811 Whites Ferry Road

Dickerson MD 20842

Landholding Agency: DOI-NPS

Property Number: 61202410061

Status: Excess

Directions:

RPUID:255785; PMIS#319030

Reasons:

Structural Damage - Extensive Deterioration  
Documented Deficiencies-Contamination

Comments:

Rotting & broken foundation piles, broken windows & doors, severe leans, sagging floors, water damage from flooding & failed roofing. Lead-based paint; asbestos; land contains spilled diesel fuel.

## UNSUITABLE PROPERTIES

## BUILDING

## MARYLAND

Whites Ferry Sportsmans Club

Cabin 17-116-12

24812 Whites Ferry Road

Dickerson MD 20842

Landholding Agency: DOI-NPS

Property Number: 61202410062

Status: Excess

Directions:

RPUID:255786; PMIS#319030

Reasons:

Structural Damage - Extensive Deterioration

Documented Deficiencies-Contamination

Comments:

Rotting & broken foundation piles, broken windows & doors, severe leans, sagging floors, water damage from flooding & failed roofing. Lead-based paint; asbestos; land contains spilled diesel fuel.

Whites Ferry Sportsmans Club

Cabin 17-116-13

24813 Whites Ferry Road

Dickerson MD 20842

Landholding Agency: DOI-NPS

Property Number: 61202410063

Status: Excess

Directions:

RPUID:255787; PMIS#319030

Reasons:

Structural Damage - Extensive Deterioration

Documented Deficiencies-Contamination

Comments:

Rotting & broken foundation piles, broken windows & doors, severe leans, sagging floors, water damage from flooding & failed roofing. Lead-based paint; asbestos; land contains spilled diesel fuel.

Whites Ferry Sportsmans Club

Cabin 17-116-14

24814 Whites Ferry Road

Dickerson MD 20842

Landholding Agency: DOI-NPS

Property Number: 61202410064

Status: Excess

Directions:

RPUID:255788; PMIS#319030

## UNSUITABLE PROPERTIES

### BUILDING

#### MARYLAND

Reasons:

Structural Damage - Extensive Deterioration  
Documented Deficiencies-Contamination

Comments:

Rotting & broken foundation piles, broken windows & doors, severe leans, sagging floors, water damage from flooding & failed roofing. Lead-based paint; asbestos; land contains spilled diesel fuel.

Whites Ferry Sportsmans Club

Cabin 17-116-15

24815 Whites Ferry Road

Dickerson MD 20842

Landholding Agency: DOI-NPS

Property Number: 61202410065

Status: Excess

Directions:

RPUID:255789; PMIS#319030

Reasons:

Documented Deficiencies-Contamination  
Structural Damage - Extensive Deterioration

Comments:

Rotting & broken foundation piles, broken windows & doors, severe leans, sagging floors, water damage from flooding & failed roofing. Lead-based paint; asbestos; land contains spilled diesel fuel.

Whites Ferry Sportsmans Club

Cabin 17-116-16

24816 Whites Ferry Road

Dickerson MD 20842

Landholding Agency: DOI-NPS

Property Number: 61202410066

Status: Excess

Directions:

RPUID:255790; PMIS#319030

Reasons:

Documented Deficiencies-Contamination  
Structural Damage - Extensive Deterioration

Comments:

Rotting & broken foundation piles, broken windows & doors, severe leans, sagging floors, water damage from flooding & failed roofing. Lead-based paint; asbestos; land contains spilled diesel fuel.



## UNSUITABLE PROPERTIES

## BUILDING

## MARYLAND

Whites Ferry Sportsmans Club

Cabin 17-116-17

24817 Whites Ferry Road

Dickerson MD 20842

Landholding Agency: DOI-NPS

Property Number: 61202410067

Status: Excess

Directions:

RPUID255791: PMIS#319030

Reasons:

Structural Damage - Extensive Deterioration

Documented Deficiencies-Contamination

Comments:

Rotting & broken foundation piles, broken windows & doors, severe leans, sagging floors, water damage from flooding & failed roofing. Lead-based paint; asbestos; land contains spilled diesel fuel.

Whites Ferry Sportsmans Club

Cabin 17-116-18

24818 Whites Ferry Road

Dickerson MD 20842

Landholding Agency: DOI-NPS

Property Number: 61202410068

Status: Excess

Directions:

RPUID:255792; PMIS#319030

Reasons:

Structural Damage - Extensive Deterioration

Documented Deficiencies-Contamination

Comments:

Rotting & broken foundation piles, broken windows & doors, severe leans, sagging floors, water damage from flooding & failed roofing. Lead-based paint; asbestos; land contains spilled diesel fuel.

Whites Ferry Sportsmans Club

Cabin 17-116-19

24819 Whites Ferry Road

Dickerson MD 20842

Landholding Agency: DOI-NPS

Property Number: 61202410069

Status: Excess

Directions:

RPUID:255793; PMIS#319030

## UNSUITABLE PROPERTIES

### BUILDING

#### MARYLAND

Reasons:

Documented Deficiencies-Contamination  
Structural Damage - Extensive Deterioration

Comments:

Rotting & broken foundation piles, broken windows & doors, severe leans, sagging floors, water damage from flooding & failed roofing. Lead-based paint; asbestos; land contains spilled diesel fuel.

Whites Ferry Sportsmans Club

Cabin 17-116-20

24820 Whites Ferry Road

Dickerson MD 20842

Landholding Agency: DOI-NPS

Property Number: 61202410070

Status: Excess

Directions:

RPUID:255784; PMIS#319030

Reasons:

Documented Deficiencies-Contamination  
Structural Damage - Extensive Deterioration

Comments:

Rotting & broken foundation piles, broken windows & doors, severe leans, sagging floors, water damage from flooding & failed roofing. Lead-based paint; asbestos; land contains spilled diesel fuel.

Whites Ferry Sportsmans Club

Cabin 17-116-21

24821 Whites Ferry Road

Dickerson MD 20842

Landholding Agency: DOI-NPS

Property Number: 61202410071

Status: Excess

Directions:

RPUID:255795; PMIS#319030

Reasons:

Documented Deficiencies-Contamination  
Structural Damage - Extensive Deterioration

Comments:

Rotting & broken foundation piles, broken windows & doors, severe leans, sagging floors, water damage from flooding & failed roofing. Lead-based paint; asbestos; land contains spilled diesel fuel.

## UNSUITABLE PROPERTIES

### BUILDING

#### MARYLAND

Whites Ferry Sportsmans Club

Cabin 17-116-22

24822 Whites Ferry Road

Dickerson MD

Landholding Agency: DOI-NPS

Property Number: 61202410072

Status: Excess

Directions:

RPUID:255796; PMIS#319030

Reasons:

Documented Deficiencies-Contamination

Structural Damage - Extensive Deterioration

Comments:

Rotting & broken foundation piles, broken windows & doors, severe leans, sagging floors, water damage from flooding & failed roofing. Lead-based paint; asbestos; land contains spilled diesel fuel.

#### NEVADA

Transient Lodging Facility NAF

5642 Stafford Dr

Nellis AFB NV 89191

Landholding Agency: DoD-USAF

Property Number: 18202410017

Status: Underutilized

Directions:

RPUID: 496808, 496810, 496811, 496813

Reasons:

National Security Concerns

Comments:

Brick building that has not been utilized in years and its falling apart. Active Military installation; No public access

Transient Lodging Facility (NA

5642 Stafford Dr.

Nellis AFB NV 89191

Landholding Agency: DoD-USAF

Property Number: 18202410018

Status: Underutilized

Directions:

RPUID: 496816, 496818, 496819, 496824

Reasons:

National Security Concerns

## UNSUITABLE PROPERTIES

## BUILDING

## NEVADA

## Comments:

Brick building that has not been utilized in years and its falling apart. Active Military installation; No public access

Stewart's Point Personal

Property Vacation Cabin #38

Northshore Road

Overton NV 89040

Landholding Agency: DOI-NPS

Property Number: 61202410081

Status: Excess

## Directions:

PMIS#238165C

## Reasons:

Structural Damage - Extensive Deterioration

## Comments:

Building in poor condition; structurally unsound; HVAC units were disconnected and are deteriorated beyond repair.

Stewart's Point Personal

Property Vacation Cabin #39

Northshore Road

Overton NV 89040

Landholding Agency: DOI-NPS

Property Number: 61202410082

Status: Excess

## Directions:

PMIS#238165C

## Reasons:

Structural Damage - Extensive Deterioration

## Comments:

Building in poor condition; structurally unsound.

Stewart's Point Personal

Property Vacation Cabin #28

Northshore Road

Overton NV 89040

Landholding Agency: DOI-NPS

Property Number: 61202410083

Status: Excess

## Directions:

PMIS#238165D

## UNSUITABLE PROPERTIES

### BUILDING

#### NEVADA

Reasons:

Documented Deficiencies-Contamination  
Structural Damage - Extensive Deterioration

Comments:

Building in poor condition; HVAC units were disconnected and are deteriorated beyond repair. Friable Regulated Asbestos Containing Material (RACM) window putty was found in eight of the windows.

Echo Bay Trailer Village

Mobile Home #79

Northshore Road

Overton NV 89040

Landholding Agency: DOI-NPS

Property Number: 61202410084

Status: Excess

Directions:

PMIS#238165D

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Poor condition; structurally unsound; HVAC units were disconnected and are deteriorated beyond repair.

Echo Bay Trailer Village

Mobile Home #98

Northshore Road

Overton NV 89040

Landholding Agency: DOI-NPS

Property Number: 61202410085

Status: Excess

Directions:

PMIS#238156D

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Poor condition; structurally unsound; HVAC units were disconnected and are deteriorated beyond repair.

Echo Bay Trailer Village

Mobile Home #129

Northshore Road

Overton NV 89040

## UNSUITABLE PROPERTIES

### BUILDING

#### NEVADA

Landholding Agency: DOI-NPS

Property Number: 61202410086

Status: Excess

Directions:

PMIS#238165D

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Poor condition; floor partially collapsed in kitchen; structurally unsound; HVAC units were disconnected and are deteriorated beyond repair.

#### NEW YORK

Hancock Airfield-00625, 00668

6001 E. Molloy Road

Syracuse NY 13211

Landholding Agency: DoD-USAF

Property Number: 18202410016

Status: Underutilized

Reasons:

National Security Concerns

Comments:

Active Military installation; No public access

JABA BU-NSFB-154 Sewage

Plant Lift Station Bldg

Aviation Road; Floyd Bennett Field

Brooklyn NY 11234

Landholding Agency: DOI-NPS

Property Number: 61202410079

Status: Excess

Directions:

RPUID:45355

Reasons:

Structural Damage - Extensive Deterioration

Documented Deficiencies-Contamination

Comments:

Building in poor condition; no windows; holes present on building envelope. Asbestos is in the exterior façade.

## UNSUITABLE PROPERTIES

### BUILDING

#### NEW YORK

JABA BU-NSFB-60B Utility

Vault Building

Aviation Road; Floyd Bennett Field

Brooklyn NY 11234

Landholding Agency: DOI-NPS

Property Number: 61202410080

Status: Excess

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Building in poor condition. Abandoned utility vault containing non-functional high voltage wiring & transformers.

#### NORTH DAKOTA

VOQ/Bldg 132

132 Penn Circle

Grand Forks ND 58205

Landholding Agency: DoD-USAF

Property Number: 18202410015

Status: Underutilized

Directions:

RPUID: 439630

Reasons:

National Security Concerns

Comments:

Active Military installation; No public access

## UNSUITABLE PROPERTIES

### BUILDING

#### OHIO

IGLOO STORAGE,001A1,001A2,  
001A3,001A4,001A5)

8451 State Route 5

Ravenna Arsenal OH 44266

Landholding Agency: DoD-Army

Property Number: 21202410058

Status: Excess

Directions:

RPUID: 1048421, 1048417, 1048423, 1048418,223229

Reasons:

National Security Concerns

Structural Damage - Extensive Deterioration

Comments:

Active Military installation; no public access. Front walls are detaching from the magazine.

IGLOO STORAGE DEPOT (001B1,  
001B2,001B3,001B4,001B5, 001B6)

8451 State Route 5

Ravenna Arsenal OH 44266

Landholding Agency: DoD-Army

Property Number: 21202410059

Status: Excess

Directions:

RPUID: 223230,223231,223232,223233,223417,223418

Reasons:

National Security Concerns

Comments:

Active Military installation; no public access. Front walls are detaching from the magazine.

IGLOO STORAGE DEPOT (001C1,  
001C2,001C3,001C4,001C5, 001C6,001C7,001C8,00

8451 State Route 5

Ravenna Arsenal OH 44266

Landholding Agency: DoD-Army

Property Number: 21202410060

Status: Excess

Directions:

RPUID: 223419,223420,223422,223423,223424,223425, 223426,22427

Reasons:

Structural Damage - Extensive Deterioration

National Security Concerns



## UNSUITABLE PROPERTIES

### BUILDING

#### OHIO

Comments:

Active Military installation; no public access. Front walls are detaching from the magazine.

#### VIRGINIA

VOQ Dodd Hall Bldg 446

141 Dodd Blvd

JBLE-Langley AFB VA 23665

Landholding Agency: DoD-USAF

Property Number: 18202410014

Status: Underutilized

Reasons:

National Security Concerns

Comments:

Lead and Asbestos. Active Military installation; No public access

Tom's Cove Visitor Center

Beach Road

Chincoteague VA 23336

Landholding Agency: DOI-NPS

Property Number: 61202410073

Status: Excess

Directions:

RPUID:47518; PMIS#332387

Reasons:

Floodway

Comments:

Building floods during storms and in 100 year floodplain, marsh wetlands.

## UNSUITABLE PROPERTIES

## BUILDING

## WEST VIRGINIA

Jacob Henkle Farm House  
District 4, Map 9, Parcel 21  
Harpers Ferry WV 25425  
Landholding Agency: DOI-NPS  
Property Number: 61202410074  
Status: Excess  
Directions:

RPUID:105864; PMIS#254774

## Reasons:

Structural Damage - Extensive Deterioration

## Comments:

Foundation is coursed stone rubble. Floor is mounted on stone & brick piers with wood floor joist construction, that's completely rotten. Potential asbestos and Lead Based Paint.

Jacob Henkle Farm Grain Silo  
District 4, Map 9, Parcel 22  
Harpers Ferry WV 25425  
Landholding Agency: DOI-NPS  
Property Number: 61202410075  
Status: Excess  
Directions:

RPUID:254378; PMIS#254774

## Reasons:

Structural Damage - Extensive Deterioration

## Comments:

No roof exists, which causes water to fill the structure and rot the wooden components. Potential asbestos and Lead Based Paint.

Jacob Henkle Farm Dairy Barn  
District 4, Map 9, Parcel 23  
Harpers Ferry WV  
Landholding Agency: DOI-NPS  
Property Number: 61202410076  
Status: Excess  
Directions:

RPUID:254379; PMIS#254774

## Reasons:

Structural Damage - Extensive Deterioration

## Comments:

Roof is collapsed allowing water infiltration and rotting of the milled wooden timbers. Potential asbestos and Lead Based Paint.

## UNSUITABLE PROPERTIES

## BUILDING

## WEST VIRGINIA

Jacob Henkle Farm Milk House

District 4, Map 9, Parcel 24

Harpers Ferry WV 26525

Landholding Agency: DOI-NPS

Property Number: 61202410077

Status: Excess

Directions:

RPUID:254380; PMIS#254774

Reasons:

Structural Damage - Extensive Deterioration

Comments:

One wall is missing. Potential asbestos and Lead Based Paint.

Jacob Henkle Farm Shed/Corn Cr

District 4, Map 9, Parcel 25

Harpers Ferry WV 25425

Landholding Agency: DOI-NPS

Property Number: 61202410078

Status: Excess

Directions:

RPUID:254381; PMIS#254774

Reasons:

Structural Damage - Extensive Deterioration

Comments:

The roof is partially collapsed and wall structure has failed. Potential asbestos and Lead Based Paint.

## UNSUITABLE PROPERTIES

### LAND

#### FLORIDA

1.5 acres next to Shoppette  
 2587 W. Elgin Blvd  
 Eglin AFB FL 32542  
 Landholding Agency: DoD-USAF  
 Property Number: 18202410013  
 Status: Unutilized  
 Directions:

RPUID:420725

Reasons:

National Security Concerns

Comments:

Active Military installation; No public access

#### TENNESSEE

0.05 acres of OLD\_C-342  
 on Old Hickory Lock and Dam Project  
 107 Imperial Point Drive  
 Hendersonville TN  
 Landholding Agency: DOD-USACE  
 Property Number: 31202410001  
 Status: Excess

Reasons:

Inaccessible

Comments:

Land is occupied by a portion of a private residence and is not available to the public any time.

### Summary for UNSUITABLE PROPERTIES

---

Total number of = 50

## SUMMARY OF ALL PROPERTIES

---

Suitable/Available	=	0
Suitable/Unavailable	=	0
Suitable/To Be	=	0
** Suitable/ Undefined	=	0
Total Suitable	=	0
Total Unsuitable	=	50
Total number of	=	50
Properties	=	0