

INTERPRETATIVE BULLETIN H-2-77
UNDERCUTTING OF BATHROOM DOORS - 3280.715(b)(1) AND (4)

Bathroom doors may be undercut regardless of the type of return air provisions utilized. However, registers or grilles used for the purpose of providing return air through the use of a return duct to the furnace shall not be installed in toilet compartment areas.

This Interpretative Bulletin is issued pursuant to 24 CFR 3280.1(c) and 3282.113. The Secretary deems that it would not be in the public interest to issue this interpretation for public comment in the Federal Register or otherwise treat this Interpretative Bulletin as rulemaking.