U.S. DEPARTMENT OF HOUSING AND URBAN DEVELOPMENT



WASHINGTON, DC 20410-5000

DEFINITIONS OF TERMS USED IN STANDARDS

The following definitions related to inspectable areas are used in the attached proposed standards:

Unit	A Unit (or "dwelling Unit") of HUD housing refers to the interior components of an individual Unit. Examples of components in the interior of a Unit may include the bathroom, call-for-aid (if applicable), ceiling, doors, electrical systems, floors, water heater, heating ventilation and air conditioning (HVAC) (where individual Units are provided), kitchen, lighting, outlets, switches, smoke detectors, stairs, walls, and windows.
Inside	Inside of HUD housing refers to the common areas and building systems that can be generally found within the building interior and are not inside a Unit. Examples of "inside" common areas may include, basements, interior or attached garages, enclosed carports, restrooms, closets, utility rooms, mechanical rooms, community rooms, day care rooms, halls, corridors, stairs, shared kitchens, laundry rooms, offices, enclosed porches, enclosed patios, enclosed balconies, and trash collection areas. Examples of building systems include those components that provide domestic water, electricity, elevators, emergency power, fire protection, HVAC, and sanitary services.
Outside	Outside of HUD housing (or "outside areas") refers to the building site, building exterior components, and any building systems located outside of the building or unit. Examples of "outside" components may include facades, fencing, retaining walls, grounds, lighting, mailboxes, project signs, parking lots, detached garage or carport, driveways, play areas and equipment, refuse disposal, roads, storm drainage, non-dwelling buildings, and walkways. Components found on the exterior of the building are also considered outside areas, and examples may include doors, attached porches, attached patios, balconies, car ports, fire escapes, foundations, lighting, roofs, walls, and windows.

The following definitions related to health and safety are used in the attached proposed standards:

Life-Threatening	The Life-Threatening category includes deficiencies that, if evident in the home or on the property, present a high risk of death or severe illness or injury to a resident.
Severe Non-Life Threatening	The Severe Non-Life-Threatening category includes deficiencies that, if evident in the home or on the property, present a high risk of permanent disability, or serious injury or illness, to a resident; or the physical security or safety of a resident or their property would be seriously compromised.
Standard	The Standard Health and Safety category includes deficiencies that, if evident in the home or on the property, present a moderate risk of an adverse medical event requiring a healthcare visit; cause temporary harm; or if left untreated, cause or worsen a chronic condition that may have long-lasting adverse health effects; or that the physical security or safety of a resident or their property could be compromised.
Advisory	Deficiencies critical to habitability but not presenting a substantive health or safety risk to resident.
HCV Pass/Fail	Units participating in the Housing Choice Voucher (HCV) programs do not receive a score for physical inspections, so deficiencies are indicated only as a pass or fail. Items that fail must be corrected per the guidelines in the regulations.

TABLE 1—ADDRESS AND SIGNAGE STANDARD

Definition and Location	
Definition	Unique number and name identifiers assigned to property.
Location	Outside: Near building entrances (either above or alongside the entrance or on a nearby post) and road entrances where the property's private road meets a public road.
Deficiency 1 – Address a	nd Signage: Outside
Deficiency	Address, signage, or building identification codes are broken, illegible, or not visible.
Deficiency Criteria	Address or building identification codes are broken, illegible, or not visible.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If address, signage, or building identification codes are broken, illegible, or not visible, and there is an emergency, then first responders may be delayed if they are unable to efficiently locate the property.
	If address, signage, or building identification codes are broken, illegible, or not visible, then it is likely that routine or daily maintenance activities are not being addressed.

TABLE 2—BATHTUB AND SHOWER STANDARD

Definition and Location	
Definition	Fixtures typically found in bathrooms that dispense clean water used for bathing and self-care which also contain a method for draining used water.
Location	Unit: Bathroom
	Inside: Bathroom
Deficiency 1 – Bathtub	and Shower: Unit
Deficiency	Only 1 bathtub or shower is present, and it is inoperable or does not drain.
Deficiency Criteria	Only 1 bathtub or shower is present within the unit, and it is inoperable (i.e., overall system is not meeting function or purpose, with or without visible damage) or standing water is present such that the inspector believes water is unable to drain.

Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If only 1 bathtub or shower is present within the Unit and it is inoperable or standing water is present such that the inspector believes water is unable to drain, then the resident's ability to maintain hygienic practices is limited, which may result in an increased risk of illness from infectious disease.
	If only 1 bathtub or shower is present within the Unit and it is inoperable or standing water is present such that the inspector believes water is unable to drain, then the resident may not be able to use a feature that is expected to be provided and maintained as part of their rent.
	A resident is likely to notice if only 1 bathtub or shower is present within the Unit and it is inoperable or standing water is present, and to recognize it is important enough to report it to property management because it may present sanitary hazards or usability barriers. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in sanitary hazards.
Deficiency 1 – Bathtub ar	nd Shower: Inside
Deficiency	Only 1 bathtub or shower is present, and it is inoperable or does not drain.
Deficiency Criteria	Only 1 bathtub or shower is present within the Inside, and it is inoperable (i.e., overall system is not meeting function or purpose, with or without visible damage) or standing water is present such that the inspector believes water is unable to drain.
Health and Safety determination	Advisory
Correction Timeframe	Advisory
HCV Correction Timeframe	Advisory
HCV Pass/Fail	Pass

Rationale

If only 1 bathtub or shower is present within the Inside and it is inoperable or standing water is present such that the inspector believes water is unable to drain, then the resident may not be able to use a feature that is expected to be provided and maintained as part of their rent.

Property management would be expected to ensure that staff members understand how to identify if there is only 1 bathtub or shower present within the Inside and it is inoperable or standing water is present such that the inspector believes water is unable to drain. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in usability barriers.

Deficiency 2 – Bathtub and Shower: Unit Deficiency A bathtub or shower is inoperable or does not drain and at least 1 bathtub or shower is present elsewhere that is operational. Deficiency Criteria A bathtub or shower is inoperable (i.e., overall system is not meeting

A bathtub or shower is inoperable (i.e., overall system is not meeting function or purpose, with or without visible damage) or standing water is present such that the inspector believes water is unable to drain and at least 1 bathtub or shower is present elsewhere within the Unit that is operational.

Health and Safety Determination

Standard

Correction Timeframe

30 days

HCV Correction Timeframe

30 days

HCV Pass/Fail

Fail

Rationale

If a bathtub or shower is inoperable or standing water is present such that the inspector believes water is unable to drain and at least 1 bathtub or shower is present elsewhere within the Unit that is operational, then the resident's ability to maintain hygienic practices is limited, which may result in an increased risk of illness from infectious disease.

If a bathtub or shower is inoperable or standing water is present such that the inspector believes water is unable to drain and at least 1 bathtub or shower is present elsewhere within the Unit that is operational, then the resident may not be able to use a feature that is expected to be provided and maintained as part of their rent.

If there are multiple bathtubs or showers present with the Unit, the resident is likely to notice if one is inoperable or has standing water and to recognize it is important enough to report it to property management because it may present sanitary hazards or usability barriers. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in sanitary hazards.

- ··	nd Shower: Inside
Deficiency	A bathtub or shower is inoperable or does not drain and at least 1 bathtub or shower is present elsewhere that is operational.
Deficiency Criteria	A bathtub or shower is inoperable (i.e., overall system is not meeting function or purpose, with or without visible damage) or standing water is present such that the inspector believes water is unable to drain and at least 1 bathtub or shower is present elsewhere within the Inside that is operational.
Health and Safety Determination	Advisory
Correction Timeframe	Advisory
HCV Correction Timeframe	Advisory
HCV Pass/Fail	Pass
Rationale	If a bathtub or shower is inoperable or standing water is present such that the inspector believes water is unable to drain and at least 1 bathtub or shower is present elsewhere within the Inside that is operational, then the resident may not be able to use a feature that is expected to be provided and maintained as part of their rent. Property management would be expected to ensure that staff members understand how to identify if there are multiple bathtubs or showers present within the Inside and one is inoperable or has standing water present such that the inspector believes water is unable to drain.
	Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in usability barriers.
Deficiency 3 – Bathtub a	nd Shower: Unit
Deficiency	Bathtub component or shower component is damaged, inoperable, or missing such that it may limit the resident's ability to maintain personal hygiene.
Deficiency criteria	Bathtub component or shower component is damaged (i.e., visibly defective; impacts functionality) such that it may limit the resident's ability to maintain personal hygiene.
	OR
	Bathtub component or shower component is inoperable (i.e., component is not meeting function or purpose, with or without visible damage) such that
	it may limit the resident's ability to maintain personal hygiene.

	Bathtub component or shower component is missing (i.e., evidence of prior installation, but is now not present or is incomplete) such that it may limit the resident's ability to maintain personal hygiene.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a bathtub component or shower component is damaged, inoperable, or missing such that it may limit the resident's ability to maintain personal hygiene, then the resident may be at an increased risk of illness from infectious diseases.
	If a bathtub component or shower component is damaged, inoperable, or missing such that it may limit the resident's ability to maintain personal hygiene, then the resident may not be able to use a feature that is expected to be provided and maintained as part of their rent.
	If a bathtub component or shower component is damaged, inoperable, or missing such that it may limit the resident's ability to maintain personal hygiene, then the resident is likely to notice this and to recognize it is important enough to report it to property management because it may present sanitary hazards or usability barriers. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in sanitary hazards.
Deficiency 3 – Bathtub a	nd Shower: Inside
Deficiency	Bathtub component or shower component is damaged, inoperable, or missing such that it may limit the resident's ability to maintain personal hygiene.
Deficiency criteria	Bathtub component or shower component is damaged (i.e., visibly defective; impacts functionality) such that it may limit the resident's ability to maintain personal hygiene.
	OR
	Bathtub component or shower component is inoperable (i.e., component is not meeting function or purpose, with or without visible damage) such that it may limit the resident's ability to maintain personal hygiene.
	OR
	Bathtub component or shower component is missing (i.e., evidence of prior installation, but is now not present or is incomplete) such that it may limit the resident's ability to maintain personal hygiene.

Health and Safety Determination	Advisory
Correction Timeframe	Advisory
HCV Correction Timeframe	Advisory
HCV Pass/Fail	Pass
Rationale	If a bathtub component or shower component is damaged, inoperable, or missing such that it may limit the resident's ability to maintain personal hygiene, then the resident may not be able to use a feature that is expected to be provided and maintained as part of their rent.
	Property management would be expected to ensure that staff members understand how to identify a bathtub component or shower component that is damaged, inoperable, or missing such that it may not provide a sanitary area to maintain personal hygiene. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this defect, because it may result in sanitary hazards or usability barriers.
Deficiency 4 – Bathtub ar	nd Shower: Unit
Deficiency	Bathtub component or shower component is damaged, inoperable, or missing and it does not limit the resident's ability to maintain personal hygiene.
Deficiency criteria	Bathtub component or shower component is damaged (i.e., visibly defective; impacts functionality) and it does not limit the resident's ability to maintain personal hygiene.
	OR
	Bathtub component or shower component is inoperable (i.e., component is not meeting function or purpose, with or without visible damage) and it does not limit the resident's ability to maintain personal hygiene.
	OR
	Bathtub component or shower component is missing (i.e., evidence of prior installation, but is now not present or is incomplete) and it does not limit the resident's ability to maintain personal hygiene.
Health and Safety Determination	Advisory
Correction Timeframe	Advisory
HCV Correction	Advisory
Timeframe	

Rationale If the resident's ability to maintain personal hygiene is not limited, but a bathtub component or shower component is damaged, inoperable, or missing, then the resident's ability to fully utilize an aspect of the fixture may be reduced. If a bathtub component or shower component is damaged, inoperable, or missing and it does not limit the resident's ability to maintain personal

missing and it does not limit the resident's ability to maintain personal hygiene, then the resident may notice this and report it to property management. Property management may be expected to prioritize a work order to remedy this deficiency because it may result in the resident's limited ability to fully utilize an aspect of the fixture.

TABLE 3—CABINETS STANDARD

Definition and Location	
Definition	A box-shaped piece of furniture with doors or drawers. Some cabinets are free-standing while others may be built into, or attached to, a wall. Generally, cabinets may have: One or more doors on the front, mounted with door hardware, and occasionally a lock One or more doors, drawers, or shelves.
Location	Unit: Kitchens, bathroom, laundry
	Inside: Kitchens, bathroom, laundry
Deficiency 1 – Cabinets: I	Unit
Deficiency	Cabinets are missing in Unit kitchen.
Deficiency Criteria	Within the Unit kitchen, 25% or more of the cabinets are missing (i.e., evidence of prior installation, but now not present or is incomplete).
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If cabinets are missing in the Unit kitchen, then the resident may not have sufficient ability to store food and dishes in a safe manner. If cabinets are missing in the Unit kitchen, then the resident is unable to use a feature that is expected to be included and maintained as a part of their
	rent.

If cabinets are missing in the Unit kitchen, then the resident will likely report this defect and for facilities management to prioritize a work order response to fix that deficiency.

Deficiency	Cabinet components are damaged or missing.
Deficiency Criteria	50% or more of the kitchen, bath, or laundry cabinet doors, drawers, or shelves are missing (i.e., evidence of prior installation, but now not present or is incomplete).
	OR
	50% or more of the kitchen, bath, or laundry cabinet doors, drawers, or shelves are damaged (i.e., visibly defective; impacts functionality).
	OR
	50% or more of the kitchen, bath, or laundry cabinet doors, drawers, or shelves are inoperable (i.e., overall system or component thereof not meeting function or purpose; with or without visible damage).
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If cabinet components are damaged or missing, then the resident may not have sufficient ability to store food, dishes, or personal or cleaning items in a safe and sanitary manner.
	If cabinet components are damaged or missing, then the resident may be unable to use a feature that is expected to be included and maintained in their rent.
	If cabinet components are damaged or missing, then this should be identified through normal maintenance activities, and the presence of this deficiency may indicate that routine maintenance activities are not being addressed.
Deficiency 2 – Cabinets:	nside
Deficiency	Cabinet components are damaged or missing.
Deficiency Criteria	50% or more of the kitchen, bath, or laundry cabinet doors, drawers, or shelves are missing (i.e., evidence of prior installation, but now not present or is incomplete).
	OR

	50% or more of the kitchen, bath, or laundry cabinet doors, drawers, or shelves are damaged (i.e., visibly defective; impacts functionality).
	OR
	50% or more of the kitchen, bath, or laundry cabinet doors, drawers, or shelves are inoperable (i.e., overall system or component thereof not meeting function or purpose; with or without visible damage).
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If cabinet components are damaged or missing, then the resident may not have sufficient ability to store food, dishes, or cleaning items in a safe and sanitary manner.
	If cabinet components are damaged or missing, the then resident may be unable to use a feature that is expected to be included and maintained in their rent.
	If cabinet components are damaged or missing, then this should be identified through normal maintenance activities and the presence of this deficiency may indicate that routine maintenance activities are not being addressed.

TABLE 4—CALL-FOR-AID SYSTEM STANDARD

Definition and Location	1
Definition	A call system used by a resident to summon aid during a medical
	emergency.
Location	Unit: Bathroom, bedroom, hallway
	Inside: Common area, including bathroom and hallway
Deficiency 1 – Call-for-	Aid System: Unit
Deficiency	Pull cord is missing or end is higher than 6 inches off the floor.
Deficiency Criteria	Pull cord is missing (i.e., evidence of prior installation, but now not present or is incomplete).
	OR
	Pull-cord end is higher than 6 inches off the floor.

Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a pull-cord is missing or the end is higher than 6 inches off the floor, and the resident is unable to reach the cord, they may not have access to medical care as their ability to alert emergency services is impacted.
	If a pull-cord is missing or the end is higher than 6 inches off the floor, and the resident is unable to reach the cord, they may be injured when attempting to reach the cord.
	If a pull cord is missing or the end is higher than 6 inches off the floor, then the resident may not be able to fully use the device, which is assumed to be maintained as part of their rent.
	If a pull-cord is missing or the end is higher than 6 inches off the floor, then it is likely that complaint-based work orders are not being addressed.
	If a pull-cord is missing or the end is higher than 6 inches off the floor, then it is likely that routine maintenance activities are not being addressed.

d System: Inside
Pull-cord is missing or end is higher than 6 inches off the floor.
Pull-cord is missing (i.e., evidence of prior installation, but now not present or is incomplete).
OR
Pull-cord end is higher than 6 inches off the floor.
Severe Non-Life Threatening
24 hours
30 days
Fail

Rationale

If a pull-cord is missing or the end is higher than 6 inches off the floor, and the resident is unable to reach the cord, they may not have access to medical care as their ability to alert emergency services is impacted.

If a pull-cord is missing or the end is higher than 6 inches off the floor, and the resident is unable to reach the cord, then they may be injured when attempting to reach the cord.

If a pull-cord is missing or the end is higher than 6 inches off the floor, then the resident may not be able to fully use the device, which is assumed to be maintained as part of their rent.

If a pull-cord is missing or the end is higher than 6 inches off the floor, then it is likely that complaint-based work orders are not being addressed.

If a pull-cord is missing or the end is higher than 6 inches off the floor, then it is likely that routine maintenance activities are not being addressed.

Deficiency	System does not function properly.
Deficiency Criteria	A call-for-aid system does not emit sound or light or send signal to annunciator.
	OR
	The annunciator does not indicate the correct corresponding room.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If a call-for-aid system does not function properly, then the resident may not have access to medical care as their ability to alert emergency services is impacted.
	If a call-for-aid system does not function properly, then the resident may not be able to fully use a feature that is expected to be maintained as part of their rent.
	If a call-for-aid system does not function properly, then the resident will likely report the deficiency, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.

	If a call-for-aid system does not function properly, then the presence of this deficiency may indicate that routine maintenance activities are not being addressed.
Deficiency 2 – Call-for-Aid	d System: Inside
Deficiency	System does not function properly.
Deficiency Criteria	A call-for-aid system does not emit sound or light or send signal to annunciator.
	OR
	The annunciator does not indicate the correct corresponding room.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If a call-for-aid system does not function properly, then the resident may not have access to medical care as their ability to alert emergency services is impacted.
	If a call-for-aid system does not function properly, then the resident may not be able to fully use a feature that is expected to be maintained as part of their rent.
	If a call-for-aid system does not function properly, then the resident will likely report the deficiency, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	If a call-for-aid system does not function properly, then the presence of this deficiency may indicate that routine maintenance activities are not being addressed.
Deficiency 3 – Call-for-Aid	d System: Unit
Deficiency	System is blocked.
Deficiency Criteria	Resident is physically impeded from using the call-for-aid pull cord.
Health and Safety Determination	Severe Non-Life Threatening

24 hours

Correction Timeframe

HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the call-for-aid system is blocked, then the resident may not have access to medical care as their ability to alert emergency services is impacted.
	If the call-for-aid system is blocked, then the resident may not be able to fully use a feature that is expected to be maintained as part of their rent.
	If the call-for-aid system is blocked, then the presence of this deficiency may indicate that routine maintenance activities are not being addressed.
Deficiency 3 – Call-for-Ai	d System: Inside
Deficiency	System is blocked.
Deficiency Criteria	Resident is physically impeded from using the call-for-aid pull cord.
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the call-for-aid system is blocked, then the resident may not have access to medical care as their ability to alert emergency services is impacted.
	If the call-for-aid system is blocked, then the resident may not be able to fully use a feature that is expected to be maintained as part of their rent.
	If the call-for-aid system is blocked, then the presence of this deficiency may indicate that routine maintenance activities are not being addressed.

TABLE 5—CARBON MONOXIDE ALARM STANDARD

Definition and Location	
Definition	Device that detects elevated levels of carbon monoxide and signals via auditory or visual alarm in order to prevent carbon monoxide poisoning.
Location	Unit: Where required as described in the Deficiency Criteria Inside: Where required as described in the Deficiency Criteria

Deficiency 1 - Carbon Monoxide Alarm: Unit

Deficiency

Carbon monoxide alarm is missing, not installed, or not installed in a proper location.

Deficiency Criteria

Carbon monoxide alarm is missing (i.e., evidence of prior installation, but is now not present or is incomplete).

OR

One (1) or more of the following scenarios exists:

- 1. Unit contains a fuel-burning appliance or fuel-burning fireplace, and a carbon monoxide alarm is not installed:
 - a. in the immediate vicinity of each sleeping area.
 OR
 - b. within each sleeping area.
- 2. Sleeping area or bathroom attached to sleeping area:
 - a. contains a fuel-burning appliance or fuel-burning fireplace.
 OR
 - b. has adjacent spaces from which byproducts of combustion gases can flow.

AND

- c. Carbon monoxide alarm is not installed in each sleeping area.
- 3. Unit or sleeping area is served by a forced-air furnace that is located elsewhere and a carbon monoxide alarm is not installed:
 - a. $\,$ in the immediate vicinity of each sleeping area.

OR

b. within each sleeping area.

OR

- c. within the room or area with the first duct register and the carbon monoxide alarm signals are automatically transmitted to an approved location.
- 4. Unit or sleeping area is located in a building that contains a fuel-burning appliance or fuel-burning fireplace and:
 - a carbon monoxide alarm is not installed in an approved location between the fuel-burning appliance or fuel-burning fireplace and the Unit or sleeping area.

OR

 a carbon monoxide alarm is not installed on the ceiling of the room containing the fuel-burning appliance or fuel-burning fireplace.

OR

- c. the Unit or sleeping area has communicated openings to the fuel-burning appliance or fuel-burning fireplace and a carbon monoxide alarm is not installed:
 - i. in the immediate vicinity of each sleeping area.

OR

	ii. within each sleeping area.
	 Unit or sleeping area is located one (1) story or less above or below an attached private garage that: a. does not have natural ventilation.
	OR b. is enclosed and does not have a ventilation system for vehicle exhaust. AND c. Carbon monoxide alarm is not installed:
	i. in the immediate vicinity of each sleeping area.ORii. within each sleeping area.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If a carbon monoxide alarm is missing, not installed, or not installed in a proper location and there is an elevated level of carbon monoxide in the Unit, then the health of the resident may be at risk due to potential carbon monoxide poisoning. If a carbon monoxide alarm is missing, not installed, or not installed in a proper location, then this will likely be observed during routine
	maintenance activities, and the presence of this deficiency may indicate self-generated work orders are not being addressed.
Deficiency 1 – Carbon M	onoxide Alarm: Inside
Deficiency	Carbon monoxide alarm is missing, not installed, or not installed in a proper location.
Deficiency Criteria	Carbon monoxide alarm is missing (i.e., evidence of prior installation, but now not present or is incomplete). OR
	One (1) or more of the following scenarios exists: 1. Classroom contains a fuel-burning appliance or fuel-burning fireplace, and a carbon monoxide alarm is not installed: a. in the immediate vicinity of each sleeping area. OR b. within each sleeping area.
	Sleeping area or bathroom attached to sleeping area:

- a. contains a fuel-burning appliance or fuel-burning fireplace.
- b. has adjacent spaces from which byproducts of combustion gases can flow.

AND

- c. Carbon monoxide alarm is not installed in each sleeping area.
- 3. Sleeping area or classroom is served by a forced-air furnace that is located elsewhere and a carbon monoxide alarm is not installed:
 - a. in the immediate vicinity of each sleeping area.

 \cap R

b. within each sleeping area.

OR

- c. within the room or area with the first duct register and the carbon monoxide alarm signals are automatically transmitted to an approved location.
- 4. Sleeping area or classroom is located in a building that contains a fuel-burning appliance or fuel-burning fireplace and:
 - a. a carbon monoxide alarm is not installed in an approved location between the fuel-burning appliance or fuel-burning fireplace and the sleeping area or classroom.

OR

b. a carbon monoxide alarm is not installed on the ceiling of the room containing the fuel-burning appliance or fuel-burning fireplace.

OR

- c. the sleeping area or classroom has communicated openings to the fuel-burning appliance or fuel-burning fireplace and a carbon monoxide alarm is not installed:
 - i. in the classroom

OR

ii. in the immediate vicinity of each sleeping area.

OR

- iii. within each sleeping area.
- 5. Sleeping area or classroom is located one (1) story or less above or below an attached private garage that:
 - a. does not have natural ventilation.

OR

b. is enclosed and does not have a ventilation system for vehicle exhaust.

AND

- c. Carbon monoxide alarm is not installed:
 - i. in the classroom.

OR

ii. in the immediate vicinity of each sleeping area.

ΟR

iii. within each sleeping area.

Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a carbon monoxide alarm is missing, not installed, or not installed in a
	proper location and there is an elevated level of carbon monoxide in the
	classroom, then the health of the care provider or recipient may be at risk
	due to potential carbon monoxide poisoning.
	If a carbon monoxide alarm is missing, not installed, or not installed in a
	proper location, then this will likely be observed during routine
	maintenance activities, and the presence of this deficiency may indicate
	self-generated work orders are not being addressed.
Deficiency 2 – Carbon M	onoxide Alarm: Unit
Deficiency	Carbon monoxide alarm is obstructed.
Deficiency Criteria	Carbon monoxide alarm is obstructed.
Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a carbon monoxide alarm is obstructed and there is a carbon monoxide
	leak, then the resident's health may be at risk.
	If a carbon monoxide alarm is obstructed and there is a carbon monoxide
	leak, then the resident may not be alerted.
	If a carbon monoxide alarm is obstructed, then the resident may not be able
	to use a feature that is expected to be provided and maintained as part of the rent.
	If a carbon monoxide alarm is obstructed, then this will likely be observed
	during routine maintenance activities and the presence of this deficiency
	may indicate self-generated work orders are not being addressed.
	.,

Deficiency 2 – Carbon Monoxide Alarm: Inside

Deficiency	Carbon monoxide alarm is obstructed.
Deficiency Criteria	Carbon monoxide alarm is obstructed.
Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a carbon monoxide alarm is obstructed and there is a carbon monoxide leak, then the resident's health may be at risk.
	If a carbon monoxide alarm is obstructed, then this will likely be observed during routine maintenance activities and the presence of this deficiency may indicate self-generated work orders are not being addressed.

Deficiency 3 – Carbon Mo	onoxide Alarm: Unit
Deficiency	Carbon monoxide alarm does not produce an audio or visual alarm when
	tested.
Deficiency Criteria	Carbon monoxide alarm does not produce audio or visual alarm when
	tested.
Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a carbon monoxide alarm does not produce an audio or visual alarm, and
	there is carbon monoxide leak, then the health and safety of the resident
	could be at risk as they may not be alerted.
	If a carbon monoxide alarm does not produce an audio or visual alarm, then
	this will likely be observed during routine maintenance activities, and the
	presence of this deficiency may indicate self-generated work orders are not
	being addressed, as carbon monoxide alarms should be tested monthly and
	batteries changed yearly.

Deficiency 3 – Carbon Monoxide Alarm: Inside

Deficiency	Carbon monoxide alarm does not produce audio or visual alarm when tested.
Deficiency Criteria	Carbon monoxide alarm does not produce an audio or visual alarm when tested.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If a carbon monoxide alarm does not produce an audio or visual alarm, and there is carbon monoxide leak, then the health and safety of the resident could be at risk as they may not be alerted.
	If a carbon monoxide alarm does not produce an audio or visual alarm, then this will likely be observed during routine maintenance activities, and the presence of this deficiency may indicate self-generated work orders are not being addressed, as carbon monoxide alarms should be tested monthly and batteries changed yearly.

TABLE 6—CEILING STANDARD

Definition and Location	
Definition	The upper interior surface of a room that provides separation between rooms, spaces, and floors.
Location	Unit: Upper interior surface of room
	Inside: Upper interior surface of room
Deficiency 1 – Ceiling: Ur	iit
Deficiency	Ceiling has an unstable surface.
Deficiency Criteria	Ceiling has an unstable surface.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction Timeframe	30 days

HCV Pass/Fail	Fail
Rationale	If the ceiling has an unstable surface, then the resident could be injured by falling debris.
	If the ceiling has an unstable surface, then a feature of the home that is expected to be provided and maintained as part of the resident's rent may be jeopardized.
	If the ceiling has an unstable surface, then it is likely the resident will report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
Deficiency 1 – Ceiling: Ins	side
Deficiency	Ceiling has an unstable surface.
Deficiency Criteria	Ceiling has an unstable surface.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the ceiling has an unstable surface, then the resident could be injured by falling debris.
	If the ceiling has an unstable surface, then a feature of the home that is expected to be provided and maintained as part of the resident's rent may be jeopardized.
	If the ceiling has an unstable surface, then it is likely the resident will report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
Deficiency 2 – Ceiling: Ur	nit
Deficiency	Ceiling has a hole.
Deficiency Criteria	A hole is present that opens directly to the outside environment.
	OR
	A hole is present that is 2 inches or greater in diameter.
Health and Safety	Standard

Determination

Correction Timeframe 30 days

HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the ceiling has a hole, then the resident may be exposed to potentially harmful materials that may be in the space above the ceiling (e.g., weather, insulation, vermin).
	If the ceiling has a hole, then it may compromise the fire stop and smoke stop properties of the ceiling. Openings (including those due to breaking, displacing, or removing ceiling tiles) can enable hot gases and smoke from a fire to rise and accumulate above detectors and sprinklers, which can delay their activation, enabling fires to rapidly grow larger before an alarm and response can occur. This has the potential to put the resident at increased risk in the event of a fire.
	If the ceiling has a hole, then the resident is unable to fully rely on or use a feature that is expected to be provided and maintained as part of their rent.
	If the ceiling has a hole, and the resident is responsible for utilities, then this may result in increased utility costs to the resident.
	If the ceiling has a hole, then it is likely the resident will report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.

Deficiency 2 – Ceiling: Ins	Deficiency 2 – Ceiling: Inside	
Deficiency	Ceiling has a hole.	
Deficiency Criteria	A hole is present that opens directly to the outside environment.	
	OR	
	A hole is present that is 2 inches or greater in diameter.	
Health and Safety	Standard	
Determination		
Correction Timeframe	30 days	
HCV Correction	30 days	
Timeframe		
HCV Pass/Fail	Fail	
Rationale	If the ceiling has a hole, then the resident may be exposed to potentially	
	harmful materials that may be in the space above the ceiling (e.g., weather, insulation, vermin).	

If the ceiling has a hole, then it may compromise the fire stop and smoke stop properties of the ceiling. Openings (including those due to breaking, displacing, or removing ceiling tiles) can enable hot gases and smoke from a fire to rise and accumulate above detectors and sprinklers, which can delay their activation, enabling fires to rapidly grow larger before an alarm and response can occur. This has the potential to put the resident at increased risk in the event of a fire.

If the ceiling has a hole, then the resident is unable to fully rely on or use a feature that is expected to be provided and maintained as part of their rent.

If the ceiling has a hole, and the resident is responsible for utilities, then this may result in increased utility costs to the resident.

If the ceiling has a hole, then it is likely the resident will report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.

Deficiency 3 – Ceiling: Ur	11t
Deficiency	Ceiling has a sign of structural failure.
Deficiency Criteria	There is sagging or dropping of the plasterboard sheeting or the cornice.
	OR
	There is cracking or small circles or blisters (nail pops) on the ceiling (which are a sign the plasterboard sheeting may be pulling away from the nails or screws).
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the ceiling has a sign of structural failure, then the resident could be injured by failing materials.
	If the ceiling has a sign of structural failure, then the resident is unable to fully rely on or use a feature that is expected to be provided and maintained as part of their rent.
	If the ceiling has a sign of structural failure, then it is likely the resident will report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.

If the ceiling has a sign of structural failure, then it may be costly to repair.

If the ceiling has a sign of structural failure, then there may be a structural failure of the building.

Deficiency 3 – Ceiling: Ins	side
Deficiency	Ceiling has a sign of structural failure.
Deficiency Criteria	There is sagging or dropping of the plasterboard sheeting or the cornice.
	OR
	There is cracking or small circles or blisters (nail pops) on the ceiling (which are a sign the plasterboard sheeting may be pulling away from the nails or screws).
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the ceiling has a sign of structural failure, then the resident could be injured by failing materials.
	If the ceiling has a sign of structural failure, then the resident is unable to fully rely on or use a feature that is expected to be provided and maintained as part of their rent.
	If the ceiling has a sign of structural failure, then it is likely the resident will report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	If the ceiling has a sign of structural failure, then it may be costly to repair.
	If the ceiling has a sign of structural failure, then there may be a structural failure of the building.

TABLE 7—CHIMNEY STANDARD

Definition and Location

A vertical or near vertical passageway connected to a fireplace or wood- burning appliance.
Unit: Any enclosed, habitable space where a gas fireplace, wood-burning fireplace, or wood-burning appliance is located
Inside: Any enclosed, shared space where a gas fireplace, wood-burning fireplace, or wood-burning appliance is located
Outside: Any exterior, visually accessible component of a gas fireplace, wood-burning fireplace, or wood-burning appliance
Jnit
A visually accessible chimney, flue, or firebox connected to a fireplace or wood-burning appliance is incomplete or damaged such that it may not safely contain fire and convey smoke and combustion gases to the exterior.
A visually accessible (i.e., can be reasonably accessed and observed) chimney, flue, or firebox connected to a fireplace or wood-burning appliance is incomplete (i.e., evidence of a previously installed component that is now not present) such that it may not safely contain fire and convey smoke and combustion gases to the exterior.
OR
A visually accessible (i.e., can be reasonably accessed and observed) chimney, flue, or firebox connected to a fireplace or wood-burning appliance is damaged (i.e., visibly defective; impacts functionality) such that it may not safely contain fire and convey smoke and combustion gases to the exterior.
Life-Threatening
24 hours
24 hours
Fail
If a visually accessible chimney, flue, or firebox connected to a fireplace or wood-burning appliance is incomplete or damaged such that it may not safely contain fire and convey smoke and combustion gases to the exterior when used, then the resident may be at an increased risk of exposure to gases or smoke, which may result in respiratory issues or asphyxiation. If a visually accessible chimney, flue, or firebox connected to a fireplace or wood-burning appliance is incomplete or damaged such that it may not

when used, then there may be an increased safety risk to the resident of fire spread, which may result in injury or death.

Property management would be expected to ensure that staff members understand how to identify if a visually accessible chimney, flue, or firebox connected to a fireplace or wood-burning appliance is incomplete or damaged such that it may not safely contain fire and convey smoke and combustion gases to the exterior. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may lead to health and safety hazards.

Deficiency 1 - Chimney: Inside

Deficiency

A visually accessible chimney, flue, or firebox connected to a fireplace or wood-burning appliance is incomplete or damaged such that it may not safely contain fire and convey smoke and combustion gases to the exterior.

Deficiency Criteria

A visually accessible (i.e., can be reasonably accessed and observed) chimney, flue, or firebox connected to a fireplace or wood-burning appliance is incomplete (i.e., evidence of a previously installed component that is now not present) such that it may not safely contain fire and convey smoke and combustion gases to the exterior.

OR

A visually accessible (i.e., can be reasonably accessed and observed) chimney, flue, or firebox connected to a fireplace or wood-burning appliance is damaged (i.e., visibly defective; impacts functionality) such that it may not safely contain fire and convey smoke and combustion gases to the exterior.

Health and Safety Determination

Life-Threatening

Correction Timeframe

24 hours

HCV Correction Timeframe

24 hours

HCV Pass/Fail

Fail

Rationale

If a visually accessible chimney, flue, or firebox connected to a fireplace or wood-burning appliance is incomplete or damaged such that it may not safely contain fire and convey smoke and combustion gases to the exterior when used, then the resident may be at an increased risk of exposure to gases or smoke, which may result in respiratory issues or asphyxiation.

If a visually accessible chimney, flue, or firebox connected to a fireplace or wood-burning appliance is incomplete or damaged such that it may not safely contain fire and convey smoke and combustion gases to the exterior when used, then there may be an increased safety risk to the resident of fire spread, which may result in injury or death.

Property management would be expected to ensure that staff members understand how to identify if a visually accessible chimney, flue, or firebox connected to a fireplace or wood-burning appliance is incomplete or damaged such that it may not safely contain fire and convey smoke and combustion gases to the exterior. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may lead to health and safety hazards.

Deficiency 1 - Chimney: Outside

Deficiency

A visually accessible chimney, flue, or firebox connected to a fireplace or wood-burning appliance is incomplete or damaged such that it may not safely contain fire and convey smoke and combustion gases to the exterior.

Deficiency Criteria

A visually accessible (i.e., can be reasonably accessed and observed) chimney, flue, or firebox connected to a fireplace or wood-burning appliance is incomplete (i.e., evidence of a previously installed component that is now not present) such that it may not safely contain fire and convey smoke and combustion gases to the exterior.

OR

A visually accessible (i.e., can be reasonably accessed and observed) chimney, flue, or firebox connected to a fireplace or wood-burning appliance is damaged (i.e., visibly defective; impacts functionality) such that it may not safely contain fire and convey smoke and combustion gases to the exterior.

Health and Safety Determination

Life-Threatening

Correction Timeframe

24 hours

HCV Correction Timeframe

24 hours

HCV Pass/Fail

Fail

Rationale

If a visually accessible chimney, flue, or firebox connected to a fireplace or wood-burning appliance is incomplete or damaged such that it may not safely contain fire and convey smoke and combustion gases to the exterior when used, then there may be an increased safety risk to the resident of fire spread, which may result in injury or death.

Property management would be expected to ensure that staff members understand how to identify if a visually accessible chimney, flue, or firebox connected to a fireplace or wood-burning appliance is incomplete or

damaged such that it may not safely contain fire and convey smoke and combustion gases to the exterior. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may lead to health and safety hazards.

Deficiency 2 – Chimney:	Outside
Deficiency	Chimney exhibits signs of structural failure.
Deficiency Criteria	The chimney exhibits signs of structural failure such that the integrity of the
	chimney is jeopardized.
Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the chimney exhibits signs of structural failure such that the integrity of the chimney is jeopardized, then there may be an increased safety risk to the resident due to falling debris, instability, or fire spread, which may result in injury or death.
	If the chimney exhibits signs of structural failure such that the integrity of the chimney is jeopardized, then the resident may not be able to safely use the fireplace or wood-burning appliance.
	Property management would be expected to ensure that staff members understand how to identify if a chimney exhibits signs of structural failure such that the integrity of the chimney is jeopardized. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards or usability barriers.
	If the chimney exhibits signs of structural failure such that the integrity of the chimney is jeopardized, then the chimney may be unable to safely support its related components.

TABLE 8—CLOTHES DRYER EXHAUST VENTILATION STANDARD

Definition and Location	
Definition	The system connected to the clothes dryer vent outlet that exhausts air from the dryer blower to a designated area.
Location	Unit: Laundry room, washer and dryer area

Inside: Laundry room, washer and dryer area

Outside: Exterior vent cover

•	ryer Exhaust Ventilation: Unit
Deficiency	Electric dryer transition duct is detached or missing.
Deficiency Criteria	Electric dryer transition duct is detached or missing (i.e., evidence of prior
	installation, but is now not present or is incomplete).
Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the electric dryer transition duct is detached or missing, this may increase
	interior moisture levels, which provides an environment favorable for mold
	growth and may trigger respiratory issues.
	If the electric dryer transition duct is detached or missing, and there is a fire
	within the appliance or dryer transition duct, the ducting cannot adequately
	contain the fire, and the resident may be at an increased risk of injury or
	death.
	If the electric dryer transition duct is detached or missing, then the resident
	may not be able to fully utilize features of an appliance.
	Property management would be expected to ensure that staff members
	understand how to identify an electric dryer transition duct that is detached
	or missing. Management practices would be expected to assure prompt
	creation and prioritization of a work order to remedy this deficiency,
	because it may result in health or safety hazards or usability barriers.
Deficiency 1 – Clothes Dr	yer Exhaust Ventilation: Inside

Deficiency 1 – Clothes Dryer Exhaust Ventilation: Inside	
Deficiency	Electric dryer transition duct is detached or missing.
Deficiency Criteria	Electric dryer transition duct is detached or missing (i.e., evidence of prior installation, but is now not present or is incomplete).
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours

HCV Correcti Timeframe	n 24 hours
HCV Pass/Fai	Fail
Rationale	If the electric dryer transition duct is detached or missing, this may increase interior moisture levels, which provides an environment favorable for mold growth and may trigger respiratory issues.
	If the electric dryer transition duct is detached or missing, and there is a fire within the appliance or dryer transition duct, the ducting cannot adequately contain the fire, and the resident may be at an increased risk of injury or death.
	If the electric dryer transition duct is detached or missing, then the resident may not be able to fully utilize features of an appliance.
	Property management would be expected to ensure that staff members understand how to identify an electric dryer transition duct that is detached or missing. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in health or safety hazards or usability barriers.

Deficiency	Gas dryer transition duct is detached or missing.
Deficiency Criteria	Gas dryer transition duct is detached or missing (i.e., evidence of prior
	installation, but is now not present or is incomplete).
Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the gas dryer transition duct is detached or missing, then the resident may
	be at an increased risk of carbon monoxide exposure, which may cause
	respiratory issues or death due to carbon monoxide poisoning.
	If the gas dryer transition duct is detached or missing, and there is a fire
	within the appliance or dryer transition duct, the ducting cannot adequately
	contain the fire, and the resident may be at an increased risk of injury or
	death.
	If the gas dryer transition duct is detached or missing, then the resident may
	not be able to safely utilize features of an appliance.

Property management would be expected to ensure that staff members understand how to identify a gas dryer transition duct that is detached or missing. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in health hazards or usability barriers.

Deficiency	yer Exhaust Ventilation: Inside
Deliciency	Gas dryer transition duct is detached or missing.
Deficiency Criteria	Gas dryer transition duct is detached or missing (i.e., evidence of prior
	installation, but is now not present or is incomplete).
Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the gas dryer transition duct is detached or missing, then the resident may
	be at an increased risk of carbon monoxide exposure, which may cause
	respiratory issues or death due to carbon monoxide poisoning.
	If the gas dryer transition duct is detached or missing, and there is a fire
	within the appliance or dryer transition duct, the ducting cannot adequately
	contain the fire, and the resident may be at an increased risk of injury or
	death.
	If the gas dryer transition duct is detached or missing, then the resident may
	not be able to safely utilize features of an appliance.
	Property management would be expected to ensure that staff members
	understand how to identify a gas dryer transition duct that is detached or
	missing. Management practices would be expected to assure prompt
	creation and prioritization of a work order to remedy this deficiency,
	because it may result in health hazards or usability barriers.

Deficiency 3 – Clothes Dryer Exhaust Ventilation: Unit		
Deficiency	Electric dryer exhaust ventilation system has restricted airflow.	
Deficiency Criteria	Electric dryer exhaust ventilation system is blocked or damaged such that airflow may be restricted.	
Health and Safety Determination	Life-Threatening	

Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If the electric dryer exhaust ventilation system is blocked or damaged such that airflow may be restricted, this may increase interior moisture levels, which provides an environment favorable for mold growth and may trigger respiratory issues.
	If the electric dryer exhaust ventilation system is blocked or damaged such that airflow may be restricted, and the clothes dryer achieves a high enough temperature due to the obstruction, there may be an increased safety risk to the resident of fire, which may result in injury or death.
	If the electric dryer exhaust ventilation system is blocked or damaged such that airflow may be restricted, then the resident may not be able to fully utilize features of an appliance.
	A resident is likely to notice if the electric dryer exhaust ventilation system is blocked or damaged such that airflow may be restricted within the unit and to recognize it is important enough to report it to property management because it may present usability barriers. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in health or safety hazards.

lectric dryer exhaust ventilation system has restricted airflow. lectric dryer exhaust ventilation system is blocked or damaged such that irflow may be restricted.
irflow may be restricted.
, , , , , , , , , , , , , , , , , , ,
ife-Threatening
4 hours
4 hours
ail
the electric dryer exhaust ventilation system is blocked or damaged such
hat airflow may be restricted, this may increase interior moisture levels,
which provides an environment favorable for mold growth and may trigger espiratory issues.
·

If the electric dryer exhaust ventilation system is blocked or damaged such that airflow may be restricted, and the clothes dryer achieves a high enough temperature due to the obstruction, there may be an increased safety risk to the resident of fire, which may result in injury or death.

If the electric dryer exhaust ventilation system is blocked or damaged such that airflow may be restricted, then the resident may not be able to fully utilize features of an appliance.

Property management would be expected to ensure that staff members understand how to identify an electric dryer exhaust ventilation system that is blocked or damaged such that airflow may be restricted. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in health or safety hazards or usability barriers.

Deficiency 3 – Clothes Dryer Exhaust Ventilation: Outside	
Deficiency	Electric dryer exhaust ventilation system has restricted airflow.
Deficiency Criteria	Electric dryer exhaust ventilation system is blocked or damaged such that
	airflow may be restricted.
Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the electric dryer exhaust ventilation system is blocked or damaged such that airflow may be restricted, this may increase interior moisture levels, which provides an environment favorable for mold growth and may trigger respiratory issues.
	If the electric dryer exhaust ventilation system is blocked or damaged such that airflow may be restricted, and the clothes dryer achieves a high enough temperature due to the obstruction, there may be an increased safety risk to the resident of fire, which may result in injury or death.
	If the electric dryer exhaust ventilation system is blocked or damaged such that airflow may be restricted, then the resident may not be able to fully utilize features of an appliance.
	Property management would be expected to ensure that staff members understand how to identify an electric dryer exhaust ventilation system that is blocked or damaged such that airflow may be restricted. Management

practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in health or safety hazards or usability barriers.

is missing.
is missing (i.e.,
s incomplete).
at staff members
r, cap, or a
tices would be
of a work order to
ccess the dryer
ge.
rial.
approved material.
or an approved
or an approved er transition duct, the
er transition duct, the
• •
er transition duct, the
er transition duct, the sident may be at an
i t

to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards.

Deficiency 5 – Clothes Dryer Exhaust Ventilation: Inside		
Dryer transition duct is constructed of unsuitable material.		
Dryer transition duct is not constructed of metal or an approved material.		
Life-Threatening		
24 hours		
24 hours		
Fail		
If the dryer transition duct is not constructed of metal or an approved material, and there is a fire within the appliance or dryer transition duct, the ducting cannot adequately contain the fire, and the resident may be at an increased risk of injury or death.		
Property management would be expected to ensure that staff members understand how to identify a dryer transition duct that is not constructed of metal or an approved material. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards.		

Deficiency 6 – Clothes Dryer Exhaust Ventilation: Unit		
Deficiency	Gas dryer exhaust ventilation system has restricted airflow.	
Deficiency Criteria	Gas dryer exhaust ventilation system is blocked or damaged such that	
	airflow may be restricted.	
Health and Safety	Life-Threatening	
Determination		
Correction Timeframe	24 hours	
HCV Correction	24 hours	
Timeframe		
HCV Pass/Fail	Fail	
Rationale	If the gas dryer exhaust ventilation system is blocked or damaged such that airflow may be restricted, then the resident may be at an increased risk of	

carbon monoxide exposure, which may cause respiratory issues or death due to carbon monoxide poisoning.

If the gas dryer exhaust ventilation system is blocked or damaged such that airflow may be restricted, this may increase interior moisture levels, which provides an environment favorable for mold growth and may trigger respiratory issues.

If the gas dryer exhaust ventilation system is blocked or damaged such that airflow may be restricted, and the clothes dryer achieves a high enough temperature due to the obstruction, there may be an increased safety risk to the resident of fire, which may result in injury or death.

If the gas dryer exhaust ventilation system is blocked or damaged such that airflow may be restricted, then the resident may not be able to fully utilize features of an appliance.

A resident is likely to notice if the gas dryer exhaust ventilation system is blocked or damaged such that airflow may be restricted within the unit and to recognize it is important enough to report it to property management because it may present usability barriers. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in health or safety hazards.

Deficiency 6 – Clothes Dr	yer Exhaust Ventilation: Inside
Deficiency	Gas dryer exhaust ventilation system has restricted airflow.
Deficiency Criteria	Gas dryer exhaust ventilation system is blocked or damaged such that
	airflow may be restricted.
Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the gas dryer exhaust ventilation system is blocked or damaged such that airflow may be restricted, then the resident may be at an increased risk of carbon monoxide exposure, which may cause respiratory issues or death due to carbon monoxide poisoning.
	If the gas dryer exhaust ventilation system is blocked or damaged such that airflow may be restricted, this may increase interior moisture levels, which provides an environment favorable for mold growth and may trigger respiratory issues.

If the gas dryer exhaust ventilation system is blocked or damaged such that airflow may be restricted, and the clothes dryer achieves a high enough temperature due to the obstruction, there may be an increased safety risk to the resident of fire, which may result in injury or death.

If the gas dryer exhaust ventilation system is blocked or damaged such that airflow may be restricted, then the resident may not be able to fully utilize features of an appliance.

Property management would be expected to ensure that staff members understand how to identify a gas dryer exhaust ventilation system that is blocked or damaged such that airflow may be restricted. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in health or safety hazards or usability barriers.

Deficiency 6 – Clothes Dryer Exhaust Ventilation: Outside	
Deficiency	Gas dryer exhaust ventilation system has restricted airflow.
Deficiency Criteria	Gas dryer exhaust ventilation system is blocked or damaged such that
	airflow may be restricted.
Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the gas dryer exhaust ventilation system is blocked or damaged such that
	airflow may be restricted, then the resident may be at an increased risk of
	carbon monoxide exposure, which may cause respiratory issues or death due to carbon monoxide poisoning.
	If the gas dryer exhaust ventilation system is blocked or damaged such that
	airflow may be restricted, this may increase interior moisture levels, which
	provides an environment favorable for mold growth and may trigger respiratory issues.
	If the gas dryer exhaust ventilation system is blocked or damaged such that
	airflow may be restricted, and the clothes dryer achieves a high enough
	temperature due to the obstruction, there may be an increased safety risk to the resident of fire, which may result in injury or death.

If the gas dryer exhaust ventilation system is blocked or damaged such that airflow may be restricted, then the resident may not be able to fully utilize features of an appliance.

Property management would be expected to ensure that staff members understand how to identify a gas dryer exhaust ventilation system that is blocked or damaged such that airflow may be restricted. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in health or safety hazards or usability barriers.

TABLE 9—COOKING APPLIANCE STANDARD

Definition and Location	
Definition	Cooking range: An electric or gas stove with several burners and one or more connected ovens.
	<u>Cooktop</u> : Usually a standalone device that may be built into a counter and has one or more electric or gas burners.
	Oven: A thermally insulated chamber used for cooking, heating, and baking food.
Location	Unit: Kitchen
	Inside: Kitchen
Deficiency 1 – Cooking A	ppliance: Unit
Deficiency	Cooking range, cooktop, or oven is not producing heat or regulating heat temperature.
Deficiency Criteria	50% of the burners on the cooking range or cooktop are not producing heat.
	OR
	50% of the burners on the cooking range or cooktop are not regulating heat temperature.
	OR
	The oven is not producing heat.
	OR
	The oven is not regulating heat temperature.
Health and Safety Determination	Standard
Correction Timeframe	30 days

HCV Correction Timeframe	30 days	
HCV Pass/Fail	Fail	
Rationale	If the cooking range, cooktop, or oven is not producing heat or igniting, and there is a gas burner on, then gas may be released into the environment, resulting in a fire hazard.	
	If the cooking range, cooktop, or oven is not producing heat, then the resident is unable to use an appliance that is expected to be include in their rent.	
	If the cooking range, cooktop, or oven is not producing or regulating heat, then it is likely the resident will report this deficiency and its presence may indicate that maintenance is not addressing complaint-based work orders.	
Deficiency 1 – Cooking Appliance: Inside		
Deficiency	Cooking range, cooktop, or oven is not producing heat or regulating heat temperature.	
Deficiency Criteria	50% of the burners on the cooking range or cooktop are not producing heat.	
	OR	
	50% of the burners on the cooking range or cooktop are not regulating heat temperature.	
	OR	
	The oven is not producing heat.	
	OR	
	The oven is not regulating heat temperature.	
Health and Safety Determination	Standard	
Correction Timeframe	30 days	
HCV Correction	30 days	
Timeframe		
HCV Pass/Fail	Fail	
Rationale	If the cooking range, cooktop, or oven is not producing heat or igniting, and there is a gas burner on, then gas may be released into the environment, resulting in a fire hazard.	

If the cooking range, cooktop, or oven is not producing heat, then the resident is unable to use an appliance that is expected to be include in their rent.

If the cooking range, cooktop, or oven is not producing or regulating heat, then it is likely the resident will report this deficiency and its presence may indicate that maintenance is not addressing complaint-based work orders.

Deficiency 2 – Cooking Appliance: Unit		
Deficiency	Cooking range, cooktop, or oven components are missing.	
Deficiency Criteria	Burner grate, oven rack, oven handle, or seal is missing (i.e., evidence of prior installation, but now not present or is incomplete).	
Health and Safety Determination	Advisory	
Correction Timeframe	Advisory	
HCV Correction Timeframe	Advisory	
HCV Pass/Fail	Pass	
Rationale	If the cooking range, cooktop, or oven components are missing, then the resident may be unable to fully use an appliance that is expected to be included in their rent.	
	If the components are missing, then it is likely the resident will report this deficiency and its presence may indicate that maintenance is not addressing complaint-based work orders.	

Deficiency 2 – Cooking Appliance: Inside	
Deficiency	Cooking range, cooktop, or oven components are missing.
Deficiency Criteria	Burner grate, oven rack, oven handle, or seal is missing (i.e., evidence of prior installation, but now not present or is incomplete).
Health and Safety Determination	Advisory
Correction Timeframe	Advisory
HCV Correction Timeframe	Advisory
HCV Pass/Fail	Pass

Rationale	If cooking range, cooktop, or oven components are missing, then the resident may be unable to fully use an appliance that is expected to be included in their rent.
	If the components are missing, then it is likely the resident will report this deficiency and its presence may indicate that maintenance is not addressing complaint-based work orders.
Deficiency 3 – Cook	king Appliance: Unit
Deficiency	Primary cooking appliance is missing.

Deficiency 3 – Cooking Appliance: Unit		
Deficiency	Primary cooking appliance is missing.	
Deficiency Criteria	Primary cooking appliance is missing (i.e., evidence of prior installation, but now not present or is incomplete).	
Health and Safety Determination	Standard	
Correction Timeframe	30 days	
HCV Correction	30 days	
Timeframe		
HCV Pass/Fail	Fail	
Rationale	If the primary cooking appliance is missing, then the resident may be unable to cook food in a sanitary manner.	
	If the primary cooking appliance is missing, then the resident cannot use an appliance that is expected to be included in their rent.	
	If the primary cooking appliance is missing, then it is likely the resident will report this deficiency and its presence may indicate that maintenance is not addressing complaint-based work orders.	

Deficiency 3 – Cooking Appliance: Inside	
Deficiency	Primary cooking appliance is missing.
Deficiency Criteria	Primary cooking appliance is missing (i.e., evidence of prior installation, but now not present or is incomplete).
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail

Rationale	If the primary cooking appliance is missing, then the resident may be unable to cook food in a sanitary manner.
	If the primary cooking appliance is missing, then the resident cannot use an appliance that is expected to be included in their rent.
	If the primary cooking appliance is missing, then it is likely the resident will report this deficiency and its presence may indicate that maintenance is not addressing complaint-based work orders.

TABLE 10—DOOR – ENTRY STANDARD

Definition and Location	
Definition	A door that provides a means of access to the Unit from the Inside or Outside.
	OR
	A door that provides a means of access to the Inside from the Outside.
Location	Unit: Entrance to the Unit from the Outside or Inside
	Inside: Entrance to the Inside from the Outside
Deficiency 1 – Door – Ent	ry: Unit
Deficiency	Entry door will not open.
Deficiency Criteria	Entry door will not open.
Health and Safety Determination	Life Threatening
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the entry door will not open, then the resident's ability to leave or grant access to the Unit may be limited, which may result in an increased safety risk in the event of an emergency. If the entry door will not open, then the resident's ability to grant access to
	the Unit may be limited.

If the entry door will not open, then the resident's ability to leave or grant access to the Unit may be limited.

A resident is likely to notice if the entry door will not open and to recognize it is important enough to report it to property management because it may present safety hazards or usability barriers. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in safety hazards.

Deficiency 1 – Door – Entry: Inside	
Deficiency	Entry door will not open.
Deficiency Criteria	Entry door will not open.
Health and Safety	Life Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the entry door will not open, then the resident's ability to leave or grant access to the Unit may be limited, which may result in an increased safety risk in the event of an emergency.
	If the entry door will not open, then the resident's ability to grant access to the Unit may be limited.
	If the entry door will not open, then the resident's ability to leave or grant access to the Unit may be limited.
	Property management would be expected to ensure that staff members understand how to identify an entry door that will not open. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards or usability barriers.

Deficiency 2 – Door – Entry: Unit	
Deficiency	Entry door will not close.
Deficiency Criteria	Entry door does not close (i.e., door seats in frame).
Health and Safety Determination	Life Threatening
Correction Timeframe	24 hours

HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If the entry door will not close, and there is inclement weather, then the resident may be at an increased risk of environmental exposure, which may result in illness.
	If the entry door will not close, then the resident's ability to manage access to the unit may be limited.
	If the entry door will not close, then the resident may be unable to reasonably ensure privacy within the unit.
	If the entry door will not close, then the resident's ability to manage access to the Unit may be limited.
	A resident is likely to notice if the entry door will not close and to recognize it is important enough to report it to property management because it may present health or safety hazards, or privacy or usability barriers. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in health or safety hazards or privacy or usability barriers.

Deficiency 2 – Door – Ent	ry: Inside
Deficiency	Entry door will not close.
Deficiency Criteria	Entry door does not close (i.e., door seats in frame).
Health and Safety	Life Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the entry door will not close, then the resident's ability to manage access to the building may be limited.
	If the entry door will not close, then the resident or POA's ability to manage access to the building may be limited.
	Property management would be expected to ensure that staff members understand how to identify an entry door that will not close. Management practices would be expected to assure prompt creation and prioritization of

a work order to remedy this deficiency because it may result in security	
hazards or usability barriers.	

Deficiency 3 – Door – Entry: Unit	
Deficiency	Entry door self-closing mechanism is damaged, inoperable, or missing.
Deficiency Criteria	The self-closing mechanism is damaged (i.e., visibly defective; impacts functionality).
	OR
	The self-closing mechanism does not pull the door closed and engage the latch.
	OR
	The self-closing mechanism is missing (i.e., evidence of prior installation, but now not present or is incomplete).
Health and Safety Determination	Life Threatening
	24 hours
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the entry door self-closer will not pull the door closed and latch, and there
	is an environmental threat, then the resident cannot reasonably assume
	measures are in place to mitigate exposure.
	If the entry door self-closer will not pull the door closed and latch, then the
	resident is unable to fully use the door, which is expected to be part of their
	rent.
Deficiency 3 – Door – Ent	ry: Inside
Deficiency	Entry door self-closing mechanism is damaged, inoperable, or missing.
Deficiency Criteria	The self-closing mechanism is damaged (i.e., visibly defective; impacts functionality).
	OR
	The self-closing mechanism does not pull the door closed and engage the latch.
	OR
	The self-closing mechanism is missing (i.e., evidence of prior installation, but now not present or is incomplete).

Health and Safety Determination	Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If the entry door self-closer will not pull the door closed and latch, and there is an environmental threat, then the resident cannot reasonably assume measures are in place to mitigate exposure.
	If the entry door self-closer will not pull the door closed and latch, then the resident is unable to fully use the door, which is expected to be part of their rent.
Deficiency 4 – Door – Ent	try: Unit
Deficiency	Entry door cannot be secured.
Deficiency Criteria	Entry door cannot be secured (i.e., access controlled) by at least 1 installed lock.
Health and Safety Determination	Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If the entry door cannot be secured by at least 1 installed lock, then the resident's ability to control access to the unit may be limited.
	If the entry door cannot be secured by at least 1 installed lock, then the resident may be unable to reasonably ensure privacy within the unit.
	If the entry door cannot be secured by at least 1 installed lock, then the resident's ability to control access to the unit may be limited.
	A resident is likely to notice if the entry door cannot be secured by at least 1 installed lock within the unit and to recognize it is important enough to report it to property management because it may limit their security or privacy. Property management should be expected to prioritize a work order to remedy this deficiency because it may limit the resident's security or privacy.

Deficiency	Hole, split, or crack that penetrates completely through entry door.
Deficiency Criteria	A hole $\mbox{\ensuremath{\mbox{\upega}}}$ inch or greater in diameter that penetrates all the way through the door.
	OR
	A split or crack $\frac{1}{4}$ inch or greater in width that penetrates all the way through the door.
	OR
	A hole or a crack with separation is present, or the glass is missing within the door, sidelites, or transom.
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the entry door has a hole that penetrates all the way through the door, and there is inclement weather, then resident is in danger of excess cold and heat, dampness, and mold growth, and spread of smoke, fire, or poisonous gas, which will affect the resident's physical health.
	If the entry door has a hole that penetrates all the way through the door, then the resident may be in danger of intruders gaining access to the interior space.
	If the entry door has a hole that penetrates all the way through the door, then the resident cannot secure their privacy within the interior space.
	If the entry door has a hole that penetrates all the way through the door, then the resident is unable to fully use a feature of home that is expected to be part of their rent.
	If the entry door has a hole that penetrates all the way through the door, and the resident is responsible for utilities, then the resident may experience an increase in utility costs.
	If the entry door has a hole that penetrates all the way through the door, then it is likely complaint-based work orders are not being addressed.
	If the entry door has a hole that penetrates all the way through the door, then it is likely routine work orders are not being addressed.

Deficiency 5 – Door – Entry: Inside

Deficiency	Hole, split, or crack that penetrates completely through entry door.
	Thore, spire, or crack that penetrates completely through entry door.
Deficiency Criteria	A hole $\mbox{\ensuremath{\%}}$ inch or greater in diameter that penetrates all the way through the door.
	OR
	A split or crack $\frac{1}{4}$ inch or greater in width that penetrates all the way through the door.
	OR
	A hole or a crack with separation is present, or the glass is missing within the door, sidelites, or transom.
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the entry door has a hole that penetrates all the way through the door, and there is inclement weather, then the resident is in danger of excess cold and heat, dampness, and mold growth, and spread of smoke, fire, or poisonous gas, which will affect the resident's physical health.
	If the entry door has a hole that penetrates all the way through the door, then the resident may be in danger of intruders gaining access to the interior space.
	If the entry door has a hole that penetrates all the way through the door, then the resident cannot secure their privacy within the interior space.
	If the entry door has a hole that penetrates all the way through the door, then the resident is unable to fully use a feature that is expected to be part of their rent.
	If the entry door has a hole that penetrates all the way through the door, then it is likely complaint-based work orders are not being addressed.
	If the entry door has a hole that penetrates all the way through the door, then it is likely routine work orders are not being addressed.
Deficiency 6 Deer Ent	11

Deficiency 6 – Door – Entry: Unit	
Deficiency	Entry door is missing.
Deficiency Criteria	Entry door is missing.

Health and Safety	Life Threatening
Determination	Life Tilleatering
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the entry door is missing, and there is inclement weather or an
	emergency, then the resident's physical health may be in jeopardy.
	If the entry door is missing, then the resident cannot reasonably secure the
	property from intruders.
	If the entry door is missing, then the resident cannot secure their privacy
	within the interior space.
	If the entry door is missing, then the resident is unable to fully use a feature
	which is expected to be part of their rent.
	If the entry door is missing and the resident is responsible for utilities, then
	the resident may experience an increase in utility costs due to inability to
	protect from the outside environment.
	If the entry door is missing, then it is likely complaint-based work orders are
	not being addressed.
	If the entry door is missing, then it is likely routine work orders are not
	being addressed.
	If the entry door is missing, property visitors will observe the deficiency,
	which will impact their perception of the property.
	missi im impact their perception of the property.

Deficiency 6 – Door – Entry: Inside	
Deficiency	Entry door is missing
Deficiency Criteria	Entry door is missing.
Health and Safety	Life Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail

Rationale	If the entry door is missing, and there is inclement weather or an emergency, then the resident's physical health may be in jeopardy.
	If the entry door is missing, then the resident cannot reasonably secure the property from intruders.
	If the entry door is missing, then the resident cannot secure their privacy within the interior space.
	If the entry door is missing, then the resident is unable to fully use a feature, which is expected to be part of their rent.
	If the entry door is missing, then it is likely complaint-based work orders are not being addressed.
	If the entry door is missing, then it is likely routine work orders are not being addressed.
	If the entry door is missing, property visitors will observe the deficiency, which will impact their perception of the property.

Deficiency 7 – Door – Ent	Deficiency 7 – Door – Entry: Unit	
Deficiency	Entry door surface is delaminated or separated.	
Deficiency Criteria	There is delamination or separation of the door surface 2 inches wide or greater.	
	OR	
	There is delamination or separation that affects the integrity of the door (i.e., surface protection or the strength of the door).	
Health and Safety	Standard	
Determination		
Correction Timeframe	30 days	
HCV Correction Timeframe	30 days	
HCV Pass/Fail	Fail	
Rationale	If an entry door surface is pulling away from the door inner core, then pests (e.g., wasps) may be able to nest in the open space, which could affect the resident's physical health.	
	If there is delamination or separation of the entry door, and it impacts the door's integrity, then intruders may be able to easily access the unit.	

If an entry door surface is pulling away from the door's inner core, then infestation (e.g., wasps) may occur in the open space. The resident will likely call this in; may indicate work orders are not being addressed.

If the entry door is delaminated or separating, then the public or visitors

If the entry door is delaminated or separating, then the public or visitors may see this deficiency, potentially resulting in decreased property reputation.

Deficiency 7 – Door – Ent	ry: Inside
Deficiency	Entry door surface is delaminated or separated.
Deficiency Criteria	There is delamination or separation of the door surface 2 inches wide or greater.
	OR
	There is delamination or separation that affects the integrity of the door (i.e., surface protection or the strength of the door).
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If an entry door surface is pulling away from the door inner core, then pests (e.g., wasps) may be able to nest in the open space, which could affect the resident's physical health.
	If there is delamination or separation of the entry door, and it impacts the door's integrity, then intruders may be able to easily access the unit.
	If an entry door surface is pulling away from the door's inner core, then infestation (e.g., wasps) may occur in the open space. The resident will likely call this in; may indicate work orders are not being addressed.
	If the entry door is delaminated or separating, then the public or visitors may see this defect, potentially resulting in decreased property reputation.

Deficiency 8 – Door – Entry: Unit	
Deficiency	Entry door frame, threshold, or trim is damaged or missing.
Deficiency Criteria	The entry door frame, threshold, or trim is damaged (i.e., visibly defective; impacts functionality).
	OR

	The entry door frame, threshold, or trim is missing (i.e., evidence of prior
	installation, but now not present or is incomplete).
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the entry door frame, threshold, or trim is damaged, and there is inclement weather or an emergency, then the resident's physical health
	may be in jeopardy.
	If the entry door frame, threshold, or trim is damaged or missing, then the resident cannot reasonably secure the property from intruders.
	If the entry door frame, threshold, or trim is damaged or missing, then the
	resident cannot secure their privacy within the interior space.
	If the entry door frame, threshold, or trim is damaged or missing, then the resident is unable to fully use a feature, which is expected to be part of their rent.
	If the entry door frame, threshold, or trim is damaged or missing, and the resident is responsible for utilities, then the resident may experience an increase in utility costs due to inability to protect from the outside environment.
	If the entry door frame, threshold, or trim is damaged or missing, then it is likely complaint-based work orders are not being addressed.
	If the entry door frame, threshold, or trim is damaged or missing, then it is likely routine work orders are not being addressed.

Deficiency 8 – Door – Entry: Inside	
Deficiency	Entry door frame, threshold, or trim is damaged or missing.
Deficiency Criteria	The entry door frame, threshold, or trim is damaged (i.e., visibly defective; impacts functionality).
	OR
	The entry door frame, threshold, or trim is missing (i.e., evidence of prior installation, but now not present or is incomplete).
Health and Safety	Standard
Determination	

Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the entry door frame, threshold, or trim is damaged, and there is inclement weather or an emergency, then the resident's physical health may be in jeopardy.
	If the entry door frame, threshold, or trim is damaged or missing, then the resident cannot reasonably secure the property from intruders.
	If the entry door frame, threshold, or trim is damaged or missing, then the resident cannot secure their privacy within the interior space.
	If the entry door frame, threshold, or trim is damaged or missing, then the resident is unable to fully use a feature, which is expected to be part of their rent.
	If the entry door frame, threshold, or trim is damaged or missing, then it is likely complaint-based work orders are not being addressed.
	If the entry door frame, threshold, or trim is damaged or missing, then it is likely routine work orders are not being addressed.

Deficiency 9 – Door – Entry: Unit

Deficiency

Entry door seal, gasket, or stripping is damaged, inoperable, or missing.

Deficiency Criteria

The entry door seal, gasket, or stripping is:

- damaged (i.e., visibly defective; impacts functionality);
- inoperable (i.e., overall system or component thereof is not meeting function/purpose, with or without visible damage); or
- missing (i.e., evidence of prior installation, but now not present or is incomplete).

AND ONE OF THE FOLLOWING CONDITIONS:

Condition 1:

- General door type: Results in a gap of ¼ inch wide or greater between the door slab and the stop molding on the jamb or the jamb itself, or between the bottom of the door and the threshold or floor AND permits light around the closed door.
- <u>Special door type</u>: Results in a gap of ¼ inch wide or greater around or under the door or where the doors meet AND permits light around the closed door or where the doors meet.

Condition 2:

- General door type: There is evidence of water penetrating (e.g., water damage or dry rot) around or under the door.
- Special door type: There is evidence of water penetrating (e.g., water damage or dry rot) around or under the door or where the doors meet.

Health and Safety Determination

Standard

Correction Timeframe

30 days

HCV Correction Timeframe

30 days

HCV Pass/Fail

Fail

Rationale

If the entry door seal, gasket, or stripping is damaged, inoperable, or missing and there is inclement weather or an emergency (e.g., smoke or fire spread), then the resident's physical health may be in jeopardy.

If the entry door seal, gasket, or stripping is damaged, inoperable, or missing and the resident is responsible for utilities, then the resident may experience an increase in utility costs due to inability to protect from the outside environment.

Deficiency 9 - Door - Entry: Inside

Deficiency

Entry door seal, gasket, or stripping is damaged, inoperable, or missing.

Deficiency Criteria

The entry door seal, gasket, or stripping is:

- damaged (i.e., visibly defective; impacts functionality);
- inoperable (i.e., overall system or component thereof is not meeting function/purpose; with or without visible damage); or
- missing (i.e., evidence of prior installation, but now not present or is incomplete).

AND ONE OF THE FOLLOWING CONDITIONS:

Condition 1:

 General door type: Results in a gap of ¼ inch wide or greater between the door slab and the stop molding on the jamb or the jamb itself, or between the bottom of the door and the threshold or floor AND permits light around the closed door. - <u>Special door type</u>: Results in a gap of ¼ inch wide or greater around or under the door or where the doors meet AND permits light around the closed door or where the doors meet.

Condition 2:

- <u>General door type</u>: There is evidence of water penetrating (e.g., water damage or dry rot) around or under the door.
- Special door type: There is evidence of water penetrating (e.g., water damage or dry rot) around or under the door or where the doors meet.

Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the entry door seal, gasket, or stripping is damaged, inoperable, or missing and there is inclement weather or an emergency (e.g., smoke or fire spread), then the resident's physical health may be in jeopardy.

Deficiency 10 – Door –	Deficiency 10 – Door – Entry: Unit	
Deficiency	Entry door component is damaged, inoperable, or missing and it does not limit the door's ability to provide privacy or protection from weather or infestation.	
Deficiency Criteria	Entry door component is damaged (i.e., visibly defective; impacts functionality) and it does not limit the door's ability to provide privacy or protection from weather or infestation.	
	OR	
	Entry door component is inoperable (i.e., component is not meeting function or purpose, with or without visible damage), and it does not limit the door's ability to provide privacy or protection from weather or infestation.	
	OR	
	Entry door component is missing (i.e., evidence of prior installation, but it is now not present or is incomplete) and it does not limit the door's ability to provide privacy or protection from weather or infestation.	

Health and Safety Determination	Advisory
Correction Timeframe	Advisory
HCV Correction	Advisory
Timeframe	
HCV Pass/Fail	Pass
Rationale	If the door's ability to provide privacy or protection from weather or infestation is not limited, but an entry door component is damaged, inoperable, or missing, then the resident may notice this within the Unit and may recognize it is important enough to report it to property management. Property management may be expected to prioritize a work order to remedy this deficiency because it may lead to usability barriers.
Deficiency 10 – Door – Er	<u> </u>
Deficiency	Entry door component is damaged, inoperable, or missing and it does not limit the door's ability to provide privacy or protection from weather or infestation.
Deficiency Criteria	Entry door component is damaged (i.e., visibly defective; impacts functionality) and it does not limit the door's ability to provide privacy or protection from weather or infestation.
	OR
	Entry door component is inoperable (i.e., component is not meeting function or purpose, with or without visible damage), and it does not limit the door's ability to provide privacy or protection from weather or infestation.
	OR
	Entry door component is missing (i.e., evidence of prior installation, but it is now not present or is incomplete) and it does not limit the door's ability to provide privacy or protection from weather or infestation.
Health and Safety Determination	Advisory
Correction Timeframe	Advisory
HCV Correction Timeframe	Advisory
HCV Pass/Fail	Pass
Rationale	If the door's ability to provide privacy or protection from weather or infestation is not limited, but an entry door component is damaged,

inoperable, or missing, then property management would be expected to ensure that staff members understand how to identify this deficiency.

Management practices may be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may lead to usability barriers.

TABLE 11—DOOR - FIRE LABELED STANDARD

A door with a fire-resistant rating (i.e., the time within which materials or
assemblies have withstood fire exposure).
Unit: All fire labeled doors throughout the Unit.
Inside: All fire labeled doors throughout the Inside.
Outside: All fire labeled doors throughout the Outside.
Labeled: Unit
Fire labeled door does not open.
Fire labeled door does not open such that it may limit access between
spaces.
Standard
30 days
30 days
Fail
If a fire labeled door does not open such that it may limit access between
spaces, then there may be an increased safety risk for the resident in the event of an emergency.
If a fire labeled door does not open, then the resident's ability to move
freely between spaces may be limited.
A resident is likely to notice if a fire labeled door does not open such that it may limit access between spaces and to recognize it is important enough to report it to property management because it may present safety hazards or usability barriers. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in safety hazards.

Deficiency 1 – Door – Fire Labeled: Inside

Deficiency	Fire labeled door does not open.
Deficiency Criteria	Fire labeled door does not open such that it may limit access between
	spaces.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a fire labeled door does not open such that it may limit access between spaces, then there may be an increased safety risk for the resident in the event of an emergency.
	If a fire labeled door does not open, then the resident's ability to move freely between spaces may be limited.
	Property management would be expected to ensure that staff members understand how to identify a fire labeled door that does not open such that it may limit access between spaces. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards or usability barriers.
Deficiency 1 – Door – Fire	e Labeled: Outside
Deficiency	Fire labeled door does not open.
Deficiency Criteria	Fire labeled door does not open such that it may limit access between spaces.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a fire labeled door does not open such that it may limit access between spaces, then there may be an increased safety risk for the resident in the event of an emergency. Property management would be expected to ensure that staff members
	understand how to identify a fire labeled door that does not open such that

it may limit access between spaces. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards.

	Labeled: Unit
Deficiency	Fire labeled door does not close and latch or the self-closing hardware is
	damaged or missing such that the door does not self-close and latch.
Deficiency Criteria	Fire labeled door does not close (i.e., door seats in frame) and latch. OR
	Fire labeled door self-closing hardware is damaged (i.e., visibly defective; impacts functionality) or missing (i.e., evidence of prior installation, but is
	now not present or is incomplete) such that the door does not self-close
	(i.e., door seats in frame) and latch.
Health and Safety	Severe Non Life Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a fire labeled door does not close and latch or the fire labeled door self- closing hardware is damaged or missing such that the door does not self- close and latch, and there is a fire, then the door may not limit the spread of fire or smoke, which may result in an increased safety risk to the resident.
	If a fire labeled door does not close and latch or the fire labeled door self- closing hardware is damaged or missing such that the door does not self- close and latch, and there is a fire, then the resident may not be protected by this feature that is expected to be provided and maintained as part of their rent.
	A resident is likely to notice if a fire labeled door does not close and latch or the fire labeled door self-closing hardware is damaged or missing such that the door does not self-close and latch and to recognize it is important enough to report it to property management because it may present safety hazards or usability barriers. Property management should be expected to prioritize a work order to remedy this defect because it may result in safety hazards or usability barriers.
eficiency 2 – Door – Fire	Labeled: Inside

Fire labeled door does not close and latch or the self-closing hardware is

damaged or missing such that the door does not self-close and latch.

Deficiency

Deficiency Criteria Fire labeled door does not close (i.e., door seats in frame) and latch. OR Fire labeled door self-closing hardware is damaged (i.e., visibly defective; impacts functionality) or missing (i.e., evidence of prior installation, but is now not present or is incomplete) such that the door does not self-close (i.e., door seats in frame) and latch. **Health and Safety** Severe Non-Life Threatening Determination **Correction Timeframe** 24 hours **HCV Correction** 30 days Timeframe **HCV Pass/Fail** Fail Rationale If a fire labeled door does not close and latch or the fire labeled door selfclosing hardware is damaged or missing such that the door does not selfclose and latch, and there is a fire, then the door may not limit the spread of fire or smoke, which may result in an increased safety risk to the resident. If a fire labeled door does not close and latch or the fire labeled door selfclosing hardware is damaged or missing such that the door does not selfclose and latch, and there is a fire, then the resident may not be protected by this feature that is expected to be provided and maintained as part of their rent. Property management would be expected to ensure that staff understand how to identify a fire labeled door that does not close and latch or if the fire labeled door self-closing hardware is damaged or missing such that the door does not self-close and latch. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this defect, because it may result in safety hazards or usability barriers. **Deficiency 2 – Door – Fire Labeled: Outside** Deficiency Fire labeled door does not close and latch or the self-closing hardware is damaged or missing such that the door does not self-close and latch. **Deficiency Criteria** Fire labeled door does not close (i.e., door seats in frame) and latch. Fire labeled door self-closing hardware is damaged (i.e., visibly defective; impacts functionality) or missing (i.e., evidence of prior installation, but is now not present or is incomplete) such that the door does not self-close (i.e., door seats in frame) and latch. **Health and Safety** Severe Non-Life Threatening **Determination**

Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a fire labeled door does not close and latch or the fire labeled door self- closing hardware is damaged or missing such that the door does not self- close and latch, and there is a fire, then the door may not limit the spread of fire or smoke, which may result in an increased safety risk to the resident.
	If a fire labeled door does not close and latch or the fire labeled door self- closing hardware is damaged or missing such that the door does not self- close and latch, and there is a fire, then the resident may not be protected by this feature that is expected to be provided and maintained as part of their rent.
	Property management would be expected to ensure that staff understand how to identify a fire labeled door that does not close and latch or if the fire labeled door self-closing hardware is damaged or missing such that the door does not self-close and latch. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this defect, because it may result in safety hazards or usability barriers.
Deficiency 3 – Door – Fire	e Labeled: Unit
Deficiency	Fire labeled door assembly has a hole of any size or is damaged such that its integrity may be compromised.
Deficiency Criteria	A fire labeled door assembly has a hole of any size.
	OR
	A fire labeled door assembly is damaged (i.e., visibly defective; impacts functionality) such that its integrity may be compromised.
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a fire labeled door assembly has a hole of any size or is damaged such that its integrity may be compromised, and there is a fire, then the door may not limit the spread of fire or smoke, which may result in an increased safety risk to the resident.

A resident is likely to notice if a fire labeled door assembly has a hole of any size or is damaged such that its integrity may be compromised and to recognize it is important enough to report it to property management because it may present safety hazards. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in safety hazards.

Deficiency 3 – Door – Fire	e Labeled: Inside
Deficiency	Fire labeled door assembly has a hole of any size or is damaged such that its integrity may be compromised.
Deficiency Criteria	A fire labeled door assembly has a hole of any size.
	OR
	A fire labeled door assembly is damaged (i.e., visibly defective; impacts functionality) such that its integrity may be compromised.
	OR
	25% of the door surface has rust that affects the integrity of the door.
	OR
	There is broken or missing glass.
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a fire labeled door assembly has a hole of any size or is damaged such that its integrity may be compromised, and there is a fire, then the door may not limit the spread of fire or smoke, which may result in an increased safety risk to the resident.
	Property management would be expected to ensure that staff members understand how to identify a fire labeled door assembly that has a hole of any size or is damaged such that its integrity may be compromised. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards.

integrity may be compromised.

Fire labeled door assembly has a hole of any size or is damaged such that its

Deficiency 3 – Door – Fire Labeled: Outside

Deficiency

Deficiency Criteria	A fire labeled door assembly has a hole of any size.
	OR
	A fire labeled door assembly is damaged (i.e., visibly defective; impacts
	functionality) such that its integrity may be compromised.
Health and Safety	Severe Non-Life Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a fire labeled door assembly has a hole of any size or is damaged such that its integrity may be compromised, and there is a fire, then the door may not limit the spread of fire or smoke, which may result in an increased safety risk to the resident.
	Property management would be expected to ensure that staff members understand how to identify a fire labeled door assembly that has a hole of any size or is damaged such that its integrity may be compromised. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards.
Deficiency 4 – Door – Fire	e Labeled: Unit
Deficiency	Fire labeled door seal or gasket is damaged or missing.
Deficiency Criteria	A fire labeled door seal or gasket is damaged (i.e., visibly defective; impacts functionality).
	OR
	A fire labeled door seal or gasket is missing (i.e., evidence of prior
	installation, but now not present or is incomplete).
Health and Safety	Severe Non-Life Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail

Rationale	If a fire labeled door seal or gasket is damaged or missing, and there is a
	fire, then the door may not limit the spread of fire or smoke, which may
	result in an increased safety risk to the resident.
	A resident is likely to notice if a fire labeled door seal or gasket is damaged
	or missing and to recognize it is important enough to report it to property
	management because it may present safety hazards. Property management
	should be expected to prioritize a work order to remedy this deficiency
	because it may result in safety hazards.
Deficiency 4 – Door – Fire	
Deficiency	Fire labeled door seal or gasket is damaged or missing.
Deficiency Criteria	A fire labeled door seal or gasket is damaged (i.e., visibly defective; impacts functionality).
	OR
	A fire labeled door seal or gasket is missing (i.e., evidence of prior
	installation, but now not present or is incomplete).
Health and Safety	Severe Non-Life Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a fire labeled door seal or gasket is damaged or missing, and there is a
	fire, then the door may not limit the spread of fire or smoke, which may
	result in an increased safety risk to the resident.
	Property management would be expected to ensure that staff members
	understand how to identify a fire labeled door seal or gasket that is
	damaged or missing. Management practices would be expected to assure
	prompt creation and prioritization of a work order to remedy this
	deficiency, because it may result in safety hazards.
Deficiency 4 – Door – Fire	e Labeled: Outside
Deficiency	Fire labeled door seal or gasket is damaged or missing.
Deficiency Criteria	A fire labeled door seal or gasket is damaged (i.e., visibly defective; impacts functionality).
	OR
	A fire labeled door seal or gasket is missing (i.e., evidence of prior
	installation, but now not present or is incomplete).

Haalth and Cafety	Covers New Life Threatening
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a fire labeled door seal or gasket is damaged or missing, and there is a fire, then the door may not limit the spread of fire or smoke, which may result in an increased safety risk to the resident.
	Property management would be expected to ensure that staff members understand how to identify a fire labeled door seal or gasket that is damaged or missing. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards.
Deficiency 5 – Door – Fire	Labeled: Unit
Deficiency	An object is present that may prevent the fire labeled door from closing and latching or self-closing and latching.
Deficiency Criteria	An object is present that may prevent the fire labeled door from closing (i.e., door seats in frame) and latching.
	OR
	An object is present that may prevent the fire labeled door from self-closing (i.e., door seats in frame) and latching.
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If an object is present that may prevent the fire labeled door from closing and latching or self-closing and latching, and there is a fire, then the door may not limit the spread of fire or smoke, which may result in an increased safety risk to the resident. If an object is present that may prevent the fire labeled door from closing and latching or self-closing and latching, then the resident may not be able
	to fully use a feature of that is expected to be provided and maintained as part of their rent.

	A resident is likely to notice if an object is present that may prevent the fire labeled door from closing and latching or self-closing and latching and to recognize it is important enough to report it to property management because it may present safety hazards or usability barriers. Property management should be expected to prioritize a work order to remedy this defect because it may result in safety hazards or usability barriers.
Deficiency 5 – Door – Fir	e Labeled: Inside
Deficiency	An object is present that may prevent the fire labeled door from closing and latching or self-closing and latching.
Deficiency Criteria	An object is present that may prevent the fire labeled door from closing (i.e., door seats in frame) and latching. OR
	An object is present that may prevent the fire labeled door from self-closing (i.e., door seats in frame) and latching.
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If an object is present that may prevent the fire labeled door from closing and latching or self-closing and latching, and there is a fire, then the door may not limit the spread of fire or smoke, which may result in an increased safety risk to the resident.
	If an object is present that may prevent the fire labeled door from closing and latching or self-closing and latching, then the resident may not be able to fully use a feature of that is expected to be provided and maintained as part of their rent.
	Property management would be expected to ensure that staff understand how to identify if an object is present that may prevent the fire labeled door from closing and latching or self-closing and latching. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this defect, because it may result in safety hazards or usability barriers.
Deficiency 5 – Door – Fir	e Labeled: Outside
Deficiency	An object is present that may prevent the fire labeled door from closing and latching or self-closing and latching.

Deficiency Criteria	An object is present that may prevent the fire labeled door from closing (i.e., door seats in frame) and latching.
	OR
	An object is present that may prevent the fire labeled door from self-closing (i.e., door seats in frame) and latching.
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If an object is present that may prevent the fire labeled door from closing and latching or self-closing and latching, and there is a fire, then the door may not limit the spread of fire or smoke, which may result in an increased safety risk to the resident.
	If an object is present that may prevent the fire labeled door from closing and latching or self-closing and latching, then the resident may not be able to fully use a feature of that is expected to be provided and maintained as part of their rent.
	Property management would be expected to ensure that staff understand how to identify if an object is present that may prevent the fire labeled door from closing and latching or self-closing and latching. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this defect, because it may result in safety hazards or usability barriers.
Deficiency 6 – Door – Fire	e Labeled: Unit
Deficiency	Fire labeled door that serves as an entry door cannot be secured.
Deficiency Criteria	Fire labeled door that serves as entry door (i.e., a door that provides a means of access to the Unit from the Inside or Outside) cannot be secured (i.e., access controlled) by at least 1 installed lock.
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail

Rationale	If the fire labeled door that serves as an entry door cannot be secured by at least 1 installed lock, then the resident's ability to control access to the Unit may be limited.
	If the fire labeled door that serves as an entry door cannot be secured by at least 1 installed lock, then the resident may be unable to reasonably ensure privacy within the unit.
	If the fire labeled door that serves as an entry door cannot be secured by at least 1 installed lock, then the resident's ability to control access to the unit may be limited.
	A resident is likely to notice if the fire labeled door that serves as an entry door cannot be secured by at least 1 installed lock within the Unit and to recognize it is important enough to report it to property management because it may limit their security or privacy.

TABLE 12—DOOR – GENERAL STANDARD

Definition and Location

Definition	Panel that provides an opening in a building or room and provides separation (i.e., closes an opening).
Location	Unit: All passage doors throughout the Unit (i.e., a door between rooms, door into a walk-in closet, or door into a utility room, storage room, or room that contains washers and dryers).
	Inside: All passage doors throughout the Inside (i.e., a door between rooms, door into a walk-in closet, or door into a utility room, storage room, or room that contains washers and dryers).
	Outside: All exterior doors throughout the Outside (i.e., a door into a utility room, storage room, or mechanical room).
Deficiency 1 – Door – Ge	neral: Unit
Deficiency	A passage door does not open.
Deficiency Criteria	A passage door does not open such that it may limit the resident's ability to move freely between rooms.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	

Rationale

If a passage door does not open such that it may limit the resident's ability to move freely between rooms, then there may be an increased safety risk for the resident in the event of an emergency.

If a passage door does not open, then the resident's ability to move freely between rooms may be limited.

A resident is likely to notice if a passage door does not open such that it may limit the resident's ability to move freely between rooms and to recognize it is important enough to report it to property management because it may present safety hazards or usability barriers. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in safety hazards.

	deficiency because it may result in safety mazards.
Deficiency 1 – Door – Ger	neral: Inside
Deficiency	A passage door does not open.
Deficiency Criteria	A passage door does not open such that it may limit the resident's ability to
	move freely between rooms.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a passage door does not open such that it may limit the resident's ability
	to move freely between rooms, then there may be an increased safety risk
	for the resident in the event of an emergency.
	If a passage door does not open, then the resident's ability to move freely
	between rooms may be limited.
	Property management would be expected to ensure that staff members
	understand how to identify a passage door that does not open such that it
	may limit the resident's ability to move freely between rooms. Management practices would be expected to assure prompt creation and
	prioritization of a work order to remedy this deficiency, because it may
	result in safety hazards or usability barriers.

Deficiency 2 – Door – Ge	neral: Unit
Deficiency	A passage door component is damaged, inoperable, or missing and the door is not functionally adequate.
Deficiency Criteria	A passage door component is damaged (i.e., visibly defective; impacts functionality) and the door is not functionally adequate (i.e., unable to provide privacy, separation between rooms, or manage the physical atmosphere within a room).
	OR
	A passage door component is inoperable (i.e., component is not meeting function or purpose; with or without visible damage) and the door is not functionally adequate (i.e., unable to provide privacy, separation between rooms, or manage the physical atmosphere within a room).
	OR
	A passage door component is missing (i.e., evidence of prior installation, but is now not present or is incomplete) and the door is not functionally adequate (i.e., unable to provide privacy, separation between rooms, or
	manage the physical atmosphere within a room).
Health and Safety	Advisory
Determination	
Correction Timeframe	Advisory
HCV Correction Timeframe	Advisory
HCV Pass/Fail	Pass
Rationale	If a passage door component is damaged, inoperable, or missing and the door is not functionally adequate, then the resident's reasonable expectation of privacy may be limited.
	If a passage door component is damaged, inoperable, or missing and the door is not functionally adequate, then the resident may not be able to fully use a feature of the Unit that is expected to be provided and maintained as part of the rent.
	A resident is likely to notice a passage door component that is damaged, inoperable, or missing and the door is not functionally adequate, and to recognize it is important enough to report it to property management because it may limit the resident's privacy. Property management should be expected to prioritize a work order to remedy this deficiency because it may limit the resident's privacy.

Deficiency 2 – Door – Ge	neral: Inside
Deficiency	A passage door component is damaged, inoperable, or missing and the door is not functionally adequate.
Deficiency Criteria	A passage door component is damaged (i.e., visibly defective; impacts functionality) and the door is not functionally adequate (i.e., unable to provide privacy, separation between rooms, or manage the physical atmosphere within a room).
	OR
	A passage door component is inoperable (i.e., component is not meeting function or purpose; with or without visible damage) and the door is not functionally adequate (i.e., unable to provide privacy, separation between rooms, or manage the physical atmosphere within a room).
	OR
	A passage door component is missing (i.e., evidence of prior installation, but is now not present or is incomplete) and the door is not functionally adequate (i.e., unable to provide privacy, separation between rooms, or manage the physical atmosphere within a room).
Health and Safety Determination	Advisory
Correction Timeframe	Advisory
HCV Correction Timeframe	Advisory
HCV Pass/Fail	Pass
Rationale	If a passage door component is damaged, inoperable, or missing and the door is not functionally adequate, then the resident may not be able to fully use a feature that is expected to be provided and maintained as part of the rent.
	Property management would be expected to ensure that staff members understand how to identify a passage door component that is damaged, inoperable, or missing and the door is not functionally adequate. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in usability barriers.
Deficiency 3 – Door – Ge	neral: Unit
Deficiency	A passage door that is not intended to permit access between rooms has a damaged, inoperable, or missing component.
Deficiency Criteria	A passage door that is not intended to permit access between rooms has a damaged (i.e., visibly defective; impacts functionality) component.

	OR
	A passage door that is not intended to permit access between rooms has an inoperable (i.e., component is not meeting function or purpose, with or without visible damage) component.
	OR
	A passage door that is not intended to permit access between rooms has a missing (i.e., evidence of prior installation, but is now not present or is incomplete) component.
Health and Safety Determination	Advisory
Correction Timeframe	Advisory
HCV Correction Timeframe	Advisory
HCV Pass/Fail	Pass
Rationale	If a passage door that is not intended to permit access between rooms has a damaged, inoperable, or missing component, then the resident's reasonable expectation of privacy of their personal property may be limited. If a passage door that is not intended to permit access between rooms has a damaged, inoperable, or missing component, then the resident may not be able to fully use a feature of the Unit that is expected to be provided and maintained as part of the rent. A resident is likely to notice a passage door that is not intended to permit access between rooms and has a damaged, inoperable, or missing component and to recognize it is important enough to report it to property management because it may limit the resident's privacy or present usability barriers. Property management should be expected to prioritize a work order to remedy this deficiency because it may limit the resident's privacy or present usability barriers.
Deficiency 4 – Door – Ge	neral: Outside
Deficiency	An exterior door component is damaged, inoperable, or missing.
Deficiency Criteria	An exterior door component is damaged (i.e., visibly defective; impacts functionality), inoperable (i.e., component is not meeting function or purpose, with or without visible damage), or missing (i.e., evidence of prior installation, but is now not present or is incomplete).
Health and Safety Determination	Standard

30 days

Correction Timeframe

HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If an exterior door component is damaged, inoperable, or missing, then the resident may be able to access areas that may be unsafe or not intended for the resident's use, which may result in an increased safety risk to the resident of injury.
	Property management would be expected to ensure that staff members understand how to identify an exterior door component that is damaged, inoperable, or missing. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards.

TABLE 13—EGRESS STANDARD

Definition and Location	
Definition	A safe, continuous, and unobstructed path of travel from any point in the
	building, unit, or structure to the public way.
Location	Unit: Hallway, stairwell, corridor
	Inside: Hallway, stairwell, corridor
Deficiency 1 – Egress: Un	nit
Deficiency	Obstructed egress on building 4 stories or more.
Deficiency Criteria	Egress door or window does not fully open.
	OR
	There is not a minimum of 2 unobstructed means of egress from a building
	to the public way and 1 unobstructed primary means of egress from the
	unit to the exit access.
Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	In a building with 4 stories or more, if an egress door or window does not
	fully open or there is not the minimum number of unobstructed means of

egress and there is a fire, then the resident may be unable to safely and expeditiously exit, which may result in injury or death.

In a building with 4 stories or more, if an egress door or window does not fully open or there is not the minimum number of unobstructed means of egress and there is a fire, then the resident may not be able to fully use the egress points to safely exit.

In a building with 4 stories or more, a resident is likely to notice an egress door or window does not fully open or there is not the minimum number of unobstructed means of egress within the Unit and to recognize this is important enough to report to property management because it may present safety hazards. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in safety hazards.

Deficiency 1 – Egress: Inside	
Deficiency	Obstructed egress on building 4 stories or more.
Deficiency Criteria	Egress door or window does not fully open.
	OR
	There is not a minimum of 2 unobstructed means of egress from a building
	to the public way, if so designed, and 1 unobstructed primary means of
	egress from the inside location to the exit access.
Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	In a building with 4 stories or more, if an egress door or window does not
	fully open or there is not the minimum number of unobstructed means of
	egress and there is a fire, then the resident may be unable to safely and
	expeditiously exit, which may result in injury or death.
	In a building with 4 stories or more, if an egress door or window does not
	fully open or there is not the minimum number of unobstructed means of
	egress and there is a fire, then the resident may not be able to fully use the
	egress points to safely exit.
	In a building with 4 stories or more, property management would be
	expected to ensure that staff members understand how to identify an
	egress door or window that does not fully open or has less than the
	minimum number of unobstructed means of egress. Management practices

would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards or usability barriers.

Doficionay	Obstructed egress on building 3 stories or less.
Deficiency	Obstructed egress on building 3 stories or less.
Deficiency Criteria	Egress door or window does not fully open.
	OR
	There is not a minimum of 2 unobstructed means of egress from a building to the public way and 1 unobstructed primary means of egress from the unit to the exit access.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	In a building with 3 stories or less, if an egress door or window does not fully open or there is not the minimum number of unobstructed means of egress and there is a fire, then the resident may be unable to safely and expeditiously exit, which may result in injury or death.
	In a building with 3 stories or less, if an egress door or window does not fully open or there is not the minimum number of unobstructed means of egress and there is a fire, then the resident may not be able to fully use the egress points to safely exit.
	In a building with 3 stories or less, a resident is likely to notice an egress door or window does not fully open or there is not the minimum number of unobstructed means of egress within the unit and to recognize it is important enough to report it to property management because it may present safety hazards. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in safety hazards.
Deficiency 2 – Egress: Ins	ide
Deficiency	Obstructed egress on building 3 stories or less.
Deficiency Criteria	Egress door or window does not fully open.
	OR

	There is not a minimum of 2 unobstructed means of egress from a building to the public way and 1 unobstructed primary means of egress from the inside location to the exit access.
	lliside location to the exit access.
Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	In a building with 3 stories or less, if an egress door or window does not
	fully open or there is not the minimum number of unobstructed means of
	egress and there is a fire, then the resident may be unable to safely and
	expeditiously exit, which may result in injury or death.
	In a building with 3 stories or less, if an egress door or window does not
	fully open or there is not the minimum number of unobstructed means of
	egress and there is a fire, then the resident may not be able to fully use the
	egress points to safely exit.
	In a building with 3 stories or less, property management would be
	expected to ensure that staff members understand how to identify an
	egress door or window that does not fully open or has less than the
	minimum number of unobstructed means of egress. Management practice
	would be expected to assure prompt creation and prioritization of a work
	order to remedy this deficiency because it may result in safety hazards or
	usability barriers.

TABLE 14—ELECTRICAL – CONDUCTOR STANDARD

An object or type of material that carries electrical current.
Unit: Throughout the Unit.
Inside: Throughout the Inside.
Outside: Throughout the Outside.
l – Conductor: Unit
Exposed electrical conductor.
Electrical conductor is not enclosed or properly insulated (e.g., damaged sheathing, open port, missing knockout, missing outlet or switch cover, missing breaker or fuse, or missing lightbulb).

	OR
	An opening or gap is present and measures greater than ¼ inch.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If an electrical conductor is not enclosed or properly insulated or an opening or gap is present and measures greater than ¼ inch, then the resident may come into contact with the exposed electrical conductor and be at an increased risk of electrical shock or shock-related injury, which may result in permanent disability or death.
	If an electrical conductor is not enclosed or properly insulated or an opening or gap is present and measures greater than ¼ inch, and there is a short or arc that causes a fire, then the enclosure may not be able to adequately contain the fire, resulting in an increased fire spread risk, which may result in injury.
	A resident is likely to notice if an electrical conductor is not enclosed or properly insulated or an opening or gap is present and measures greater than ¼ inch within the unit and to recognize it is important enough to report it to property management because it may present safety hazards. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in safety hazards.
Deficiency 1 – Electrical –	- Conductor: Inside
Deficiency	Exposed electrical conductor.
Deficiency Criteria	Electrical conductor is not enclosed or properly insulated (e.g., damaged sheathing, open port, missing knockout, missing outlet or switch cover, missing breaker or fuse, or missing lightbulb).
	OR
	An opening or gap is present and measures greater than ¼ inch.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours

HCV Pass/Fail	Fail
Rationale	If an electrical conductor is not enclosed or properly insulated or an opening or gap is present and measures greater than ¼ inch, then the resident may come into contact with the exposed electrical conductor and be at an increased risk of electrical shock or shock-related injury, which may result in permanent disability or death.
	If an electrical conductor is not enclosed or properly insulated or an opening or gap is present and measures greater than $\frac{1}{2}$ inch, and there is a short or arc that causes a fire, then the enclosure may not be able to adequately contain the fire, resulting in an increased fire spread risk, which may result in injury.
	Property management would be expected to ensure that staff members understand how to identify an electrical conductor that is not enclosed or properly insulated or if there is an opening or gap present that measures greater than ¼ inch. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards.
Deficiency 1 – Electrical -	- Conductor: Outside
Deficiency	Exposed electrical conductor.
Deficiency Criteria	Electrical conductor is not enclosed or properly insulated (e.g., damaged sheathing, open port, missing knockout, missing outlet or switch cover, missing breaker or fuse, or missing lightbulb).
	OR
	An opening or gap is present and measures greater than ¼ inch.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If an electrical conductor is not enclosed or properly insulated or an opening or gap is present and measures greater than ¼ inch, then the resident may come into contact with the exposed electrical conductor and be at an increased risk of electrical shock or shock-related injury, which may result in permanent disability or death.

If an electrical conductor is not enclosed or properly insulated or an opening or gap is present and measures greater than $\frac{1}{2}$ inch, and there is a short or

arc that causes a fire, then the enclosure may not be able to adequately contain the fire, resulting in an increased fire spread risk, which may result in injury.

Property management would be expected to ensure that staff members understand how to identify an electrical conductor that is not enclosed or properly insulated or if there is an opening or gap present that measures greater than ¼ inch. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards.

TABLE 15—ELECTRICAL – GROUND-FAULT CIRCUIT INTERRUPTER (GFCI) OR ARC-FAULT CIRCUIT INTERRUPTER (AFCI) – OUTLET OR BREAKER STANDARD

Definition and Location

Unit: Living room, bedroom, kitchen, bathroom, office, mechanical room,
closet, hallway, any wall surface.
Inside: Living room, kitchen, bathroom, office, mechanical room, closet, hallway, any wall surface.
Outside: Exterior wall surface, service panels, or site.
- Ground-Fault Circuit Interrupter (GFCI) or Arc-Fault Circuit Interrupter (AFCI
GFCI outlet or GFCI breaker is not visibly damaged and the test or reset button is inoperable.
GFCI outlet or GFCI breaker does not have visible damage and the test or
reset button is inoperable (i.e., overall system or component thereof is not
meeting function or purpose).
Severe Non-Life Threatening
24 hours
30 days
Fail
If a GFCI outlet or GFCI breaker does not have visible damage and the test or reset button is inoperable, and a ground fault occurs, there may be an increased safety risk to the resident of electrical shock, which may result in injury.

If a GFCI outlet or GFCI breaker does not have visible damage and the test or reset button is inoperable, then the resident may not be able to test or reset the GFCI outlet or GFCI breaker, which may result in limited use of devices.

Property management would be expected to ensure that staff members understand how to identify a GFCI outlet or GFCI breaker that does not have visible damage and the test or reset button is inoperable. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards or usability barriers.

GFCI outlet or GFCI breaker is not visibly damaged and the test or reset
button is inoperable.
GFCI outlet or GFCI breaker does not have visible damage and the test or
reset button is inoperable (i.e., overall system or component thereof is not
meeting function or purpose).
Severe Non-Life Threatening
24 hours
30 days
Fail
If a GFCI outlet or GFCI breaker does not have visible damage and the test
or reset button is inoperable, and a ground fault occurs, there may be an
increased safety risk to the resident of electrical shock, which may result in injury.
If a GFCI outlet or GFCI breaker does not have visible damage and the test
or reset button is inoperable, then the resident may not be able to test or
reset the GFCI outlet or GFCI breaker, which may result in limited use of devices.
Property management would be expected to ensure that staff members
understand how to identify a GFCI outlet or GFCI breaker that does not have visible damage and the test or reset button is inoperable. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards or usability barriers.

Deficiency 1 – Electrical -	- Ground-Fault Circuit Interrupter (GFCI) or Arc-Fault Circuit Interrupter (AFCI)
 Outlet or Breaker: Outs 	side
Deficiency	GFCI outlet or GFCI breaker is not visibly damaged and the test or reset
	button is inoperable.
Deficiency Criteria	GFCI outlet or GFCI breaker does not have visible damage and the test or
	reset button is inoperable (i.e., overall system or component thereof is not
	meeting function or purpose).
Health and Safety	Severe Non-Life Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a GFCI outlet or GFCI breaker does not have visible damage and the test or reset button is inoperable, and a ground fault occurs, there may be an
	increased safety risk to the resident of electrical shock, which may result in
	injury.
	If a GFCI outlet or GFCI breaker does not have visible damage and the test
	or reset button is inoperable, then the resident may not be able to test or
	reset the GFCI outlet or GFCI breaker, which may result in limited use of
	devices.
	Property management would be expected to ensure that staff members
	understand how to identify a GFCI outlet or GFCI breaker that does not have
	visible damage and the test or reset button is inoperable. Management
	practices would be expected to assure prompt creation and prioritization of
	a work order to remedy this deficiency because it may result in safety
	hazards or usability barriers.

Deficiency	AFCI outlet or AFCI breaker is not visibly damaged and the test or reset
	button is inoperable.
Deficiency Criteria	AFCI outlet or AFCI breaker does not have visible damage and the test or
	reset button is inoperable (i.e., overall system or component thereof is not
	meeting function or purpose).
Health and Safety	Severe Non-Life Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If an AFCI outlet or AFCI breaker does not have visible damage and the test
	or reset button is inoperable, and an arc fault occurs, there may be an
	increased safety risk to the resident of fire, which may result in injury.
	If an AFCI outlet or AFCI breaker does not have visible damage and the test
	or reset button is inoperable, then the resident may not be able to test or
	reset the AFCI outlet or AFCI breaker, which may result in limited use of
	devices.
	Property management would be expected to ensure that staff members
	understand how to identify an AFCI outlet or AFCI breaker that does not
	have visible damage and the test or reset button is inoperable.
	Management practices would be expected to assure prompt creation and
	prioritization of a work order to remedy this deficiency, because it may
	result in safety hazards or usability barriers.
Deficiency 2 – Electrical – Outlet or Breaker: Insic	- Ground-Fault Circuit Interrupter (GFCI) or Arc-Fault Circuit Interrupter (AFC
Deficiency	AFCI outlet or AFCI breaker is not visibly damaged and the test or reset
,	button is inoperable.
Deficiency Criteria	AFCI outlet or AFCI breaker does not have visible damage and the test or
	reset button is inoperable (i.e., overall system or component thereof is not
	meeting function or purpose).
Health and Safety	Severe Non-Life Threatening
Determination	
Correction Timeframe	24 hours

HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If an AFCI outlet or AFCI breaker does not have visible damage and the test or reset button is inoperable, and an arc fault occurs, there may be an increased safety risk to the resident of fire, which may result in injury.
	If an AFCI outlet or AFCI breaker does not have visible damage and the test or reset button is inoperable, then the resident may not be able to test or reset the AFCI outlet or AFCI breaker, which may result in limited use of devices.
	Property management would be expected to ensure that staff members understand how to identify an AFCI outlet or AFCI breaker that does not have visible damage and the test or reset button is inoperable. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards or usability barriers.
Deficiency 2 – Electrical – – Outlet or Breaker: Outs	- Ground-Fault Circuit Interrupter (GFCI) or Arc-Fault Circuit Interrupter (AFCI) side
Deficiency	AFCI outlet or AFCI breaker is not visibly damaged and the test or reset button is inoperable.
Deficiency Criteria	AFCI outlet or AFCI breaker does not have visible damage and the test or reset button is inoperable (i.e., overall system or component thereof is not meeting function or purpose).
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If an AFCI outlet or AFCI breaker does not have visible damage and the test

or reset button is inoperable, and an arc fault occurs, there may be an increased safety risk to the resident of fire, which may result in injury.

devices.

If an AFCI outlet or AFCI breaker does not have visible damage and the test or reset button is inoperable, then the resident may not be able to test or reset the AFCI outlet or AFCI breaker, which may result in limited use of

Property management would be expected to ensure that staff members understand how to identify an AFCI outlet or AFCI breaker that does not have visible damage and the test or reset button is inoperable.

Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards or usability barriers.

TABLE 16—ELECTRICAL – OUTLET AND SWITCH STANDARD

Definition and Location	
Definition	Installations that connect to an electricity supply.
Location	Unit: Throughout the Unit.
	Inside: Throughout the Inside.
	Outside: Throughout the Outside.
Deficiency 1 – Electrical -	- Outlet and Switch: Unit
Deficiency	Outlet or switch is damaged.
Deficiency Criteria	Any portion of a visually accessible (i.e., can be reasonably accessed and observed) outlet or switch is damaged (i.e., visibly defective; impacts functionality) such that it may not safely carry or control electrical current at the outlet or switch.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If any portion of a visually accessible outlet or switch is damaged such that it may not safely carry or control electrical current at the outlet or switch, then there may be an increased safety risk to the resident of fire or electrical shock, which may result in injury or death.
	If any portion of a visually accessible outlet or switch is damaged such that it may not safely carry or control electrical current at the outlet or switch, then the resident may not be able to safely use appliances, lighting fixtures, or other devices.
	A resident is likely to notice if any portion of a visually accessible outlet or switch is damaged such that it may not safely carry or control electrical

current at the outlet or switch and recognize it is important enough to report to property management because it may present safety hazards. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in safety hazards or usability barriers.

Deficiency	Outlet and Switch: Inside Outlet or switch is damaged.
Deficiency	Outlet of Switch is damaged.
Deficiency Criteria	Any portion of a visually accessible (i.e., can be reasonably accessed and
	observed) outlet or switch is damaged (i.e., visibly defective; impacts
	functionality) such that it may not safely carry or control electrical current
	at the outlet or switch.
Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If any portion of a visually accessible outlet or switch is damaged such that
	it may not safely carry or control electrical current at the outlet or switch,
	then there may be an increased safety risk to the resident of fire or
	electrical shock, which may result in injury or death.
	If any portion of a visually accessible outlet or switch is damaged such that
	it may not safely carry or control electrical current at the outlet or switch,
	then the resident may not be able to safely use appliances, lighting fixtures
	or other devices.
	Property management would be expected to ensure that staff members
	understand how to identify if any portion of a visually accessible outlet or
	switch is damaged such that it may not safely carry or control electrical
	current at the outlet or switch. Management practices would be expected
	to assure prompt creation and prioritization of a work order to remedy this
	deficiency because it may result in safety hazards or usability barriers.
eficiency 1 – Electrical -	- Outlet and Switch: Outside
Deficiency	Outlet or switch is damaged.
Deficiency Criteria	Any portion of a visually accessible (i.e., can be reasonably accessed and
	observed) outlet or switch is damaged (i.e., visibly defective; impacts

functionality) such that it may not safely carry or control electrical current

at the outlet or switch.

Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If any portion of a visually accessible outlet or switch is damaged such that it may not safely carry or control electrical current at the outlet or switch, then there may be an increased safety risk to the resident of fire or electrical shock, which may result in injury or death.
	If any portion of a visually accessible outlet or switch is damaged such that it may not safely carry or control electrical current at the outlet or switch, then the resident may not be able to safely use appliances, lighting fixtures, or other devices.
	Property management would be expected to ensure that staff members understand how to identify if any portion of a visually accessible outlet or switch is damaged such that it may not safely carry or control electrical current at the outlet or switch. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards or usability barriers.
Deficiency 2 – Electrical –	- Outlet and Switch: Unit
Deficiency	Testing indicates a three-pronged outlet is not properly wired or grounded.
Deficiency Criteria	Testing of a three-pronged outlet that is reasonably accessible (i.e., can be reached without moving obstructions, dismantling, destructive measures, or actions that may pose a risk to persons or property) indicates that it is not properly wired or grounded.
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If testing of a three-pronged outlet that is reasonably accessible indicates that it is not properly wired or grounded, and a device is plugged into the outlet, then the outlet may not safely conduct the electrical current through

the device, which may result in an increased risk to the resident of electrical shock.

If testing of a three-pronged outlet that is reasonably accessible indicates that it is not properly wired or grounded, then the resident may not be able to safely use the outlet, which may result in limited use of appliances or lighting fixtures.

Property management would be expected to ensure that staff members understand how to identify a three-pronged outlet that is reasonably accessible and is not properly wired or grounded. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards or usability barriers.

Testing indicates a three-pronged outlet is not properly wired or grounded.

Deficiency	Testing indicates a three-pronged outlet is not properly wired or grounded.
Deficiency Criteria	Testing of a three-pronged outlet that is reasonably accessible (i.e., can be
	reached without moving obstructions, dismantling, destructive measures, or
	actions that may pose a risk to persons or property) indicates that it is not
	properly wired or grounded.
Health and Safety	Severe Non-Life Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If testing of a three-pronged outlet that is reasonably accessible indicates
	that it is not properly wired or grounded, and a device is plugged into the
	outlet, then the outlet may not safely conduct the electrical current through
	the device, which may result in an increased risk to the resident of electrical shock.
	Property management would be expected to ensure that staff members
	understand how to identify a three-pronged outlet that is reasonably
	accessible and is not properly wired or grounded. Management practices
	would be expected to assure prompt creation and prioritization of a work
	order to remedy this deficiency because it may result in safety hazards or usability barriers.

Deficiency 2 – Electrical – Outlet and Switch: Outside

Deficiency

Deficiency Criteria	Testing of a three-pronged outlet that is reasonably accessible (i.e., can be reached without moving obstructions, dismantling, destructive measures, or actions that may pose a risk to persons or property) indicates that it is not properly wired or grounded.
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If testing of a three-pronged outlet that is reasonably accessible indicates that it is not properly wired or grounded, and a device is plugged into the outlet, then the outlet may not safely conduct the electrical current through the device, which may result in an increased risk to the resident of electrical shock. Property management would be expected to ensure that staff members understand how to identify a three-pronged outlet that is reasonably accessible and is not properly wired or grounded. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards or usability barriers.
<u>-</u>	- Outlet and Switch: Unit
Deficiency	An unprotected outlet is present within six feet of a water source.
Deficiency Criteria	An unprotected outlet is present within six feet of a water source (i.e., sink, bathtub, shower, water faucet, toilet) that is located in the same room.
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a device is plugged into an unprotected outlet that is present within six feet of a water source within the same room, then there may be an increased safety risk to the resident of electrical shock, which may result in injury.

Property management would be expected to ensure that staff members understand how to identify an unprotected outlet that is present within six feet of a water source that is located in the same room. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards.

Deficiency 3 – Electrical -	- Outlet and Switch: Inside
Deficiency	An unprotected outlet is present within six feet of a water source.
Deficiency Criteria	An unprotected outlet is present within six feet of a water source (i.e., sink,
	bathtub, shower, water faucet, toilet) that is located in the same room.
Health and Safety	Severe Non-Life Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a device is plugged into an unprotected outlet that is present within six
	feet of a water source within the same room, then there may be an
	increased safety risk to the resident of electrical shock, which may result in injury.
	Property management would be expected to ensure that staff members understand how to identify an unprotected outlet that is present within six foot of a water source that is leasted in the same room. Management
	feet of a water source that is located in the same room. Management practices would be expected to assure prompt creation and prioritization of
	a work order to remedy this deficiency because it may result in safety
	hazards.

Deficiency 3 – Electrical – Outlet and Switch: Outside		
Deficiency	An unprotected outlet is present within six feet of a water source.	
Deficiency Criteria	An unprotected outlet is present throughout the Outside.	
Health and Safety	Severe Non-Life Threatening	
Determination		
Correction Timeframe	24 hours	
HCV Correction	30 days	
Timeframe		
HCV Pass/Fail	Fail	

If a device is plugged into an unprotected outlet within the Outside area, then there may be an increased safety risk to the resident of electrical shock, which may result in injury.

Property management would be expected to ensure that staff members understand how to identify an unprotected outlet that is present within the Outside area. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards.

Deficiency 4 – Electrical – Outlet and Switch: Unit

Deficiency

Outlet does not have visible damage and testing indicates it is not energized.

Deficiency Criteria

An outlet that is reasonably accessible (i.e., can be reached without moving obstructions, dismantling, destructive measures, or actions that may pose a risk to persons or property) does not have visible damage and testing indicates that it is not energized.

Health and Safety Determination

Severe Non-Life Threatening

Correction Timeframe

24 hours

HCV Correction Timeframe

30 days

HCV Pass/Fail

Fail

Rationale

If an outlet that is reasonably accessible does not have visible damage and testing indicates that it is not energized, then the outlet may not safely conduct the electrical current through the device, possibly resulting in an increased safety risk to the resident of fire, which may result in injury.

If an outlet that is reasonably accessible does not have visible damage and testing indicates that it is not energized, then the resident may not be able to safely use the outlet, which may result in limited use of devices.

A resident is likely to notice if an outlet is not energized within the unit and to recognize it is important enough to report it to property management because it may present usability barriers. Property management should be expected to prioritize a work order for an outlet that does not have visible damage and testing indicates that it is not energized because it may result in safety hazards or usability barriers.

Deficiency 4 - Electrical - Outlet and Switch: Inside

Deficiency

Outlet does not have visible damage and testing indicates it is not energized.

Deficiency Criteria	An outlet that is reasonably accessible (i.e., can be reached without moving obstructions, dismantling, destructive measures, or actions that may pose a risk to persons or property) does not have visible damage and testing indicates that it is not energized.
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If an outlet that is reasonably accessible does not have visible damage and testing indicates that it is not energized, then the outlet may not safely conduct the electrical current through the device, possibly resulting in an increased safety risk to the resident of fire, which may result in injury.
	If an outlet that is reasonably accessible does not have visible damage and testing indicates that it is not energized, then the resident may not be able to safely use the outlet, which may result in limited use of devices.
	Property management would be expected to ensure that staff members understand how to identify an outlet that does not have visible damage and testing indicates that it is not energized. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards or usability barriers.
Deficiency 4 – Electrical –	- Outlet and Switch: Outside
Deficiency	Outlet does not have visible damage and testing indicates it is not energized.
Deficiency Criteria	An outlet that is reasonably accessible (i.e., can be reached without moving obstructions, dismantling, destructive measures, or actions that may pose a risk to persons or property) does not have visible damage and testing indicates that it is not energized.
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail

Definition and Location

If an outlet that is reasonably accessible does not have visible damage and testing indicates that it is not energized, then the outlet may not safely conduct the electrical current through the device, possibly resulting in an increased safety risk to the resident of fire, which may result in injury.

If an outlet that is reasonably accessible does not have visible damage and testing indicates that it is not energized, then the resident may not be able to safely use the outlet, which may result in limited use of devices.

Property management would be expected to ensure that staff members understand how to identify an outlet that does not have visible damage and testing indicates that it is not energized. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards or usability barriers.

TABLE 17—ELECTRICAL – SERVICE PANEL STANDARD

Definition	An enclosure, cabinet, box, or panelboard containing overcurrent protection devices for the control of light, heat, appliances and power circuits.
Location	Unit: Living room, bedroom, kitchen, bathroom, closet, hallway, office, mechanical room, any wall surface, emergency generator, trash compactor garage, and storage.
	Inside: Living room, kitchen, bathroom, closet, hallway, office, mechanical room, any wall surface, emergency generator, trash compactor, garage, storage, and all common areas.
	Outside: Anywhere on site, any wall surface, HVAC condensers, emergency generator, and trash compactor.
Deficiency 1 – Electrical –	- Service Panel: Unit
Deficiency	Electrical service panel is not readily accessible.
Deficiency Criteria	Electrical service panel is not reasonably accessible (i.e., cannot be reached and opened without moving obstructions, dismantling, destructive measures, or actions that may pose a risk to persons or property).
Health and Safety Determination	Standard
Correction Timeframe	30 days

HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the electrical service panel is not reasonably accessible and there is a need to shutoff the electrical circuit, there may be an increased safety risk to the resident of fire or electrical shock, which may result in injury.
	If the electrical service panel is not reasonably accessible, then the resident may not be able to reset a tripped breaker, which may result in limited use of appliances or lighting fixtures.
	Property management would be expected to ensure that staff members understand how to identify if an electrical service panel is not reasonably accessible. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards or usability barriers.
Deficiency 1 – Electrical -	
Deficiency	Electrical service panel is not readily accessible.
Deficiency Criteria	Electrical service panel is not reasonably accessible (i.e., cannot be reached and opened without moving obstructions, dismantling, destructive measures, or actions that may pose a risk to persons or property).
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the electrical service panel is not reasonably accessible and there is a need to shutoff the electrical circuit, there may be an increased safety risk to the resident of fire or electrical shock, which may result in injury.
	If the electrical service panel is not reasonably accessible, then the resident may not be able to reset a tripped breaker, which may result in limited use of appliances or lighting fixtures.
	Property management would be expected to ensure that staff members understand how to identify if an electrical service panel is not reasonably accessible. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards or usability barriers.

Deficiency 1 – Electrical -	- Service Panel: Outside
Deficiency	Electrical service panel is not readily accessible.
Deficiency Criteria	Electrical service panel is not reasonably accessible (i.e., cannot be reached and opened without moving obstructions, dismantling, destructive measures, or actions that may pose a risk to persons or property).
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the electrical service panel is not reasonably accessible and there is a need to shutoff the electrical circuit, there may be an increased safety risk to the resident of fire or electrical shock, which may result in injury. If the electrical service panel is not reasonably accessible, then the resident may not be able to reset a tripped breaker, which may result in limited use of appliances or lighting fixtures. Property management would be expected to ensure that staff members understand how to identify if an electrical service panel is not reasonably accessible. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards or usability barriers.
Deficiency 2 – Electrical -	- Service Panel: Unit
Deficiency	The overcurrent protection device is damaged.
Deficiency Criteria	The overcurrent protection device (i.e., fuse or breaker) is damaged (i.e., visibly defective; impacts functionality) such that it may not interrupt the circuit during an overcurrent condition.
Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail

If the overcurrent protection device is damaged, then it may malfunction and not provide overcurrent protection when required, resulting in an increased safety risk to the resident of fire or electrical shock, which may result in injury or death.

If the overcurrent protection device is damaged, then the resident will not be able to safely reset or replace an overcurrent protection device, which may result in limited use of appliances or lighting fixtures.

If the overcurrent protection device is damaged, and it malfunctions resulting in the resident's inability to use an appliance or lighting fixture, then the resident is likely to notice this issue and will report it to property management because it may present usability barriers. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in safety hazards or usability barriers.

Deficiency 2 – Electrical -	- Service Panel: Inside
Deficiency	The overcurrent protection device is damaged.
Deficiency Criteria	The overcurrent protection device (i.e., fuse or breaker) is damaged (i.e.,
	visibly defective; impacts functionality) such that it may not interrupt the
	circuit during an overcurrent condition.
Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the overcurrent protection device is damaged, then it may malfunction and not provide overcurrent protection when required, resulting in an
	increased safety risk to the resident of fire or electrical shock, which may result in injury or death.
	If the overcurrent protection device is damaged, then the resident will not
	be able to safely reset or replace an overcurrent protection device, which may result in limited use of appliances or lighting fixtures.
	Property management would be expected to ensure that staff understand
	how to identify an overcurrent protections device that is damaged.
	Management practices would be expected to assure prompt creation and
	prioritization of a work order to remedy this deficiency, because it may result in safety hazards or usability barriers.

Deficiency 2 – Electrical -	- Service Panel: Outside
Deficiency	The overcurrent protection device is damaged.
Deficiency Criteria	The overcurrent protection device (i.e., fuse or breaker) is damaged (i.e., visibly defective; impacts functionality) such that it may not interrupt the circuit during an overcurrent condition.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If the overcurrent protection device is damaged, then it may malfunction and not provide overcurrent protection when required, resulting in an increased safety risk to the resident of fire or electrical shock, which may result in injury or death.
	If the overcurrent protection device is damaged, then the resident will not be able to safely reset or replace an overcurrent protection device, which may result in limited use of appliances or lighting fixtures.
	Property management would be expected to ensure that staff understand how to identify an overcurrent protections device that is damaged. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards or usability barriers.
Deficiency 3 – Electrical -	- Service Panel: Unit
Deficiency	The overcurrent protection device is contaminated.
Deficiency Criteria	The overcurrent protection device (i.e., fuse or breaker) is contaminated (e.g., water, rust, corrosion).
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail

If the overcurrent protection device is contaminated, then it may malfunction and not provide overcurrent protection when required, resulting in an increased safety risk to the resident of fire, which may result in injury.

If the overcurrent protection device is contaminated, then the resident may not be able to safely reset or replace an overcurrent protection device, which may result in limited use of appliances or lighting fixtures.

Property management would be expected to ensure that staff members understand how to identify a contaminated overcurrent protection device. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards or usability barriers.

Deficiency 3 – Electrical -	Deficiency 3 – Electrical – Service Panel: Inside	
Deficiency	The overcurrent protection device is contaminated.	
Deficiency Criteria	The overcurrent protection device (i.e., fuse or breaker) is contaminated (e.g., water, rust, corrosion).	
Health and Safety Determination	Severe Non-Life Threatening	
Correction Timeframe	24 hours	
HCV Correction Timeframe	30 days	
HCV Pass/Fail	Fail	
Rationale	If the overcurrent protection device is contaminated, then it may	

If the overcurrent protection device is contaminated, then it may malfunction and not provide overcurrent protection when required, resulting in an increased safety risk to the resident of fire, which may result in injury.

If the overcurrent protection device is contaminated, then the resident may not be able to safely reset or replace an overcurrent protection device, which may result in limited use of appliances or lighting fixtures.

Property management would be expected to ensure that staff members understand how to identify a contaminated overcurrent protection device. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards or usability barriers.

Deficiency 3 - Electrical - Service Panel: Outside

Deficiency

The overcurrent protection device is contaminated.

Deficiency Criteria	The overcurrent protection device (i.e., fuse or breaker) is contaminated (e.g., water, rust, corrosion).
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the overcurrent protection device is contaminated, then it may malfunction and not provide overcurrent protection when required, resulting in an increased safety risk to the resident of fire, which may result in injury.
	If the overcurrent protection device is contaminated, then the resident may not be able to safely reset or replace an overcurrent protection device, which may result in limited use of appliances or lighting fixtures.
	Property management would be expected to ensure that staff members understand how to identify a contaminated overcurrent protection device. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards or usability barriers.

TABLE 18—ELEVATOR STANDARD

Definition and Location	
Definition	A vertical transport vehicle, generally powered by electric motors that either drive traction cables and counterweight systems or pump hydraulic
	fluid to raise a cylindrical piston.
Location	Inside: Hallway, building entrance or lobby, parking garage.
Deficiency 1 – Elevator: I	nside
Deficiency	Elevator is inoperable.
Deficiency Criteria	Elevator is inoperable (i.e., overall system or component thereof not
	meeting function or purpose; with or without visible damage).
Health and Safety	Standard
Determination	
Correction Timeframe	30 days

HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the elevator is inoperable, then the resident's accessibility and egress or ingress is reduced. If the elevator is inoperable, then the resident may be trapped inside the elevator.
	If the elevator is inoperable, then the resident may be unable to use a feature that is expected to be provided and maintained as part of their rent.
	If the elevator is inoperable, then the resident will likely report this deficiency, and presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	If the elevator is inoperable, then this will likely be identified through routine maintenance activities, and the presence of this deficiency may indicate that self-generated work orders are not being addressed.
	If the elevator is inoperable, then capital costs may be required to repair the deficiency.

Deficiency 2 – Elevator: I	nside
Deficiency	Elevator door does not fully open and close.
Deficiency Criteria	Elevator door does not fully open and close.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the elevator door does not fully open and close, there may be an increased safety risk to the resident due to fall hazards, which may result in injury.
	If the elevator door does not fully open and close, then the resident may be unable to use a feature that is expected to be provided and maintained as part of their rent.
	Property management would be expected to ensure that staff members understand how to identify when an elevator door does not fully open and close. Management practices would be expected to assure prompt creation

and prioritization of a work order to repair the elevator door because it may result in safety hazards or usability barriers.

Elevators should be checked during periodic property inspections, and according to industry best practices, should be included in a preventative maintenance plan. If the elevator door does not fully open and close, then it may indicate preventative maintenance activities could be improved.

Deficiency	Elevator cab is not level with the floor.
Deficiency Criteria	There is more than a ¾-inch difference in level between the elevator cab
	and the building's floor.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the elevator cab is not level with the floor, then there is a trip hazard for the resident.
	If the elevator cab is not level with the floor, then the resident will likely report this deficiency, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	If the elevator cab is not level with the floor, then this will likely be identified through routine maintenance activities, and the presence of this deficiency may indicate that self-generated work orders are not being addressed.
	Elevators should be checked during periodic property inspections, and according to industry best practices, should be included in a preventative maintenance plan. If the elevator cab is not level with the floor, this may indicate that preventative maintenance activities are not being addressed.

Deficiency 4 – Elevator: Inside	
Deficiency	Safety door or emergency phone is inoperable.
Deficiency Criteria	Safety door has malfunctioned or is inoperable (i.e., overall system or component thereof is not meeting function or purpose; with or without visible damage). OR

	Emergency call system has malfunctioned or is inoperable (i.e., overall
	system or component thereof is not meeting function or purpose; with or
	without visible damage).
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the elevator safety door or emergency call system is inoperable, then the resident may be injured by the closing door.
	If the elevator safety door or emergency call system is inoperable, then the resident may be unable to use a feature that is expected to be provided and maintained as part of their rent.
	If the elevator safety door or emergency call system is inoperable, then the resident will likely report this deficiency, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	If the elevator safety door or emergency call system is inoperable, then this will likely be identified through routine maintenance activities and the presence of this deficiency may indicate that self-generated work orders are not being addressed.
	Elevators should be checked during periodic property inspections, and according to industry best practices, should be included in a preventative maintenance plan. If the elevator safety door or emergency call system is inoperable, this may indicate that preventative maintenance activities are not being addressed.
	not being addressed.

TABLE 19—EXIT SIGN STANDARD

ition
Device or placard that identifies the egress route in case of an emergency.
Inside: Hallway; stairway; corridor.
Outside: Hallway; stairway; corridor.
Sign: Inside
Exit sign is damaged, missing, obstructed, or not adequately illuminated.

OR	ective; impacts functionality).
	, ,
Exit sign is missing (i.e., evidence of or is incomplete).	prior installation, but is now not present
OR	
Exit sign is obstructed such that the	word "EXIT" is not clearly visible.
OR	
Exit sign is not adequately illuminat	ed.
Health and Safety Life-Threatening Determination	
Correction Timeframe 24 hours	
HCV Correction 24 hours	
Timeframe	
HCV Pass/Fail Fail	
Rationale If an exit sign is damaged, missing, of illuminated, and there is an emerge safely and expeditiously exit.	obstructed, or not adequately ncy, then the resident may be unable to
If an exit sign is damaged, missing, of illuminated, and there is an emerge safely and expeditiously exit.	obstructed, or not adequately ncy, then the resident may be unable to
how to identify an exit sign that is d	pected to ensure that staff understand amaged, missing, obstructed, or not ent practices would be expected to eation of a work order to remedy this lith or safety hazards.
assure prompt creation and prioritize defect, because it may result in hea	
assure prompt creation and prioritize defect, because it may result in hea Deficiency 1 – Exit Sign: Outside	ucted, or not adequately illuminated.
assure prompt creation and prioritize defect, because it may result in hea Deficiency 1 – Exit Sign: Outside	ucted, or not adequately illuminated.
assure prompt creation and prioritize defect, because it may result in head Deficiency 1 – Exit Sign: Outside Exit sign is damaged, missing, obstructions of the control o	ucted, or not adequately illuminated.
assure prompt creation and prioritize defect, because it may result in head defect sign is damaged, missing, obstruction defect sign is damaged, missing, obstruction defect sign is damaged (i.e., visibly defect of the head defect sign is damaged (i.e., visibly defect of the head defect sign is damaged (i.e., visibly defect of the head defect sign is damaged (i.e., visibly defect of the head defect sign is damaged (i.e., visibly defect of the head defect sign is damaged (i.e., visibly defect of the head defect sign is damaged (i.e., visibly defect of the head defect sign is damaged (i.e., visibly defect of the head defect sign is damaged (i.e., visibly defect of the head defect sign is damaged (i.e., visibly defect of the head defect sign is damaged (i.e., visibly defect of the head defect sign is damaged (i.e., visibly defect of the head defect sign is damaged (i.e., visibly defect of the head defect sign is damaged (i.e., visibly defect of the head defect sign is damaged (i.e., visibly defect of the head defect sign is damaged (i.e., visibly defect of the head defect sign is damaged (i.e., visibly defect of the head defect sign is damaged (i.e., visibly defect of the head defect sign is damaged (i.e., visibly defect of the head defect sign is damaged (i.e., visibly	ucted, or not adequately illuminated.
assure prompt creation and prioritize defect, because it may result in head defect sign is damaged, missing, obstruction of the defect of the	ucted, or not adequately illuminated. ective; impacts functionality).
assure prompt creation and prioritize defect, because it may result in head Deficiency 1 – Exit Sign: Outside Deficiency Exit sign is damaged, missing, obstruction Exit sign is damaged (i.e., visibly deform on the complete).	ucted, or not adequately illuminated. ective; impacts functionality). prior installation, but is now not present

	Exit sign is not adequately illuminated.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If an exit sign is damaged, missing, obstructed, or not adequately illuminated, and there is an emergency, then the resident may be unable to safely and expeditiously exit.
	If an exit sign is damaged, missing, obstructed, or not adequately illuminated, and there is an emergency, then the resident may be unable to safely and expeditiously exit.
	Property management would be expected to ensure that staff understand how to identify an exit sign that is damaged, missing, obstructed, or not adequately illuminated. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this defect, because it may result in health or safety hazards.

TABLE 20—FENCE – SECURITY STANDARD

Definition and Location	
Definition	A locking barrier, railing, or other upright structure, typically of wood or
	wire, fully enclosing an area of ground to mark a boundary and control
	access. Fence must be 4 feet or greater.
Location	Outside: Decks, patios, perimeter of property.
Deficiency 1 – Fence – Security: Outside	
Deficiency	Fence components are missing.
Deficiency Criteria	Fence components are missing (i.e., evidence of prior installation, but now not present or is incomplete), resulting in a hole that is approximately 10% or greater of the area of a single section of fence.
	Components may include, but are not limited to, pickets, posts, and panels.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days

HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a fence has missing components, and it falls, then the resident may be exposed to hazards.
	If a fence has missing components, then the resident may be unable to control access to the property.
	If a fence has missing components, then it may limit the privacy of the property.
	If a fence has missing components, then the resident may be unable to use a feature of the home that is expected to be provided and maintained as part of their rent.
	If a fence has missing components, then it will likely be observed through regular maintenance activities, and the presence of this deficiency may indicate that self-generated work orders are not being addressed.

	maleute that sen generated work orders are not being addressed.
Deficiency 2 – Fence – Se	ecurity: Outside
Deficiency	Gate does not open, close, latch, or lock.
Deficiency Criteria	Gate will not open.
	OR
	Gate will open when locked or latched.
	OR
	Gate will not close.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a gate does not open, and there is an emergency, then the resident may be limited in their ability to leave the property or this may delay entry by emergency personnel.
	If a gate does not close, latch, or lock, then the resident may be unable to control access to the property.

If a gate does not open, close, latch, or lock, then the resident may not be able to fully use a feature that is expected to be provided and maintained as part of their rent.

If a gate does not open, close, latch, or lock, then it will likely be observed through regular maintenance activities, and the presence of this deficiency may indicate that self-generated work orders are not being addressed.

Deficiency 3 – Fence – Security: Outside	
Deficiency	Fence demonstrates signs of collapse.
Deficiency Criteria	Fence demonstrates signs of collapse.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a fence demonstrates signs of collapse, then it may present a hazard to the resident.
	If a fence demonstrates signs of collapse, then the resident may not be able to control access to the property.
	If a fence demonstrates signs of collapse, then the resident may not be able to fully use a feature that is expected to be included and maintained as part of their rent.
	If a fence demonstrates signs of collapse, then it will likely be observed through regular maintenance activities, and the presence of this deficiency may indicate that self-generated work orders are not being addressed.

TABLE 21—FIRE ESCAPE STANDARD

Dofinition and Lasstic	
Definition and Location	An appearance and the austrial of a building used for asserting from the 1939 of
Definition	An apparatus on the outside of a building used for escaping from a building on fire.
Location	Outside: Exterior of building—typically high-rises and other multi-story buildings—near windows and exterior doors.
Deficiency 1 – Fire Escape	e: Outside
Deficiency	Fire escape component is damaged or missing.
Deficiency Criteria	Any stair, ladder, platform, guardrail, or handrail is damaged (i.e., visibly defective; impacts functionality).
	OR
	Any stair, ladder, platform, guardrail, or handrail is missing (i.e., evidence of prior installation, but now not present or is incomplete).
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If a fire escape component is damaged or missing, and there is an emergency, then resident may sustain an injury when using.
	If a fire escape component is damaged or missing, and there is an emergency, then the resident's ability to safely egress the building is limited, which may jeopardize their safety.
	If a fire escape component is damaged or missing, then the resident may be unable to fully use a feature that is expected to be provided and maintained as part of their rent.
	If a fire escape component is damaged or missing, then it should be detected through daily maintenance activities and its presence may indicate that self-generated work orders are not being addressed.
	If a fire escape component is damaged or missing, then property management may not be following their preventative maintenance plan.
	If a fire escape component is damaged or missing, then it may be very expensive to replace or fix the defect.

TABLE 22—FIRE EXTINGUISHER STANDARD

Definition and Location	
Definition	A portable fire safety device that discharges a jet of water, foam, gas, or other material to extinguish a fire.
Location	Unit: Includes, but is not limited to: hallways, kitchens, laundry rooms, mechanical rooms.
	Inside: Includes, but is not limited to: hallways, kitchens, laundry rooms, common areas, mechanical rooms.
	Outside: Parking garages, breezeways, property exterior, roof tops.
Deficiency 1 – Fire Exting	uisher: Unit
Deficiency	Fire extinguisher pressure gauge reads over or under-charged.
Deficiency Criteria	Pressure gauge indicates that the fire extinguisher is over or under-charged.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If a fire extinguisher pressure gauge reads over or under-charged, and there is a fire, then the resident may be injured.
	If a fire extinguisher pressure gauge reads over or under-charged, then the resident may be unable to use a feature that is expected to be provided and maintained as part of their rent.
	If a fire extinguisher pressure gauge reads over or under-charged, then this should be identified through routine maintenance, and the presence of this deficiency may indicate that self-generated work orders are not being addressed.
	If a fire extinguisher pressure gauge reads over or under-charged, then it may indicate that preventative maintenance activities are not occurring.
Deficiency 1 – Fire Exting	uisher: Inside
Deficiency	Fire extinguisher pressure gauge reads over or under-charged.
Deficiency Criteria	Pressure gauge indicates that the fire extinguisher is over or under-charged.
Health and Safety Determination	Life-Threatening

Coursetion Time of wares	24 have	
Correction Timeframe	24 hours	
HCV Correction	24 hours	
Timeframe		
HCV Pass/Fail	Fail	
Rationale	If a fire extinguisher pressure gauge reads over or under-charged, and there is a fire, then the resident may be injured.	
	If a fire extinguisher pressure gauge reads over or under-charged, then the resident may be unable to use a feature that is expected to be provided and maintained as part of their rent.	
	If a fire extinguisher pressure gauge reads over or under-charged, then this should be identified through routine maintenance and the presence of this deficiency may indicate that self-generated work orders are not being addressed.	
	If a fire extinguisher pressure gauge reads over or under-charged, then it may indicate that preventative maintenance activities are not occurring.	

Deficiency 1 – Fire Extinguisher: Outside		
Deficiency	Fire extinguisher pressure gauge reads over or under-charged.	
Deficiency Criteria	Pressure gauge indicates that the fire extinguisher is over or under-charged.	
Health and Safety	Life-Threatening	
Determination		
Correction Timeframe	24 hours	
HCV Correction	24 hours	
Timeframe		
HCV Pass/Fail	Fail	
Rationale	If a fire extinguisher pressure gauge reads over or under-charged, and there is a fire, then the resident may be injured.	
	If a fire extinguisher pressure gauge reads over or under-charged, then the resident may be unable to use a feature that is expected to be provided and maintained as part of their rent.	
	If a fire extinguisher pressure gauge reads over or under-charged, then this should be identified through routine maintenance and the presence of this deficiency may indicate that self-generated work orders are not being addressed.	

If a fire extinguisher pressure gauge reads over or under-charged, then it may indicate that preventative maintenance activities are not occurring.

Deficiency 2 – Fire Extinguisher: Unit		
Deficiency	Fire extinguisher service tag is missing, illegible, or expired.	
Deficiency Criteria	The date on the service tag of any fire extinguisher has exceeded one year.	
	OR	
	The fire extinguisher tag is missing or illegible.	
	OR	
	A nonchargeable or disposable fire extinguisher is more than 12 years old (based on manufacture date).	
Health and Safety Determination	Life-Threatening	
Correction Timeframe	24 hours	
HCV Correction	24 hours	
Timeframe		
HCV Pass/Fail	Fail	
Rationale	If a fire extinguisher service tag is missing, illegible, or expired, and there is a fire, then it may not function and result in the resident being unable to extinguish the fire.	
	If a fire extinguisher service tag is missing, illegible, or expired, then the resident may be unable to use a feature that is expected to be provided and maintained as part of their rent.	
	If a fire extinguisher service tag is missing, illegible, or expired, then this should be identified through routine maintenance, and the presence of this deficiency may indicate that self-generated work orders are not being addressed.	
	If a fire extinguisher service tag is missing, illegible, or expired, then it may indicate that preventative maintenance activities are not occurring.	
Deficiency 2 – Fire Exting	uisher: Inside	
Deficiency	Fire extinguisher service tag is missing, illegible, or expired.	
Deficiency Criteria	The date on the service tag of any fire extinguisher has exceeded one year.	
	OR	
	The fire extinguisher tag is missing or illegible.	

	A nonchargeable or disposable fire extinguisher is more than 12 years old	
	(based on manufacture date).	
Health and Safety	Life-Threatening	
Determination		
Correction Timeframe	24 hours	
HCV Correction	24 hours	
Timeframe		
HCV Pass/Fail	Fail	
Rationale	If a fire extinguisher service tag is missing, illegible, or expired, and there is a fire, then it may not function and result in the resident being unable to extinguish the fire.	
	If a fire extinguisher service tag is missing, illegible, or expired, then the resident may be unable to use a feature that is expected to be provided and maintained as part of their rent.	
	If a fire extinguisher service tag is missing, illegible, or expired, then this should be identified through routine maintenance, and the presence of this deficiency may indicate that self-generated work orders are not being addressed.	
	If a fire extinguisher service tag is missing, illegible, or expired, then it may indicate that preventative maintenance activities are not occurring.	
Deficiency 2 – Fire Exting	guisher: Outside	
Deficiency	Fire extinguisher service tag is missing, illegible, or expired.	
Deficiency Criteria	The date on the service tag of any fire extinguisher has exceeded one year.	
	OR	
	The fire extinguisher tag is missing or illegible.	
	OR	
	A nonchargeable or disposable fire extinguisher is more than 12 years old (based on manufacture date).	
Health and Safety Determination	Life-Threatening	
Correction Timeframe	24 hours	
HCV Correction Timeframe	24 hours	
HCV Pass/Fail	Fail	

Rationale

Deficiency

If a fire extinguisher service tag is missing, illegible, or expired, and there is a fire, then it may not function and result in the resident being unable to extinguish the fire.

If a fire extinguisher service tag is missing, illegible, or expired, then the resident may be unable to use a feature that is expected to be provided and maintained as part of their rent.

If a fire extinguisher service tag is missing, illegible, or expired, then this should be identified through routine maintenance, and the presence of this deficiency may indicate that self-generated work orders are not being addressed.

If a fire extinguisher service tag is missing, illegible, or expired, then it may indicate that preventative maintenance activities are not occurring.

Deficiency	Fire extinguisher is damaged or missing.		
Deficiency Criteria	Fire extinguisher is damaged (i.e., visibly defective; impacts functionality). OR		
	Fire extinguisher is missing (i.e., evidence of prior installation, but now not present or is incomplete).		
Health and Safety	Life-Threatening		
Determination			
Correction Timeframe	24 hours		
HCV Correction	24 hours		
Timeframe			
HCV Pass/Fail	Fail		
Rationale	If a fire extinguisher is damaged or missing and there is a fire, then there may be an increased safety risk to the resident of fire-related injury, such as burns or smoke inhalation.		
	If a fire extinguisher is damaged or missing, then the resident may not be able to use the fire extinguisher in the event of a fire.		
	A resident is likely to notice if a fire extinguisher is damaged or missing and		
	to recognize it is important enough to report to property management		
	because it may present safety hazards. Property management should be		
	expected to prioritize a work order to remedy this defect because it may result in safety hazards.		

Fire extinguisher is damaged or missing.

Deficiency Criteria	Fire extinguisher is damaged (i.e., visibly defective; impacts functionality).	
	OR	
	Fire extinguisher is missing (i.e., evidence of prior installation, but now not	
	present or is incomplete).	
Health and Safety	Life-Threatening	
Determination		
Correction Timeframe	24 hours	
HCV Correction	24 hours	
Timeframe		
HCV Pass/Fail	Fail	
Rationale	If a fire extinguisher is damaged or missing and there is a fire, then there	
	may be an increased safety risk to the resident of fire-related injury, such as	
	burns or smoke inhalation.	
	If a fire extinguisher is damaged or missing, then the resident may not be	
	able to use the fire extinguisher in the event of a fire.	
	Description of the latest and the second of	
	Property management would be expected to ensure that staff understand	
	how to identify if a fire extinguisher is damaged or missing. Management	
	practices would be expected to assure prompt creation and prioritization of	
	a work order to remedy this defect, because it may result in safety hazards	
	or usability barriers.	
Deficiency 3 – Fire Exting	uisher: Outside	
Deficiency	Fire extinguisher is damaged or missing.	
Deficiency Criteria	Fire extinguisher is damaged (i.e., visibly defective; impacts functionality). OR	
	Fire extinguisher is missing (i.e., evidence of prior installation, but now not	
	present or is incomplete).	
Haralda and Cafee		
Health and Safety	Life-Threatening	
Determination		
Correction Timeframe	24 hours	
HCV Correction	24 hours	
Timeframe		
HCV Pass/Fail	Fail	
Rationale	If a fire extinguisher is damaged or missing and there is a fire, then there	
	may be an increased safety risk to the resident of fire-related injury, such as	
	burns or smoke inhalation.	

If a fire extinguisher is damaged or missing, then the resident may not be able to use the fire extinguisher in the event of a fire.

Property management would be expected to ensure that staff understand how to identify if a fire extinguisher is damaged or missing. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this defect, because it may result in safety hazards or usability barriers.

TABLE 23—FLAMMABLE AND COMBUSTIBLE ITEM STANDARD

Definition and Location		
Definition	A combustible material is any material that, in the form in which it is used and under the conditions anticipated, will ignite and burn or will add appreciable heat to an ambient fire.	
Location	Unit: Within Unit, near water heater, furnace, stove, oven, fireplace, garage, attic, basement.	
	Inside: Near water heater, near furnace, stove, oven, fireplace, garage, attic, basement.	
	Outside: Outside of Unit, yard.	

	e and Combustible Item: Unit	
Deficiency	Improperly stored flammable or combustible item on or near an ignition source.	
Deficiency Criteria	Flammable or combustible material is on or near an ignition source.	
	OR	
	Improperly stored chemicals.	
Health and Safety Determination	Life-Threatening	
Correction Timeframe	24 hours	
HCV Correction Timeframe	24 hours	
HCV Pass/Fail	Fail	
Rationale	If flammable or combustible material is on or near an ignition source or chemicals are improperly stored, then the resident could be at risk of fire or explosion.	
	If flammable or combustible material is on or near an ignition source or chemicals are improperly stored, then this should be identified through routine maintenance and the deficiency's presence may indicate that self-generated work orders are not being addressed.	
Deficiency 1 – Flammable	e and Combustible Item: Inside	
Deficiency	Improperly stored flammable or combustible item on or near an ignition source.	
Deficiency Criteria	Flammable or combustible material is on or near an ignition source.	
	OR	
	Improperly stored chemicals.	
Health and Safety	Life-Threatening	
Determination		
Correction Timeframe	24 hours	
HCV Correction	24 hours	
Timeframe		

Rationale

If flammable or combustible material is on or near an ignition source or chemicals are improperly stored, then the resident could be at risk of fire or explosion.

If flammable or combustible material is on or near an ignition source or chemicals are improperly stored, then this should be identified through routine maintenance and the deficiency's presence may indicate that self-generated work orders are not being addressed.

Deficiency 1 – Flammable and Combustible Item: Outside		
Deficiency	Improperly stored flammable or combustible item on or near an ignition	
	source.	
Deficiency Criteria	Flammable or combustible material is on or near an ignition source.	
	OR	
	Improperly stored chemicals.	
Health and Safety	Life-Threatening	
Determination		
Correction Timeframe	24 hours	
HCV Correction	24 hours	
Timeframe		
HCV Pass/Fail	Fail	
Rationale	If flammable or combustible material is on or near an ignition source or chemicals are improperly stored, then the resident could be at risk of fire or explosion.	
	If flammable or combustible material is on or near an ignition source or chemicals are improperly stored, then this should be identified through routine maintenance and the deficiency's presence may indicate that self-generated work orders are not being addressed.	

TABLE 24—FLOOR COVERING AND FINISH STANDARD

Definition and Location	
Definition	Floor: Lower surface of a room.
	Floor Covering or Floor Finish: Any surface material applied over a floor structure to provide a walking surface (e.g., tile, carpet, concrete, wood, vinyl, sealant, paint, stain).

Location Unit: Dining room, living room, kitchen, bathroom, bedroom, closet, hallway, or other unit spaces. Inside: Dining room, living room, kitchen, bathroom, closet, hallway, or other common spaces.

Deficiency 1 – Floor Covering and Finish: Unit		
Deficiency	Floor substrate is exposed.	
Deficiency Criteria	10% or more of the floor substrate area is exposed in any room.	
Health and Safety	Standard	
Determination		
Correction Timeframe	30 days	
HCV Correction	30 days	
Timeframe		
HCV Pass/Fail	Fail	
Rationale	If 10% or more of the floor substrate area is exposed in any room, then it is	

If 10% or more of the floor substrate area is exposed in any room, then it is not a cleanable surface and could harbor pathogens, mold, mildew, dust, or allergens, thereby impacting the resident's physical health.

If 10% or more of the floor substrate area is exposed in any room, then the resident may be injured by splinters or trip hazards.

If 10% or more of the floor substrate area is exposed in any room, then it is not a cleanable covering and could harbor mold, mildew, dust, or allergens.

If 10% or more of the floor substrate area is exposed in any room, then the resident may be unable to fully use a feature of their home that is expected to be provided and maintained as part of their rent.

If 10% or more of the floor substrate area is exposed in any room, then the resident will likely report this deficiency and its presence may indicate that complaint-based work orders are not being addressed.

If 10% or more of the floor substrate area is exposed in any room, then this will likely be observed during routine maintenance activities and may indicate that self-generated work orders are not being addressed.

If 10% or more of the floor substrate area is exposed in any room, and it is occurring across a significant portion of the property, then it may result in a capital cost expenditure to repair the deficiency.

Deficiency 1 – Floor Covering and Finish: Inside		
Deficiency	Floor substrate is exposed.	

Deficiency Criteria	10% or more of the floor substrate area is exposed in any room.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If 10% or more of the floor substrate area is exposed in any room, then it is not a cleanable surface and could harbor pathogens, mold, mildew, dust, or allergens, thereby impacting the resident's physical health.
	If 10% or more of the floor substrate area is exposed in any room, then the resident may be injured via splinters or trip hazards.
	If 10% or more of the floor substrate area is exposed in any room, then it is not a cleanable covering and could harbor mold, mildew, dust, or allergens.
	If 10% or more of the floor substrate area is exposed in any room, then the resident may be unable to fully use a feature of their home that is expected to be provided and maintained as part of their rent.
	If 10% or more of the floor substrate area is exposed in any room, then the resident will likely report this deficiency and its presence may indicate that complaint-based work orders are not being addressed.
	If 10% or more of the floor substrate area is exposed in any room, then this will likely be observed during routine maintenance activities and may indicate that self-generated work orders are not being addressed.
	If 10% or more of the floor substrate area is exposed in any room, and it is occurring across a significant portion of the property, then it may result in a capital cost expenditure to repair the deficiency.

Deficiency 2 – Floor Covering and Finish: Unit	
Deficiency	Floor covering is curling, buckling, bulging, or separating.
Deficiency Criteria	Any portion of the floor covering is curling, buckling, or bulging, resulting in a ¾-inch deviation in elevation.
	OR
	Any portion of the floor covering is curling, buckling, or bulging, resulting in a 2-inch horizontal separation.
Health and Safety	Standard
Determination	

Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the floor covering is curling, buckling, bulging, or separating, then the resident may be exposed to a trip hazard.
	If the floor covering is curling, buckling, bulging, or separating, then the resident will likely report this deficiency and its presence may indicate that complaint-based work orders are not being addressed.
	If the floor covering is curling, buckling, bulging, or separating, then this will likely be observed during routine maintenance activities and may indicate that self-generated work orders are not being addressed.
	If the floor covering is curling, buckling, bulging, or separating, and it is occurring across a significant portion of the property, then it may result in a capital cost expenditure to repair the deficiency.
Deficiency 2 – Floor Cove	ering and Finish: Inside

Deficiency 2 – Floor Cove	•
Deficiency	Floor covering is curling, buckling, bulging, or separating.
Deficiency Criteria	Any portion of the floor covering is curling, buckling, or bulging, resulting in a ¾-inch deviation in elevation.
	OR
	Any portion of the floor covering is curling, buckling, or bulging, resulting in a 2-inch horizontal separation.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the floor covering is curling, buckling, bulging, or separating, then the resident may be exposed to a trip hazard.
	If the floor covering is curling, buckling, bulging, or separating, then the resident will likely report this deficiency and its presence may indicate that complaint-based work orders are not being addressed.

If floor covering is curling, buckling, bulging, or separating, then this will likely be observed during routine maintenance activities and may indicate that self-generated work orders are not being addressed.

If floor covering is curling, buckling, bulging, or separating, and it is occurring across a significant portion of the property, then it may result in a capital cost expenditure to repair the deficiency.

Deficiency	Subfloor is bowing, buckling, bulging, sagging, misaligned, or not attached.
Deficiency Criteria	Subfloor is bowing, buckling, bulging, sagging, or misaligned within any room.
	OR
	More than 10% of the floor area is not attached to the subfloor or floor joists within any room.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the subfloor is bowing, buckling, bulging, sagging, misaligned, or not attached, then the resident may be exposed to a trip hazard.
	If the subfloor is bowing, buckling, bulging, sagging, misaligned, or not attached, and it is in a location the resident normally accesses, then the resident will likely report this deficiency and its presence may indicate that complaint-based work orders are not being addressed.
	If the subfloor is bowing, buckling, bulging, sagging, misaligned, or not attached, then this will likely be observed during routine maintenance activities and may indicate that self-generated work orders are not being addressed.
	If the subfloor is bowing, buckling, bulging, sagging, misaligned, or not attached, and it is occurring across a significant portion of the property, then it may result in a capital cost expenditure to repair the deficiency.
	If the subfloor is bowing, buckling, bulging, sagging, misaligned, or not attached, then it may indicate the presence of a structural failure.

Deficiency 3 – Floor Cove	ering and Finish: Inside
Deficiency	Subfloor is bowing, buckling, bulging, sagging, misaligned, or not attached.
Deficiency Criteria	Subfloor is bowing, bulging, buckling, sagging, or misaligned within any room.
	OR
	More than 10% of the floor area is not attached to the subfloor or floor joists within any room.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the subfloor is bowing, buckling, bulging, sagging, misaligned, or not attached, then the resident may be exposed to a trip hazard.
	If the subfloor is bowing, buckling, bulging, sagging, misaligned, or not attached, and it is in a location the resident normally accesses, then the resident will likely report this deficiency and its presence may indicate that complaint-based work orders are not being addressed.
	If the subfloor is bowing, buckling, bulging, sagging, misaligned, or not attached, then this will likely be observed during routine maintenance activities and may indicate that self-generated work orders are not being addressed.
	If the subfloor is bowing, buckling, bulging, sagging, misaligned, or not attached, and it is occurring across a significant portion of the property, then it may result in a capital cost expenditure to repair the deficiency.
	If the subfloor is bowing, buckling, bulging, sagging, misaligned, or not attached, then it may indicate the presence of a structural failure.
Deficiency 4 – Floor Cove	ering and Finish: Unit
Deficiency	Subfloor has presence of decay.

Deficiency 4 – Floor Covering and Finish: Unit	
Deficiency	Subfloor has presence of decay.
Deficiency Criteria	Greater than 1 square foot of rot or spongy flooring is present.
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours

HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If greater than 1 square foot of rot or spongy flooring is present, then it may harbor pathogens, mold, mildew, dust, or allergens, thereby impacting the resident's physical health.
	If greater than 1 square foot of rot or spongy flooring is present, and the flooring is unstable, then the resident may fall through the floor.
	If greater than 1 square foot of rot or spongy flooring is present, then the resident will likely report this deficiency and its presence may indicate that complaint-based work orders are not being addressed.
	If greater than 1 square foot of rot or spongy flooring is present, then this will likely be observed during routine maintenance activities and may indicate that self-generated work orders are not being addressed.
	If greater than 1 square foot of rot or spongy flooring is present, and it is occurring across a significant portion of the property, then it may result in a capital cost expenditure to repair the deficiency.
	If greater than 1 square foot of rot or spongy flooring is present, then it may indicate the presence of a structural failure.

Deficiency 4 – Floor Covering and Finish: Inside		
Deficiency	Subfloor has presence of decay.	
Deficiency Criteria	Greater than 1 square foot of rot or spongy flooring is present.	
Health and Safety Determination	Severe Non-Life Threatening	
Correction Timeframe	24 hours	
HCV Correction Timeframe	30 days	
HCV Pass/Fail	Fail	
Rationale	If greater than 1 square foot of rot or spongy flooring is present, then it may harbor pathogens, mold, mildew, dust, or allergens, thereby impacting the resident's physical health.	
	If greater than 1 square foot of rot or spongy flooring is present, and the flooring is unstable, then the resident may fall through the floor.	

If greater than 1 square foot of rot or spongy flooring is present, then the resident will likely report this deficiency and its presence may indicate that complaint-based work orders are not being addressed.

If greater than 1 square foot of rot or spongy flooring is present, then this will likely be observed during routine maintenance activities and may indicate that self-generated work orders are not being addressed.

If greater than 1 square foot of rot or spongy flooring is present, and it is occurring across a significant portion of the property, then it may result in a capital cost expenditure to repair the deficiency.

If greater than 1 square foot of rot or spongy flooring is present, then it may indicate the presence of a structural failure.

TABLE 25—FLOOR DRAIN STANDARD

Definition and Location	
Definition	An opening in the floor that drains water into the plumbing system.
Location	Unit: Bathroom, basement, utility room, maintenance closet, laundry, stairwell, etc.
	Inside: Bathroom, basement, utility room, maintenance closet, laundry, stairwell, etc.
Deficiency 1 – Floor Drai	n: Unit
Deficiency	Drain is fully blocked.
Deficiency Criteria	Standing water is present over the floor drain, or the floor drain is blocked such that the inspector believes water would be unable to drain.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If standing water is present over the floor drain or the floor drain is blocked such that the inspector believes water would be unable to drain, this may increase interior moisture levels, which provides an environment favorable for mold growth and may trigger respiratory issues.
	If standing water is present over the floor drain or the floor drain is blocked such that the inspector believes water would be unable to drain, there may

be an increased safety risk to the resident of slipping or falling in the standing water, which may result in injury.

If standing water is present over the floor drain, it may be contaminated with pathogens. The resident may come into contact with this potentially contaminated water, possibly leading to infectious diseases.

A resident is likely to notice standing water within the unit and to recognize it is important enough to report to property management because it may result in damage to personal property. Property management should be expected to prioritize a work order for standing water because it may result in water damage to finish materials.

Deficiency 1 – Floor Drain: Inside		
Deficiency	Drain is fully blocked.	
Deficiency Criteria	Standing water is present over the floor drain, or the floor drain is blocked such that the inspector believes water would be unable to drain.	
Health and Safety Determination	Standard	
Correction Timeframe	30 days	
HCV Correction Timeframe	30 days	
HCV Pass/Fail	Fail	
Rationale	In an area accessible to the resident, if standing water is present over the floor drain or the floor drain is blocked such that the inspector believes water would be unable to drain, this may increase interior moisture levels, which provides an environment favorable for mold growth and may trigger respiratory issues.	
	In an area accessible to the resident, if standing water is present over the floor drain or the floor drain is blocked such that the inspector believes water would be unable to drain, there may be an increased safety risk to the resident of slipping or falling in the standing water, which may result in injury.	
	In an area accessible to the resident, if standing water is present over the floor drain, it may be contaminated with pathogens. The resident may come into contact with this potentially contaminated water, possibly leading to infectious diseases.	
	Property management would be expected to ensure that staff members understand how to identify blockages or standing water over a floor drain within the Inside area. Management practices would be expected to assure prompt creation and prioritization of a work order to unblock the drain,	

because standing water due to a blockage may result in water damage to interior finish materials.

Deficiency 1 – Floor Drain: Outside		
Deficiency	Drain is fully blocked.	
Deficiency Criteria	Standing water is present over the floor drain, or the floor drain is blocked such that the inspector believes water would be unable to drain.	
Health and Safety Determination	Standard	
Correction Timeframe	30 days	
HCV Correction Timeframe	30 days	
HCV Pass/Fail	Fail	
Rationale	In an area accessible to the resident, if standing water is present over the floor drain or the floor drain is blocked such that the inspector believes water would be unable to drain, there may be an increased safety risk to the resident of slipping or falling in the standing water, which may result in injury.	
	In an area accessible to the resident, if standing water is present over the floor drain, it may be contaminated with pathogens. The resident may come into contact with this potentially contaminated water, possibly leading to infectious diseases.	
	Property management would be expected to ensure that staff members understand how to identify blockages or standing water over a floor drain throughout the exterior built environment. Management practices would be expected to assure prompt creation and prioritization of a work order to unblock the drain, because standing water due to a blockage may result in safety or sanitary hazards.	

TABLE 26—FOUNDATION STANDARD

Definition and Loca	ation
Definition	Lowest load-bearing part of a building.
Location	Unit: Basement; floor; wall; ceiling.
	Inside: Basement; floor; wall; ceiling.
	Outside: Exterior of property.

Deficiency 1 – Foundatio	n: Unit
Deficiency	Foundation is cracked.
Deficiency Criteria	Crack is present with a width of ¼-inch or greater and a length of 12 inches
	or greater.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the foundation is cracked, then the structure could be compromised,
	resulting in potential health hazards to the resident.
	If the foundation is cracked, then the structure could be compromised,
	resulting in potential safety hazards to the resident.
	If the foundation is cracked, then the thermal envelope could be broken, resulting in the home being less energy efficient.
	It is reasonable to expect the resident to report issues that are
	characteristics of foundation damage, such as windows and doors not opening or closing.
	Depending on the extent of the damage, the cost may be significant enough to be a capital cost to repair.
	A cracked foundation may indicate a potential structural failure.

Deficiency 1 – Foundation: Inside	
Deficiency	Foundation is cracked.
Deficiency Criteria	Crack is present with a width of ¼-inch or greater and a length of 12 inches or greater.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail

Rationale	If the foundation is cracked, then the structure could be compromised, resulting in potential health hazards to the resident.
	If the foundation is cracked, then the structure could be compromised, resulting in potential safety hazards to the resident.
	It is reasonable to expect the resident to report issues that are characteristics of foundation damage, such as windows and doors not opening or closing.
	Depending on the extent of the damage, the cost may be significant enough to be a capital cost to repair.
	If the foundation is cracked, then the thermal envelope could be broken, resulting in the property being less energy efficient.
	A cracked foundation may indicate a potential structural failure.

Deficiency	Foundation is cracked.
Deficiency Criteria	Crack is present with a width of ¼-inch or greater and a length of 12 inches
	or greater.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the foundation is cracked, then the structure could be compromised,
	resulting in potential health hazards to the resident.
	If the foundation is cracked, then the structure could be compromised,
	resulting in potential safety hazards to the resident.
	It is reasonable to expect facilities management to recognize issues that are
	characteristics of foundation damage, such as windows and doors not
	opening or closing.
	Depending on the extent of the damage, the cost may be significant enough
	to be a capital cost to repair.
	If the foundation is cracked, then the thermal envelope could be broken,
	resulting in the home being less energy efficient.
	A cracked foundation may indicate a potential structural failure.

Deficiency	Foundation vent cover is missing or damaged.
Deficiency	Todination vent cover is missing or damaged.
Deficiency Criteria	Foundation vent cover is missing (i.e., evidence of prior installation, but nov
	not present or is incomplete) or damaged (i.e., visibly defective; impacts
	functionality).
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a foundation vent cover is missing or damaged, then insects or vermin
	may penetrate the dwelling and damage building components (e.g.,
	electrical, insulation), which may result in an increased safety risk to the
	resident of injury, such as electrocution.
	If a foundation vent cover is missing or damaged, then the resident's ability
	to control access may be limited, which may present a security risk.
eficiency 3 – Foundatio	
Deficiency	Foundation has exposed rebar or foundation is spalling, flaking, or chipping.
Deficiency Criteria	The structure has any exposed rebar.
	OR
	Foundation is spalling, flaking, or chipping, and the affected area is 12x12
	inches or greater and goes into the foundation at a depth of ¾-inch or
	greater.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the foundation has exposed rebar or is spalling, flaking, or chipping, then
	it may be a cut hazard to residents.
	If the foundation has exposed rebar or is spalling, flaking, or chipping, this

	presence of this deficiency may indicate that self-generated work orders are not being addressed.
	If the foundation has exposed rebar or is spalling, flaking, or chipping, there may be a structural defect.
Deficiency 3 – Foundatio	n: Inside
Deficiency	Foundation has exposed rebar or foundation is spalling, flaking, or chipping.
Deficiency Criteria	The structure has any exposed rebar.
	OR
	Foundation is spalling, flaking, or chipping, and the affected area is 12x12 inches or greater and goes into the foundation at a depth of ¾-inch or greater.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the foundation has exposed rebar or is spalling, flaking, or chipping, then it may be a cut hazard to residents.
	If the foundation has exposed rebar or is spalling, flaking, or chipping, this should be detected through regular maintenance activities, and the presence of this deficiency may indicate that self-generated work orders are not being addressed.
	If the foundation has exposed rebar or is spalling, flaking, or chipping, there may be a structural defect.
Deficiency 3 – Foundatio	n: Outside
Deficiency	Foundation has exposed rebar or foundation is spalling, flaking, or chipping.
Deficiency Criteria	The structure has any exposed rebar.
	OR
	Foundation is spalling, flaking, or chipping, and the affected area is $12x12$ inches or greater and goes into the foundation at a depth of $\%$ -inch or greater.
Health and Safety Determination	Standard

Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the foundation has exposed rebar or is spalling, flaking, or chipping, then it may be a cut hazard to residents.
	If the foundation has exposed rebar or is spalling, flaking, or chipping, this should be detected through regular maintenance activities, and the presence of this deficiency may indicate that self-generated work orders are not being addressed.
	If the foundation has exposed rebar or is spalling, flaking, or chipping, there may be a structural defect.
Deficiency 4 – Foundation	n: Unit
Deficiency	Foundation is infiltrated by water.
Deficiency Criteria	Evidence of water infiltration through the foundation.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the foundation is infiltrated by water, then there is an increased risk of mold exposure, which could negatively impact air quality.
	If the foundation is infiltrated by water, then the resident may be exposed to an unsanitary environment.
	If the foundation is infiltrated by water, then the resident may be unable to fully use a feature (i.e., sealed foundation) that is expected to be provided and maintained as part of their rent.
	If the foundation is infiltrated by water, then the resident will likely report this deficiency, and the presence of this deficiency may indicate a lack of corrective maintenance.
	If the foundation is infiltrated by water, then this should be identified through routine maintenance and the presence of this deficiency may indicate self-generated work orders are not being addressed.

If the foundation is infiltrated by water, then it may cause the structure to deteriorate.

Deficiency 4 – Foundation: Inside		
Deficiency	Foundation is infiltrated by water.	
Deficiency Criteria	Evidence of water infiltration through the foundation.	
Health and Safety	Standard	
Determination		
Correction Timeframe	30 days	
HCV Correction	30 days	
Timeframe		
HCV Pass/Fail	Fail	
Rationale	If the foundation is infiltrated by water, then there is an increased risk of	
	mold exposure which could negatively impact air quality.	
	If the foundation is infiltrated by water, then the resident may be exposed to an unsanitary environment.	
	If the foundation is infiltrated by water, then the resident may be unable to fully use a feature (i.e., sealed foundation) that is expected to be provided and maintained as part of their rent.	
	If the foundation is infiltrated by water, then the resident will likely report this deficiency, and the presence of this deficiency may indicate a lack of corrective maintenance.	
	If the foundation is infiltrated by water, then this should be identified through routine maintenance, and the presence of this deficiency may indicate self-generated work orders are not being addressed.	
	If the foundation is infiltrated by water, then it may cause the structure to deteriorate.	

Deficiency 5 – Foundation: Unit	
Deficiency	Foundation support post, column, beam, or girder is damaged.
Deficiency Criteria	Any support post, column, or girder area is damaged (i.e., visibly defective; impacts functionality).
Health and Safety	Standard
Determination	
Correction Timeframe	30 days

HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a foundation support post, column, beam, or girder is damaged, then it may cause the structure to become unstable.
	If a foundation support post, column, beam, or girder is damaged, then maintenance should identify it through regular maintenance activities and the presence of this deficiency may indicate self-generated work orders are not being addressed.
	If a foundation support post, column, beam, or girder is damaged, then it could be a sign of a structural issue.
Deficiency 5 – Foundatio	n: Inside
Deficiency	Foundation support post, column, beam, or girder is damaged.
Deficiency Criteria	Any support post, column, or girder area is damaged (i.e., visibly defective; impacts functionality).
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a foundation support post, column, beam, or girder is damaged, then it may cause the structure to become unstable.
	If a foundation support post, column, beam, or girder is damaged, then maintenance should identify this through regular maintenance activities, and the presence of this deficiency may indicate self-generated work orders are not being addressed.
	If a foundation support post, column, beam, or girder is damaged, then it could be a sign of a structural issue.
Deficiency 5 – Foundatio	n: Outside
Deficiency	Foundation support post, column, beam, or girder is damaged.
Deficiency Criteria	Any support post, column, or girder area is damaged (i.e., visibly defective; impacts functionality).

Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a foundation support post, column, beam, or girder is damaged, then it may cause the structure to become unstable.
	If a foundation support post, column, beam, or girder is damaged, then maintenance should identify this through regular maintenance activities and the presence of this deficiency may indicate self-generated work orders are not being addressed.
	If a foundation support post, column, beam, or girder is damaged, then it could be a sign of a structural issue.
Deficiency 6 – Foundatio	n: Unit
Deficiency	Foundation appears to be in imminent danger of collapse or failure.
Deficiency Criteria	The foundation appears to be in imminent danger of collapse or failure.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If the foundation appears to be in imminent danger of collapse or failure, then this could impact the health of the resident.
	If the foundation appears to be in imminent danger of collapse or failure, then the resident may be at a high risk of injury.
	If the foundation appears to be in imminent danger of collapse or failure, then the resident may be unable to fully use a feature that is expected to be provided and maintained as part of their rent.
	If the foundation appears to be in imminent danger of collapse or failure, then the resident will likely report this deficiency, and the presence of the deficiency may indicate a lack of corrective maintenance.

If the foundation appears to be in imminent danger of collapse or failure, then this should be identified through routine maintenance activities, and the presence of the deficiency may indicate self-generated work orders are not being addressed.

If the foundation appears to be in imminent danger of collapse or failure, then this may result in a capital expenditure.

If the foundation appears to be in imminent danger of collapse or failure, then there is a structural failure.

If the foundation appears to be in imminent danger of collapse or failure, then HUD could suffer reputational harm.

eficiency 6 – Foundatio Deficiency	Foundation appears to be in imminent danger of collapse or failure.
Deficiency	roundation appears to be in infinitely danger of collapse of failure.
Deficiency Criteria	The foundation appears to be in imminent danger of collapse or failure.
Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the foundation appears to be in imminent danger of collapse or failure, then this could affect the health of the resident.
	If the foundation appears to be in imminent danger of collapse or failure, then the resident may be at a high risk of injury.
	If the foundation appears to be in imminent danger of collapse or failure,
	then the resident may be unable to fully use a feature that is expected to be provided and maintained as part of their rent.
	If the foundation appears to be in imminent danger of collapse or failure,
	then the resident will likely report this deficiency, and the presence of this deficiency may indicate a lack of corrective maintenance.
	If the foundation appears to be in imminent danger of collapse or failure,
	then this should be identified through routine maintenance activities, and the presence of this deficiency may indicate self-generated work orders are not being addressed.
	If the foundation appears to be in imminent danger of collapse or failure,
	then this may result in a capital expenditure.

If the foundation appears to be in imminent danger of collapse or failure, then there is a structural failure.

If the foundation appears to be in imminent danger of collapse or failure, then HUD could suffer reputational harm.

	then 1100 codia sarier reputational narm.
Deficiency 6 – Foundatio	n: Outside
Deficiency	Foundation appears to be in imminent danger of collapse or failure.
Deficiency Criteria	The foundation appears to be in imminent danger of collapse or failure.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If the foundation appears to be in imminent danger of collapse or failure, then this could affect the health of the resident.
	If the foundation appears to be in imminent danger of collapse or failure, then the resident may be at a high risk of injury.
	If the foundation appears to be in imminent danger of collapse or failure, then the resident may be unable to fully use a feature that is expected to be provided and maintained as part of their rent.
	If the foundation appears to be in imminent danger of collapse or failure, then the resident will likely report this deficiency, and the presence of this deficiency may indicate a lack of corrective maintenance.
	If the foundation appears to be in imminent danger of collapse or failure, then this should be identified through routine maintenance activities, and the presence of this deficiency may indicate self-generated work orders are not being addressed.
	If the foundation appears to be in imminent danger of collapse or failure, then this may result in a capital expenditure.
	If the foundation appears to be in imminent danger of collapse or failure, then there is a structural failure.
	If the foundation appears to be in imminent danger of collapse or failure, then HUD could suffer reputational harm.

TABLE 27—GARAGE DOOR STANDARD

	TABLE 27 GARAGE DOOR STANDARD
Definition and Location	
Definition	A large door on a garage that opens either manually or by an electric motor. Garage doors are frequently large enough to accommodate automobiles and other vehicles. Small garage doors may be constructed as a single panel that tilts up and back across the garage ceiling.
Location	Unit: Attached or detached garage.
	Inside: Attached or detached garage.
	Outside: Attached or detached garage.
Deficiency 1 – Garage Do	oor: Unit
Deficiency	Garage door has a hole.
Deficiency Criteria	Garage door has a hole of any size that penetrates through to the interior.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the garage door has a hole of any size that penetrates through to the interior, then the resident may be unable to control access to their personal property.
	If the garage door has a hole of any size that penetrates through to the interior, then it is likely the resident will report this deficiency and its presence may indicate complaint-based work orders are not being addressed.
	If the garage door has a hole of any size that penetrates through to the interior, then it is likely to be observed during routine maintenance activities and its presence may indicate that self-generated work orders are not being addressed.
Deficiency 1 – Garage Do	oor: Inside
Deficiency	Garage door has a hole.
Deficiency Criteria	Garage door has a hole of any size that penetrates through to the interior.
Health and Safety Determination	Standard

Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the garage door has a hole of any size that penetrates through to the interior, then the resident may be unable to control access to their personal property.
	If the garage door has a hole of any size that penetrates through to the interior, then it is likely the resident will report this deficiency and its presence may indicate complaint-based work orders are not being addressed.
	If the garage door has a hole of any size that penetrates through to the interior, then it is likely to be observed during routine maintenance activities and its presence may indicate that self-generated work orders are not being addressed.

Deficiency 1 – Garage Do	or: Outside
Deficiency	Garage door has a hole.
Deficiency Criteria	Garage door has a hole of any size that penetrates through to the interior.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the garage door has a hole of any size that penetrates through to the interior, then the resident may be unable to control access to their personal property.
	If the garage door has a hole of any size that penetrates through to the interior, then it is likely the resident will report this deficiency and its presence may indicate complaint-based work orders are not being addressed.
	If the garage door has a hole of any size that penetrates through to the interior, then it is likely to be observed during routine maintenance activities and its presence may indicate that self-generated work orders are not being addressed.

Garage door does not open, close, or remain open or closed.
Door will not open and remain open.
OR
Door will not close and remain closed.
Standard
30 days
30 days
Fail
If the garage door does not open and remain open or close and remain closed, then the resident may be exposed to associated hazards (e.g., the door closing on them).
If the garage door does not close or remain closed, then the resident may be unable to control access to their personal property.
If the garage door does not open and remain open or close and remain closed, then it is likely the resident will report this deficiency and its presence may indicate complaint-based work orders are not being addressed.
If the garage door does not open and remain open or close and remain closed, then it is likely to be observed during routine maintenance activities and its presence may indicate that self-generated work orders are not being addressed.
or: Inside
Garage door does not open, close, or remain open or closed.

Deficiency 2 – Garage Door: Inside	
Deficiency	Garage door does not open, close, or remain open or closed.
Deficiency Criteria	Door will not open and remain open.
	OR
	Door will not close and remain closed.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	

HCV Pass/Fail	Fail
Rationale	If the garage door does not open and remain open or close and remain closed, then the resident may be exposed to associated hazards (e.g., the door closing on them).
	If the garage door does not close or remain closed, then the resident may be unable to control access to their personal property.
	If the garage door does not open and remain open or close and remain closed, then it is likely the resident will report this deficiency and its presence may indicate complaint-based work orders are not being addressed.
	If the garage door does not open and remain open or close and remain closed, then it is likely to be observed during routine maintenance activities and its presence may indicate that self-generated work orders are not being addressed.
Deficiency 2 – Garage Do	or: Outside
Deficiency	Garage door does not open, close, or remain open or closed.
Deficiency Criteria	Door will not open and remain open.
	OR
	Door will not close and remain closed.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the garage door does not open and remain open or close and remain closed, then the resident may be exposed to associated hazards (e.g., the door closing on them).
	If the garage door does not close or remain closed, then the resident may be unable to control access to their personal property.
	If the garage door does not open and remain open or close and remain closed, then it is likely the resident will report this deficiency and its presence may indicate complaint-based work orders are not being addressed.

If the garage door does not open and remain open or close and remain closed, then it is likely to be observed during routine maintenance activities and its presence may indicate that self-generated work orders are not being addressed.

TABLE 28—GRAB BAR STANDARD

Definition and Location	
Definition	Safety device designed to be grasped and enable a person to maintain balance.
Location	Unit: Bathroom.
	Inside: Bathroom.
Deficiency 1 – Grab Bar:	Unit
Deficiency	Grab bar is not secure.
Deficiency Criteria	Any movement whatsoever is detected in the grab bar.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If any movement whatsoever is detected in the grab bar, and the resident grabs it for stability, then they may fall and be injured.
	If any movement whatsoever is detected in the grab bar, then resident may be unable to use a fixture that is expected to be provided and maintained as part of their rent.
	If any movement whatsoever is detected in the grab bar, then the resident will likely report the deficiency and its presence may indicate that complaint-based work orders are not being addressed.
	If any movement whatsoever is detected in the grab bar, then it should be identified through routine maintenance activities and the deficiency's presence may indicate that self-generated work orders are not being addressed.
Deficiency 1 – Grab Bar:	Inside
Deficiency	Grab bar is not secure.

Deficiency Criteria	Any movement whatsoever is detected in the grab bar.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If any movement whatsoever is detected in the grab bar, and the resident grabs it for stability, then they may fall and be injured.
	If any movement whatsoever is detected in the grab bar, then the resident may be unable to use a fixture that is expected to be provided and maintained as part of their rent.
	If any movement whatsoever is detected in the grab bar, then the resident will likely report the deficiency and its presence may indicate that complaint-based work orders are not being addressed.
	If any movement whatsoever is detected in the grab bar, then it should be identified through routine maintenance activities and the deficiency's presence may indicate that self-generated work orders are not being addressed.

TABLE 29—GRAFFITI STANDARD

Definition	Any unapproved or unauthorized text, images, or symbols that are penned,
Deminion	painted, sprayed, or scratched on any permanent surface or structure of the
	property.
Location	Inside: Hallways, stairwells, mechanical rooms, community rooms, offices,
	storage areas, entryways, walls, floors, ceilings, doors.
	Outside: Decks, patios, detached buildings, walls, floors, fences, sidewalks,
	balconies, doors.
Deficiency 1 – Graffiti:	Inside
Deficiency	Graffiti is present.
Deficiency Criteria	On one wall, graffiti is present and cumulatively equals 1 square foot or
	greater.
	OR

	Graffiti is determined to be obscene, vulgar, inappropriate, or offensive.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If graffiti is present, then the resident's mental health and emotional well-being may be harmed.
	If graffiti is present, then the resident will likely report it and its presence may indicate that complaint-based work orders are not being addressed.
	If graffiti is present, then it should be identified through routine maintenance activities and the deficiency's presence may indicate that self-generated work orders are not being addressed.
	If graffiti is present, then a visitor will likely see this, and it will influence their opinion of the property.

Deficiency 1 – Graffiti: Outside		
Deficiency	Graffiti is present.	
Deficiency Criteria	On one wall, graffiti is present and cumulatively equals 1 square foot or greater.	
	OR	
	Graffiti is determined to be obscene, vulgar, inappropriate, or offensive.	
Health and Safety	Standard	
Determination		
Correction Timeframe	30 days	
HCV Correction Timeframe	30 days	
HCV Pass/Fail	Fail	
Rationale	If graffiti is present, then the resident's mental health and emotional wellbeing may be harmed.	
	If graffiti is present, then the resident will likely report it and its presence may indicate that complaint-based work orders are not being addressed.	

If graffiti is present, then it should be identified through routine
maintenance activities and the deficiency's presence may indicate that self-
generated work orders are not being addressed.
If graffiti is present, then a visitor will likely see this, and it will influence
their opinion of the property.

TABLE 30—GUARDRAIL STANDARD

Definition and Location	
Definition	A barrier along an open, raised walking surface.
Location	Unit: All accessible walking surfaces within the dwelling and those areas to which the resident has sole access (e.g., dwelling balconies, stairs, ramps, decks, hallways).
	Inside: All accessible walking surfaces within the interior common spaces (e.g., stairs, ramps, hallways).
	Outside: All accessible walking surfaces (e.g., balconies, stairs, ramps, decks, rooftops, retaining walls) throughout the exterior built environment (i.e., human-made structures, features, and facilities).
Deficiency 1 – Guardrail:	Unit
Deficiency	Guardrail is missing or not installed.
Deficiency Criteria	The guardrail is missing (i.e., evidence of prior installation, but is now not present or is incomplete) or not installed (i.e., never installed, but should have been) along a walking surface that is more than 30 inches above the floor or grade below.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If a guardrail is missing or not installed along a walking surface that is more than 30 inches above the floor or grade below, then there may be an increased safety risk to the resident of fall hazards, which may result in injury or death.
	A resident is likely to notice if a guardrail is missing or not installed along a walking surface that is more than 30 inches above the floor or grade below

and to recognize it is important enough to report to property management because it may present safety hazards. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in safety hazards.

Deficiency 1 – Guardrail:	Inside
Deficiency	Guardrail is missing or not installed.
Deficiency Criteria	The guardrail is missing (i.e., evidence of prior installation, but is now not present or is incomplete) or not installed (i.e., never installed, but should have been) along a walking surface that is more than 30 inches above the floor or grade below.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If a guardrail is missing or not installed along a walking surface that is more than 30 inches above the floor or grade below, then there may be an increased safety risk to the resident of fall hazards, which may result in injury or death. Property management would be expected to ensure that staff members understand how to identify if a guardrail is missing or not installed along a walking surface that is more than 30 inches above the floor or grade below.
	Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards.
Deficiency 1 – Guardrail:	Outside
Deficiency	Guardrail is missing or not installed.
Deficiency Criteria	The guardrail is missing (i.e., evidence of prior installation, but is now not present or is incomplete) or not installed (i.e., never installed, but should have been) along a walking surface that is more than 30 inches above the floor or grade below.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours

HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If a guardrail is missing or not installed along a walking surface that is more than 30 inches above the floor or grade below, then there may be an increased safety risk to the resident of fall hazards, which may result in injury or death.
	Property management would be expected to ensure that staff members understand how to identify if a guardrail is missing or not installed along a walking surface that is more than 30 inches above the floor or grade below Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards.
eficiency 2 – Guardrail:	
Deficiency	Guardrail component(s) missing and the guardrail is functionally adequate.
Deficiency Criteria	Guardrail component(s) missing (i.e., evidence of prior installation, but now is not present or is incomplete) and the guardrail is functionally adequate (i.e., protecting from fall hazards along balconies, stairs, ramps, decks, rooftops, hallways, retaining walls, and other walking surfaces).
Health and Safety Determination	Advisory
Correction Timeframe	Advisory
HCV Correction Timeframe	Advisory
HCV Pass/Fail	Pass
Rationale	Property management would be expected to ensure that staff members understand how to identify a guardrail component that is missing. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may lead to continued deterioration of the guardrail.
Deficiency 2 – Guardrail:	Inside
Deficiency	Guardrail component(s) missing and the guardrail is functionally adequate.
Deficiency Criteria	Guardrail component(s) missing (i.e., evidence of prior installation, but now is not present or is incomplete) and the guardrail is functionally adequate (i.e., protecting from fall hazards along balconies, stairs, ramps, decks, rooftops, hallways, retaining walls, and other walking surfaces).

Health and Safety	Advisory
Determination	
Correction Timeframe	Advisory
HCV Correction	Advisory
Timeframe	
HCV Pass/Fail	Pass
Rationale	Property management would be expected to ensure that staff members understand how to identify a guardrail component that is missing.
	Management practices would be expected to assure prompt creation and
	prioritization of a work order to remedy this deficiency, because it may lead
	to continued deterioration of the guardrail.
Deficiency 2 – Guardrail:	Outside
Deficiency	Guardrail component(s) missing and the guardrail is functionally adequate.
Deficiency Criteria	Guardrail component(s) missing (i.e., evidence of prior installation, but now
	is not present or is incomplete) and the guardrail is functionally adequate
	(i.e., protecting from fall hazards along balconies, stairs, ramps, decks,
	rooftops, hallways, retaining walls, and other walking surfaces).
Health and Safety Determination	Advisory
Correction Timeframe	Advisory
HCV Correction	Advisory
Timeframe	
HCV Pass/Fail	Pass
Rationale	Property management would be expected to ensure that staff members
	understand how to identify a guardrail component that is missing.
	Management practices would be expected to assure prompt creation and
	prioritization of a work order to remedy this deficiency, because it may lead
	to continued deterioration of the guardrail.
Deficiency 3 – Guardrail:	Unit
Deficiency	Guardrail anchor or fastener is not secure and the guardrail is functionally adequate.
Definien en Cuitenie	There is movement at the guardrail anchor or fastener and the guardrail is
Deficiency Criteria	There is movement at the guardran anchor of fasterier and the guardran is
Deficiency Criteria	functionally adequate (i.e., protecting from fall hazards along balconies,
Deficiency Criteria	-

Health and Safety Determination	Advisory
Correction Timeframe	Advisory
HCV Correction	Advisory
Timeframe	
HCV Pass/Fail	Pass
Rationale	Property management would be expected to ensure that staff members understand how to identify any movement at the guardrail anchor or fastener. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may lead to continued deterioration of the guardrail.
Deficiency 3 – Guardrail:	Inside
Deficiency	Guardrail anchor or fastener is not secure and the guardrail is functionally adequate.
Deficiency Criteria	There is movement at the guardrail anchor or fastener and the guardrail is functionally adequate (i.e., protecting from fall hazards along balconies, stairs, ramps, decks, rooftops, hallways, retaining walls, and other walking surfaces).
Health and Safety Determination	Advisory
Correction Timeframe	Advisory
HCV Correction Timeframe	Advisory
HCV Pass/Fail	Pass
Rationale	Property management would be expected to ensure that staff members understand how to identify any movement at the guardrail anchor or fastener. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may lead to continued deterioration of the guardrail.
Deficiency 3 – Guardrail:	Outside
Deficiency	Guardrail anchor or fastener is not secure and the guardrail is functionally adequate.
Deficiency Criteria	There is movement at the guardrail anchor or fastener and the guardrail is functionally adequate (i.e., protecting from fall hazards along balconies, stairs, ramps, decks, rooftops, hallways, retaining walls, and other walking surfaces).

Health and Safety Determination	Advisory
Correction Timeframe	Advisory
HCV Correction	Advisory
Timeframe	
HCV Pass/Fail	Pass
Rationale	Property management would be expected to ensure that staff members understand how to identify any movement at the guardrail anchor or fastener. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may lead to continued deterioration of the guardrail.
Deficiency 4 – Guardrail:	Unit
Deficiency	Guardrail is not functionally adequate.
Deficiency Criteria	Guardrail is missing functional component(s) (i.e., a component that is critical to the guardrail protecting from fall hazards).
	OR
	Guardrail is damaged (i.e., visibly defective; impacts functionality).
	OR
	Guardrail is less than 30 inches in height.
	OR
	Guardrail is not securely attached and cannot reasonably protect from fall hazards.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If a guardrail is missing functional component(s), damaged, less than 30 inches in height, or not securely attached, there may be an increased safety risk to the resident of falling from a walking surface, which may result in injury or death.
	Property management would be expected to ensure that staff members understand how to identify a guardrail that is missing functional component(s), damaged, less than 30 inches in height, or not securely

attached. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may lead to safety hazards.

Deficiency	Guardrail is not functionally adequate.
Deficiency Criteria	Guardrail is missing functional component(s) (i.e., a component that is critical to the guardrail protecting from fall hazards).
	OR
	Guardrail is damaged (i.e., visibly defective; impacts functionality).
	OR
	Guardrail is less than 30 inches in height.
	OR
	Guardrail is not securely attached and cannot reasonably protect from fall hazards.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If a guardrail is missing functional component(s), damaged, less than 30 inches in height, or not securely attached, there may be an increased safety risk to the resident of falling from a walking surface, which may result in injury or death.
	Property management would be expected to ensure that staff members understand how to identify a guardrail that is missing functional component(s), damaged, less than 30 inches in height, or not securely attached. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may lead to safety hazards.
Peficiency 4 – Guardrail:	Outside
Deficiency	Guardrail is not functionally adequate.
Deficiency Criteria	Guardrail is missing functional component(s) (i.e., a component that is critical to the guardrail protecting from fall hazards).
	OR

	Guardrail is damaged (i.e., visibly defective; impacts functionality).
	OR
	Guardrail is less than 30 inches in height.
	OR
	Guardrail is not securely attached and cannot reasonably protect from fall hazards.
Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a guardrail is missing functional component(s), damaged, less than 30 inches in height, or not securely attached, there may be an increased safety risk to the resident of falling from a walking surface, which may result in injury or death.
	Property management would be expected to ensure that staff members understand how to identify a guardrail that is missing functional component(s), damaged, less than 30 inches in height, or not securely attached. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may lead to safety hazards.

TABLE 31—HANDRAIL STANDARD

Definition	A rail fixed to posts or a wall for people to hold on to for support.
Location	Unit: Stairs, hallways, ramps.
	Inside: Stairs, hallways, ramps, elevators.
	Outside: Stairs, ramps, elevators.
Deficiency 1 – Handrai	l: Unit
Deficiency	Handrail is missing or not installed.
Deficiency Criteria	Handrail is missing (i.e., evidence of prior installation, but now not present or is incomplete) or not installed.

Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a handrail is missing, then there is an increased probability of falls that may lead to injury.
	If a handrail is missing, then the resident is unable to use a feature that is expected to be provided and maintained as part of their rent.
	If a handrail is missing, then it is likely to be observed during daily maintenance activities, and the presence of this deficiency may indicate that self-generated work orders are not being addressed.
eficiency 1 – Handrail: I	nside
Deficiency	Handrail is missing.
Deficiency Criteria	Handrail is missing (i.e., evidence of prior installation, but now not present
	or is incomplete).
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction Timeframe	30 days

Deficiency Criteria	Handrail is missing (i.e., evidence of prior installation, but now not present or is incomplete).
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a handrail is missing, then there is an increased probability of falls that may lead to injury.
	If a handrail is missing, then the resident is unable to use a feature that is expected to be provided and maintained as part of their rent.
	If a handrail is missing, then it is likely to be observed during daily maintenance activities, and the presence of this deficiency may indicate that self-generated work orders are not being addressed.

Deficiency 1 – Handrail: Outside	
Deficiency	Handrail is missing.
Deficiency Criteria	Handrail is missing (i.e., evidence of prior installation, but now not present or is incomplete).

Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a handrail is missing, then there is an increased probability of falls that may lead to injury.
	If a handrail is missing, then the resident is unable to use a feature that is
	expected to be provided and maintained as part of their rent.
	If a handrail is missing, then it is likely to be observed during daily maintenance activities, and the presence of this deficiency may indicate that self-generated work orders are not being addressed.
Deficiency 2 – Handrail:	Unit
Deficiency	Handrail is not secure.
Deficiency Criteria	There is movement in the anchors of the handrail.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a handrail is not secure, then there is an increased probability of falls that may lead to injury.
	If a handrail is not secure, then the resident will likely report this deficiency, and its presence may indicate that complaint-based work orders are not being addressed.
	If a handrail is not secure, then it is likely to be observed during daily maintenance activities, and the presence of this deficiency may indicate that self-generated work orders are not being addressed.
Deficiency 2 – Handrail:	
Deficiency 2 – Handrail.	Handrail is not secure.
Deficiency Criteria	There is movement in the anchors of the handrail.
,	

Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a handrail is not secure, then there is an increased probability of falls that may lead to injury.
	If a handrail is not secure, then the resident will likely report this deficiency and its presence may indicate that complaint-based work orders are not being addressed.
	If a handrail is not secure, then it is likely to be observed during daily maintenance activities, and the presence of this deficiency may indicate that self-generated work orders are not being addressed.
Deficiency 2 – Handrail: (Outside
Deficiency	Handrail is not secure.
Deficiency Criteria	There is movement in the anchors of the handrail.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a handrail is not secure, then there is an increased probability of falls that may lead to injury.
	If a handrail is not secure, then the resident will likely report this deficiency and its presence may indicate that complaint-based work orders are not being addressed.
	If a handrail is not secure, then it is likely to be observed during daily maintenance activities, and the presence of this deficiency may indicate that self-generated work orders are not being addressed.
Deficiency 3 – Handrail: l	Jnit
Deficiency	Handrail is not functionally adequate.

Deficiency Criteria	Handrail is not functionally adequate (i.e., it cannot reasonably be grasped by hand to provide stability or support when ascending or descending stairways).
	OR
	Handrail is not continuous for the full length of each stair flight.
	OR
	Handrail is not between 28 inches and 42 inches in height.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a handrail is not functionally adequate or not continuous for the full length of each stair flight, or not between 28 inches and 42 inches in height, there may be an increased safety risk to the resident of falling down a staircase, which may result in injury.
Deficiency 3 – Handrail: I	nside
Deficiency	Handrail is not functionally adequate.
Deficiency Criteria	Handrail is not functionally adequate (i.e., it cannot reasonably be grasped by hand to provide stability or support when ascending or descending stairways).
	OR
	Handrail is not continuous for the full length of each stair flight.
	OR
	Handrail is not between 28 inches and 42 inches in height.
Health and Safety Determination	Standard
Correction Timeframe	30 days
Correction rimename	
HCV Correction Timeframe	30 days

Rationale	If a handrail is not functionally adequate or not continuous for the full
	length of each stair flight, or not between 28 inches and 42 inches in height,
	there may be an increased safety risk to the resident of falling down a
	staircase, which may result in injury.
Deficiency 3 – Handrail: (Outside
Deficiency	Handrail is not functionally adequate.
Deficiency Criteria	Handrail is not functionally adequate (i.e., it cannot reasonably be grasped by hand to provide stability or support when ascending or descending stairways).
	OR
	Handrail is not continuous for the full length of each stair flight.
	OR
	Handrail is not between 28 inches and 42 inches in height.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a handrail is not functionally adequate or not continuous for the full length of each stair flight, or not between 28 inches and 42 inches in height, there may be an increased safety risk to the resident of falling down a staircase, which may result in injury.

TABLE 32—HEATING, VENTILATION, AND AIR CONDITIONING (HVAC) STANDARD

Definition and Location	
Definition	<u>Heating</u> : A system consisting of a heat source and method of distribution designed to heat the surrounding air and area.
	<u>Ventilation</u> : A method of air distribution by air ducts to transfer air from one location to another. Air can be distributed passively or forced.
	<u>Air Conditioning</u> : A system consisting of a cooling source and method of distribution designed to cool the surrounding air and area.
Location	Unit: Living room, bedroom, kitchen, bathroom, closet.

	Inside: Any indoor common area (e.g., hall, bath, kitchen, office, exercise room, etc.).
Deficiency 1 – Heating, V	Pentilation, and Air Conditioning (HVAC): Unit
Deficiency	A permanently installed heating source is damaged, inoperable, missing, or not installed and the outside temperature is below 68 degrees Fahrenheit.
Deficiency Criteria	A permanently installed heating source is damaged (i.e., visibly defective; impacts functionality). OR
	A permanently installed heating source is inoperable (i.e., not meeting function or purpose, with or without visible damage). OR
	A permanently installed heating source is missing (i.e., evidence of prior installation, but is now not present or is incomplete). OR
	A permanently installed heating source is not installed. AND
	The outside temperature is below 68 degrees Fahrenheit.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If a permanently installed heating source is damaged, inoperable, missing, or not installed and the outside temperature is below 68 degrees Fahrenheit, then the resident's body may lose heat faster than it can make it, leading to symptoms of hypothermia, which may result in unconsciousness or death.
	If a permanently installed heating source is damaged, inoperable, missing, or not installed and the outside temperature is below 68 degrees Fahrenheit, and the resident uses an unsafe heating source (e.g., space heater, oven, or open fire), then there may be an increased safety risk to the resident.
	If a permanently installed heating source is damaged, inoperable, missing, or not installed and the outside temperature is below 68 degrees Fahrenheit, then the resident may be unable to use the appliance to safely heat the unit.
	A resident is likely to notice if a permanently installed heating source is damaged, inoperable, missing, or not installed and the outside temperature

is below 68 degrees Fahrenheit and to recognize it is important enough to report to property management because it may present health or safety hazards. Property management should be expected to prioritize a work order to remedy this defect because it may result in health or safety hazards.

Deficiency 1 – Heating, V	Pentilation, and Air Conditioning (HVAC): Inside
Deficiency	A permanently installed heating source is damaged, inoperable, missing, or
	not installed and the outside temperature is below 68 degrees Fahrenheit.
Deficiency Criteria	A permanently installed heating source is damaged (i.e., visibly defective;
	impacts functionality).
	OR
	A permanently installed heating source is inoperable (i.e., not meeting
	function or purpose, with or without visible damage).
	OR
	A permanently installed heating source is missing (i.e., evidence of prior
	installation, but is now not present or is incomplete).
	OR
	A permanently installed heating source is not installed.
	AND
	The outside temperature is below 68 degrees Fahrenheit.
Health and Safety	Advisory
Determination	
Correction Timeframe	Advisory
HCV Correction	Advisory
Timeframe	
HCV Pass/Fail	Pass
Rationale	If a permanently installed heating source is damaged, inoperable, missing,
	or not installed and the outside temperature is below 68 degrees
	Fahrenheit, then the resident may be unable to use a feature that is
	reasonably assumed to be part of their rent.
	Property management would be expected to ensure that staff understand
	how to identify a permanently installed heating source that is damaged,
	inoperable, missing, or not installed and the outside temperature is below
	68 degrees Fahrenheit. Management practices would be expected to
	assure prompt creation and prioritization of a work order to remedy this
	defect, because it may result in usability barriers.
Deficiency 2 – Heating, V	entilation, and Air Conditioning (HVAC): Unit
Deficiency	A permanently installed heating source is damaged, inoperable, missing, or
-	not installed and the outside temperature is 68 degrees Fahrenheit or
	above.

A permanently installed heating source is damaged (i.e., visibly defective; impacts functionality).
OR
A permanently installed heating source is inoperable (i.e., not meeting function or purpose, with or without visible damage). OR
A permanently installed heating source is missing (i.e., evidence of prior installation, but is now not present or is incomplete). OR
A permanently installed heating source is not installed. AND
The outside temperature is 68 degrees Fahrenheit or above.
Advisory
Advisory
Advisory
Pass
If a permanently installed heating source is damaged, inoperable, missing, or not installed and the outside temperature is 68 degrees Fahrenheit or above, then the resident may be unable to use the appliance to safely heat the unit.
A resident is likely to notice if a permanently installed heating source is damaged, inoperable, missing, or not installed and the outside temperature is 68 degrees Fahrenheit or above and to recognize it is important enough to report to property management because it may present usability barriers. Property management should be expected to prioritize a work order to remedy this defect because it may result in usability barriers.
entilation, and Air Conditioning (HVAC): Inside
A permanently installed heating source is damaged, inoperable, missing, or not installed and the outside temperature is 68 degrees Fahrenheit or above.
A permanently installed heating source is damaged (i.e., visibly defective; impacts functionality). OR A permanently installed heating source is inoperable (i.e., not meeting function or purpose, with or without visible damage). OR A permanently installed heating source is missing (i.e., evidence of prior installation, but is now not present or is incomplete). OR

	A permanently installed heating source is not installed. AND
	The outside temperature is 68 degrees Fahrenheit or above.
Health and Safety Determination	Advisory
Correction Timeframe	Advisory
HCV Correction Timeframe	Advisory
HCV Pass/Fail	Pass
Rationale	If a permanently installed heating source is damaged, inoperable, missing, or not installed and the outside temperature is 68 degrees Fahrenheit or above, then the resident may be unable to use the appliance to safely heat the unit.
	Property management would be expected to ensure that staff understand how to identify a permanently installed heating source that is damaged, inoperable, missing, or not installed and the outside temperature is 68 degrees Fahrenheit or above. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this defect, because it may result in usability barriers.
Deficiency 3 – Heating, V	entilation, and Air Conditioning (HVAC): Unit
Deficiency	Air conditioning system or device is not operational.
Deficiency Criteria	System or device does not turn on. OR
	System or device only produces hot or room temperature air.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail

Rationale If the air conditioning system or device does not turn on or it only produces hot or room temperature air, then the resident may be at an increased risk of heat-related illness. If the air conditioning system or device does not turn on or it only produces hot or room temperature air, then the resident may be unable to utilize the appliance. The resident is likely to notice if the air conditioning system or device does not turn on or it only produces hot or room temperature air and to recognize it is important enough to report it to property management because it may present health hazards or usability barriers. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in health hazards. Deficiency 3 – Heating, Ventilation, and Air Conditioning (HVAC): Inside Deficiency Air conditioning system or device is not operational. **Deficiency Criteria** System or device does not turn on. OR System or device only produces hot or room temperature air. **Health and Safety** Advisory **Determination Correction Timeframe** Advisory **HCV Correction** Advisory Timeframe **HCV Pass/Fail** Pass Rationale If the air conditioning system or device does not turn on or it only produces hot or room temperature air, then the resident may be unable to utilize the

Property management would be expected to ensure that staff members understand how to identify an air conditioning system or device that does not turn on or only produces hot or room temperature air. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in usability

Deficiency 4 - Heating, Ventilation, and Air Conditioning (HVAC): Unit

appliance.

barriers.

Deficiency	Heating system or device fueled by combustion has a misaligned, disconnected, improperly connected, damaged, blocked, or missing exhaust vent.
Deficiency Criteria	Exhaust vent is misaligned, blocked, disconnected, or improperly connected through to the ceiling or wall.
	OR
	Exhaust vent is damaged (i.e., visibly defective; impacts functionality).
	OR
	Exhaust vent is missing (i.e., evidence of prior installation, but now not present or is incomplete).
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If the heating system or device fueled by combustion has a misaligned, disconnected, improperly connected, damaged, blocked, or missing exhaust vent, then the resident may be exposed to carbon monoxide leaks, which may cause health issues.
	If the heating system or device fueled by combustion has a misaligned, disconnected, improperly connected, damaged, blocked, or missing exhaust vent, then the resident could be exposed to carbon monoxide, which may cause safety issues.
	If the heating system or device fueled by combustion has a misaligned, disconnected, improperly connected, damaged, blocked, or missing exhaust vent, then it should be identified during preventative maintenance activities, and the presence of this deficiency may indicate that self-generated work orders are not being addressed.
Deficiency 4 – Heating, V	entilation, and Air Conditioning (HVAC): Inside
Deficiency	Heating system or device fueled by combustion has a misaligned, disconnected, improperly connected, damaged, blocked, or missing exhaust vent.
Deficiency Criteria	Exhaust vent is misaligned, blocked, disconnected, or improperly connected through to the ceiling or wall.
	OR

	Exhaust vent is damaged (i.e., visibly defective; impacts functionality).
	OR
	Exhaust vent is missing (i.e., evidence of prior installation, but now not present or is incomplete).
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If the heating system or device fueled by combustion has a misaligned, disconnected, improperly connected, damaged, blocked, or missing exhaust vent, then the resident may be exposed to carbon monoxide leaks, which may cause health issues.
	If the heating system or device fueled by combustion has a misaligned, disconnected, improperly connected, damaged, blocked, or missing exhaust vent, then the resident could be exposed to carbon monoxide, which may cause safety issues.
	If the heating system or device fueled by combustion has a misaligned, disconnected, improperly connected, damaged, blocked, or missing exhaust vent, then it should be identified during preventative maintenance activities, and the presence of this deficiency may indicate that self-generated work orders are not being addressed.
Deficiency 5 – Heating, V	entilation, and Air Conditioning (HVAC): Unit
Deficiency	Combustion chamber cover or gas shutoff valve is missing from a combustion-fueled heating appliance.
Deficiency Criteria	Combustion chamber cover or gas shutoff valve is missing (i.e., evidence of prior installation, but is now not present or is incomplete) from a combustion-fueled heating appliance.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail

Rationale

If a combustion chamber cover or gas shutoff valve is missing from a combustion-fueled heating appliance, and there is a need to isolate the appliance, there may be an increased safety risk to the resident of fire, which may result in injury (e.g., burns) or death.

If a combustion chamber cover or gas shutoff valve is missing from a combustion-fueled heating appliance, then the resident may not be able to safely isolate the appliance in the event of a malfunction.

Property management would be expected to ensure that staff members understand how to identify a combustion chamber cover or gas shutoff valve that is missing from a combustion-fueled heating appliance.

Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards or usability barriers.

	· · · · · · · · · · · · · · · · · · ·
Deficiency 5 – Heating, Ve	entilation, and Air Conditioning (HVAC): Inside
Deficiency	Combustion chamber cover or gas shutoff valve is missing from a
	combustion-fueled heating appliance.
Deficiency Criteria	Combustion chamber cover or gas shutoff valve is missing (i.e., evidence of
	prior installation, but is now not present or is incomplete) from a
	combustion-fueled heating appliance.
Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a combustion chamber cover or gas shutoff valve is missing from a
	combustion-fueled heating appliance, and there is a need to isolate the
	appliance, there may be an increased safety risk to the resident of fire,
	which may result in injury (e.g., burns) or death.
	If a combustion chamber cover or gas shutoff valve is missing from a
	combustion-fueled heating appliance, then the resident may not be able to
	safely isolate the appliance in the event of a malfunction.
	Property management would be expected to ensure that staff members
	understand how to identify a combustion chamber cover or gas shutoff
	valve that is missing from a combustion-fueled heating appliance.
	Management practices would be expected to assure prompt creation and
	Property management would be expected to ensure that staff mem understand how to identify a combustion chamber cover or gas shurvalve that is missing from a combustion-fueled heating appliance.

prioritization of a work order to remedy this deficiency because it may result in safety hazards or usability barriers.

TABLE 33—INFESTATION STANDARD

Definition and Location	
Definition	The presence of potentially disease carrying animals or insects.
Location	Unit: Kitchen, cabinet, refrigerator, cooking appliance, bathroom, furniture, bed, carpet, drapes.
	Inside: Kitchen, cabinet, refrigerator, cooking appliance, bathroom, furniture, carpet, drapes.
	Outside: Near refuse enclosure or anywhere garbage is present, eaves of roofing.
Deficiency 1 – Infestation	ı: Unit
Deficiency	Evidence of cockroaches.
Deficiency Criteria	Evidence of cockroaches is found. Presence of dead or live cockroaches, shed skins, droppings (small black specks or smears), and egg cases (brown oblong cases: 5–9mm long). Three or fewer live cockroaches observed simultaneously in one location during the day are evidence of cockroaches.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	Cockroach allergen has been identified as one of the most important asthma triggers for children and severe asthma often results in the need for acute emergency care or hospitalization.
	If there is evidence of cockroaches, then the resident may be unable to maintain a sanitary environment.
	If there is evidence of cockroaches, then the resident will likely report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.

Deficiency 1 – Infestation: Inside	
	generated work orders are not being addressed.
	routine maintenance activities and their presence may indicate that self-
	If there is evidence of cockroaches, then it should be identified through

Deficiency 1 – Infestation	n: Inside
Deficiency	Evidence of cockroaches.
Deficiency Criteria	Evidence of cockroaches is found. Presence of dead or live cockroaches,
	shed skins, droppings (small black specks or smears), and egg cases (brown
	oblong cases: 5–9mm long). Three or fewer live cockroaches observed
	simultaneously in one location during the day are evidence of cockroaches.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	Cockroach allergen has been identified as one of the most important asthma triggers for children and severe asthma often results in the need for acute emergency care or hospitalization.
	If there is evidence of cockroaches, then the resident may be unable to maintain a sanitary environment.
	If there is evidence of cockroaches, then the resident will likely report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	If there is evidence of cockroaches, then it should be identified through routine maintenance activities and their presence may indicate that self-generated work orders are not being addressed.

Deficiency 2 – Infestation: Unit	
Deficiency	Extensive cockroach infestation.
Deficiency Criteria	Multiple (more than 3) live cockroaches observed simultaneously during the day are a sign of extensive infestation. At least one cockroach in more than one location in the Unit is a sign of extensive infestation.
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours

HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	Cockroach allergen has been identified as one of the most important asthma triggers for children and severe asthma often results in the need for acute emergency care or hospitalization. Extensive cockroach infestation provides an increased risk of resident contact with cockroach allergen.
	If there is extensive cockroach infestation, then the resident may be unable to maintain a sanitary environment.
	If there is extensive cockroach infestation, then the resident will likely report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	If there is extensive cockroach infestation, then it should be identified through routine maintenance activities and their presence may indicate that self-generated work orders are not being addressed.
Deficiency 2 – Infestation	n: Inside
Deficiency	Extensive cockroach infestation.
Deficiency Criteria	Multiple (more than 3) live cockroaches observed simultaneously during the day are a sign of extensive infestation. At least one cockroach in more than one location in the Unit is a sign of extensive infestation.
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	Cockroach allergen has been identified as one of the most important asthma triggers for children and severe asthma often results in the need for acute emergency care or hospitalization. Extensive cockroach infestation provides increased risk of resident contact with cockroach allergen. Residents, if they are not in the Unit but within the Inside inspectable area, can avoid lengthy exposure in areas with extensive cockroach infestation.
	If there is extensive cockroach infestation, then the resident may be unable

to maintain a sanitary environment.

If there is extensive cockroach infestation, then the resident will likely report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.

If there is extensive cockroach infestation, then it should be identified through routine maintenance activities and their presence may indicate that self-generated work orders are not being addressed.

Deficiency 3 – Infestation	ı: Unit
Deficiency	Evidence of bedbugs.
Deficiency Criteria	Evidence of bedbugs is found.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If there is evidence of bedbugs, then the resident may be subjected skin irritants.
	If there is evidence of bedbugs, then the resident may be unable to maintain a sanitary environment.
	If there is evidence of bedbugs, then the resident will likely report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.

Deficiency 3 – Infestation: Inside	
Deficiency	Evidence of bedbugs.
Deficiency Criteria	Evidence of bedbugs is found.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail

Rationale	If there is evidence of bedbugs, then the resident may be subjected skin irritants.
	If there is evidence of bedbugs, then the resident may be unable to maintain a sanitary environment.
	If there is evidence of bedbugs, then it should be identified through routine maintenance activities and their presence may indicate that self-generated work orders are not being addressed.

Deficiency 4 – Infestation	n: Unit
Deficiency	Evidence of mice.
Deficiency Criteria	Evidence of mice is found.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If there is evidence of mice, then the resident may be exposed to numerous infectious diseases.
	If there is evidence of mice, then the resident may be unable to maintain a sanitary environment.
	If there is evidence of mice, then the resident will likely report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	If there is evidence of mice, then it should be identified through routine maintenance activities and their presence may indicate that self-generated work orders are not being addressed.

Deficiency 4 – Infestation: Inside	
Deficiency	Evidence of mice.
Deficiency Criteria	Evidence of mice is found.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days

HCV Pass/Fail	Fail
Rationale	If there is evidence of mice, then the resident may be exposed to numerous infectious diseases.
	If there is evidence of mice, then the resident may be unable to maintain a sanitary environment.
	If there is evidence of mice, then the resident will likely report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	If there is evidence of mice, then it should be identified through routine maintenance activities and their presence may indicate that self-generated work orders are not being addressed.
Deficiency 5 – Infestation	n: Unit
Deficiency	Evidence of rats.
Deficiency Criteria	Evidence of rats is found.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If there is evidence of rats, then the resident may be exposed to numerous infectious diseases.
	If there is evidence of rats, then the resident may be unable to maintain a sanitary environment.
	If there is evidence of rats, then the resident will likely report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	If there is evidence of rats, then it should be identified through routine maintenance activities and their presence may indicate that self-generated work orders are not being addressed.
Deficiency 5 – Infestation	n: Inside
Deficiency	Evidence of rats.
Deficiency Criteria	Evidence of rats is found.

Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If there is evidence of rats, then the resident may be exposed to numerous
	infectious diseases.
	in conous discuscon
	If there is evidence of rats, then the resident may be unable to maintain a
	•
	sanitary environment.
	If there is evidence of rats, then the resident will likely report this, and the
	presence of this deficiency may indicate that complaint-based work orders
	are not being addressed.
	If there is evidence of rats, then it should be identified through routine
	maintenance activities and their presence may indicate that self-generated
	work orders are not being addressed.
	work or delib are not being dual esseu.

Deficiency 5 – Infestation	n: Outside
Deficiency	Evidence of rats.
Deficiency Criteria	Evidence of rats is found.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If there is evidence of rats, then the resident may be exposed to numerous infectious diseases.
	If there is evidence of rats, then the resident may be unable to maintain a sanitary environment.
	If there is evidence of rats, then the resident will likely report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.

If there is evidence of rats, then it should be identified through routine
maintenance activities and their presence may indicate that self-generated
work orders are not being addressed.

Deficiency 6 – Infestation	n: Unit
Deficiency	Evidence of other pests.
Deficiency Criteria	Evidence is present of other pest infestations, including but not limited to a trail of ants, wasps or beehives, squirrels, birds, and bats in an interior area.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If there is evidence of infestation, then the resident may be exposed to numerous infectious diseases.
	If there is evidence of infestation, then the resident may be unable to maintain a sanitary environment.
	If there is evidence of infestation, then the resident will likely report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	If there is evidence of infestation, then it should be identified through routine maintenance activities and their presence may indicate that self-generated work orders are not being addressed.

Deficiency 6 – Infestation	n: Inside
Deficiency	Evidence of other pests.
Deficiency Criteria	Evidence is present of other pest infestations, including but not limited to a trail of ants, wasps or beehives, squirrels, birds, and bats in an interior area.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail

Rationale	If there is evidence of infestation, then the resident may be exposed to numerous infectious diseases.
	If there is evidence of infestation, then the resident may be unable to maintain a sanitary environment.
	If there is evidence of infestation, then the resident will likely report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	If there is evidence of infestation, then it should be identified through routine maintenance activities and their presence may indicate that self-generated work orders are not being addressed.

TABLE 34—KITCHEN COUNTERTOP STANDARD

Definition and Location	
	The section of the se
Definition	Flat surface installations in kitchens or food preparation spaces.
Location	Unit: Kitchen or food preparation space.
	Inside: Kitchen or food preparation space.
Deficiency 1 – Kitchen Co	untertop: Unit
Deficiency	Countertop is missing.
Deficiency Criteria	Countertop is missing (i.e., evidence of prior installation, but now not
	present or is incomplete) from the kitchen or food preparation space.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the countertop is missing from the kitchen or food preparation space,
	then the resident's ability to prepare food safely and in a sanitary manner may be limited.
	If the countertop is missing from the kitchen or food preparation space,
	then the resident is unable to use a feature that is expected to be provided and maintained as part of their rent and may not be able to safely prepare food.

A resident is likely to notice a countertop missing from the kitchen or food preparation space within the Unit and to recognize it is important enough to report to property management because it may present sanitation hazards and usability barriers. Property management should be expected to prioritize a work order for a missing countertop because it may result in sanitation hazards or usability barriers.

Deficiency	Countertop is missing.
Deficiency Criteria	Countertop is missing (i.e., evidence of prior installation, but now not present or is incomplete) from the kitchen or food preparation space.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the countertop is missing from the kitchen or food preparation space, then the resident's ability to prepare food safely and in a sanitary manner may be limited.
	If the countertop is missing from the kitchen or food preparation space, then the resident is unable to use a feature that is expected to be provided and maintained as part of their rent and may not be able to safely prepare food.
	Property management would be expected to ensure that staff members understand how to identify a countertop missing from the kitchen or food preparation space. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in sanitary hazards or usability barriers.
Deficiency 2 – Kitchen Co	•
Deficiency	Countertop is damaged or is not functionally adequate.
Deficiency Criteria	Exposed substrate surface comprises at least 10% or more of the total kitchen countertop or food preparation space.
	OR
	The kitchen countertop or food preparation space is not functionally adequate (i.e., it does not reasonably allow for adequate preparation of food).

Deficiency 1 – Kitchen Countertop: Inside

Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the kitchen countertop or food preparation space has exposed substrate or is not functionally adequate, then the resident's ability to prepare food safely and in a sanitary manner is impacted.
	If the kitchen countertop or food preparation space has exposed substrate or is not functionally adequate, then the resident may be unable to use a feature that is expected to be provided and maintained as part of their rent and may not be able to safely prepare food.
	A resident is likely to notice if the kitchen countertop or food preparation space has exposed substrate or is not functionally adequate and to recognize it is important enough to report to property management because it may present sanitation hazards and usability barriers. Property management should be expected to prioritize a work order for a countertop with exposed substrate or one that is functionally inadequate because it may result in sanitation hazards or usability barriers.
Deficiency 2 – Kitchen Co	ountertop: Inside
Deficiency	Countertop is damaged or is not functionally adequate.
Deficiency Criteria	Exposed substrate surface comprises at least 10% or more of the total kitchen countertop or food preparation space.
	OR
	The kitchen countertop or food preparation space is not functionally adequate (i.e., it does not reasonably allow for adequate preparation of food).
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days

HCV Pass/Fail

Fail

Rationale

If the kitchen countertop or food preparation space has exposed substrate or is not functionally adequate, then the resident's ability to prepare food safely and in a sanitary manner is impacted.

If the kitchen countertop or food preparation space has exposed substrate or is not functionally adequate, then the resident is unable to use a feature that is expected to be provided and maintained as part of their rent and may not be able to safely prepare food.

Property management would be expected to ensure that staff members understand how to identify a kitchen countertop or food preparation space that has exposed substrate or is not functionally adequate. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in sanitary hazards or usability barriers.

TABLE 35—KITCHEN VENTILATION STANDARD

Definition and Location	
Definition	A mechanical system that transports air from the kitchen to the outside.
Location	Unit: Primary kitchen, primary food preparation area.
	Inside: Primary kitchen, primary food preparation area.
Deficiency 1 – Kitchen Ve	entilation: Unit
Deficiency	Exhaust system does not respond to the control switch.
Deficiency Criteria	Exhaust system does not respond to the control switch.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the exhaust system does not respond to the control switch, then it may be unable to remove the unwanted substances produced while cooking, which may result in poor air quality that may trigger respiratory issues.
	If the exhaust system does not respond to the control switch, then the resident may be unable to fully use an appliance that is expected to be provided and maintained as part of their rent.

A resident is likely to notice if the exhaust system does not respond to the control switch and to recognize it is important enough to report it to property management because it may present health hazards or usability barriers. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in health hazards or usability barriers.

Deficiency 1 – Kitchen Ve	entilation: Inside
Deficiency	Exhaust system does not respond to the control switch.
Deficiency Criteria	Exhaust system does not respond to the control switch.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the exhaust system does not respond to the control switch, then it may be unable to remove the unwanted substances produced while cooking, which may result in poor air quality that may trigger respiratory issues.
	If the exhaust system does not respond to the control switch, then the resident may be unable to fully use an appliance that is expected to be provided and maintained as part of their rent.
	Property management would be expected to ensure that staff members understand how to identify an exhaust system that does not respond to the control switch. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards or usability barriers.

Deficiency 2 – Kitchen Ventilation: Unit	
Deficiency	Exhaust system has restricted airflow.
Deficiency Criteria	Exhaust system is blocked such that airflow may be restricted.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail

Rationale

If the exhaust system is blocked such that airflow may be restricted, then it may be unable to remove the unwanted substances produced while cooking, which may result in poor air quality that may trigger respiratory issues.

If the exhaust system is blocked such that airflow may be restricted, then the resident may be unable to fully use an appliance that is expected to be provided and maintained as part of their rent.

A resident is likely to notice if the exhaust system is blocked such that airflow may be restricted and to recognize it is important enough to report it to property management because it may present health hazards or usability barriers. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in health hazards or usability barriers.

Deficiency 2 – Kitchen Ventilation: Inside	
Deficiency	Exhaust system has restricted airflow.
Deficiency Criteria	Exhaust system is blocked such that airflow may be restricted.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the exhaust system is blocked such that airflow may be restricted, then it may be unable to remove the unwanted substances produced while cooking, which may result in poor air quality that may trigger respiratory issues.
	If the exhaust system is blocked such that airflow may be restricted, then the resident may be unable to fully use an appliance that is expected to be provided and maintained as part of their rent.
	Property management would be expected to ensure that staff members understand how to identify an exhaust system that is blocked such that airflow may be restricted. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards or usability barriers.

Deficiency 3 – Kitchen Ventilation: Unit

Deficiency

Exhaust system component is damaged or missing.

Deficiency Criteria	Exhaust system component is damaged (i.e., visibly defective; impacts functionality).
	OR
	Exhaust system component is missing (i.e., evidence of prior installation, but now not present or is incomplete).
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If an exhaust system component is damaged or missing, then it may be unable to remove the unwanted substances produced while cooking, which may result in poor air quality that may trigger respiratory issues.
	If an exhaust system component is damaged or missing, then the resident may be unable to fully use an appliance that is expected to be provided and maintained as part of their rent.
	A resident is likely to notice if an exhaust system component is damaged or missing and to recognize it is important enough to report it to property management because it may present health hazards or usability barriers. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in health hazards or usability barriers.

Deficiency 3 – Kitchen Ve	Deficiency 3 – Kitchen Ventilation: Inside	
Deficiency	Exhaust system component is damaged or missing.	
Deficiency Criteria	Exhaust system component is damaged (i.e., visibly defective; impacts functionality).	
	OR	
	Exhaust system component is missing (i.e., evidence of prior installation, but now not present or is incomplete).	
Health and Safety Determination	Standard	
Correction Timeframe	30 days	
HCV Correction Timeframe	30 days	

HCV Pass/Fail	Fail
Rationale	If an exhaust system component is damaged or missing, then it may be unable to remove the unwanted substances produced while cooking, which may result in poor air quality that may trigger respiratory issues.
	If an exhaust system component is damaged or missing, then the resident may be unable to fully use an appliance that is expected to be provided and maintained as part of their rent.
	Property management would be expected to ensure that staff members understand how to identify an exhaust system component that is damaged or missing. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards or usability barriers.

TABLE 36—LEAK STANDARD

Definition and Location

Definition

<u>Gas or Oil</u>: A fuel or gas leak refers to an unintended leak of natural gas or another gaseous product from a pipeline or other containment into any area where the gas or fuel should not be present. Gas leaks can be hazardous to health and the environment.

<u>Sewage System</u>: A sewage system leak refers to the leakage of wastewater out of a sanitary sewer system through broken or damaged pipes.

<u>Water</u>: A water leak can be caused by damage; including a puncture, gash, rust or other corrosion hole, very tiny pinhole leak (possibly in imperfect welds), crack or microcrack, or inadequate sealing between components or parts joined together.

Location

Unit:

- Gas or Oil: Around fuel-fired appliances.
- <u>Sewage System</u>: Floor drains, toilets, vents.
- <u>Water</u>: Ceilings, floors, walls, toilets, sinks, dishwashers, washer and dryer, water heaters, central water supply lines, sewer lines, steam pipes, drainpipes, central gas line.

Inside:

- Gas or Oil: Around fuel-fired appliances.
- Sewage System: Floor drains, toilets, vents.
- <u>Water</u>: Ceilings, floors, walls, toilets, sinks, dishwashers, washer and dryer, water heaters, central water supply lines, sewer lines, steam pipes, drainpipes, central gas line.

Outside:

	- Gas or Oil: Around fuel-fired appliances.
	- <u>Sewage System</u> : Lawn, sewer cleanout.
	- <u>Water</u> : None.
Deficiency 1 Leeks Unit	
Deficiency 1 – Leak: Unit	
Deficiency	Natural gas, propane, or oil leak.
Deficiency Criteria	There is evidence of a gas, propane, or oil leak.
•	OR
	There is an uncapped gas or fuel supply line.
Health and Safety	Life-Threatening
Determination	· ·
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If there is evidence of a gas, propane, or oil leak, or there is an uncapped
	gas or fuel supply line, then the resident may be exposed to harmful gases
	and be at an increased risk of asphyxiation, which may result in death.
	If there is evidence of a gas, propane, or oil leak, or there is an uncapped
	gas or fuel supply line, then there may be an increased safety risk to the
	resident of fire or explosion, which may result in injury or death.
	If there is evidence of a gas, prepage or ail look, or there is an unconned gas
	If there is evidence of a gas, propane or oil leak, or there is an uncapped gas
	or fuel supply line, then the resident may not be able to operate the
	affected appliances, which are expected to be provided and maintained as
	part of their rent.
	A resident is likely to notice evidence of a gas, propane, or oil leak, or that
	there is an uncapped gas or fuel supply line within the unit, and to recognize
	it is important enough to report to property management because it may
	present health or safety hazards. Property management should be
	expected to prioritize a work order for evidence of a gas, propane, or oil
	leak because it may result in health or safety hazards.
Deficiency 1 – Leak: Insic	le
Deficiency	Natural gas, propane, or oil leak.
Deficiency Criteria	There is evidence of a gas, propane, or oil leak.
	OR
	There is an uncapped gas or fuel supply line.
Health and Safety	Life-Threatening

Determination

Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If there is evidence of a gas, propane, or oil leak, or there is an uncapped gas or fuel supply line, then the resident may be exposed to harmful gases and be at an increased risk of asphyxiation, which may result in death.
	If there is evidence of a gas, propane, or oil leak, or there is an uncapped gas or fuel supply line, then there may be an increased safety risk to the resident of fire or explosion, which may result in injury or death.
	If there is evidence of a gas, propane or oil leak, or there is an uncapped gas or fuel supply line, then the resident may not be able to operate the affected appliances, which are expected to be provided and maintained as part of their rent.
	Property management would be expected to ensure that staff members understand how to identify evidence of a gas, propane, or oil leak or there is an uncapped gas or fuel supply line. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy the leak, because it may result in health and safety hazards.

Deficiency 1 – Leak: Outs	Deficiency 1 – Leak: Outside		
Deficiency	Natural gas, propane, or oil leak.		
Deficiency Criteria	There is evidence of a gas, propane, or oil leak. OR		
	There is an uncapped gas or fuel supply line.		
Health and Safety	Life-Threatening		
Determination			
Correction Timeframe	24 hours		
HCV Correction	24 hours		
Timeframe			
HCV Pass/Fail	Fail		
Rationale	If there is evidence of a gas, propane, or oil leak, or there is an uncapped gas or fuel supply line, then the resident may be exposed to harmful gasses and be at an increased risk of illness.		
	If there is evidence of a gas, propane, or oil leak, or there is an uncapped gas or fuel supply line, then there may be an increased safety risk to the resident of fire or explosion, which may result in injury or death.		

If there is evidence of a gas, propane or oil leak, or there is an uncapped gas or fuel supply line, then the resident may not be able to operate the affected appliances, which are expected to be provided and maintained as part of their rent.

Property management would be expected to ensure that staff members understand how to identify evidence of a gas, propane, or oil leak or there is an uncapped gas or fuel supply line. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy the leak, because it may result in health and safety hazards.

Deficiency 2 – Leak: Unit	
Deficiency	Blocked sewage system.
Deficiency Criteria	Wastewater is unable to drain resulting in sewer backup.
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If wastewater is unable to drain resulting in sewer backup, then the resident may be exposed to raw sewage.
	If wastewater is unable to drain resulting in sewer backup, then the resident may not have access to the use of a toilet or shower.
	If wastewater is unable to drain resulting in sewer backup, then the resident will likely report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	It is reasonable to expect this deficiency will be observed through routine maintenance, and its presence may indicate that routine work orders are not being addressed.
	Sewage systems should be checked during periodic property inspections, and according to industry best practices, should be included in a preventative maintenance plan. If wastewater is unable to drain resulting in sewer backup, then it may indicate preventative maintenance activities could be improved.
	If wastewater is unable to drain resulting in sewer backup, then the repair may be costly depending on the scope of the deficiency.

Deficiency 2 – Leak: Insid	
Deficiency	Blocked sewage system.
Deficiency Criteria	Wastewater is unable to drain resulting in sewer backup.
Health and Safety	Severe Non-Life Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If wastewater is unable to drain resulting in sewer backup, then the residen
	may be exposed to raw sewage.
	If wastewater is unable to drain resulting in sewer backup, then the residen
	may not have access to the use of a toilet or shower.
	If wastewater is unable to drain resulting in sewer backup, then the residen
	will likely report this, and the presence of this deficiency may indicate that
	complaint-based work orders are not being addressed.
	It is reasonable to expect this deficiency will be observed through routine
	maintenance, and the presence of this deficiency may indicate that routine
	work orders are not being addressed.
	Sewage systems should be checked during periodic property inspections,
	and according to industry best practices, should be included in a
	preventative maintenance plan. If wastewater is unable to drain resulting in
	sewer backup, then it may indicate preventative maintenance activities
	could be improved.
	If wastewater is unable to drain resulting in sewer backup, then the repair
	may be costly depending on the scope of the deficiency.

Deficiency 2 – Leak: Outside	
Deficiency	Blocked sewage system.
Deficiency Criteria	Wastewater is unable to drain resulting in sewer backup.
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days

HCV Pass/Fail	Fail
Rationale	If wastewater is unable to drain resulting in sewer backup, then the resident may be exposed to raw sewage.
	If wastewater is unable to drain resulting in sewer backup, then the resident may not have access to the use of a toilet or shower.
	If wastewater is unable to drain resulting in sewer backup, then the resident will likely report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	It is reasonable to expect this deficiency to be observed through routine maintenance and its presence may indicate that routine work orders are not being addressed.
	Sewage systems should be checked during periodic property inspections, and according to industry best practices, should be included in a preventative maintenance plan. If wastewater is unable to drain resulting in sewer backup, then it may indicate preventative maintenance activities could be improved.
	If wastewater is unable to drain resulting in sewer backup, then the repair may be costly depending on the scope of the deficiency.

Deficiency 3 – Leak: Unit	
Deficiency	Leak in sewage system.
Deficiency Criteria	There is evidence of a sewer line or fitting leaking.
Health and Safety	Severe Non-Life Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If there is evidence of a sewer line or fitting leaking, then the resident may
	be exposed to raw sewage.
	If sewer has a leak, then the resident may be exposed to raw sewage.
	If there is evidence of a sewer line or fitting leaking, then the resident may
	not have access to the use of a toilet or shower.

If there is evidence of a sewer line or fitting leaking, then the resident will likely report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.

It is reasonable to expect this deficiency will be observed through routine maintenance, and the presence of this deficiency may indicate that routine work orders are not being addressed.

Sewage systems should be checked during periodic property inspections, and according to industry best practices, should be included in a preventative maintenance plan. If there is evidence of a sewer line or fitting leaking, then it may indicate preventative maintenance activities could be improved.

If there is evidence of a sewer line or fitting leaking, then the repair may be costly depending on the scope of the deficiency.

Deficiency 3 – Leak: Insid	۵
Deficiency	Leak in sewage system.
Deficiency Criteria	There is evidence of a sewer line or fitting leaking.
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If there is evidence of a sewer line or fitting leaking, then the resident may be exposed to raw sewage.
	If there is evidence of a sewer line or fitting leaking, then the resident may not have access to the use of a toilet or shower.
	If there is evidence of a sewer line or fitting leaking, then the resident will likely report this, and the presence of this defect may indicate that complaint-based work orders are not being addressed.
	It is reasonable to expect this deficiency will be observed through routine maintenance, and the presence of this deficiency may indicate that routine work orders are not being addressed.
	Sewage systems should be checked during periodic property inspections, and according to industry best practices, should be included in a preventative maintenance plan. If there is evidence of a sewer line or fitting

leaking, then it may indicate preventative maintenance activities could be improved.

If there is evidence of a sewer line or fitting leaking, then the repair may be costly depending on the scope of the deficiency.

Deficiency 3 – Leak: Outs	ide
Deficiency	Leak in sewage system.
Deficiency Criteria	There is evidence of a sewer line or fitting leaking.
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If there is evidence of a sewer line or fitting leaking, then the resident may be exposed to raw sewage.
	If there is evidence of a sewer line or fitting leaking, then the resident may not have access to the use of a toilet or shower.
	If there is evidence of a sewer line or fitting leaking, then the resident will likely report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	It is reasonable to expect this deficiency will be observed through routine maintenance, and the presence of this deficiency may indicate that routine work orders are not being addressed.
	Sewage systems should be checked during periodic property inspections, and according to industry best practices, should be included in a preventative maintenance plan. If there is evidence of a sewer line or fitting leaking, then it may indicate preventative maintenance activities could be improved.
	If there is evidence of a sewer line or fitting leaking, then the repair may be costly depending on the scope of the deficiency.
Doficionay A. Looky Unit	

Deficiency 4 – Leak: Unit	
Deficiency	Cap to the cleanout is detached or missing.
Deficiency Criteria	Cap to the cleanout is detached or is missing (i.e., evidence of prior installation, but now not present or is incomplete).

Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the cap to the cleanout is detached or missing, then the resident may be exposed to raw sewage or sewage gases, which may result in illness.
	Property management would be expected to ensure that staff members understand how to identify a cap to the cleanout that is detached or missing. Management practices would be expected to assure prompt creation and prioritization of a work order to attach or replace the cleanout cap because it may result in health hazards.
Deficiency 4 – Leak: Insid	le
Deficiency	Cap to the cleanout is detached or missing.
Deficiency Criteria	Cap to the cleanout is detached or is missing (i.e., evidence of prior installation, but now not present or is incomplete).
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the cap to the cleanout is detached or missing, then the resident may be exposed to raw sewage or sewage gases, which may result in illness.
	Property management would be expected to ensure that staff members understand how to identify a cap to the cleanout that is detached or missing. Management practices would be expected to assure prompt creation and prioritization of a work order to attach or replace the cleanout cap because it may result in health hazards.
Deficiency 4 – Leak: Outs	ide
Deficiency	Cap to the cleanout is detached or missing.
Deficiency Criteria	Cap to the cleanout is detached or is missing (i.e., evidence of prior installation, but now not present or is incomplete).

Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the cap to the cleanout is detached or missing, then the resident may be exposed to raw sewage, which may result in illness.
	Property management would be expected to ensure that staff members understand how to identify a cap to the cleanout that is detached or missing. Management practices would be expected to assure prompt creation and prioritization of a work order to attach or replace the cleanout cap because it may result in health hazards.
Deficiency 5 – Leak: Unit	
Deficiency	Cleanout cap or riser has penetrative hole or crack.
Deficiency Criteria	There is a hole or crack penetrating through a cleanout cap or riser.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If there is a hole or crack penetrating through a cleanout cap or riser, then the resident may be exposed to raw sewage or sewage gases, which may result in illness.
	Property management would be expected to ensure that staff members understand how to identify a hole or crack penetrating through a cleanout cap or riser. Management practices would be expected to assure prompt creation and prioritization of a work order to repair or replace the cleanout cap, because it may result in health hazards.
Deficiency 5 – Leak: Insid	e
Deficiency	Cleanout cap or riser has penetrative hole or crack.
Deficiency Criteria	There is a hole or crack penetrating through a cleanout cap or riser.

Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If there is a hole or crack penetrating through a cleanout cap or riser, then the resident may be exposed to raw sewage or sewage gases, which may result in illness.
	Property management would be expected to ensure that staff members understand how to identify a hole or crack penetrating through a cleanout cap or riser. Management practices would be expected to assure prompt creation and prioritization of a work order to repair or replace the cleanout cap, because it may result in health hazards.
Deficiency 5 – Leak: Outs	ide
Deficiency	Cleanout cap or riser has penetrative hole or crack.
Deficiency Criteria	There is a hole or crack penetrating through a cleanout cap or riser.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If there is a hole or crack penetrating through a cleanout cap or riser, then the resident may be exposed to raw sewage, which may result in illness.
	Property management would be expected to ensure that staff members understand how to identify a hole or crack penetrating through a cleanout cap or riser. Management practices would be expected to assure prompt creation and prioritization of a work order to repair or replace the cleanout cap, because it may result in health hazards.
Deficiency 6 – Leak: Unit	
Deficiency	Environmental water intrusion.
Deficiency Criteria	Environment water intrusion is present.

Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If environmental water intrusion is present, then the resident may be subjected to mold and mildew or unstable surfaces.
	If environmental water intrusion is present, then the resident may be subjected to mold and mildew or unstable surfaces resulting in poor air quality.
	If environmental water intrusion is present, then the resident may be exposed to an unsanitary environment.
	If environmental water intrusion is present, then it is reasonable to expect the resident will report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	If environmental water intrusion is present, then the repair may be costly depending on the length of time the intrusion was present.
	If environmental water intrusion is present, it may damage structural components.

Deficiency 6 – Leak: Insid	Deficiency 6 – Leak: Inside	
Deficiency	Environmental water intrusion.	
Deficiency Criteria	Environmental water intrusion is present.	
Health and Safety Determination	Standard	
Correction Timeframe	30 days	
HCV Correction Timeframe	30 days	
HCV Pass/Fail	Fail	
Rationale	If environmental water intrusion is present, then the resident may be subjected to mold and mildew or unstable surfaces. If environmental water intrusion is present, then the resident may be subjected to mold and mildew or unstable surfaces resulting in poor air quality.	

If environmental water intrusion is present, then the resident may be exposed to an unsanitary environment.

If environmental water intrusion is present, then it is reasonable to expect the resident will report this, and the presence of this defect may indicate that complaint-based work orders are not being addressed.

If environmental water intrusion is present, then the repair may be costly depending on the length of time the intrusion was present.

If environmental water intrusion is present, it may damage structural components.

Plumbing leaks.
Failure of a plumbing system that allows for water intrusion in unintended areas.
Standard
30 days
30 days
Fail
If there is a failure of a plumbing system that allows for water intrusion in unintended areas, then the resident may be subjected to mold and mildew or unstable surfaces.
If there is a failure of a plumbing system that allows for water intrusion in unintended areas, then the resident may be subjected to mold and mildew or unstable surfaces resulting in poor air quality.
If there is a failure of a plumbing system that allows for water intrusion in unintended areas, then the resident may be exposed to an unsanitary environment.
If there is a failure of a plumbing system that allows for water intrusion in unintended areas, then the resident may be unable to use a fixture or appliance that is expected to be provided and maintained as part of their rent.
If there is a failure of a plumbing system that allows for water intrusion in unintended areas, then it is reasonable to expect the resident will report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.

If there is a failure of a plumbing system that allows for water intrusion in unintended areas, then the repair may be costly depending on the length of time the intrusion was present.

If there is a failure of a plumbing system that allows for water intrusion in unintended areas, then it may damage structural components.

Deficiency 7 – Leak: Inside	
Deficiency	Plumbing leaks.
Deficiency Criteria	Failure of a plumbing system that allows for water intrusion in unintended areas.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If there is a failure of a plumbing system that allows for water intrusion in unintended areas, then the resident may be subjected to mold and mildew or unstable surfaces.
	If there is a failure of a plumbing system that allows for water intrusion in unintended areas, then the resident may be subjected to mold and mildew or unstable surfaces resulting in poor air quality.
	If there is a failure of a plumbing system that allows for water intrusion in unintended areas, then the resident may be exposed to an unsanitary environment.
	If there is a failure of a plumbing system that allows for water intrusion in unintended areas, then the resident may be unable to use a fixture or appliance that is expected to be provided and maintained as part of their rent.
	If there is a failure of a plumbing system that allows for water intrusion in unintended areas, then it is reasonable to expect the resident will report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	If there is a failure of a plumbing system that allows for water intrusion in unintended areas, then the repair may be costly depending on the length of time the intrusion was present.

If there is a failure of a plumbing system that allows for water intrusion in
unintended areas, then it may damage structural components.

TABLE 37—LIGHTING – AUXILIARY STANDARD

Definition and Location	
Definition	Lighting that is essential to safety in the event of primary power supply
	failure.
Location	Inside: Throughout the Inside.
	Outside: Throughout the Outside.
Deficiency 1 – Lighting –	Auxiliary: Inside
Deficiency	Auxiliary lighting fails to illuminate when tested.
Deficiency Criteria	After pressing the test button, the auxiliary light does not illuminate.
Health and Safety	Severe Non-Life Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If after pressing the test button, the auxiliary light does not illuminate, and
	there is an emergency, then the resident may be unable to safely exit the
	building due to inability to see the egress.
	If after pressing the test button the auxiliary light does not illuminate, then
	the resident may be unable to use a feature that is expected to be provided
	and maintained as part of their rent.
	Property management would be expected to ensure that staff members
	understand how to identify an auxiliary light that does not illuminate after
	pressing the test button. Management practices would be expected to
	ensure prompt creation and prioritization of a work order to remedy this
	deficiency because it may result in safety hazards or usability barriers.
Deficiency 1 – Lighting –	•
Deficiency	Auxiliary lighting fails to illuminate when tested.
Deficiency Criteria	After pressing the test button, the auxiliary light does not illuminate.
Health and Safety	Severe Non-Life Threatening
Determination	

Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If after pressing the test button, the auxiliary light does not illuminate, and there is an emergency, then the resident may be unable to safely exit the building due to inability to see the egress.
	If after pressing the test button the auxiliary light does not illuminate, then the resident may be unable to use a feature that is expected to be provided and maintained as part of their rent.
	Property management would be expected to ensure that staff members understand how to identify an auxiliary light that does not illuminate after pressing the test button. Management practices would be expected to ensure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards or usability barriers.
Deficiency 2 – Lighting –	Auxiliary: Inside
Deficiency	Auxiliary lighting component is damaged or missing.
Deficiency Criteria	Auxiliary lighting component is damaged (i.e., visibly defective).
	OR
	Auxiliary lighting component is missing (i.e., evidence of prior installation,
	but now not present or is incomplete).
Health and Safety Determination	Advisory
Correction Timeframe	Advisory
HCV Correction	Advisory
Timeframe	
HCV Pass/Fail	Pass
Rationale	Property management would be expected to ensure that staff members understand how to identify an auxiliary lighting component that is damaged or missing. Management practices would be expected to ensure prompt creation and prioritization of a work order to remedy this deficiency.
Deficiency 2 – Lighting –	Auxiliary: Outside
Deficiency	Auxiliary lighting component is damaged or missing.
Deficiency Criteria	Auxiliary lighting component is damaged (i.e., visibly defective).

OR
Auxiliary lighting component is missing (i.e., evidence of prior installation,
but now not present or is incomplete).
Advisory
Advisory
Advisory
Pass
Property management would be expected to ensure that staff members understand how to identify an auxiliary lighting component that is damaged or missing. Management practices would be expected to ensure prompt creation and prioritization of a work order to remedy this deficiency.

TABLE 38—LIGHTING – EXTERIOR STANDARD

Definition and Location	
Definition	Fixed artificial lighting (e.g., walkway lighting, pole lighting, wall packs, and
	canopy lights) that is used to illuminate exterior areas (e.g., entryways,
	parking lots, and exterior stairwells).
Location	Outside: Throughout the Outside.
Deficiency 1 – Lighting –	Exterior: Outside
Deficiency	A permanently installed light fixture is missing, damaged, or not secure.
Deficiency Criteria	A permanently installed light fixture is missing (i.e., evidence of prior installation, but now not present or is incomplete).
	OR
	A permanently installed light fixture is damaged (i.e., visibly defective; impacts functionality).
	OR
	A permanently installed light fixture is not secure to the designed
	attachment point or the attachment point is not stable.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days

HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a permanently installed light fixture is missing, damaged, or not secure to the designed attachment point or the attachment point is not stable, then it may indicate conditions are present that may result in a short or arc, which may lead to an increased fire risk that could cause injury.
	Property management would be expected to ensure that staff members understand how to identify a permanently installed light fixture that is missing, damaged, or not secure to the designed attachment point or the attachment point is not stable. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards.

TABLE 39—LIGHTING – INTERIOR STANDARD

Definition and Location	
Definition	Permanently installed light fixture.
Location	Unit: Throughout the Unit.
	Inside: Throughout the Inside.
Deficiency 1 – Lighting –	Interior: Unit
Deficiency	A permanently installed light fixture is inoperable.
Deficiency Criteria	A permanently installed light fixture is inoperable (i.e., the overall system or component thereof is not meeting function or purpose; with or without visible damage).
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail

Deficiency

If a permanently installed light fixture is inoperable, then it may indicate conditions are present that may result in a short or arc, which may lead to an increased fire risk that could cause injury.

If a permanently installed light fixture is inoperable, then the resident may not be able to fully use a fixture that is expected to be provided and maintained as part of their rent.

A resident is likely to notice if a permanently installed light fixture is inoperable and to recognize it is important enough to report it to property management because it may present safety hazards or usability barriers. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in safety hazards.

Deficiency	A permanently installed light fixture is inoperable.
Deficiency Criteria	A permanently installed light fixture is inoperable (i.e., the overall system or
Deficiency criteria	component thereof is not meeting function or purpose; with or without
	visible damage).
	visible dalliage).
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a permanently installed light fixture is inoperable, then it may indicate
	conditions are present that may result in a short or arc, which may lead to
	an increased fire risk that could cause injury.
	If a permanently installed light fixture is inoperable, then the resident may
	not be able to fully use a fixture that is expected to be provided and
	maintained as part of their rent.
	maintained as part of their rent.
	Property management would be expected to ensure that staff members
	understand how to identify a permanently installed light fixture that is
	inoperable. Management practices would be expected to assure prompt
	creation and prioritization of a work order to remedy this deficiency
	because it may result in safety hazards or usability barriers.

A permanently installed light fixture is not secure.

Deficiency Criteria	A permanently installed light fixture is not secure to the designed
	attachment point or the attachment point is not stable.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a permanently installed light fixture is not secure to the designed attachment point or the attachment point is not stable, then it may indicate conditions are present that may result in a short or arc, which may lead to an increased fire risk that could cause injury.
	A resident is likely to notice if a permanently installed light fixture is not secure to the designed attachment point or the attachment point is not stable and to recognize it is important enough to report it to property management because it may present safety hazards. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in safety hazards.
Deficiency 2 – Lighting –	Interior: Inside
Deficiency	A permanently installed light fixture is not secure.
Deficiency Criteria	A permanently installed light fixture is not secure to the designed
·	attachment point or the attachment point is not stable.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a permanently installed light fixture is not secure to the designed attachment point or the attachment point is not stable, then it may indicate conditions are present that may result in a short or arc, which may lead to an increased fire risk that could cause injury.
	Property management would be expected to ensure that staff members understand how to identify if a permanently installed light fixture is not secure to the designed attachment point or the attachment point is not stable. Management practices would be expected to assure prompt

creation and prioritization of a work order to rem	edy this deficiency
because it may result in safety hazards.	

Deficiency 3 – Lighting –	Interior: Unit
Deficiency	Insufficient illumination in kitchen or bathroom.
Deficiency Criteria	Insufficient illumination in kitchen or bathroom resulting in increased risk due to safety hazards (e.g., falls, cuts, burns).
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If there is insufficient illumination in the kitchen or bathroom, there may be an increased safety risk to the resident due to their inability to visually navigate these spaces, which may result in injury.
	A resident is likely to notice if there is insufficient illumination in the kitchen or bathroom within the unit and to recognize it is important enough to report to property management because it may present safety hazards. Property management should be expected to prioritize a work order for an insufficiently illuminated space because it may result in safety hazards.
Deficiency 3 – Lighting –	Interior: Inside
Deficiency	Insufficient illumination in kitchen or bathroom.
Deficiency Criteria	Insufficient illumination in kitchen or bathroom resulting in increased risk due to safety hazards (e.g., falls, cuts, burns).
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If there is insufficient illumination in the kitchen or bathroom, there may be an increased safety risk to the resident due to their inability to visually navigate these spaces, which may result in injury.
	Property management would be expected to ensure that staff members

understand how to identify a kitchen or bathroom that is insufficiently

illuminated. Management practices would be expected to assure prompt creation and prioritization of a work order to illuminate these spaces, because it may result in safety hazards.

TABLE 40—LITTER STANDARD

Definition and Location	
Definition	Waste discarded or disposed of in a location that is not designated for waste.
Location	Inside: Throughout the Inside.
	Outside: Throughout the Outside.
eficiency 1 – Litter: Insi	de
Deficiency	Litter is accumulated in an undesignated area.
Deficiency Criteria	10 or more small items of litter (e.g., food wrappers, pieces of food, newspapers) are present within a 10-foot by 10-foot area not designated for garbage.
	OR
	Any number of large items (e.g., furniture or appliances) have been clearly
	discarded in an area not designated for garbage.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If litter is accumulated, then it may lead to infestation, which may negatively impact the resident's health.
	If litter is accumulated, then the resident may be exposed to unsanitary conditions.
	If litter is accumulated, then it will likely be identified during routine maintenance activities and the presence of this deficiency may indicate that self-generated work orders are not being addressed.
	If litter is accumulated and it is visible to a visitor, then the property may suffer reputational harm.

e small items of litter (e.g., food wrappers, pieces of food, rs) are present within a 10-foot by 10-foot area not designated e. er of large items (e.g., furniture or appliances) have been clearly n an area not designated for garbage.
er of large items (e.g., furniture or appliances) have been clearly
ccumulated, then it will likely be identified during routine
1

TABLE 41—MOLD-LIKE SUBSTANCE STANDARD

Definition and Location	
Definition	A "Mold-like substance" can include regular or irregular patches or spots on surfaces that may be colored differently than the surface (coloration can be white, green, yellow, gray, brown, or black), and can be raised from the surface. A "Mold-like substance" can appear "fuzzy" or "cottony" and a musty or earthy odor can be associated with it.
	"Mold-like substance" would also include what is often identified as "mildew," i.e., small patches, generally on non-porous surfaces, and dusty (friable) when dry; mildew is generally a thin surface growth that can be wiped off easily. Note that algae are not to be recorded (algae are grass-green).
Location	Unit: Includes areas where there could be potential water intrusion or captive moisture: e.g., walls, floors, ceilings, bathrooms, kitchens, bedrooms, closets, basements, laundry rooms, any other area that wood, drywall, and moisture are present.

Inside: Includes areas where there could be potential water intrusion or captive moisture: e.g., walls, floors, ceilings, bathrooms, kitchens, mechanical rooms, basements, laundry rooms, any other area that wood, drywall, and moisture are present.

Deficiency 1 – Mold-Like Substance: Unit	
Deficiency	Presence of mold-like substance at very low levels is observed visually.
Deficiency Criteria	Patches or spots are cumulatively less than 4 square inches, i.e., below de minimis. Odor is an indicator, but not a diagnostic; if a musty odor is detected, visual confirmation of "mold-like substance" is required. Odor may be indicated in a "notes" field. This deficiency is not recorded if observed on household items (e.g., clothing, upholstery, food).
Health and Safety Determination	Advisory
Correction Timeframe	Advisory
HCV Correction Timeframe	Advisory
HCV Pass/Fail	Pass
Rationale	Presence of a mold-like substance at very low levels may be an indicator of conditions that may in turn lead to conditions that affect indoor air quality that may negatively impact respiratory health, including triggering asthma events.
Deficiency 1 – Mold-Like	Substance: Inside
Deficiency	Presence of mold-like substance at very low levels is observed visually.
Deficiency Criteria	Patches or spots are cumulatively less than 4 square inches, i.e., below de minimis. Odor is an indicator, but not a diagnostic; if a musty odor is detected, visual confirmation of "mold-like substance" is required. Odor may be indicated in a "notes" field. This deficiency is not recorded if observed on household items (e.g., clothing, upholstery, food).
Health and Safety	Advisory
Determination	
Correction Timeframe	Advisory
HCV Correction Timeframe	Advisory
HCV Pass/Fail	Pass

Presence of a mold-like substance at very low levels may be an indicator of conditions that may in turn lead to conditions that affect indoor air quality that may negatively impact respiratory health, including triggering asthma events.

	events.	
Deficiency 2 – Mold-Like Substance: Unit		
Deficiency	Presence of mold-like substance at moderate levels is observed visually.	
Deficiency Criteria	Cumulative area of patches is more than 4 square inches, i.e., above de minimis, and less than 1 square foot in a room. Odor is an indicator, but not a diagnostic; if a musty odor is detected, visual confirmation of "mold-like substance" is required. Odor may be indicated in a "notes" field. This deficiency is not recorded if observed on household items (e.g., clothing, upholstery, food).	
Health and Safety Determination	Standard	
Correction Timeframe	30 days	
HCV Correction Timeframe	30 days	
HCV Pass/Fail	Fail	
Rationale	A mold-like substance may be indicative of conditions that affect indoor air quality that may negatively impact respiratory health, including triggering asthma events.	
	A resident is likely to notice a mold-like substance and recognize it is important enough to report it to property management. Property management should be expected to prioritize a work order for this condition and its presence may imply there are areas of opportunity to improve corrective maintenance practices.	
	A mold-like substance may be indicative of conditions that may negatively impact structural conditions of the building, such as leaks or ventilation, that would require repair in order to appropriately remediate the mold-like substance.	
	A mold-like substance may be indicative of conditions that affect indoor air quality that may negatively impact respiratory health, including triggering asthma events; HUD may be financially liable for subsequent health impacts.	

Deficiency 2 – Mold-Like Substance: Inside	
Deficiency	Presence of mold-like substance at moderate levels is observed visually.
Deficiency Criteria	Cumulative area of patches is more than 4 square inches, i.e., above de minimis, and less than 1 square foot in a room. Odor is an indicator, but not

	a diagnostic; if a musty odor is detected, visual confirmation of "mold-like substance" is required. Odor may be indicated in a "notes" field. This deficiency is not recorded if observed on household items (e.g., clothing, upholstery, food).
Health and Safety Determination	Advisory
Correction Timeframe	Advisory
HCV Correction Timeframe	Advisory
HCV Pass/Fail	Pass
Rationale	A mold-like substance may be indicative of conditions that affect indoor air quality that may negatively impact respiratory health, including triggering asthma events. Outside of the Unit, residents may avoid lengthy exposure in areas with moderate levels of a mold-like substance.
	A resident is likely to notice a mold-like substance and recognize it is important enough to report it to property management. Property management should be expected to prioritize a work order for this condition and its presence may imply there are areas of opportunity to improve corrective maintenance practices.
	Facilities management and staff are likely to notice a mold-like substance during their regular, routine activities and its importance is likely to be recognized by facilities management and staff. Property management should be expected to prioritize a work order for this condition and its presence may imply there are areas of opportunity to improve routine maintenance practices.
	A mold-like substance may be indicative of conditions that may negatively impact structural conditions of the building, such as leaks or ventilation, that would require repair in order to appropriately remediate the mold-like substance.
	A mold-like substance may be indicative of conditions that affect indoor air quality that may negatively impact respiratory health, including triggering asthma events; HUD may be financially liable for subsequent health impacts.
Deficiency 3 – Mold-Like Deficiency	Substance: Unit Presence of mold-like substance at high levels is observed visually.

Deficiency 3 – Mold-Like Substance: Unit	
Deficiency	Presence of mold-like substance at high levels is observed visually.
Deficiency Criteria	Cumulative area of patches is more than 1 square foot and less than 9 square feet in a room. Odor is an indicator, but not a diagnostic; if a musty odor is detected, visual confirmation of "mold-like substance" is required.

	Odor may be indicated in a "notes" field. This deficiency is not recorded if
	observed on household items (e.g., clothing, upholstery, food).
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	A mold-like substance may be indicative of conditions that affect indoor air quality that may negatively impact respiratory health, including triggering asthma events.
	A resident is likely to notice a mold-like substance and recognize it is important enough to report it to property management. Property management should be expected to prioritize a work order for this condition and its presence may imply there are areas of opportunity to improve corrective maintenance practices.
	A mold-like substance may be indicative of conditions that may negatively impact structural conditions of the building, such as leaks or ventilation, that would require repair in order to appropriately remediate the mold-like substance.
	A mold-like substance may be indicative of conditions that affect indoor air quality that may negatively impact respiratory health, including triggering asthma events; HUD may be financially liable for subsequent health impacts.
Deficiency 3 – Mold-Like	Substance: Inside
Deficiency	Presence of mold-like substance at high levels is observed visually.
Deficiency Criteria	Cumulative area of patches is more than 1 square foot and less than 9 square feet in a room. Odor is an indicator, but not a diagnostic; if a musty odor is detected, visual confirmation of "mold-like substance" is required. Odor may be indicated in a "notes" field. This deficiency is not recorded if observed on household items (e.g., clothing, upholstery, food).
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction Timeframe	30 days

A mold-like substance may be indicative of conditions that affect indoor air quality that may negatively impact respiratory health, including triggering asthma events. Outside of the Unit, residents may temporarily avoid lengthy exposure in areas with high levels of a mold-like substance.

A resident is likely to notice a mold-like substance and recognize it is important enough to report it to property management. Property management should be expected to prioritize a work order for this condition and its presence may imply there are areas of opportunity to improve corrective maintenance practices.

Facilities management and staff are likely to notice a mold-like substance during their regular, routine activities and its importance is likely to be recognized by facilities management and staff. Property management should be expected to prioritize a work order for this condition and its presence may imply there are areas of opportunity to improve routine maintenance practices.

A mold-like substance may be indicative of conditions that may negatively impact structural conditions of the building, such as leaks or ventilation, that would require repair in order to appropriately remediate the mold-like substance.

A mold-like substance may be indicative of conditions that affect indoor air quality that may negatively impact respiratory health, including triggering asthma events; HUD may be financially liable for subsequent health impacts.

Deficiency 4 – Mold-Like	Substance: Unit
Deficiency	Presence of mold-like substance at extremely high levels is observed
	visually.
Deficiency Criteria	Cumulative area of patches is more than 9 square foot in a room. Odor is an indicator, but not a diagnostic; if a musty odor is detected, visual
	confirmation of "mold-like substance" is required. Odor may be indicated in a "notes" field. This deficiency is not recorded if observed on household
	items (e.g., clothing, upholstery, food).
Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail

A mold-like substance may be indicative of conditions that present a severe health risk due to indoor air quality that may negatively impact respiratory health, including triggering asthma events.

A resident is likely to notice a mold-like substance and recognize it is important enough to report it to property management. Property management should be expected to prioritize a work order for this condition and its presence may imply there are areas of opportunity to improve corrective maintenance practices.

Facilities management and staff are likely to notice a mold-like substance during their regular, routine activities and its importance is likely to be recognized by facilities management and staff. Property management should be expected to prioritize a work order for this condition and its presence may imply there are areas of opportunity to improve routine maintenance practices.

A mold-like substance may be indicative of conditions that may negatively impact structural conditions of the building, such as leaks or ventilation, that would require repair in order to appropriately remediate the mold-like substance.

Deficiency 4 – Mold-Like	Substance: Inside
Deficiency	Presence of mold-like substance at extremely high levels is observed visually.
Deficiency Criteria	Cumulative area of patches is more than 9 square foot in a room. Odor is an indicator, but not a diagnostic; if a musty odor is detected, visual confirmation of "mold-like substance" is required. Odor may be indicated in a "notes" field. This deficiency is not recorded if observed on household items (e.g., clothing, upholstery, food).
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	A mold-like substance may be indicative of conditions that present a severe health risk due to indoor air quality that may negatively impact respiratory health, including triggering asthma events.
	A resident is likely to notice a mold-like substance and recognize it is important enough to report it to property management. Property management should be expected to prioritize a work order for this

condition and its presence may imply there are areas of opportunity to improve corrective maintenance practices.

Facilities management and staff are likely to notice a mold-like substance during their regular, routine activities and its importance is likely to be recognized by facilities management and staff. Property management should be expected to prioritize a work order for this condition and its presence may imply there are areas of opportunity to improve routine maintenance practices.

A mold-like substance may be indicative of conditions that may negatively impact structural conditions of the building, such as leaks or ventilation, that would require repair in order to appropriately remediate the mold-like substance.

Deficiency 5 – Mold-Like	Substance: Unit
Deficiency	Bathroom does not have proper ventilation or dehumidification.
Deficiency Criteria	Neither an exhaust fan, window, nor adequate means of ventilation or
	dehumidification is present and operable.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If an operable exhaust fan, window, or adequate means of ventilation or
	dehumidification is not present, then this may increase interior moisture levels, which provides an environment favorable for mold growth and may
	trigger respiratory issues.
	A resident is likely to notice an exhaust fan, window, or adequate means of ventilation or dehumidification that is inoperable or not present and to recognize it is important enough to report it to property management because it may increase moisture levels within the Unit, resulting in
	potential health hazards. Property management should be expected to prioritize a work order for an exhaust fan, window, or adequate means of ventilation or dehumidification that is inoperable or not present because it may result in health hazards.
Deficiency 5 – Mold-Like	·
Deficiency	Bathroom does not have proper ventilation or dehumidification.

Deficiency 5 – Mold-Like Substance: Inside	
Deficiency	Bathroom does not have proper ventilation or dehumidification.
Deficiency Criteria	Neither an exhaust fan, window, nor adequate means of ventilation or dehumidification is present and operable.

Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If an operable exhaust fan, window, or adequate means of ventilation or dehumidification is not present, then this may increase interior moisture levels, which provides an environment favorable for mold growth and may trigger respiratory issues.
	Property management would be expected to ensure that staff members understand how to identify an exhaust fan, window, or adequate means of ventilation or dehumidification that is inoperable or not present within the inside area. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy or repair the ventilation or dehumidification source, because it may increase moisture levels, resulting in potential health hazards.

TABLE 42—PARKING LOT STANDARD

Definition and Location	
Definition	A designated outdoor area for parking motorized vehicles.
Location	Outside: Near or adjacent to buildings
Deficiency 1 – Parking Lo	t: Outside
Deficiency	Parking lot has pothole(s).
Deficiency Criteria	Any one pothole is greater than 4 inches deep and 144 square inches.
	OR
	Any number of potholes taken cumulatively are greater than 4 inches deep
	and 144 square inches.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail

If a parking lot has pothole(s) greater than 4 inches deep and 144 square inches, then there is potential for increased risk of injury from tripping or falling.

If a parking lot has pothole(s) greater than 4 inches deep and 144 square inches, then the resident may not be able to fully use a feature that is expected to be provided and maintained as part of their rent.

If a parking lot has pothole(s) greater than 4 inches deep and 144 square inches, then there is an increased risk of damage to the resident's vehicle.

If a parking lot has pothole(s) greater than 4 inches deep and 144 square inches, then it will likely be identified during routine maintenance activities, and the presence of this deficiency may indicate that self-generated work orders are not being addressed.

If a parking lot has pothole(s) greater than 4 inches deep and 144 square inches, and they are extensive, then it may require significant expenditures to repair.

If a parking lot has pothole(s) greater than 4 inches deep and 144 square inches, then this deficiency can be seen by the public and may result in reputational harm.

Deficiency 2 – Parking Lo	t: Outside
Deficiency	Parking lot has ponding.
Deficiency Criteria	More than 3 inches of water has accumulated in a parking lot and 5% or
	more of the parking lot is unusable.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If more than 3 inches of water has accumulated in a parking lot and 5% or more of the parking lot is unusable, then infestation (e.g., mosquitos) may occur and expose the resident to health hazards.
	If more than 3 inches of water has accumulated in a parking lot and 5% or more of the parking lot is unusable, and it obscures other hazards, then the resident's risk of injury may increase.
	If more than 3 inches of water has accumulated in a parking lot and 5% or more of the parking lot is unusable, then the resident may not be able to

fully use a feature that is expected to be provided and maintained as part of their rent.

If more than 3 inches of water has accumulated in a parking lot and 5% or more of the parking lot is unusable, then it will likely be identified during routine maintenance activities, and the presence of this deficiency may indicate that self-generated work orders are not being addressed.

If more than 3 inches of water has accumulated in a parking lot and 5% or more of the parking lot is unusable, and it is extensive, then it may require significant expenditures to repair.

If more than 3 inches of water has accumulated in a parking lot and 5% or more of the parking lot is unusable, then there may be a structural issue associated with settling.

If more than 3 inches of water has accumulated in a parking lot and 5% or more of the parking lot is unusable, then this deficiency can be seen by the public and may result in reputational harm.

TABLE 43—POTENTIAL LEAD-BASED PAINT HAZARDS – VISUAL ASSESSMENT STANDARD

Definition and Location	1
Definition	Lead-based paint (LBP) is paint or other surface coatings that contain lead equal to or exceeding federal regulatory levels, currently 1.0 milligram per square centimeter or 0.5 percent by weight. Deteriorated paint or surface coatings found in homes built before 1978 are LBP hazards if the paint is LBP. Visual Assessment is surface by surface determination of paint condition.
Location	Unit: Anywhere paint is present
	Inside: Anywhere paint is present
	Outside: Anywhere paint is present
Deficiency 1 – Potentia	l Lead-Based Paint Hazards – Visual Assessment: Unit
Deficiency	Paint in a Unit or Inside the target property is deteriorated – below the level required for lead-safe work practices by a lead-certified firm or for passing clearance.
Deficiency Criteria	Paint is deteriorated (e.g., peeling, chipping, chalking, cracking, or detached from the substrate). For large surface areas in the Unit, deteriorated paint is less than or equal to 2 square feet, per room; for small surface areas, less than or equal to 10% per component ("de minimis").
Health and Safety Determination	Standard

Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	·
HCV Pass/Fail	Fail
Rationale	If deteriorated lead-based paint is present, then it may be ingested by
	young children and cause damage to the brain, the nervous system, other
	vital organs, and blood, and may also cause behavioral problems, learning
	disabilities, seizures, etc.
	If deteriorated lead-based paint is present, then significant costs may be
	incurred associated with control.
	incurred associated with control.
	If deteriorated lead-based paint is present, and a resident becomes ill as a
	result of exposure, then HUD may be financially liable.
Deficiency 1 – Potential I	ead-Based Paint Hazards – Visual Assessment: Inside
Deficiency 1 – Potential L	Paint in a Unit or Inside the target property is deteriorated – below the level
Deliciency	required for lead-safe work practices by a lead-certified firm or for passing
	, , , , , , , , , , , , , , , , , , , ,
	clearance.
Deficiency Criteria	Paint is deteriorated (e.g., peeling, chipping, chalking, cracking, or detached
	from the substrate). For large surface areas inside the target property,
	deteriorated paint is less than or equal to 2 square feet, per room; for small
	surface areas, less than or equal to 10% per component ("de minimis").
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	30 ddy3
HCV Pass/Fail	Fail
Rationale	If deteriorated lead-based paint is present, then it may be ingested by
	young children and cause damage to the brain, the nervous system, other
	vital organs, and blood, and may also cause behavioral problems, learning
	disabilities, seizures, etc.
	If deteriorated lead-based paint is present, then significant costs may be
	incurred associated with control.
	If deteriorated lead-based paint is present, and a resident becomes ill as a
	result of exposure, then HUD may be financially liable.

Onficianou 2 Detartial I	load Racad Daint Hazards - Visual Assessments Hait
•	Lead-Based Paint Hazards – Visual Assessment: Unit
Deficiency	Paint in a Unit or Inside the target property is deteriorated – above the leve required for lead-safe work practices by a lead-certified firm and passing clearance.
Deficiency Criteria	Paint is deteriorated (e.g., peeling, chipping, chalking, cracking, or detached from the substrate). For large surface areas in the Unit, deteriorated paint is more than 2 square feet, per room; for small surface areas, greater than 10% per component ("significant").
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If deteriorated lead-based paint is present, then it may be ingested by young children and cause damage to the brain, the nervous system, other vital organs, and blood, and may also cause behavioral problems, learning disabilities, seizures, etc.
	If deteriorated lead-based paint is present, then significant costs may be incurred associated with control.
	If deteriorated lead-based paint is present, and a resident becomes ill as a result of exposure, then HUD may be financially liable.
Deficiency 2 – Potential I	Lead-Based Paint Hazards – Visual Assessment: Inside
Deficiency	Paint in a Unit or Inside the target property is deteriorated – above the level required for lead-safe work practices by a lead-certified firm and passing clearance.
Deficiency Criteria	Paint is deteriorated (e.g., peeling, chipping, chalking, cracking, or detached from the substrate). For large surface areas Inside the target property, deteriorated paint is more than 2 square feet, per room; for small surface areas, greater than 10% per component ("significant").
Health and Safety	Severe Non-Life Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days

HCV Pass/Fail	Fail
Rationale	If deteriorated lead-based paint is present, then it may be ingested by young children and cause damage to the brain, the nervous system, other vital organs, and blood, and may also cause behavioral problems, learning disabilities, seizures, etc.
	If lead-based paint is present, then significant costs may be incurred associated with control.
	If lead-based paint is present, and a resident becomes ill as a result of exposure, then HUD may be financially liable.
Deficiency 3 – Potential I	ead-Based Paint Hazards – Visual Assessment: Outside
Deficiency	Paint Outside on a target property is deteriorated – below the level required for lead-safe work practices by a lead-certified firm or for passing clearance.
Deficiency Criteria	Paint is deteriorated (e.g., peeling, chipping, chalking, cracking, or detached from the substrate). Deteriorated paint is less than or equal to 20 square feet ("de minimis").
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If deteriorated lead-based paint is present, then it may be ingested by young children and cause damage to the brain, the nervous system, other vital organs, and blood, and may also cause behavioral problems, learning disabilities, seizures, etc.
	If deteriorated lead-based paint is present, then significant costs may be incurred associated with control.
	If deteriorated lead-based paint is present, and a resident becomes ill as a result of exposure, then HUD may be financially liable.
Deficiency 4 – Potential I	ead-Based Paint Hazards – Visual Assessment: Outside
Deficiency	Paint Outside on a target property is deteriorated – above the level required for lead-safe work practices by a lead-certified firm and passing clearance.

Deficiency Criteria	Paint is deteriorated (e.g., peeling, chipping, chalking, cracking, or detached
,	from the substrate). Deteriorated paint is more than 20 square feet
	("significant").
	(0.8
Health and Safety	Severe Non-Life Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If deteriorated lead-based paint is present, then it may be ingested by
	young children and cause damage to the brain, the nervous system, other
	vital organs, and blood, and may also cause behavioral problems, learning
	disabilities, seizures, etc.
	If deteriorated lead-based paint is present, then significant costs may be
	incurred associated with control.
	If deteriorated lead-based paint is present, and a resident becomes ill as a
	result of exposure, then HUD may be financially liable.

TABLE 44—PRIVATE ROADS AND DRIVEWAYS STANDARD

Definition and Location		
Definition	Road leading from a public road to a dwelling or garage.	
Location	Outside: Throughout the site	
Deficiency 1 – Private Roads and Driveways: Outside		
Deficiency	Road or driveway access to the property is blocked or impassable for vehicles.	
Deficiency Criteria	Road or driveway access to the property is blocked or impassable for vehicles.	
Health and Safety	Severe Non-Life Threatening	
Determination		
Correction Timeframe	24 hours	
HCV Correction	30 days	
Timeframe		
HCV Pass/Fail	Fail	

If road or driveway access to the property is blocked or impassable for vehicles, then emergency vehicles would have trouble accessing the property.

If road or driveway access to the property is blocked or impassable for vehicles, then the resident may not be able to fully use a feature that is expected to be provided and maintained as part of their rent.

If road or driveway access to the property is blocked or impassable for vehicles, then it will likely be identified during routine maintenance activities and the presence of this deficiency may indicate that self-generated work orders are not being addressed.

Deficiency	Road or driveway has potholes.
Deficiency Criteria	Any one pothole is greater than 4 inches deep and 144 square inches wide.
	OR
	Any number of potholes taken cumulatively is greater than 4 inches deep
	and 144 square inches wide.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a road or driveway has pothole(s), then there is potential for increased risk of injury to the resident due to tripping or falling.
	If a road or driveway has pothole(s), then the resident may not be able to fully use a feature that is expected to be provided and maintained as part of their rent.
	If a road or driveway has pothole(s), then there is an increased risk of damage to the resident's vehicle.
	If a road or driveway has pothole(s), then the resident will likely report this, and the presence of this deficiency may indicate that complaint-driven work orders are not being addressed.
	If a road or driveway has pothole(s), then it will likely be identified during routine maintenance activities and the presence of this deficiency may indicate that self-generated work orders are not being addressed.
	If a road or driveway has pothole(s), then this deficiency can be seen by the public and may result in reputational harm.

TABLE 45—REFRIGERATOR STANDARD

Definition	A device designed to keep food from spoiling by cooling and freezing.
Location	Unit: Kitchen or any area or room the resident or property may choose to have a refrigerator.
	Incides Vitaban community room or any area or room the property may
	Inside: Kitchen, community room, or any area or room the property may choose to have a refrigerator.
eficiency 1 – Refrigerato	or: Unit
Deficiency	Refrigerator is inoperable such that it may be unable to safely and adequately store food.
Deficiency Criteria	Refrigerator is inoperable (i.e., overall system is not meeting function or purpose; with or without visible damage) such that it may be unable to safely and adequately store food.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a refrigerator is inoperable such that it may be unable to safely and
	adequately store food, then the resident may be exposed to pathogen growth on food that increases the risk of foodborne illness.
	If a refrigerator is inoperable such that it may be unable to safely and adequately store food, then the resident may not be able to fully use an appliance that is expected to be provided and maintained as part of their rent.
	A resident is likely to notice if a refrigerator is inoperable such that it may be unable to safely and adequately store food and to recognize it is important enough to report it to property management because it may present health hazards or usability barriers. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in health hazards or usability barriers.

Deficiency 1 – Refrigerate	
Deficiency	Refrigerator is inoperable such that it may be unable to safely and adequately store food.
Deficiency Criteria	Refrigerator is inoperable (i.e., overall system is not meeting function or purpose; with or without visible damage) such that it may be unable to safely and adequately store food.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a refrigerator is inoperable such that it may be unable to safely and adequately store food, then the resident may be exposed to pathogen growth on food that increases the risk of foodborne illness.
	If a refrigerator is inoperable such that it may be unable to safely and adequately store food, then the resident may not be able to fully use an appliance that is expected to be provided and maintained as part of their rent.
	Property management would be expected to ensure that staff members understand how to identify a refrigerator that is inoperable such that it may be unable to safely and adequately store food. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in health hazards or usability barriers.
Deficiency 2 – Refrigerat	or: Unit
Deficiency	Refrigerator component is damaged such that it impacts functionality.
Deficiency Criteria	Refrigerator component is damaged (i.e., visibly defective) such that it impacts functionality.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail

Rationale If a refrigerator component is damaged such that it impacts functionality, then the resident may be exposed to pathogen growth on food that increases the risk of foodborne illness. If a refrigerator component is damaged such that it impacts functionality,

then the resident may not be able to fully use an appliance that is expected to be provided and maintained as part of their rent.

A resident is likely to notice if a refrigerator component is damaged such that it impacts functionality and to recognize it is important enough to report it to property management because it may present health hazards or usability barriers. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in health hazards or usability barriers.

Deficiency 2 – Refrigerate	or: Inside
Deficiency	Refrigerator component is damaged such that it impacts functionality.
Deficiency Criteria	Refrigerator component is damaged (i.e., visibly defective) such that it impacts functionality.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a refrigerator component is damaged such that it impacts functionality, then the resident may not be able to fully use an appliance that is expected to be provided and maintained as part of their rent.
	Property management would be expected to ensure that staff members understand how to identify a refrigerator component that is damaged such that it impacts functionality. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in usability barriers.

Deficiency 3 – Refrigerator: Unit	
Deficiency	Refrigerator is missing.
Deficiency Criteria	Refrigerator is missing (i.e., evidence of prior installation, but is now not present).
Health and Safety Determination	Standard

Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a refrigerator is missing, then the resident may be exposed to pathogen growth on food that increases the risk of foodborne illness.
	If a refrigerator is missing, then the resident may not be able to fully use an appliance that is expected to be provided and maintained as part of their rent.
	A resident is likely to notice if a refrigerator is missing and to recognize it is important enough to report it to property management because it may present health hazards or usability barriers. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in health hazards or usability barriers.

TABLE 46—RETAINING WALL STANDARD

Definition and Location	
Definition	A vertical structure that retains soil or rock at various grades.
Location	Outside: Property grounds.
Deficiency 1 – Retaining	Wall: Outside
Deficiency	Retaining wall is leaning away from the fill side.
Deficiency Criteria	Retaining wall is leaning away from the fill side.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a retaining wall is leaning away from the fill side, then the resident may be
	at risk of injury due to potential wall collapse.
	If a retaining wall is leaning away from the fill side, then it will likely be
	identified during routine maintenance activities and the presence of this
	deficiency may indicate that self-generated work orders are not being
	addressed.

Deficiency 2 – Retaining	Deficiency 2 – Retaining Wall: Outside	
Deficiency	Retaining wall is partially or completely collapsed.	
Deficiency Criteria	Retaining wall is partially or completely collapsed.	
Health and Safety	Standard	
Determination		
Correction Timeframe	30 days	
HCV Correction	30 days	
Timeframe		
HCV Pass/Fail	Fail	
Rationale	If a retaining wall is partially or completely collapsed, then the resident may be exposed to potential hazards.	
	If a retaining wall is partially or completely collapsed, then it will likely be identified during routine maintenance activities and the presence of this deficiency may indicate that self-generated work orders are not being addressed.	
	If a retaining wall is partially or completely collapsed, then this could be a substantial cost to correct.	

TABLE 47—ROOF ASSEMBLY STANDARD

Definition and Location	
Definition	The external upper covering of a house or other building.
Location	Outside: On top of building.
Deficiency 1 – Roof Asser	mbly: Outside
Deficiency	Restricted flow of water from a roof drain, gutter, or downspout.
Deficiency Criteria	Debris is limiting the ability of water to drain; water may not be present. OR An area of approximately 25 square feet of ponding water is located above the drain.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days

HCV Pass/Fail	Fail
Rationale	If debris is limiting the ability of water to drain, then ponding water may occur and promote infestation.
	If debris is limiting the ability of water to drain or approximately 25 square feet of ponding water is located above the drain, then it is likely routine work orders are not being addressed.
	The roof assembly should be checked during periodic property inspections, and according to industry best practices, should be included in a preventative maintenance plan. If debris is limiting the ability of water to drain or approximately 25 square feet of ponding water is located above the drain, then it may indicate preventative maintenance activities could be improved.
	If debris is limiting the ability of water to drain, and ponding water occurs, then it may indicate a level of structural failure in the roof assembly, which will likely result in significant costs to repair.
	If debris is limiting the ability of water to drain, and ponding water occurs, then there will be increased weight on the roof resulting in possible collapse. Additionally, the presence of this deficiency may indicate a level of structural failure in the roof assembly.

Deficiency 2 – Roof Asse	mbly: Outside
Deficiency	Gutter component is damaged, missing, or unfixed.
Deficiency Criteria	Gutter component is damaged (i.e., visibly defective; impacts functionality).
	OR
	Gutter component is missing (i.e., evidence of prior installation, but now not present or is incomplete).
	OR
	Gutter component is unfixed.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail

Rationale

If a gutter component is damaged, missing, or unfixed, then the resident may be injured by falling components.

If a gutter component is damaged, missing, or unfixed, and a stream of water is diverted off its intended course, then the resident cannot fully use a feature that is expected to be provided and maintained as part of their rent.

If a gutter component is damaged, missing, or unfixed, then the resident would likely report this deficiency, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.

Deficiency 3 – Roof Asser	mbly: Outside
Deficiency	Roof surface has standing water.
Deficiency Criteria	Water ponding in an area approximately 25 square feet or greater on a flat
	roof surface not near a drain or scupper.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If there is water ponding in an area approximately 25 square feet or greater on a flat roof surface not near a drain or scupper, this may promote an environment conducive to infestation, which may jeopardize the resident's health.
	If there is water ponding in an area approximately 25 square feet or greater on a flat roof surface not near a drain or scupper, then the resident would likely report this deficiency, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	If there is water ponding in an area approximately 25 square feet or greater on a flat roof surface not near a drain or scupper, then it is likely that maintenance staff is not identifying deficiencies or responding to self-generated work orders.
	If there is water ponding in an area approximately 25 square feet or greater on a flat roof surface not near a drain or scupper, then it may be a sign of roof assembly failure, which has a significant cost to repair.

If there is water ponding in an area approximately 25 square feet or greater on a flat roof surface not near a drain or scupper, then it may increase the weight on the roof assembly and indicate a level of structural failure.

Deficiency	Substrate is exposed.
Deficiency Criteria	Any amount of substrate is exposed.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the substrate is exposed, and it leads to water infiltration, then the
	resident may be exposed to mold.
	If the substrate is exposed, and there is a structural defect, then the resident could be injured as the result of collapse.
	If the substrate is exposed, then it is likely that maintenance staff is not identifying deficiencies or responding to self-generated work orders.
	If the substrate is exposed, then it is likely that preventative maintenance activities are not being addressed.
	If the substrate is exposed, the repair will likely be significant enough to incur capital costs.
	If the substrate is exposed, then the probability of water infiltration increases, which may compromise structural integrity.

Deficiency 5 – Roof Assembly: Outside	
Deficiency	Roof assembly has penetrative hole.
Deficiency Criteria	Penetrative, unintentional hole of any size is found.
	OR
	Intentional, penetrative hole of any size is found and is not covered by vents or screens.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days

HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the roof has an unintentional penetrative hole or intentional penetrative hole not covered by a vent or screen, it may lead to water infiltration that could cause mold or mildew, which could affect the resident's health.
	If the roof has an unintentional penetrative hole or intentional penetrative hole not covered by a vent or screen, and there is a structural defect, then the resident could be injured as the result of collapse.
	If the roof has an unintentional penetrative hole or intentional penetrative hole not covered by a vent or screen, then it is likely preventative maintenance activities are not being addressed.
	If the roof has an unintentional penetrative hole or intentional penetrative hole not covered by a vent or screen, then it may be a sign of roof assembly failure, which has a significant cost to repair.

Deficiency 6 – Roof Asse	mbly: Outside
<u>`</u>	•
Deficiency	Roof assembly is damaged.
Deficiency Criteria	Roof assembly is damaged (i.e., visibly defective; impacts functionality),
	causing one or more components to become unstable.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the roof assembly is damaged (i.e., visibly defective; impacts
	functionality), causing one or more components to become unstable, and
	there is a structural defect, then the resident could be injured as the result of collapse.
	If the roof assembly is damaged (i.e., visibly defective; impacts
	functionality), causing one or more components to become unstable, then
	this may indicate that maintenance staff is not identifying deficiencies or
	responding to self-generated work orders.
	If the roof assembly is damaged (i.e., visibly defective; impacts
	functionality), causing one or more components to become unstable, then it

may indicate that maintenance staff is not addressing preventive maintenance activities.
If the roof assembly is damaged (i.e., visibly defective; impacts functionality), causing one or more components to become unstable, then structural failure may occur.

TABLE 48—SHARP EDGES STANDARD

Definition and Location	
Definition and Location	Dhysical hazards within the built environment /i.e. human made structures
Delilliuoli	Physical hazards within the built environment (i.e., human-made structures,
	features, and facilities) that can lacerate or puncture skin.
Location	Unit: Throughout the Unit.
	Inside: Normal paths of travel throughout the built environment (e.g.,
	hallways, shared living spaces, shared facilities).
	Outside: Normal paths of travel throughout the built environment (e.g.,
	sidewalks, walkways, playgrounds, courtyards).
Deficiency 1 – Sharp Edg	es: Unit
Deficiency	A sharp edge that can result in a cut or puncture hazard is present.
Deficiency Criteria	A sharp edge that can result in a cut or puncture hazard that is likely to
	require emergency care (e.g., stitches) is present within the built
	environment (i.e., human-made structures, features, and facilities).
Health and Safety	Severe Non-Life Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a sharp edge that can result in a cut or puncture hazard that is likely to
	require emergency care is present within the Unit, then there may be an
	increased safety risk to the resident, which may result in injury (e.g.,
	laceration, puncture).
	A resident is likely to notice if a sharp edge that can result in a cut or
	puncture hazard that is likely to require emergency care is present within
	the Unit and to recognize it is important enough to report it to property
	management because it may present safety hazards. Property management
	management security present surery mazurus. Troperty munugement

should be expected to prioritize a work order to remedy this deficiency
because it may result safety hazards.

Deficiency 1 – Sharp Edge	es: Inside
Deficiency	A sharp edge that can result in a cut or puncture hazard is present.
Deficiency Criteria	A sharp edge that can result in a cut or puncture hazard that is likely to require emergency care (e.g., stitches) is present within the built environment (i.e., human-made structures, features, and facilities).
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a sharp edge that can result in a cut or puncture hazard that is likely to require emergency care is present within the Inside area, then there may be an increased safety risk to the resident, which may result in injury (e.g., laceration, puncture). Property management would be expected to ensure that staff members
	understand how to identify the presence of a sharp edge that can result in a cut or puncture hazard that is likely to require emergency care within the Inside area. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards.
Deficiency 1 – Sharp Edge	es: Outside
Deficiency	A sharp edge that can result in a cut or puncture hazard is present.
Deficiency Criteria	A sharp edge that can result in a cut or puncture hazard that is likely to require emergency care (e.g., stitches) is present on or adjacent to the built environment (i.e., human-made structures, features, and facilities).
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail

Rationale	If a sharp edge that can result in a cut or puncture hazard that is likely to require emergency care is present in the Outside area, then there may be an increased safety risk to the resident, which may result in injury (e.g., laceration, puncture).
	Property management would be expected to ensure that staff members understand how to identify the presence of a sharp edge that can result in a cut or puncture hazard that is likely to require emergency care in the Outside area. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards.

TABLE 49—SIDEWALK, WALKWAY, AND RAMP STANDARD

Definition and Location	
Definition	A pathway for pedestrian travel.
Location	Outside: Ingress or egress locations to buildings, pools, parking lots, or any
	area that is considered a normal course of travel for pedestrians.
Deficiency 1 – Sidewalk,	Walkway, and Ramp: Outside
Deficiency	Sidewalk, walkway, or ramp is blocked or impassable.
Deficiency Criteria	Sidewalk, walkway, or ramp is blocked or impassable.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a sidewalk, walkway, or ramp is blocked or impassable, then the
	resident's egress may be impeded.
	If a sidewalk, walkway, or ramp is blocked or impassable, then the resident
	will likely report this, and the presence of this deficiency may indicate that
	complaint-based work orders are not being addressed.
	If a sidewalk, walkway, or ramp is blocked or impassable, then this should
	be identified through daily maintenance activities and its presence may
	indicate that self-generated work orders are not being addressed.

TABLE 50—SINK STANDARD

Definition and Location	
Definition	A basin with hardware designed to dispense and hold clean water (hot and cold) and discharge wastewater.
Location	Unit: Kitchen, bathroom, laundry area, and other interior space.
	Inside: Kitchen, bathroom, laundry area, and other interior space.
Peficiency 1 – Sink: Unit	
Deficiency	Sink component is missing.
Deficiency Criteria	Sink component is missing (i.e., evidence of prior installation, but now not present or is incomplete).
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a sink component is missing, then the resident may not be able to properly dispose of wastewater.
	If a sink component is missing, then the resident may not be able to use a fixture that is expected to be provided and maintained as part of their rent.
	If a sink component is missing, then the resident will likely report this deficiency, and the presence of this deficiency may indicate complaint-based work orders are not being addressed.
	If a sink component is missing, and the resident is unable to halt waterflow from the sink, and the resident is responsible for utilities, then this may result in increased utility costs to the resident.
Deficiency 1 – Sink: Insid	e
Deficiency	Sink component is missing.
Deficiency Criteria	Sink component is missing (i.e., evidence of prior installation, but now not present or is incomplete).
Health and Safety	Standard
Determination Determination	

HCV Correction	30 days
Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a sink component is missing, then the resident may not be able to properly dispose of wastewater.
	If a sink component is missing, then the resident may not be able to use a fixture that is expected to be provided and maintained as part of their rent.
	If a sink component is missing, then the resident will likely report the deficiency, and the presence of this deficiency may indicate complaint-based work orders are not being addressed.
Deficiency 2 – Sink: Unit	
Deficiency	Improperly functioning faucet.
Deficiency Criteria	Control knobs do not activate or deactivate hot and cold water.
	OR
	Water is directed outside of the basin.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If control knobs do not activate or deactivate hot and cold water, then the resident may not be able to regulate water temperature.
	If control knobs do not activate or deactivate hot and cold water or water is directed outside of the basin, then the resident may not be able to maintain hygiene.
	If control knobs do not activate or deactivate hot and cold water or water is directed outside of the basin, then the resident may be unable to use a fixture that is expected to be provided and maintained as part of their rent.
	If control knobs do not activate or deactivate hot and cold water or water is directed outside of the basin, and the resident is unable to halt the waterflow, and the resident is responsible for utilities, then this may result in increased utility costs to the resident.
	If control knobs do not activate or deactivate hot and cold water or water is directed outside of the basin, then the resident will likely report the

deficiency, and the presence of this deficiency may indicate complaintbased work orders are not being addressed.

Deficiency 2 – Sink: Inside		
Deficiency	Improperly functioning faucet.	
Deficiency Criteria	Control knobs do not activate or deactivate hot and cold water.	
	OR	
	Water is directed outside of the basin.	
Health and Safety Determination	Standard	
Correction Timeframe	30 days	
HCV Correction Timeframe	30 days	
HCV Pass/Fail	Fail	
Rationale	If control knobs do not activate or deactivate hot and cold water, then the resident may not be able to regulate water temperature.	
	If control knobs do not activate or deactivate hot and cold water or water is directed outside of the basin, then the resident may not be able to maintain hygiene.	
	If control knobs do not activate or deactivate hot and cold water or water is directed outside of the basin, then the resident may be unable to use a fixture that is expected to be provided and maintained as part of their rent.	
	If control knobs do not activate or deactivate hot and cold water or water is directed outside of the basin, then this will likely be observed during routine maintenance activities, and the presence of this deficiency may indicate self-generated work orders are not being addressed.	
Deficiency 3 – Sink: Unit		
Deficiency	Sink is not draining.	
Deficiency Criteria	Water is not draining from the basin of the sink.	
Health and Safety Determination	Standard	
Correction Timeframe	30 days	
HCV Correction Timeframe	30 days	

HCV Pass/Fail	Fail
Rationale	If water is not draining from the basin of the sink, then the resident may not be able to dispose of waste.
	If water is not draining from the basin of the sink, then the resident may be unable to use a fixture that is expected to be provided and maintained as part of their rent.
	If water is not draining from the basin of the sink, then the resident will likely report the deficiency, and the presence of this deficiency may indicate complaint-based work orders are not being addressed.
Deficiency 3 – Sink: Inside	e
Deficiency	Sink is not draining.
Deficiency Criteria	Water is not draining from the basin of the sink.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If water is not draining from the basin of the sink, then the resident may not be able to dispose of waste.
	If water is not draining from the basin of the sink, then the resident may be unable to use a fixture that is expected to be provided and maintained as part of their rent.
	If water is not draining from the basin of the sink, then this will likely be observed during routine maintenance activities, and the presence of this deficiency may indicate self-generated work orders are not being addressed.
Deficiency 4 – Sink: Unit	
Deficiency	Sink is improperly installed, pulling away from the wall, leaning, or there are gaps between the sink and wall.
Deficiency Criteria	Sink is improperly installed, pulling away from the wall, leaning, or there are gaps between the sink and wall.
Health and Safety Determination	Standard

Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the sink is improperly installed, pulling away from the wall, leaning, or there are gaps between the sink and wall, then the resident may be injured if the sink were to fall.
	If the sink is improperly installed, pulling away from the wall, leaning, or there are gaps between the sink and wall, then the resident will likely report this deficiency, and the presence of this deficiency may indicate complaint-based work orders are not being addressed.
	If the sink is improperly installed, pulling away from the wall, leaning, or there are gaps between the sink and wall, then this should be observed during daily maintenance activities, and the presence of this deficiency may indicate self-generated work orders are not being addressed.
Deficiency 4 – Sink: Insid	e
Deficiency	Sink is improperly installed, pulling away from wall, leaning, or there are gaps between the sink and wall.
Deficiency Criteria	Sink is improperly installed, pulling away from the wall, leaning, or there are gaps between the sink and wall.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the sink is improperly installed, pulling away from the wall, leaning, or there are gaps between the sink and wall, then the resident may be injured if the sink were to fall.
	If the sink is improperly installed, pulling away from the wall, leaning, or there are gaps between the sink and wall, then the resident will likely report this deficiency, and the presence of this deficiency may indicate complaint-based work orders are not being addressed.
	If the sink is improperly installed, pulling away from the wall, leaning, or there are gaps between the sink and wall, then this should be observed

	during daily maintenance activities, and the presence of this deficiency may indicate self-generated work orders are not being addressed.
Deficiency 5 – Sink: Unit	
Deficiency	Sink is damaged and does not hold water.
Deficiency Criteria	Sink is damaged (i.e., visibly defective; impacts functionality) and unable to hold water.
	OR
	Sink is damaged (i.e., visibly defective; impacts functionality) and there are obvious indications that the sink would be unable to hold water.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the sink is damaged and does not hold water, then the resident's ability to maintain a sanitary environment may be limited.
	If the sink is damaged and does not hold water, then the resident may not be able to use a fixture that is expected to be provided and maintained as part of their rent.
	If the sink is damaged and does not hold water, then the resident will likely report this deficiency, and the presence of this deficiency may indicate complaint-based work orders are not being addressed.
Deficiency 5 – Sink: Insid	e
Deficiency	Sink is damaged and does not hold water.
Deficiency Criteria	Sink is damaged (i.e., visibly defective; impacts functionality) and unable to hold water.
	OR
	Sink is damaged (i.e., visibly defective; impacts functionality) and there are obvious indications that the sink would be unable to hold water.
Health and Safety Determination	Standard
Correction Timeframe	30 days

HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the sink is damaged and does not hold water, then the resident's ability to maintain a sanitary environment may be limited.
	If the sink is damaged and does not hold water, then the resident may not be able to use a fixture that is expected to be provided and maintained as part of their rent.
	If the sink is damaged and does not hold water, then this should be observed during daily maintenance activities, and the presence of this deficiency may indicate self-generated work orders are not being addressed.

TABLE 51—SITE DRAINAGE STANDARD

Definition and Location	
Definition	An exterior system that directs the flow of surface water.
Location	Outside: Throughout the entire Outside area, especially adjacent to the built environment.
Deficiency 1 – Site Draina	age: Outside
Deficiency	Water runoff is unable to flow through the site drainage system.
Deficiency Criteria	Standing water is present above the outflow pipe entrance. OR Drainage is blocked such that the inspector believes water is unable to drain
	in the event of precipitation.
Health and Safety Determination	Advisory
Correction Timeframe	Advisory
HCV Correction Timeframe	Advisory
HCV Pass/Fail	Pass

Rationale	If standing water is present above the outflow pipe entrance or drainage is blocked, then it would likely be noticeable during a precipitation event and this should trigger a self-generated work order that would be prioritized and addressed.
	By design, site drainage systems require periodic monitoring for accumulation of debris, and according to industry best practices, to prevent water damage, should be included in a preventative maintenance plan. The presence of this deficiency may indicate preventative maintenance activities could be improved.
Deficiency 2 – Site Drain	age: Outside
Deficiency	Erosion is present.
Deficiency Criteria	Erosion is present and the footer is exposed. OR
	Erosion is more than 2 feet away from the built environment and its depth is equal to or greater than its measured distance from the built environment, and the inspector believes it may undermine the supporting soil.
Health and Safety Determination	Advisory
Correction Timeframe	Advisory
HCV Correction Timeframe	Advisory
HCV Pass/Fail	Pass
Rationale	According to industry best practices, maintaining the site to prevent erosion of soil should be included in a preventative maintenance plan as it is likely to occur over time, and the presence of this deficiency may indicate preventative maintenance activities could be improved.
Deficiency 3 – Site Drain	age: Outside
Deficiency	Grate is not secure or does not cover the site drainage system's collection point.
Deficiency Criteria	Grate is not secure or does not cover the site drainage system's collection

Deficiency 3 – Site Drainage: Outside	
Deficiency	Grate is not secure or does not cover the site drainage system's collection point.
Deficiency Criteria	Grate is not secure or does not cover the site drainage system's collection point.
Health and Safety Determination	Standard
Correction Timeframe	30 days

HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the grate is not secure or does not cover the drainage system's collection point, then it may result in an opening that increases the resident's risk of injury.
	The site drainage system should be checked during routine site walkthroughs and if the grate is not secure or does not cover the drainage system's collection point, then it would likely be observed and should trigger a self-generated work order that would be prioritized and addressed.
	By design, site drainage systems require periodic monitoring, including inspecting for safety hazards, and according to industry best practices, should be included in a preventative maintenance plan. The presence of this deficiency may indicate preventative maintenance activities could be improved.

TABLE 52—SMOKE ALARM STANDARD

Definition and Location	
Definition	A self-contained device that detects the presence of smoke, typically as an
	indicator of fire, and provides a visual or audio signal as an alert.
Location	Unit: Bedrooms, hallways, kitchens, stairwells.
	Inside: Hallways, kitchens, stairwells, common areas.
Deficiency 1 – Smoke Ala	rm: Unit
Deficiency	Smoke alarm is not installed where required.
Deficiency Criteria	Smoke alarm is not installed inside each sleeping area, outside each
	sleeping area, and on each level.
Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a smoke alarm is not installed inside each sleeping area, outside each
	sleeping area, and on each level, and there is a fire, then there may be an

increased safety risk to the resident due to fire-related hazards, such as smoke inhalation and burns, which may result in injury or death.

Property management would be expected to ensure that staff members understand how to identify a smoke alarm that is not installed inside each sleeping area, outside each sleeping area, and on each level. Management practices would be expected to assure prompt creation and prioritization of a work order to replace or install a smoke alarm, because it may result in safety hazards.

Deficiency 1 – Smoke Ala	Deficiency 1 – Smoke Alarm: Inside		
Deficiency	Smoke alarm is not installed where required.		
Deficiency Criteria	Smoke alarm is not installed on each level.		
Health and Safety	Life-Threatening		
Determination			
Correction Timeframe	24 hours		
HCV Correction	24 hours		
Timeframe			
HCV Pass/Fail	Fail		
Rationale	If a smoke alarm is not installed on each level, and there is a fire, then there may be an increased safety risk to the resident due to fire-related hazards, such as smoke inhalation and burns, which may result in injury or death.		
	Property management would be expected to ensure that staff members understand how to identify a smoke alarm that is not installed on each level. Management practices would be expected to assure prompt creation and prioritization of a work order to replace or install a smoke alarm because it may result in safety hazards.		

Deficiency 2 – Smoke Alarm: Unit	
Deficiency	Smoke alarm does not produce an audio or visual alarm when tested.
Deficiency Criteria	Smoke alarm does not produce an audio or visual alarm when tested.
Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail

Rationale

If a smoke alarm does not produce an audio or visual alarm when tested, then the resident may not receive warning of fire, resulting in an increased safety risk to the resident due to fire-related hazards, such as smoke inhalation and burns, which may result in injury or death.

Property management would be expected to ensure that staff members understand how to identify a smoke alarm that does not produce an audio or visual alarm when tested. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards.

Deficiency 2 – Smoke Alarm: Inside		
Deficiency	Smoke alarm does not produce an audio or visual alarm when tested.	
Deficiency Criteria	Smoke alarm does not produce an audio or visual alarm when tested.	
Health and Safety	Life-Threatening	
Determination		
Correction Timeframe	24 hours	
HCV Correction	24 hours	
Timeframe		
HCV Pass/Fail	Fail	
Rationale	If a smoke alarm does not produce an audio or visual alarm when tested, then the resident may not receive warning of fire, resulting in an increased safety risk to the resident due to fire-related hazards, such as smoke inhalation and burns, which may result in injury or death.	
	Property management would be expected to ensure that staff members understand how to identify a smoke alarm that does not produce an audio or visual alarm when tested. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards.	

TABLE 53—SPRINKLER ASSEMBLY STANDARD

Definition and Location	
Definition	Part of the fire protection (sprinkler) system that discharges water when activated once reaching a certain (predetermined) temperature.
Location	Unit: Bedrooms, living rooms, dining rooms, closets, kitchens, hallways, stairwells.

	Inside: Living rooms, dining rooms, closets, kitchens, hallways, stairwells, common areas.
	Outside: Covered decks, patios.
Deficiency 1 – Sprinkler	Assembly: Unit
Deficiency	Sprinkler head assembly is obstructed by an item, object, or encasement within 18 inches of the sprinkler head.
Deficiency Criteria	Sprinkler head assembly is obstructed by item, object, or encasement within
	18 inches of the sprinkler head.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a sprinkler head assembly is obstructed by an item, object, or encasement within 18 inches of the sprinkler head, then the coverage area of the sprinkler may be limited. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members understand how to identify a sprinkler head assembly that is obstructed by an item, object, or encasement within 18 inches of the sprinkler head. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may
	result in safety hazards.
Deficiency 1 – Sprinkler A	Assembly: Inside
Deficiency	Sprinkler head assembly is obstructed by an item, object, or encasement
	within 18 inches of the sprinkler head.
Deficiency Criteria	Sprinkler head assembly is obstructed by item, object, or encasement within 18 inches of the sprinkler head.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours

HCV Pass/Fail	Fail
Rationale	If a sprinkler head assembly is obstructed by an item, object, or encasement within 18 inches of the sprinkler head, then the coverage area of the sprinkler may be limited. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death.
	Property management would be expected to ensure that staff members understand how to identify a sprinkler head assembly that is obstructed by an item, object, or encasement within 18 inches of the sprinkler head. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards.
Deficiency 1 – Sprinkler	Assembly: Outside
Deficiency	Sprinkler head assembly is obstructed by an item, object, or encasement within 18 inches of the sprinkler head.
Deficiency Criteria	Sprinkler head assembly is obstructed by item, object, or encasement within 18 inches of the sprinkler head.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If a sprinkler head assembly is obstructed by an item, object, or encasement within 18 inches of the sprinkler head, then the coverage area of the sprinkler may be limited. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death.
	Property management would be expected to ensure that staff members understand how to identify a sprinkler head assembly that is obstructed by an item, object, or encasement within 18 inches of the sprinkler head. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards.
Deficiency 2 – Sprinkler	Assembly: Unit
Deficiency	Paint or foreign material on the sprinkler head assembly.
Deficiency Criteria	There is paint or a foreign material on the sprinkler head assembly.

Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If there is paint or a foreign material on the sprinkler head assembly, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death.
	Property management would be expected to ensure that staff members understand how to identify if there is paint or a foreign material on the sprinkler head assembly. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards.
eficiency 2 – Sprinkler A	Assembly: Inside
Deficiency	Paint or foreign material on the sprinkler head assembly.
Deficiency Criteria	There is paint or a foreign material on the sprinkler head assembly.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If there is paint or a foreign material on the sprinkler head assembly, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death.
	Property management would be expected to ensure that staff members understand how to identify if there is paint or a foreign material on the sprinkler head assembly. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards.
Deficiency 2 – Sprinkler <i>A</i>	Assembly: Outside
Deficiency	Paint or foreign material on the sprinkler head assembly.
•	

Deficiency Criteria	There is paint or a foreign material on the sprinkler head assembly.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If there is paint or a foreign material on the sprinkler head assembly, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death.
	Property management would be expected to ensure that staff members understand how to identify if there is paint or a foreign material on the sprinkler head assembly. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency, because it may result in safety hazards.
Deficiency 3 – Sprinkler A	Assembly: Unit
Deficiency	Sprinkler head escutcheon is missing.
Deficiency Criteria	Sprinkler head escutcheon is missing (i.e., evidence of prior installation, but
	now not present or is incomplete).
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members understand how to identify if a sprinkler head escutcheon is missing.
	Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards.

Deficiency 3 – Sprinkler Assembly: Inside Deficiency Sprinkler head escutcheon is missing. Deficiency Criteria Sprinkler head escutcheon is missing (i.e., evidence of prior installation, but now not present or is incomplete). Health and Safety Determination Correction Timeframe 24 hours HCV Correction 24 hours HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members understand how to identify if a sprinkler head escutcheon is missing. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards. Deficiency 3 – Sprinkler Assembly: Outside Deficiency Criteria Sprinkler head escutcheon is missing. Deficiency Criteria Sprinkler head escutcheon is missing (i.e., evidence of prior installation, but now not present or is incomplete). Health and Safety Life-Threatening HCV Correction 24 hours HCV Correction 24 hours HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members understand how to identify if a sprinkler head escutcheon is missing.		
Deficiency Criteria Sprinkler head escutcheon is missing (i.e., evidence of prior installation, but now not present or is incomplete). Health and Safety Determination Correction Timeframe 24 hours HCV Correction 24 hours HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members understand how to identify if a sprinkler head escutcheon is missing. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards. Deficiency 3 – Sprinkler Assembly: Outside Deficiency Criteria Sprinkler head escutcheon is missing. Deficiency Criteria Sprinkler head escutcheon is missing (i.e., evidence of prior installation, but now not present or is incomplete). Health and Safety Determination Correction Timeframe 24 hours HCV Correction 4 Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members	Deficiency 3 – Sprinkler A	Assembly: Inside
Health and Safety Life-Threatening	Deficiency	Sprinkler head escutcheon is missing.
Health and Safety Determination Correction Timeframe 24 hours HCV Correction 24 hours Timeframe HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members understand how to identify if a sprinkler head escutcheon is missing. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards. Deficiency 3 – Sprinkler Assembly: Outside Deficiency Criteria Sprinkler head escutcheon is missing. Deficiency Criteria Sprinkler head escutcheon is missing (i.e., evidence of prior installation, but now not present or is incomplete). Health and Safety Life-Threatening Determination Correction Timeframe 24 hours HCV Correction 24 hours Timeframe HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members	Deficiency Criteria	Sprinkler head escutcheon is missing (i.e., evidence of prior installation, but
Determination 24 hours		now not present or is incomplete).
Correction Timeframe 24 hours HCV Correction 24 hours HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members understand how to identify if a sprinkler head escutcheon is missing. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards. Deficiency 3 – Sprinkler Assembly: Outside Deficiency Sprinkler head escutcheon is missing. Deficiency Criteria Sprinkler head escutcheon is missing (i.e., evidence of prior installation, but now not present or is incomplete). Health and Safety Life-Threatening Correction Timeframe 24 hours HCV Correction 24 hours HCV Correction 15 Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members	Health and Safety	Life-Threatening
HCV Correction Timeframe HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members understand how to identify if a sprinkler head escutcheon is missing. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards. Deficiency 3 – Sprinkler Assembly: Outside Deficiency Criteria Sprinkler head escutcheon is missing. Deficiency Criteria Sprinkler head escutcheon is missing (i.e., evidence of prior installation, but now not present or is incomplete). Health and Safety Life-Threatening Determination Correction Timeframe 24 hours HCV Correction 24 hours HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members	Determination	
Timeframe HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members understand how to identify if a sprinkler head escutcheon is missing. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards. Deficiency 3 – Sprinkler Assembly: Outside Deficiency Sprinkler head escutcheon is missing. Deficiency Criteria Sprinkler head escutcheon is missing (i.e., evidence of prior installation, but now not present or is incomplete). Health and Safety Life-Threatening Determination Correction Timeframe 24 hours HCV Correction 24 hours HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members	Correction Timeframe	24 hours
HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members understand how to identify if a sprinkler head escutcheon is missing. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards. Deficiency 3 – Sprinkler Assembly: Outside Deficiency Sprinkler head escutcheon is missing. Deficiency Criteria Sprinkler head escutcheon is missing (i.e., evidence of prior installation, but now not present or is incomplete). Health and Safety Determination Correction Timeframe 24 hours HCV Correction 24 hours HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members	HCV Correction	24 hours
Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members understand how to identify if a sprinkler head escutcheon is missing. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards. Deficiency 3 – Sprinkler Assembly: Outside Deficiency Sprinkler head escutcheon is missing. Deficiency Criteria Sprinkler head escutcheon is missing (i.e., evidence of prior installation, but now not present or is incomplete). Health and Safety Life-Threatening Determination Correction Timeframe 24 hours HCV Correction 24 hours HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members	Timeframe	
may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members understand how to identify if a sprinkler head escutcheon is missing. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards. Deficiency 3 – Sprinkler Assembly: Outside Deficiency Sprinkler head escutcheon is missing. Deficiency Criteria Sprinkler head escutcheon is missing (i.e., evidence of prior installation, but now not present or is incomplete). Health and Safety Life-Threatening Determination Correction Timeframe 24 hours HCV Correction 24 hours HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members	HCV Pass/Fail	Fail
be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members understand how to identify if a sprinkler head escutcheon is missing. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards. Deficiency 3 – Sprinkler Assembly: Outside Deficiency Sprinkler head escutcheon is missing. Deficiency Criteria Sprinkler head escutcheon is missing (i.e., evidence of prior installation, but now not present or is incomplete). Health and Safety Life-Threatening Determination Correction Timeframe 24 hours HCV Correction 24 hours HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members	Rationale	If a sprinkler head escutcheon is missing, then the activation of the sprinkler
risk of injury or death. Property management would be expected to ensure that staff members understand how to identify if a sprinkler head escutcheon is missing. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards. Deficiency 3 – Sprinkler Assembly: Outside Deficiency Sprinkler head escutcheon is missing. Deficiency Criteria Sprinkler head escutcheon is missing (i.e., evidence of prior installation, but now not present or is incomplete). Health and Safety Life-Threatening Determination Correction Timeframe 24 hours HCV Correction 24 hours HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members		may be impacted. If there is a fire, then the sprinkler head assembly may
Property management would be expected to ensure that staff members understand how to identify if a sprinkler head escutcheon is missing. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards. Deficiency 3 – Sprinkler Assembly: Outside Deficiency Sprinkler head escutcheon is missing. Deficiency Criteria Sprinkler head escutcheon is missing (i.e., evidence of prior installation, but now not present or is incomplete). Health and Safety Life-Threatening Determination Correction Timeframe 24 hours HCV Correction 24 hours HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members		be unable to limit the fire spread and the resident may be at an increased
understand how to identify if a sprinkler head escutcheon is missing. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards. Deficiency 3 – Sprinkler Assembly: Outside Deficiency Sprinkler head escutcheon is missing. Deficiency Criteria Sprinkler head escutcheon is missing (i.e., evidence of prior installation, but now not present or is incomplete). Health and Safety Determination Correction Timeframe 24 hours HCV Correction 24 hours Timeframe HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members		risk of injury or death.
understand how to identify if a sprinkler head escutcheon is missing. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards. Deficiency 3 – Sprinkler Assembly: Outside Deficiency Sprinkler head escutcheon is missing. Deficiency Criteria Sprinkler head escutcheon is missing (i.e., evidence of prior installation, but now not present or is incomplete). Health and Safety Determination Correction Timeframe 24 hours HCV Correction 24 hours HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members		Property management would be expected to ensure that staff members
Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards. Deficiency 3 – Sprinkler Assembly: Outside Deficiency Sprinkler head escutcheon is missing. Deficiency Criteria Sprinkler head escutcheon is missing (i.e., evidence of prior installation, but now not present or is incomplete). Health and Safety Determination Correction Timeframe 24 hours HCV Correction 24 hours HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members		
prioritization of a work order to remedy this deficiency because it may result in safety hazards. Deficiency 3 – Sprinkler Assembly: Outside Deficiency Sprinkler head escutcheon is missing. Deficiency Criteria Sprinkler head escutcheon is missing (i.e., evidence of prior installation, but now not present or is incomplete). Health and Safety Determination Correction Timeframe 24 hours HCV Correction 24 hours HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members		• • •
Deficiency 3 – Sprinkler Assembly: Outside Deficiency Sprinkler head escutcheon is missing. Deficiency Criteria Sprinkler head escutcheon is missing (i.e., evidence of prior installation, but now not present or is incomplete). Health and Safety Determination Correction Timeframe 24 hours HCV Correction 24 hours HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members		
DeficiencySprinkler head escutcheon is missing.Deficiency CriteriaSprinkler head escutcheon is missing (i.e., evidence of prior installation, but now not present or is incomplete).Health and Safety DeterminationLife-ThreateningCorrection Timeframe24 hoursHCV Correction Timeframe24 hoursHCV Pass/FailFailRationaleIf a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death.Property management would be expected to ensure that staff members		
Deficiency Criteria Sprinkler head escutcheon is missing (i.e., evidence of prior installation, but now not present or is incomplete). Health and Safety Determination Correction Timeframe HCV Correction Timeframe HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members	Deficiency 3 – Sprinkler A	Assembly: Outside
Health and Safety Determination Correction Timeframe 24 hours HCV Correction Timeframe HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members	Deficiency	Sprinkler head escutcheon is missing.
Health and Safety Determination Correction Timeframe 24 hours HCV Correction Timeframe HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members	Deficiency Criteria	Sprinkler head escutcheon is missing (i.e., evidence of prior installation, but
Correction Timeframe 24 hours HCV Correction 24 hours HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members		now not present or is incomplete).
Correction Timeframe 24 hours 24 hours HCV Correction Timeframe HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members	Health and Safety	Life-Threatening
HCV Correction Timeframe HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members	Determination	
Timeframe HCV Pass/Fail Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members	Correction Timeframe	24 hours
HCV Pass/Fail Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members	HCV Correction	24 hours
Rationale If a sprinkler head escutcheon is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members	Timeframe	
may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death. Property management would be expected to ensure that staff members	HCV Pass/Fail	Fail
	Rationale	may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased

Management practices would be expected to assure prompt creation and
prioritization of a work order to remedy this deficiency because it may
result in safety hazards.

	result in safety nazards.
Deficiency 4 – Sprinkler	Assembly: Unit
Deficiency	Concealed sprinkler cover plate assembly is missing.
Deficiency Criteria	Concealed sprinkler cover plate assembly is missing (i.e., evidence of prior installation, but now not present or is incomplete).
	installation, but now not present or is incomplete).
Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a concealed sprinkler cover plate assembly is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death.
	Property management would be expected to ensure that staff members understand how to identify if a concealed sprinkler cover plate assembly is missing. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards.
Deficiency 4 – Sprinkler	Assembly: Inside
Deficiency	Concealed sprinkler cover plate assembly is missing.
Deficiency Criteria	Concealed sprinkler cover plate assembly is missing (i.e., evidence of prior

Deficiency 4 – Sprinkler Assembly: Inside	
Deficiency	Concealed sprinkler cover plate assembly is missing.
Deficiency Criteria	Concealed sprinkler cover plate assembly is missing (i.e., evidence of prior installation, but now not present or is incomplete).
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If a concealed sprinkler cover plate assembly is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head

assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death.

Property management would be expected to ensure that staff members understand how to identify if a concealed sprinkler cover plate assembly is missing. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards.

Deficiency 4 – Sprinkler Assembly: Outside	
Deficiency	Concealed sprinkler cover plate assembly is missing.
Deficiency Criteria	Concealed sprinkler cover plate assembly is missing (i.e., evidence of prior
	installation, but now not present or is incomplete).
Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a concealed sprinkler cover plate assembly is missing, then the activation of the sprinkler may be impacted. If there is a fire, then the sprinkler head
	assembly may be unable to limit the fire spread and the resident may be at an increased risk of injury or death.
	Property management would be expected to ensure that staff members understand how to identify if a concealed sprinkler cover plate assembly is missing. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards.

TABLE 54—STAIRS STANDARD

Definition and Location	ı
Definition	A series of steps or flights of steps, connected by landings.
Location	Unit: Hallway, stairwell.
	Inside: Hallway, stairwell.
	Outside: Along elevated walking paths.

Deficiency 1 – Stairs: Unit	
Deficiency	Tread is missing or damaged.
Deficiency Criteria	Tread on a set of stairs is missing (i.e., evidence of prior installation, but now not present or is incomplete).
	OR
	Tread on a set of stairs is loose or unlevel.
	OR
	A portion of the tread nosing that is greater than 1 inch in depth or 4 inches wide is damaged or broken.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a tread is missing or damaged, then there is an increased probability of falls that may lead to injury.
	If a tread is missing or damaged, and there is an emergency, then the resident's ability to egress or ingress may be impeded.
	If a tread is missing or damaged, then the resident will likely report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	If a tread is missing or damaged, then it should be identified through regular maintenance activities and the presence of this deficiency may indicate that self-generated work orders are not being addressed.
Deficiency 1 – Stairs: Insi	de
Deficiency	Tread is missing or damaged.
Deficiency Criteria	Tread on a set of stairs is missing (i.e., evidence of prior installation, but now not present or is incomplete).
	OR
	Tread on a set of stairs is loose or unlevel.
	OR

	A portion of the tread nosing that is greater than 1 inch in depth or 4 inches wide is damaged or broken.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a tread is missing or damaged, then there is an increased probability of
	falls that may lead to injury.
	If a tread is missing or damaged, and there is an emergency, then the
	resident's ability to egress or ingress may be impeded.
	If a tread is missing or damaged, then the resident will likely report this, and
	the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	If a tread is missing or damaged, then it should be identified through regular
	maintenance activities and the presence of this deficiency may indicate that self-generated work orders are not being addressed.

Deficiency 1 – Stairs: Outside	
Deficiency	Tread is missing or damaged
Deficiency Criteria	Tread on a set of stairs is missing (i.e., evidence of prior installation, but now not present or is incomplete).
	OR
	Tread on a set of stairs is loose or unlevel.
	OR
	A portion of the tread nosing that is greater than 1 inch in depth or 4 inches wide is damaged or broken.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail

Rationale	If a tread is missing or damaged, then there is an increased probability of falls that may lead to injury.
	If a tread is missing or damaged, and there is an emergency, then the resident's ability to egress or ingress may be impeded.
	If a tread is missing or damaged, then the resident will likely report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	If a tread is missing or damaged, then it should be identified through regular maintenance activities and the presence of this deficiency may indicate that self-generated work orders are not being addressed.

Deficiency 2 – Stairs: Unit	
Deficiency	Stringer is damaged.
Deficiency Criteria	Stringer is damaged (i.e., visibly defective; impacts functionality).
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a stringer is damaged, then there is an increased probability of falls that may lead to injury.
	If a stringer is damaged, and there is an emergency, then the resident's ability to egress or ingress may be impeded.
	If a stringer is damaged, then the resident will likely report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	If a stringer is damaged, then it should be identified through regular maintenance activities and the presence of this deficiency may indicate that self-generated work orders are not being addressed.

Deficiency 2 – Stairs: Inside	
Deficiency	Stringer is damaged.
Deficiency Criteria	Stringer is damaged (i.e., visibly defective; impacts functionality).
Health and Safety Determination	Standard

Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a stringer is damaged, then there is an increased probability of falls that may lead to injury.
	If a stringer is damaged, and there is an emergency, then the resident's ability to egress or ingress may be impeded.
	If a stringer is damaged, then the resident will likely report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	If a stringer is damaged, then it should be identified through regular maintenance activities and the presence of this deficiency may indicate that self-generated work orders are not being addressed.

Deficiency 2 – Stairs: Out	Deficiency 2 – Stairs: Outside	
Deficiency	Stringer is damaged.	
Deficiency Criteria	Stringer is damaged (i.e., visibly defective; impacts functionality).	
Health and Safety	Standard	
Determination		
Correction Timeframe	30 days	
HCV Correction	30 days	
Timeframe		
HCV Pass/Fail	Fail	
Rationale	If a stringer is damaged, then there is an increased probability of falls that may lead to injury.	
	If a stringer is damaged, and there is an emergency, then the resident's ability to egress or ingress may be impeded.	
	If a stringer is damaged, then the resident will likely report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.	
	If a stringer is damaged, then it should be identified through regular maintenance activities and the presence of this deficiency may indicate that self-generated work orders are not being addressed.	

TABLE 55—STRUCTURAL SYSTEM STANDARD

Definition	Load-bearing system within the built environment (i.e., human-made
Definition	structures, features, and facilities).
Location	Unit: All accessible areas within the dwelling and those areas to which the resident has sole access (e.g., dwelling balconies, decks, patios, basements)
	Inside: All accessible areas within the interior common spaces.
	Outside: All accessible areas throughout the exterior built environment
	(e.g., rooftop decks, patios, playgrounds).
Deficiency 1 – Structural	•
Deficiency	Structural system exhibits signs of serious failure.
Deficiency Criteria	Structural system exhibits signs of serious failure and may threaten the resident's safety.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If the structural system exhibits signs of serious failure, there may be an increased safety risk to the resident due to structural instability or collapse, which may result in injury or death.
	A resident is likely to notice if a structural system exhibits signs of serious failure within the unit and to recognize it is important enough to report it to property management because it may present safety hazards. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in safety hazards.
	If the structural system exhibits signs of serious failure, then it will likely require a capital expenditure to repair.
	If the structural system exhibits signs of serious failure, then a structural failure of the building or load-bearing component may occur.
	If the structural system exhibits signs of serious failure, and it is visible to visitors or the public, then it may convey a lack of adequate property management and impact the property's market appeal.

Deficiency 1 – Structural System: Inside	
Deficiency	Structural system exhibits signs of serious failure.
Deficiency Criteria	Structural system exhibits signs of serious failure and may threaten the resident's safety.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If the structural system exhibits signs of serious failure, there may be an increased safety risk to the resident due to structural instability or collapse, which may result in injury or death.
	Property management would be expected to ensure that staff members understand how to identify if a structural system exhibits signs of serious failure. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards.
	If the structural system exhibits signs of serious failure, then it will likely require a capital expenditure to repair.
	If the structural system exhibits signs of serious failure, then a structural failure of the building or load-bearing component may occur.
	If the structural system exhibits signs of serious failure, and it is visible to visitors or the public, then it may convey a lack of adequate property management and impact the property's market appeal.

Deficiency 1 – Structural System: Outside	
Deficiency	Structural system exhibits signs of serious failure.
Deficiency Criteria	Structural system exhibits signs of serious failure and may threaten the resident's safety.
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours

HCV Pass/Fail	Fail
Rationale	If the structural system exhibits signs of serious failure, there may be an increased safety risk to the resident due to structural instability or collapse, which may result in injury or death.
	Property management would be expected to ensure that staff members understand how to identify if a structural system exhibits signs of serious failure. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards.
	If the structural system exhibits signs of serious failure, then it will likely require a capital expenditure to repair.
	If the structural system exhibits signs of serious failure, then a structural failure of the building or load-bearing component may occur.
	If the structural system exhibits signs of serious failure, and it is visible to visitors or the public, then it may convey a lack of adequate property management and impact the property's market appeal.

TABLE 56—TOILET STANDARD

Definition and Location	
Definition	A plumbing fixture used to receive human waste and to discharge it through
	a waste pipe, using water as a conveying method.
Location	Unit: Bathroom.
	Inside: Bathroom.
Deficiency 1 – Toilet: Uni	t
Deficiency	Only 1 toilet was installed, and it is missing.
Deficiency Criteria	Only 1 toilet was installed, and it is missing (i.e., evidence of prior
	installation, but now not present or is incomplete).
Health and Safety	Life-Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	24 hours
Timeframe	
HCV Pass/Fail	Fail

Rationale If the toilet is missing, then the resident may inadvertently come into contact with sewage, which may result in illness. If the toilet is missing, then the resident's ability to dispose of human waste is limited. If the toilet is missing, then resident is unable to use a fixture that is expected to be provided and maintained as part of their rent. A resident is likely to notice if the toilet is missing and to recognize it is important enough to report to property management because it may present health or sanitary hazards. Property management should be expected to prioritize a work order to replace the toilet because it may result in health or sanitary hazards. Deficiency 1 - Toilet: Inside Deficiency Only 1 toilet was installed, and it is missing. **Deficiency Criteria** Only 1 toilet was installed, and it is missing (i.e., evidence of prior installation, but now not present or is incomplete). **Health and Safety** Standard Determination **Correction Timeframe** 30 days **HCV Correction** 30 days Timeframe

HCV	Pass/Fail	Fail
-----	-----------	------

Rationale

If the toilet is missing, then the resident may inadvertently come into contact with sewage, which may result in illness.

If the toilet is missing, then the resident's ability to dispose of human waste is limited.

If the toilet is missing, then the resident is unable to use a fixture that is expected to be provided and maintained as part of their rent.

Property management would be expected to ensure that staff members understand how to identify if the toilet is missing. Management practices would be expected to assure prompt creation and prioritization of a work order to replace the toilet because it may result in safety or sanitary hazards.

Deficiency 2 – Toilet: Unit

Deficiency

A toilet is missing and at least 1 toilet is installed elsewhere that is operational.

Deficiency Criteria	A toilet is missing (i.e., evidence of prior installation, but now not present or is incomplete) and at least 1 toilet is installed elsewhere within the Unit that is operational.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a toilet is missing, then the resident may inadvertently come into contact with sewage, which may result in illness.
	If a toilet is missing, then the resident's ability to dispose of human waste is limited.
	If a toilet is missing, then resident is unable to use a fixture that is expected to be provided and maintained as part of their rent.
	A resident is likely to notice a missing toilet and to recognize it is important enough to report to property management because it may present health or sanitary hazards. Property management should be expected to prioritize a work order for a missing toilet because it may result in health or sanitary hazards.
Deficiency 2 – Toilet: Ins	ide
Deficiency	A toilet is missing and at least 1 toilet is installed elsewhere that is operational.
Deficiency Criteria	A toilet is missing (i.e., evidence of prior installation, but now not present or is incomplete) and at least 1 toilet is installed elsewhere within the Inside area that is operational.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a toilet is missing, then the resident may inadvertently come into contact with sewage, which may result in illness.

If a toilet is missing, then the resident's ability to dispose of human waste is limited.

If a toilet is missing, then the resident is unable to use a fixture that is expected to be provided and maintained as part of their rent.

Property management would be expected to ensure that staff members understand how to identify a missing toilet. Management practices would be expected to assure prompt creation and prioritization of a work order to replace the toilet because it may result in safety or sanitary hazards.

Deficiency 3 – Toilet: Uni	t
Deficiency	Only 1 toilet was installed, and it is damaged.
Deficiency Criteria	Only 1 toilet was installed, and it is damaged (i.e., visibly defective; impacts functionality).
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If the toilet is damaged or inoperable, then the resident may be at an increased risk of exposure to pathogens due to a leak or overflow of the toilet, which may result in illness.
	If the toilet is damaged or inoperable, then the resident's ability to dispose of human waste may be limited.
	If the toilet is damaged or inoperable, then the resident may be unable to use a fixture that is expected to be provided and maintained as part of their rent.
	If the toilet is damaged or inoperable, and it is not shutting off and the resident is responsible for water and sewage utilities, there may be an increased expense for both excessive water usage and sewer incurred by the resident.
	A resident is likely to notice if the toilet is damaged or inoperable and to recognize it is important enough to report to property management because it may present health or sanitary hazards. Property management should be expected to prioritize a work order for the damaged or inoperable toilet because it may result in health or sanitary hazards.

Deficiency	Only 1 toilet was installed, and it is damaged or inoperable.
Deficiency Criteria	Only 1 toilet was installed, and it is damaged (i.e., visibly defective; impacts functionality).
	OR
	Only 1 toilet was installed, and it is inoperable (i.e., overall system is not meeting function or purpose; with or without visible damage).
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the toilet is damaged or inoperable, then the resident may be at an increased risk of exposure to pathogens due to a leak or overflow of the toilet, which may result in illness.
	If the toilet is damaged or inoperable, then the resident's ability to dispose of human waste may be limited.
	If the toilet is damaged or inoperable, then the resident may be unable to use a fixture that is expected to be provided and maintained as part of their rent.
	Property management would be expected to ensure that staff members understand how to identify if the toilet is damaged or inoperable. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy the deficiency because it may result in safety or sanitary hazards.
Deficiency 4 – Toilet: Uni	t
Deficiency	A toilet is damaged or inoperable and at least 1 toilet is installed elsewhere that is operational.
Deficiency Criteria	A toilet is damaged (i.e., visibly defective; impacts functionality) and at least 1 toilet is installed elsewhere within the Unit that is operational.
	OR
	A toilet is inoperable (i.e., overall system is not meeting function or purpose; with or without visible damage) and at least 1 toilet is installed elsewhere within the Unit that is operational.

Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a toilet is damaged or inoperable, then the resident may be at an increased risk of exposure to pathogens due to a leak or overflow of the toilet, which may result in illness.
	If a toilet is damaged or inoperable, then the resident's ability to dispose of human waste may be limited.
	If a toilet is damaged or inoperable, then the resident may be unable to use a fixture that is expected to be provided and maintained as part of their rent.
	If a toilet is damaged or inoperable, and it is not shutting off and the resident is responsible for water and sewage utilities, there may be an increased expense for both excessive water usage and sewer incurred by the resident.
	A resident is likely to notice a damaged or inoperable toilet and to recognize it is important enough to report to property management because it may present health or sanitary hazards. Property management should be expected to prioritize a work order for a damaged or inoperable toilet because it may result in health or sanitary hazards.
Deficiency 4 – Toilet: Insi	ide
Deficiency	A toilet is damaged or inoperable and at least 1 toilet is installed elsewhere that is operational.
Deficiency Criteria	A toilet is damaged (i.e., visibly defective; impacts functionality) and at least 1 toilet is installed elsewhere within the Inside area that is operational.
	OR
	A toilet is inoperable (i.e., overall system is not meeting function or
	purpose; with or without visible damage) and at least 1 toilet is installed
	elsewhere within the Inside area that is operational.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days

HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a toilet is damaged or inoperable, then the resident may be at an increased risk of exposure to pathogens due to a leak or overflow of the toilet, which may result in illness.
	If a toilet is damaged or inoperable, then the resident's ability to dispose of human waste may be limited.
	If a toilet is damaged or inoperable, then the resident may be unable to use a fixture that is expected to be provided and maintained as part of their rent.
	Property management would be expected to ensure that staff members understand how to identify if a toilet is damaged or inoperable. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy the deficiency because it may result in safety or sanitary hazards.
Deficiency 5 – Toilet: Uni	t
Deficiency	Toilet component is damaged, inoperable, or missing such that it may limit the resident's ability to safely discharge human waste.
Deficiency Criteria	Toilet component is damaged (i.e., visibly defective; impacts functionality) such that it may limit the resident's ability to safely discharge human waste.
	OR
	Toilet component is inoperable (i.e., component is not meeting function or purpose; with or without visible damage) such that it may limit the resident's ability to safely discharge human waste.
	OR
	Toilet component is missing (i.e., evidence of prior installation, but now not present or is incomplete) such that it may limit the resident's ability to safely discharge human waste.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail

Rationale

If a toilet component is damaged, inoperable, or missing such that it may limit the resident's ability to safely discharge human waste, then the resident may be at an increased risk of illness from infectious disease.

If a toilet component is damaged, inoperable, or missing such that it may limit the resident's ability to safely discharge human waste, then the resident may not be able to use a feature that is expected to be provided and maintained as part of their rent.

If a toilet component is damaged, inoperable, or missing such that it may limit the resident's ability to safely discharge human waste, then the resident is likely to notice this and to recognize it is important enough to report it to property management because it may present sanitary hazards or usability barriers. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in sanitary hazards.

Deficiency 5 - Toilet: Inside

Deficiency

Toilet component is damaged, inoperable, or missing such that it may limit the resident's ability to safely discharge human waste.

Deficiency Criteria

Toilet component is damaged (i.e., visibly defective; impacts functionality) such that it may limit the resident's ability to safely discharge human waste.

OR

Toilet component is inoperable (i.e., component is not meeting function or purpose; with or without visible damage) such that it may limit the resident's ability to safely discharge human waste.

OR

Toilet component is missing (i.e., evidence of prior installation, but now not present or is incomplete) such that it may limit the resident's ability to safely discharge human waste.

Health and Safety Determination

Standard

Correction Timeframe

30 days

HCV Correction Timeframe

30 days

HCV Pass/Fail

Fail

Rationale

If a toilet component is damaged, inoperable, or missing such that it may limit the resident's ability to safely discharge human waste, then the resident may be at an increased risk of illness from infectious disease.

If a toilet component is damaged, inoperable, or missing such that it may limit the resident's ability to safely discharge human waste, then the resident may not be able to use a feature that is expected to be provided and maintained as part of their rent.

Property management would be expected to ensure that staff members understand how to identify a toilet component that is damaged, inoperable, or missing such that it may limit the resident's ability to safely discharge human waste. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in sanitary hazards or usability barriers.

Deficiency 6 – Toilet: Uni	t
Deficiency	Toilet is not secured at the base.
Deficiency Criteria	Toilet is not secured at the base.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If a toilet is not secure at the base, then the resident could be exposed to sewer leakage.
	If a toilet is not secure at the base, then there is a potential for injury to the resident.
	If a toilet is not secure at the base, then the resident's ability to dispose of human waste may be limited.
	If a toilet is not secure at the base, then the resident may be unable to use a fixture that is expected to be provided and maintained as part of their rent.
	A resident is likely to notice a toilet that is not secure at the base and to recognize it is important enough to report to property management because it may present safety hazards. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in safety hazards or usability barriers.

Deficiency 6 – Toilet: Inside	
Deficiency	Toilet is not secured at the base.

Deficiency Criteria	Toilet is not secured at the base.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a toilet is not secure at the base, then the resident could be exposed to sewer leakage.
	If a toilet is not secure at the base, then there is a potential for injury to the resident.
	If a toilet is not secure at the base, then the resident's ability to dispose of human waste may be limited.
	If a toilet is not secure at the base, then the resident may be unable to use a fixture that is expected to be provided and maintained as part of their rent.
	Property management would be expected to ensure that staff members understand how to identify a toilet that is not secure at the base. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy the deficiency because it may result in safety hazards or usability barriers.
Deficiency 7 – Toilet: Uni	t
Deficiency	Toilet component is damaged, inoperable, or missing and it does not limit the resident's ability to discharge human waste.
Deficiency Criteria	Toilet component is damaged (i.e., visibly defective; impacts functionality) and it does not limit the resident's ability to safely discharge human waste.
	OR
	Toilet component is inoperable (i.e., component is not meeting function or purpose; with or without visible damage) and it does not limit the resident's ability to safely discharge human waste.
	OR
	Toilet component is missing (i.e., evidence of prior installation, but now not present or is incomplete) and it does not limit the resident's ability to safely discharge human waste.
Health and Safety Determination	Advisory

Advisory
Advisory
Advisory
Pass
If the resident's ability to safely discharge human waste is not limited, but a toilet component is damaged, inoperable, or missing, then the resident's ability to fully utilize an aspect of the fixture may be reduced.
If the resident's ability to safely discharge human waste is not limited, but a toilet component is damaged, inoperable, or missing, then the resident's ability to fully utilize an aspect of the fixture may be reduced.
de
Toilet component is damaged, inoperable, or missing and it does not limit the resident's ability to discharge human waste.
Toilet component is damaged (i.e., visibly defective; impacts functionality) and it does not limit the resident's ability to safely discharge human waste.
OR
Toilet component is inoperable (i.e., component is not meeting function or purpose; with or without visible damage) and it does not limit the resident's ability to safely discharge human waste.
OR
Toilet component is missing (i.e., evidence of prior installation, but now not present or is incomplete) and it does not limit the resident's ability to safely discharge human waste.
Advisory
Advisory
Advisory
Pass
If the resident's ability to safely discharge human waste is not limited, but a toilet component is damaged, inoperable, or missing, then the resident's ability to fully utilize an aspect of the fixture may be reduced.
If the resident's ability to safely discharge human waste is not limited, but a toilet component is damaged, inoperable, or missing, then property management would be expected to assure prompt creation and

prioritization of a work order to remedy this deficiency because it may result in usability barriers.

TABLE 57—TRASH CHUTE STANDARD

Definition and Location	
Definition	A large tube through which refuse is carried by means of gravity to a large
	waste receptacle at the bottom end.
Location	Inside: Hallways of high-rises, hallway closets of high-rises, typically located
	in the same place on every floor.
Deficiency 1 – Trash Chu	te: Inside
Deficiency	Chute door does not open or self-close and latch.
Deficiency Criteria	Chute door does not open.
	OR
	Chute door does not self-close and latch.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the chute door does not self-close and latch, then it may present a fall risk
	for the resident. Additionally, if there is a fire, then it may provide a route for fire to move between locations through a building.
	If the chute door does not open or self-close and latch, then the resident's ability to dispose of garbage in a sanitary manner may be impacted.
	If the chute door does not open or self-close and latch, then the resident
	may be unable to use a feature that is expected to be provided and
	maintained as part of their rent.
	If the chute door does not open or self-close and latch, then the resident
	would likely report it because there is a barrier to usability, and the
	presence of this deficiency may indicate complaint-based work orders are not being addressed.
	If the chute door does not open or self-close and latch, then this should be
	identified during regular maintenance activities and the presence of this

deficiency may indicate self-generated work orders are not being addressed.

Deficiency 2 – Trash Chut	Deficiency 2 – Trash Chute: Inside	
Deficiency	Chute is clogged.	
Deficiency Criteria	Trash is overflowing or backed up inside the chute.	
Health and Safety Determination	Standard	
Correction Timeframe	30 days	
HCV Correction Timeframe	30 days	
HCV Pass/Fail	Fail	
Rationale	If trash is overflowing or backed up inside the chute, then there may be an increased risk of infestation, which may expose the resident to potential health risks (e.g., disease).	
	If trash is overflowing or backed up inside the chute, then the resident's ability to dispose of garbage in a sanitary manner may be impacted.	
	If trash is overflowing or backed up inside the chute, then the resident may be unable to use a feature that is expected to be provided and maintained as part of their rent.	
	If trash is overflowing or backed up inside the chute, then the resident would likely report it because there is a barrier to usability, and the presence of this deficiency may indicate complaint-based work orders are not being addressed.	
	If trash is overflowing or backed up inside the chute, then this should be identified during regular maintenance activities and the presence of this deficiency may indicate self-generated work orders are not being addressed.	

TABLE 58—TRIP HAZARD STANDARD

Definition and Loca	tion
Definition	Hazard caused by an abrupt change in vertical elevation or horizontal separation on any walking surface.
Location	Unit: Throughout the Unit.
	Inside: Throughout the Inside.

	Outside: Throughout the Outside.
Deficiency 1 – Trip Hazar	d: Unit
Deficiency	Trip hazard on walking surface.
Deficiency Criteria	There is an abrupt change in vertical elevation or horizontal separation on any walking surface along the normal path of travel, consisting of the following criteria:
	- An unintended %-inch or greater vertical difference, OR
	 An unintended 2-inch horizontal separation perpendicular to the path of travel.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If there is an abrupt change in vertical elevation or horizontal separation or any walking surface along the normal path of travel, then there is an increased probability of falls that may lead to injury.
	If there is an abrupt change in vertical elevation or horizontal separation on any walking surface along the normal path of travel, then the resident will likely report it and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	If there is an abrupt change in vertical elevation or horizontal separation or any walking surface along the normal path of travel, then it should be observed through regular maintenance activities and the presence of this deficiency may indicate that self-generated work orders are not being addressed.
Deficiency 1 – Trip Hazar	d: Inside
Deficiency	Trip hazard on walking surface.
Deficiency Criteria	There is an abrupt change in vertical elevation or horizontal separation on any walking surface along the normal path of travel, consisting of the following criteria:

An unintended %-inch or greater vertical difference, OR

path of travel.

An unintended 2-inch horizontal separation perpendicular to the

Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If there is an abrupt change in vertical elevation or horizontal separation on any walking surface along the normal path of travel, then there is an increased probability of falls that may lead to injury. If there is an abrupt change in vertical elevation or horizontal separation on any walking surface along the normal path of travel, then the resident will likely report it and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	If there is an abrupt change in vertical elevation or horizontal separation on any walking surface along the normal path of travel, then it should be observed through regular maintenance activities and the presence of this deficiency may indicate that self-generated work orders are not being addressed.
Deficiency 1 – Trip Hazar	d: Outside
Deficiency	Trip hazard on walking surface.
Deficiency Criteria	There is an abrupt change in vertical elevation or horizontal separation on any walking surface along the normal path of travel, consisting of the following criteria:
	 An unintended ¾-inch or greater vertical difference, OR
	 An unintended 2-inch horizontal separation perpendicular to the path of travel.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If there is an abrupt change in vertical elevation or horizontal separation on any walking surface along the normal path of travel, then there is an increased probability of falls that may lead to injury.

If there is an abrupt change in vertical elevation or horizontal separation on any walking surface along the normal path of travel, then the resident will likely report it and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.

If there is an abrupt change in vertical elevation or horizontal separation on any walking surface along the normal path of travel, then it should be observed through regular maintenance activities and the presence of this deficiency may indicate that self-generated work orders are not being addressed.

TABLE 59—WALL COVERING AND FINISH – EXTERIOR STANDARD

Definition and Location	
Definition	Exterior wall: The finished or unfinished surface that provides a vertical separation between the interior and exterior of the building and may provide security and privacy, sound proofing, and weather resistance.
	Wall covering: Material such as siding or stucco used as a covering for exterior walls.
	Note: <i>Unfinished</i> within this standard refers to concrete masonry unit or poured concrete walls.
Location	Outside: Exterior of the unit.
Deficiency 1 – Wall Cove	ring and Finish – Exterior: Outside
Deficiency	Exterior wall covering has missing sections of at least 1 square foot per wall.
Deficiency Criteria	Cumulatively, 1 square foot or more of an exterior wall covering is missing
	(i.e., evidence of prior installation, but now not present or is incomplete).
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If 1 square foot or more of an exterior wall cover is missing, and the building envelope has been compromised, then this may increase interior moisture levels, which provides an environment favorable for mold growth and may trigger respiratory issues. Property management would be expected to ensure that staff members understand how to identify if an exterior wall cover is missing.

Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in health hazards.

If 1 square foot or more of an exterior wall cover is missing, and it is visible to a visitor, then the property may suffer reputational harm.

Deficiency 2 – Wall Cove	ring and Finish – Exterior: Outside
Deficiency	Exterior wall has a hole of any size that penetrates through to the interior of the building.
	the banding.
Deficiency Criteria	A hole of any size that penetrates through to the interior of the building.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If there is a hole that penetrates through to the interior of the building, and the building envelope has been compromised, then this may increase interior moisture levels, which provides an environment favorable for mold growth and may trigger respiratory issues.
	Property management would be expected to ensure that staff members understand how to identify a hole that penetrates through to the interior of the building. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in health hazards.
	If there is a hole that penetrates through to the interior of the building, and it is visible to a visitor, then the property may suffer reputational harm.

Deficiency 3 – Wall Cove	Deficiency 3 – Wall Covering and Finish – Exterior: Outside	
Deficiency	Exterior wall has peeling paint of 10 square feet or more.	
Deficiency Criteria	Cumulatively, there is 10 square feet or more of peeling paint on an exterior wall built after 1978.	
Health and Safety Determination	Standard	
Correction Timeframe	30 days	
HCV Correction Timeframe	30 days	

HCV Pass/Fail	Fail
Rationale	If there is 10 square feet or more of peeling paint on an exterior wall, and the building envelope has been compromised, then this may increase interior moisture levels, which provides an environment favorable for mold growth and may trigger respiratory issues.
	Property management would be expected to ensure that staff members understand how to identify peeling paint on an exterior wall. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in health hazards.
	If there is 10 square feet or more of peeling paint on an exterior wall, and it is visible to a visitor, then the property may suffer reputational harm.

Deficiency 4 – Wall Covering and Finish – Exterior: Outside	
Deficiency	Evidence of structural failure.
Deficiency Criteria	There is evidence of structural failure.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If there is evidence of structural failure, then the resident may be exposed to health hazards.
	If there is evidence of structural failure, then the resident may be exposed to safety hazards.
	If there is evidence of structural failure, then it is likely the resident will report this, and the presence of this deficiency may indicate that complaint-based work orders are not being addressed.
	If there is evidence of structural failure, then it will likely be identified through routine maintenance activities and its presence may indicate that self-generated work orders are not being addressed.
	If there is evidence of structural failure, then capital expenditures will likely be required to remedy the deficiency.

TABLE 60—WALL COVERING AND FINISH – INTERIOR STANDARD

Definition and Location

A vertical surface that may define an area, and provide security, shelter, or sound proofing.
Unit: Dining room, living room, kitchen, bathroom, bedroom, closet, hallway, other interior space.
Inside: Dining room, living room, kitchen, bathroom, closet, hallway, other interior space.
ring and Finish – Interior: Unit
Interior wall has a hole of any size that penetrates to the adjoining room or space.
A hole of any size penetrates to the adjoining room or space.
Standard
30 days
30 days
Fail
If an interior wall has a hole of any size that penetrates to the adjoining room or space, then the resident may be exposed to items behind the wall (e.g., insulation, lead dust, asbestos, wires) that may harm their health.
If an interior wall has a hole of any size that penetrates to the adjoining room or space, then the resident may be unable to fully use a feature (i.e., a wall without a hole) that is expected to be provided and maintained as part of their rent.
If an interior wall has a hole of any size that penetrates to the adjoining room or space, then it should be identified during routine maintenance activities and its presence may indicate that self-generated work orders are not being addressed.
ring and Finish – Interior: Inside
ring and Finish – Interior: Inside Interior wall has a hole of any size that penetrates to the adjoining room or space.
Interior wall has a hole of any size that penetrates to the adjoining room or
Interior wall has a hole of any size that penetrates to the adjoining room or space.

HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If an interior wall has a hole of any size that penetrates to the adjoining room or space, then the resident may be exposed to items behind the wall (e.g., insulation, lead dust, asbestos, wires) that may harm their health.
	If an interior wall has a hole of any size that penetrates to the adjoining room or space, then the resident may be unable to fully use a feature (i.e., a wall without a hole) that is expected to be provided and maintained as part of their rent.
	If an interior wall has a hole of any size that penetrates to the adjoining room or space, then it should be identified during routine maintenance activities and its presence may indicate that self-generated work orders are not being addressed.
Deficiency 2 – Wall Cove	ring and Finish – Interior: Unit
Deficiency	Interior wall is buckling, bulging, bowing, or material is loose or detached.
Deficiency Criteria	Wall is buckling, bulging, or bowing.
	OR
	Wall has a loose or detached surface covering.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If an interior wall is buckling, bulging, bowing, or material is loose or detached, then the resident may be exposed to items behind the wall (e.g., insulation, lead dust, asbestos, wires) that may harm their health.
	If an interior wall is buckling, bulging, bowing, or material is loose or detached, then the resident may be injured by falling wall coverings.
	If an interior wall is buckling, bulging, bowing, or material is loose or detached, then the resident will likely report it and this deficiency's presence may indicate that complaint-based work orders are not being addressed.

Deficiency 2 – Wall Covering and Finish – Interior: Inside

Deficiency	Interior wall is buckling, bulging, bowing, or material is loose or detached.
Deficiency Criteria	Wall is buckling, bulging, or bowing.
	OR
	Wall has a loose or detached surface covering.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If an interior wall is buckling, bulging, bowing, or material is loose or
	detached, then the resident may be exposed to items behind the wall (e.g.,
	insulation, lead dust, asbestos, wires) that may harm their health.
	If an interior wall is buckling, bulging, bowing, or material is loose or
	detached, then the resident may be injured by falling wall coverings.
	If an interior wall is buckling, bulging, bowing, or material is loose or
	detached, then the resident will likely report it and this deficiency's
	presence may indicate that complaint-based work orders are not being
	addressed.
Deficiency 3 – Wall Cove	ring and Finish – Interior: Unit
Deficiency	Interior wall has a hole that is greater than 2 inches in diameter or there is
	an accumulation of holes that are cumulatively greater than 6 inches by 6
	inches.
Deficiency Criteria	A hole is greater than 2 inches in diameter.
	OR
	An accumulation of holes in any one wall that are cumulatively greater than
	6 inches by 6 inches.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
· 	

Rationale

If there is a hole that is greater than 2 inches in diameter or an accumulation of holes that are cumulatively greater than 6 inches by 6 inches, then the resident may be exposed to items behind the wall (e.g., insulation, lead dust, asbestos, wires) that may harm their health.

If there is a hole that is greater than 2 inches in diameter or an accumulation of holes that are cumulatively greater than 6 inches by 6 inches, then the resident may be unable to fully use a feature (i.e., a wall without a hole) that is expected to be provided and maintained as part of their rent.

If there is a hole that is greater than 2 inches in diameter or an accumulation of holes that are cumulatively greater than 6 inches by 6 inches, then it should be identified during routine maintenance activities and its presence may indicate that self-generated work orders are not being addressed.

Deficiency 3 – Wall Covering and Finish – Interior: Inside

Deficiency

Interior wall has a hole that is greater than 2 inches in diameter or there is an accumulation of holes that are cumulatively greater than 6 inches by 6 inches.

Deficiency Criteria

A hole is greater than 2 inches in diameter.

OR

An accumulation of holes in any one wall that are cumulatively greater than 6 inches by 6 inches.

Health and Safety Determination

Standard

Correction Timeframe

30 days

HCV Correction Timeframe

30 days

HCV Pass/Fail

Fail

Rationale

If there is a hole that is greater than 2 inches in diameter or an accumulation of holes that are cumulatively greater than 6 inches by 6 inches, then the resident may be exposed to items behind the wall (e.g., insulation, lead dust, asbestos, wires) that may harm their health.

If there is a hole that is greater than 2 inches in diameter or an accumulation of holes that are cumulatively greater than 6 inches by 6 inches, then the resident may be unable to fully use a feature (i.e., a wall without a hole) that is expected to be provided and maintained as part of their rent.

If there is a hole that is greater than 2 inches in diameter or an accumulation of holes that are cumulatively greater than 6 inches by 6 inches, then it should be identified during routine maintenance activities and its presence may indicate that self-generated work orders are not being addressed.

TABLE 61—WATER HEATER STANDARD

Definition and Location	
Definition	A device designed to generate and store hot water for domestic use.
Location	Unit: Mechanical rooms, mechanical closets, basements, under stairs, kitchens.
	Inside: Mechanical rooms, mechanical closets, basements, under stairs, kitchens.
	Outside: Back or side yard.
Deficiency 1 – Water Hea	nter: Unit
Deficiency	Temperature pressure relief (TPR) valve is obstructed or relief valve discharge piping is damaged, capped, has an upward slope, or is constructed of unsuitable material.
Deficiency Criteria	TPR valve is obstructed such that the TPR valve is unable to be fully actuated.
	OR
	Relief valve discharge piping is damaged (i.e., visibly defective; impacts functionality), capped, has an upward slope, or is constructed of unsuitable material.
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the TPR valve is obstructed such that it is unable to be fully actuated or the relief valve discharge piping is damaged, capped, has an upward slope, or is constructed of unsuitable material, and the water within the water heater reaches temperatures above its boiling point, then there may be an

increased safety risk to the resident due to a rupturing water heater, which may result in injury.

Property management would be expected to ensure that staff members understand how to identify a TPR valve that is obstructed such that it is unable to be fully actuated or relief valve discharge piping that is damaged, capped, has an upward slope, or is constructed of unsuitable material. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards.

Water heaters should be checked during periodic property inspections, and according to industry best practices, should be included in a preventative maintenance plan. If the TPR valve is obstructed such that it is unable to be fully actuated or the relief valve discharge piping is damaged, capped, has an upward slope, or is constructed of unsuitable material, then it may indicate preventative maintenance activities could be improved.

Deficiency 1 – Water Hea	Deficiency 1 – Water Heater: Inside	
Deficiency	Temperature pressure relief (TPR) valve is obstructed or relief valve discharge piping is damaged, capped, has an upward slope, or is constructed of unsuitable material.	
Deficiency Criteria	TPR valve is obstructed such that the TPR valve is unable to be fully actuated.	
	OR	
	Relief valve discharge piping is damaged (i.e., visibly defective; impacts functionality), capped, has an upward slope, or is constructed of unsuitable material.	
Health and Safety	Severe Non-Life Threatening	
Determination		
Correction Timeframe	24 hours	
HCV Correction Timeframe	30 days	
HCV Pass/Fail	Fail	
Rationale	If the TPR valve is obstructed such that it is unable to be fully actuated or the relief valve discharge piping is damaged, capped, has an upward slope, or is constructed of unsuitable material, and the water within the water heater reaches temperatures above its boiling point, then there may be an increased safety risk to the resident due to a rupturing water heater, which may result in injury.	

Property management would be expected to ensure that staff members understand how to identify a TPR valve that is obstructed such that it is unable to be fully actuated or relief valve discharge piping that is damaged, capped, has an upward slope, or is constructed of unsuitable material. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards.

Water heaters should be checked during periodic property inspections, and according to industry best practices, should be included in a preventative maintenance plan. If the TPR valve is obstructed such that it is unable to be fully actuated or the relief valve discharge piping is damaged, capped, has an upward slope, or is constructed of unsuitable material, then it may indicate preventative maintenance activities could be improved.

Deficiency	Temperature pressure relief (TPR) valve is obstructed or relief valve
	discharge piping is damaged, capped, has an upward slope, or is
	constructed of unsuitable material.
	constructed of unsuitable material.
Deficiency Criteria	TPR valve is obstructed such that the TPR valve is unable to be fully actuated.
	OR
	Relief valve discharge piping is damaged (i.e., visibly defective; impacts functionality), capped, has an upward slope, or is constructed of unsuitable material.
Health and Safety	Standard
Determination	
Correction Timeframe	30 days
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If the TPR valve is obstructed such that it is unable to be fully actuated or the relief valve discharge piping is damaged, capped, has an upward slope, or is constructed of unsuitable material, and the water within the water heater reaches temperatures above its boiling point, then there may be an increased safety risk to the resident due to a rupturing water heater, which may result in injury.
	Property management would be expected to ensure that staff members understand how to identify a TPR valve that is obstructed such that it is unable to be fully actuated or relief valve discharge piping that is damaged, capped, has an upward slope, or is constructed of unsuitable material. Management practices would be expected to assure prompt creation and

prioritization of a work order to remedy this deficiency because it may result in safety hazards.

Water heaters should be checked during periodic property inspections, and according to industry best practices, should be included in a preventative maintenance plan. If the TPR valve is obstructed such that it is unable to be fully actuated or the relief valve discharge piping is damaged, capped, has an upward slope, or is constructed of unsuitable material, then it may indicate preventative maintenance activities could be improved.

Deficiency 2 – Water Hea	eter: Unit
Deficiency	No hot water.
Deficiency Criteria	Hot water does not dispense after the handle is engaged.
Health and Safety	Severe Non-Life Threatening
Determination	
Correction Timeframe	24 hours
HCV Correction	30 days
Timeframe	
HCV Pass/Fail	Fail
Rationale	If hot water does not dispense after the handle is engaged, then the resident cannot maintain personal hygiene, which may result in sickness.
	If hot water does not dispense after the handle is engaged, then the resident is unable to maintain household hygiene, including washing clothes and dishes, cleaning, etc.
	If hot water does not dispense after the handle is engaged, then the resident is unable to fully use a fixture that is expected to be provided and maintained as part of their rent.
	A resident is likely to notice if hot water does not dispense after the handle is engaged and to recognize it is important enough to report to property management because it may present health and sanitary hazards. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in health and sanitary hazards.

Deficiency 2 – Water Heater: Inside	
Deficiency	No hot water.
Deficiency Criteria	Hot water does not dispense after the handle is engaged.
Health and Safety Determination	Advisory
Correction Timeframe	Advisory

HCV Correction	Advisory
Timeframe	
HCV Pass/Fail	Pass
Rationale	If hot water does not dispense after the handle is engaged, then the resident may not be able to fully use a fixture.
	Property management would be expected to ensure that staff members understand how to identify if hot water does not dispense after the handle is engaged. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in usability barriers.
Deficiency 3 – Water Hea	ater: Unit
Deficiency	The relief valve discharge piping is missing or terminates greater than 6 inches or less than 2 inches from waste receptor flood-level.
Deficiency Criteria	The relief valve discharge piping is missing (i.e., evidence of prior installation, but is now not present or is incomplete).
	OR
	The relief valve discharge piping terminates greater than 6 inches or less than 2 inches from waste receptor flood-level.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the relief valve discharge piping is missing or terminates greater than 6 inches or less than 2 inches from waste receptor flood-level, there may be an increased safety risk to the resident of thermal burns, which may result in injury.
	Property management would be expected to ensure that staff members understand how to identify if the relief valve discharge piping is missing or terminates greater than 6 inches or less than 2 inches from waste receptor flood-level. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency as it may result in safety hazards.
Deficiency 3 – Water Hea	ater: Inside
Deficiency	The relief valve discharge piping is missing or terminates greater than 6 inches or less than 2 inches from waste receptor flood-level.

Deficiency Criteria	The relief valve discharge piping is missing (i.e., evidence of prior installation, but is now not present or is incomplete).
	OR
	The relief valve discharge piping terminates greater than 6 inches or less than 2 inches from waste receptor flood-level.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If the relief valve discharge piping is missing or terminates greater than 6 inches or less than 2 inches from waste receptor flood-level, there may be an increased safety risk to the resident of thermal burns, which may result in injury.
	Property management would be expected to ensure that staff members understand how to identify if the relief valve discharge piping is missing or terminates greater than 6 inches or less than 2 inches from waste receptor flood-level. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency as it may result in safety hazards.
Deficiency 3 – Water Hea	ter: Outside
Deficiency	The relief valve discharge piping is missing or terminates greater than 6 inches or less than 2 inches from waste receptor flood-level.
Deficiency Criteria	The relief valve discharge piping is missing (i.e., evidence of prior installation, but is now not present or is incomplete).
	OR
	The relief valve discharge piping terminates greater than 6 inches or less than 2 inches from waste receptor flood-level.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail

Rationale

If the relief valve discharge piping is missing or terminates greater than 6 inches or less than 2 inches from waste receptor flood-level, there may be an increased safety risk to the resident of thermal burns, which may result in injury.

Property management would be expected to ensure that staff members understand how to identify if the relief valve discharge piping is missing or terminates greater than 6 inches or less than 2 inches from waste receptor flood-level. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency as it may result in safety hazards.

Deficiency 4 – Water Hea	eter: Unit
Deficiency	Chimney or flue piping is blocked, misaligned, or missing.
Deficiency Criteria	Chimney or flue piping is blocked, misaligned, or missing (i.e., evidence of prior installation, but now not present or is incomplete).
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If the chimney or flue piping is blocked, misaligned, or missing, then the resident may be exposed to carbon monoxide leaks.
	A resident is likely to notice if the chimney or flue piping is blocked, misaligned, or missing and to recognize it is important enough to report to property management because it may present safety hazards. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in safety hazards.

Deficiency 4 – Water Heater: Inside		
Deficiency	Chimney or flue piping is blocked, misaligned, or missing.	
Deficiency Criteria	Chimney or flue piping is blocked, misaligned, or missing (i.e., evidence of prior installation, but now not present or is incomplete).	
Health and Safety Determination	Life-Threatening	
Correction Timeframe	24 hours	
HCV Correction Timeframe	24 hours	

HCV Pass/Fail	Fail
Rationale	If the chimney or flue piping is blocked, misaligned, or missing, then the resident may be exposed to carbon monoxide leaks.
	Property management would be expected to ensure that staff members understand how to identify if chimney or flue piping is blocked, misaligned, or missing. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this as it may result in safety hazards.
Deficiency 5 – Water Hea	ater: Unit
Deficiency	Gas shutoff valve is damaged, missing, or not installed.
Deficiency Criteria	Gas shutoff valve is damaged (i.e., visibly defective; impacts functionality).
	OR
	Gas shutoff valve is missing (i.e., evidence of prior installation, but is now not present or is incomplete).
	OR
	Gas shutoff valve is not installed (i.e., never installed, but should have been).
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If the gas shutoff valve is damaged, missing, or not installed and there is a need to shut off the gas, then there may be an increased safety risk to the resident of fire, which may result in injury or death.
	Property management would be expected to ensure that staff members understand how to identify a gas shutoff valve that is damaged, missing, or not installed. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards.

Deficiency 5 – Water Heater: Inside	
Deficiency	Gas shutoff valve is damaged, missing, or not installed.
Deficiency Criteria	Gas shutoff valve is damaged (i.e., visibly defective; impacts functionality).

	OR
	Gas shutoff valve is missing (i.e., evidence of prior installation, but is now not present or is incomplete).
	OR
	Gas shutoff valve is not installed (i.e., never installed, but should have been).
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours
HCV Pass/Fail	Fail
Rationale	If the gas shutoff valve is damaged, missing, or not installed and there is a need to shut off the gas, then there may be an increased safety risk to the resident of fire, which may result in injury or death.
	Property management would be expected to ensure that staff members understand how to identify a gas shutoff valve that is damaged, missing, or not installed. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards.
Deficiency 5 – Water Hea	nter: Outside
Deficiency	Gas shutoff valve is damaged, missing, or not installed.
Deficiency Criteria	Gas shutoff valve is damaged (i.e., visibly defective; impacts functionality).
	OR
	Gas shutoff valve is missing (i.e., evidence of prior installation, but is now not present or is incomplete).
	OR
	Gas shutoff valve is not installed (i.e., never installed, but should have been).
Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	24 hours

HCV Pass/Fail	Fail
Rationale	If the gas shutoff valve is damaged, missing, or not installed and there is a need to shut off the gas, then there may be an increased safety risk to the resident of fire, which may result in injury or death.
	Property management would be expected to ensure that staff members understand how to identify a gas shutoff valve that is damaged, missing, or not installed. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in safety hazards.

TABLE 62—WINDOW STANDARD

Definition and Location	
Definition	Opening in a wall or roof of a building that is fitted with glass or other material.
Location	Unit: Throughout the Unit.
	Inside: Throughout the Inside.
	Outside: Throughout the Outside.
Deficiency 1 – Window: U	Jnit
Deficiency	Window will not open or stay open.
Deficiency Criteria	Window will not open.
	OR
	Once opened, window will not stay open without the use of a tool or item.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a window does not open or stay open, then it may limit ventilation of interior spaces, which may affect indoor air quality and trigger respiratory issues.
	If a window will not open or stay open, then the resident may not be able to use a feature that is expected to be provided and maintained as part of their rent.

A resident is likely to notice a window a that will not open or stay open and to recognize it is important enough to report it to property management because it may present health hazards or usability barriers. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in health hazards.

Deficiency 1 – Window: I	nside
Deficiency	Window will not open or stay open.
Deficiency Criteria	Window will not open.
	OR
	Once opened, window will not stay open without the use of a tool or item.
Health and Safety Determination	Advisory
Correction Timeframe	Advisory
HCV Correction Timeframe	Advisory
HCV Pass/Fail	Pass
Rationale	If a window will not open or stay open, then the resident may not be able to use a feature that is expected to be provided and maintained as part of their rent.
	Property management would be expected to ensure that staff members understand how to identify a window that will not open or stay open. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in usability barriers.
Deficiency 2 – Window: l	Jnit
Deficiency	Window cannot be secured.
Deficiency Criteria	Window cannot be secured (i.e., access controlled) by at least 1 installed lock.
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction	30 days

Timeframe

HCV Pass/Fail

Fail

Rationale If the window cannot be secured, then the resident may be unable to control access to the property. If the window cannot be secured, then the resident may not be able to fully use a feature that is expected to be provided and maintained as part of their rent. A resident is likely to notice if a window cannot be secured and to recognize it is important enough to report it to property management because it may present security hazards. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in security hazards. Deficiency 2 - Window: Inside Window cannot be secured. Deficiency **Deficiency Criteria** Window cannot be secured (i.e., access controlled) by at least 1 installed lock. **Health and Safety** Advisory Determination **Correction Timeframe** Advisory **HCV Correction** Advisory

Timeframe

Rationale

HCV Pass/Fail

Pass

	creation and prioritization of a work order to remedy this deficiency.
Deficiency 3 – Window: l	Unit
Deficiency	Window will not close.
Deficiency Criteria	The window will not close.
Health and Safety Determination	Severe Non-Life Threatening
Correction Timeframe	24 hours
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail

Property management would be expected to ensure that staff members understand how to identify a window that cannot be secured by at least 1 installed lock. Management practices would be expected to assure prompt

Rationale If the window will not close, then the resident may be exposed to environmental elements, which may result in illness. If the window will not close, there may be an increased safety risk to the

resident of fall hazards, which may result in injury.

If the window will not close, then the resident may be unable to control access to the property.

If the window will not close, then resident may be unable to fully use a feature that is expected to be provided and maintained as part of their rent.

A resident is likely to notice a window that will not close and to recognize it is important enough to report it to property management because it may present health or security hazards, or usability barriers. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in health or security hazards.

Deficiency 3 – Window: I	Deficiency 3 – Window: Inside		
Deficiency	Window will not close.		
Deficiency Criteria	The window will not close.		
Health and Safety Determination	Standard		
Correction Timeframe	30 days		
HCV Correction Timeframe	30 days		
HCV Pass/Fail	Fail		
Rationale	If the window will not close, there may be an increased safety risk to the resident of fall hazards, which may result in injury.		
	If the window will not close, then the resident may be unable to control access to the property.		
	If the window will not close, then resident may be unable to fully use a feature that is expected to be provided and maintained as part of their rent.		
	Property management would be expected to ensure that staff members understand how to identify a window that will not close. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency because it may result in security hazards or usability barriers.		

Deficiency	Window component is damaged or missing and the window is not functionally adequate.
Deficiency Criteria	Window component is damaged (i.e., visibly defective) and the window is not functionally adequate (i.e., cannot protect from environmental or weather related moisture, permit illumination within the interior space, or permit visual access between spaces).
	OR
	Window component is missing (i.e., evidence of prior installation, but is now not present or is incomplete) and the window is not functionally adequate (i.e., cannot protect from the elements, permit illumination within the interior space, or permit visual access between spaces).
Health and Safety Determination	Standard
Correction Timeframe	30 days
HCV Correction Timeframe	30 days
HCV Pass/Fail	Fail
Rationale	If a window component is damaged or missing and the window is not functionally adequate, then the resident may be exposed to environmental elements, which may result in illness.
	If a window component is damaged or missing and the window is not functionally adequate, then resident may be unable to fully use a feature that is expected to be provided and maintained as part of their rent.
	A resident is likely to notice if a window component is damaged or missing and the window is not functionally adequate, and to recognize it is important enough to report it to property management because it may present health hazards or usability barriers. Property management should be expected to prioritize a work order to remedy this deficiency because it may result in health hazards.

Deficiency 4 – Window: I Deficiency	Window component is damaged or missing and the window is not
Deliciency	functionally adequate.
Deficiency Criteria	Window component is damaged (i.e., visibly defective) and the window is not functionally adequate (i.e., cannot protect from the elements, permit illumination within the interior space, or permit visual access between spaces).
	OR
	Window component is missing (i.e., evidence of prior installation, but is now not present or is incomplete) and the window is not functionally adequate (i.e., cannot protect from the elements, permit illumination within the interior space, or permit visual access between spaces).
Health and Safety Determination	Advisory
Correction Timeframe	Advisory
HCV Correction Timeframe	Advisory
HCV Pass/Fail	Pass
Rationale	Property management would be expected to ensure that staff members understand how to identify a window component that is damaged or missing and the window is not functionally adequate. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency.
Deficiency 4 – Window: (Outside
Deficiency	Window component is damaged or missing and the window is not functionally adequate.
Deficiency Criteria	Window component is damaged (i.e., visibly defective) and the window is not functionally adequate (i.e., cannot protect from the elements, permit illumination within the interior space, or permit visual access between spaces).
	OR
	Window component is missing (i.e., evidence of prior installation, but is now not present or is incomplete) and the window is not functionally adequate (i.e., cannot protect from the elements, permit illumination within the interior space, or permit visual access between spaces).
Health and Safety Determination	Advisory

Correction Timeframe	Advisory
HCV Correction Timeframe	Advisory
HCV Pass/Fail	Pass
Rationale	Property management would be expected to ensure that staff members understand how to identify a window component that is damaged or missing and the window is not functionally adequate. Management practices would be expected to assure prompt creation and prioritization of a work order to remedy this deficiency.

TABLE 63—HOTMA LIFE THREATENING CONDITIONS

As described in the notice, HUD proposes to update to the list of life-threatening conditions included on the Housing Opportunity Through Modernization Act of 2016 Life-Threatening List ("HOTMA LT") for the HCV and PBV programs. Within the standards, the HOTMA LT deficiencies include the following descriptions:

Health and Safety Determination	Life-Threatening
Correction Timeframe	24 hours, if occupied
HCV Correction Timeframe	24 hours, if occupied
HCV Pass/Fail	Fail

For occupied units where the family already has a voucher and is undergoing a periodic reexamination, deficiencies on the HOTMA LT list must be corrected within 24 hours. For new units proposed for the HCV program, HOTMA LT deficiencies must be resolved before the Housing Assistance Payment (HAP) contract is executed and the family moves into the unit. Other deficiencies included in the NSPIRE standards must be resolved within timelines established by the PHA administering the voucher, typically 30 days. Where NSPIRE deficiencies are not corrected within established timeframes, PHAs will be required to suspend, abate or terminate HAP to the landlord once the standards are final.

Inspectable Item	Deficiency
Call-for-Aid System	System does not function properly.
Carbon Monoxide	Carbon monoxide alarm is missing, not installed, or not installed in a proper
Alarm	location.
	Carbon monoxide alarm is obstructed.
	Carbon monoxide alarm does not produce an audio or visual alarm when
	tested.
Chimney	A visually accessible chimney, flue, or firebox connected to a fireplace or
	wood-burning appliance is incomplete or damaged such that it may not safely
	contain fire and convey smoke and combustion gases to the exterior.
	Chimney exhibits signs of structural failure.
Clothes Dryer	Electric dryer transition duct is detached or missing.
Exhaust Ventilation	Gas dryer transition duct is detached or missing.
	Electric dryer exhaust ventilation system has restricted airflow.
	Dryer transition duct is constructed of unsuitable material.
	Gas dryer exhaust ventilation system has restricted airflow.
Egress	Obstructed egress on building 4 stories or more.
	Obstructed egress on building 3 stories or less.
Electrical -	Exposed electrical conductor.
Conductor	
Electrical - Outlet	Outlet or switch is damaged.
and Switch	
Electrical - Service Panel	The overcurrent protection device is damaged.
Exit Sign	Exit sign is damaged, missing, obstructed, or not adequately illuminated.
Fire Escape	Fire escape component is damaged or missing.
Fire Extinguisher	Fire extinguisher pressure gauge reads over or under-charged.
0	Fire extinguisher service tag is missing, illegible, or expired.
	Fire extinguisher is damaged or missing.
Flammable and	Improperly stored flammable or combustible item on or near an ignition
Combustible Items	source.
Foundation	Foundation appears to be in imminent danger of collapse or failure.
Guardrail	Guardrail is missing or not installed.
	Guardrail is not functionally adequate.
Heating, Ventilation,	A permanently installed heating source is damaged, inoperable, missing, or
and Air Conditioning	not installed and the outside temperature is below 68 degrees Fahrenheit.
(HVAC)	Heating system or device fueled by combustion has a misaligned,
	disconnected, improperly connected, damaged, blocked, or missing exhaust vent.
	Combustion chamber cover or gas shutoff valve is missing from a combustion-
	fueled heating appliance.
Leak	Natural gas, propane, or oil leak.
Lead-Based Paint	The presence of deteriorated paint surfaces in a unit built before 1978 and
	where a child under 6 years of age resides or is expected to reside is a life- threatening condition only for determining whether the family can move into

	the unit.
Mold-like Substance	Presence of mold-like substance at extremely high levels is observed visually.
Smoke Alarm	Smoke alarm is not installed where required.
	Smoke alarm does not produce an audio or visual alarm when tested.
Sprinkler Assembly	Sprinkler head assembly is obstructed by an item, object, or encasement
	within 18 inches of the sprinkler head.
	Paint or foreign material on the sprinkler head assembly.
	Sprinkler head escutcheon is missing.
	Concealed sprinkler cover plate assembly is missing.
Structural System	Structural system exhibits signs of serious failure.
Toilet	There is not at least one operable toilet in unit.
Water Heater	Chimney or flue piping is blocked, misaligned, or missing.
	Gas shutoff valve is damaged, missing, or not installed.