Hillside Heights/Spring Valley Moline IL

Inspections 92082 and 1092082

					Severity		Deduction		
Area	Bldg	Unit	Inspected Item	Defect	2.1 Inspection	2.3 Inspection	2.1 Inspection	2.3 Inspection	Difference
			1	Erosion Areas	L2		3.58	3.61	0.03
			Grounds	Overgrown/Penetrating Vegetation	L2		2.69	2.71	0.02
				Ponding/Site Drainage	L1	NOD	1.79	0	-1.79
	4			Rutting	L2	NOD	1.49	0	-1.49
	Site			Cracks	L3	NOD	3.44	0	-3.44
0,			Parking Lots/Driveways/Roads	Ponding	L1	NOD	1.15	0	-1.15
				Potholes/Loose Material	L1	NOD	1.15	0	-1.15
			Walkways/Stairs	Cracks/Settlement/Heaving	L2	NOD	2.69	0	-2.69
			vvaikways/Stail's	Spalling	L1	NOD	1.34	0	-1.34
		2	Roofs	Missing/Damaged Components	L1		0.05	0.05	0
BE			Windows	Damaged Sills/Frames/Lintels/Trim	L2	L1	0.08	0.05	-0.03
B	14 15		Windows	Damaged/Missing Screens	L1	NOD	0.05	0	-0.05
			Doors	Deteriorated Missing Seals	L1	NOD	0.14	0	-0.14
1_		19	Kitchen	Cabinets - Missing/Damaged	L2	NOD	0.07	0	-0.07
CA		13		Ceiling - Needs paint	L2	NOD	0.05	0	-0.05
		20	tchen Range/Stove - Missing/Damaged/Inoperable		L3	NOD	0.26	0	-0.26
			Kitchen	Range Stove - Missing/Damaged/Inoperable	L1	NOD	0.15	0	-0.15
		31	Electrical System	GFI Inoperable	L3		0.89	0.9	0.01
		50	Kitchen	Range Stove - Missing/Damaged/Inoperable	L3	L1	0.6	0.15	-0.45
Unit		58	Kitchen	Range Stove - Missing/Damaged/Inoperable	L1 NOD L1 L3 L1		0.15	0	-0.15
Ī			Kitchen	Range Stove - Missing/Damaged/Inoperable			0.15	0.15	0
			Call-for-aid Inoperable	Call-for-aid Inoperable			0.18	0.11	-0.07
		414	Ceiling	Water Stains/Water Damage			0.05	0.05	0
		909	Ceiling	Needs Paint	L	.1	0.05	0.05	0
							22.24	7.83	-14.41

Notes:

- 1.) "Deduction" is presented exclusive of the "zero" constraint at the area/sub-area level and therefore may be larger than the net property score deduction
- 2.) Deductions are an estimate based on the points off summary and may not account for the rounding of <0.05 defects nor H/S estimates