

HUD MHCC STATUS REPORT - STANDARDS

As Nov 21, 2014

Log#	Date Entered	Citation	First Name	Last Name	Date to MHCC	MHCC Action	Date to HUD	Subcommittee	Topic & Notes	Status
2	07/31/2003	3280.112	Earl A.	Gilson	10/2010-Preliminary Action 3-2011 SC	APR	12/1/2011	General	Accessibility: Extend hall width to 30 inches (from 20 inches). Handled by a letter ballot.	COMPLETE; 12/2011 Ballot See Log 87
3	07/31/2003	3280.105.2(b)	Earl A.	Gilson	10/2010-Preliminary Action 4-2011 SC	APR	12/1/2011	Technical Structure & Design	Accessibility: Increase door width to 32 inches (from 28 inches)	COMPLETE; 10/2011 Meeting Voice Vote
13	02/23/2004	3280.710	Dana C.	Roberts	3/2008 P&P Report - Status Unknown	A		Technical Systems	Kitchen Range Venting: Allow certain types of vents to not discharge to the exterior.	Unable to locate the proposal or date to HUD
17	11/15/2004	3280.802(42)	Kirk	Schirra	6/2008 P&P Report	APR	3/2011	Technical Systems	Electrical: Provide definition for AFCIs. Related to Log #4 for 3280.	COMPLETE; March 2011 Minutes Voted to Accept in Principle
19	11/15/2004	3280.804(m) (New)	Kirk	Schirra	6/2008 P&P Report	APR	3/1/2011	Technical Systems	Electrical: Require AFCIs for certain branch circuits in bedrooms.	COMPLETE; March 2011, Accepted in Principle. Similar to Log #4 and Log #5
20	08/10/2005	3280.403, 3280.404, 3280.405, and 3280.508(e)	Mark A.	Nunn	6/2008 P&P Report	APR	12/2012 Ballot	Technical Systems	Windows and Doors: Update to more recent editions of AAMA Standards	COMPLETE; 1/2013 Ballot - See Log 81-83
23	05/21/2007	3280.607(B)3i	Ross	Kinzler	12/2009 Ballot	APR	12/2009 Ballot	Technical Systems	Accessibility: Remove requirements for 1 inch extension at water receptor for roll in showers.	COMPLETE; 12/2009 Ballot Unable to locate the proposal or date to HUD
25	11/28/2007	3280.103	Tom	Neltner	3/2011 Meeting Agenda-SC	APR	12/2012 Ballot	Technical Systems	Indoor Air Quality: Optional compliance with ASHRAE 62.2 Permitted	COMPLETE; 1/2013 Ballot
59	12/03/2007	3280.103	Michael	Lubliner	6/2008 P&P Report	APR	12/2012 Ballot	Technical Systems	Indoor Air Quality: Require compliance with ASHRAE 62.2	COMPLETE; 1/2013 Ballot See Log 25
63	12/03/2007	3280.505	Michael	Lubliner	3/2011 - SC	MHCC Tabled 10/2012	12/2011	Technical Systems	Ventilation: Require management of exterior envelope penetrations to minimize air leakage	MHCC Tabled 10/2011 (sub recommends R) MHCC Tabled 10/2012
64	12/03/2007	3280.506(b)	Michael	Lubliner	3/2011 - SC	MHCC Tabled 10/2012	12/2011	Technical Systems	Energy Conservation: Control insulation compression.	MHCC Tabled 10/2012 Meeting
74	06/09/2010	3280.203(a)(1)(vi)	David A.	Tompos	3/2011 Meeting Agenda-SC	A	12/2011	Technical Structure & Design	Material: Clarify material thickness and allow vinyl material as an option.	COMPLETE; 10/2011 Meeting Voice Vote
75	07/06/2010	3280.715(a)(4)	Michael	Lubliner	11/2010 Ballot	A	11/2010 Ballot	Technical Systems	Ventilation: Require duct leakage test protocol.	COMPLETE; 11/2010 Ballot ; Tabled by HUD / DOE

HUD MHCC STATUS REPORT - STANDARDS

As Nov 21, 2014

Log#	Date Entered	Citation	First Name	Last Name	Date to MHCC	MHCC Action	Date to HUD	Subcommittee	Topic & Notes	Status
76	07/27/2010	3280.4 and 3280.210	Lois	Starkey	10/10/2011	APR	10/20/2011	Technical Structure & Design	Safety: Provide conditions for residential sprinkler installation for correlation with private sector codes for housing.	COMPLETE; 10/2011 Meeting Voice Vote
77	11/16/2010	3280.303(b)	Michael	Wade	7/1/2011	A	12/2012 Ballot	Technical Structure & Design	Quality Control: Insure that work is completed using approved quality assurance manual.	COMPLETE; 1/2013 Ballot
78	11/22/2010	3280.304(a)	Michael	Wade	7/1/2011		12/2011	Technical Structure & Design	Material: Moisture content in dimensional lumber. Limit to 19%	Open - Returned to the Design & Structure Subcommittee
79	04/18/2011	3280.304	Matthew	Dobson	9/30/2011	A	12/2012 Ballot	Technical Structure & Design	Vinyl Siding Issue	COMPLETE; 1/2013 Ballot
80	09/03/2011	3280.406 (new)	James P.	Van Schoyck	10/1/2012	Tabled	10/2012 Meeting	Technical Structure & Design	Formaldehyde Testing	Tabled 10/2012 Meeting
81	12/18/12	3280.403	Robert	Luter	6/26/2014	A	1/31/2013	Technical Structure & Design	AAMA 1701.2-12 Windows and Sliding Glass Doors	Complete; 10/2014 Ballot
82	12/18/2012	3280.404	Robert	Luter	6/26/2014	A	1/31/2013	Technical Structure & Design	AAMA 1704-12 Egress Windows	Complete; 10/2014 Ballot
83	12/18/2012	3280.405	Robert	Luter	6/26/2014	A	1/31/2013	Technical Structure & Design	AAMA 1702.2-12 Exterior Passage Doors	Complete; 10/2014 Ballot
84	12/18/2012	3280.813(b)	John	Walters	6/26/2014	A	1/31/2013	Technical Systems	Revise Required Label	Complete; 10/2014 Ballot
85	06/21/2013	3280.801	Vince	Baclawski	6/26/2014		7/9/2013	Technical Systems	NEC 2011	Open - Rejected by Technical Systems Subcommittee
86	06/21/2013	3280.806	Vince	Baclawski	6/26/2014		7/9/2013	Technical Systems	Tamper Resistant Receptacle Outlets	Open - Rejected by Technical Systems Subcommittee
CP4		3280.304	MHCC			A		Technical Structure & Design	ASCE 7-05	Complete; 1/2013
CP5		3280.103	MHCC			A		Technical Systems	Delete 90 CFM for Whole House	Complete; 1/2014
INSTALLATION LOG ITEMS										
1	10/4/2004	3285 Enitre Document	Boone Smith	Morris	4/2006		2/2004	Technical Structure and Design	Alternative Foundation Design/Ground Anchor Standard: Reccomendation to use an alternative foundation system. No specific language provided.	Tabled 10/2012 Meeting

HUD MHCC STATUS REPORT - STANDARDS

As Nov 21, 2014

2	01/25/2010	3285.203	Susan	Brenton	03/01/2011	APR	12/1/2011	Technical Structure and Design	Site Work: Requires drainage form the home consistent with Local AHJ rules.	COMPLETE; 10/2011 Meeting Voice Vote; Cannot locate a copy of the MHCC modified vote
---	------------	----------	-------	---------	------------	-----	-----------	--------------------------------	---	--