01/28/2021

# TITLE V, FEDERAL SURPLUS PROPERTY PROGRAM FEDERAL REGISTER REPORT FOR 01/29/2021

# SUITABLE / AVAILABLE PROPERTIES BUILDING CALIFORNIA

Border Patrol Checkpoint 728 Interstate 8 W Pine Valley CA 81906 Landholding Agency: DHS CBP Property Number: 52202110001 Status: Unutilized Directions: Interstate 8 Westbound Campo

#### Comments:

Offsite removal only. Trailer-2 restrooms, kitchen w/sink, 4 rooms, open space. 24-yr. old, modular/trailer T111 siding and metal roof. 1,440 sq. ft. Good condition. Siding needs to be replaced.

## NORTH DAKOTA

Pembina Customs House 112 W Stutsman Street Pembina ND 58271 Landholding Agency: GSA Property Number: 54202110002 Status: Surplus GSA Number: 7-G-ND-0524-AA Comments:

Comments: 3 floor concrete/block structure. 15,058 sq. ft. Includes 0.60 acres of land. Historic bldg. on National Register for Historic Places. Contact GSA for more information.

# UNSUITABLE PROPERTIES BUILDING ALASKA

FS2202 Dinkey RS Warehouse 53635 Dinkey Creek Road Shaver Lake CA 93664 Landholding Agency: USDA Property Number: 15202110008 Status: Unutilized Directions: CN. 1408.00438. Lat. 37.065362 Long. 155894 Comments: Offsite removal only. 86yr-old, metal structure. 709 sq. ft. Located in remote location. Reasons: Other - Would need to be disassembled to move. FS1901 Glen Meadow Paint Shed 50810 Dinkey Creek Road Shaver CA 93664 Landholding Agency: USDA Property Number: 15202110009 Status: Unutilized Directions: Lat 37.07708672 Long -119.1855139. CN:1403.00438 Comments: Poor Condition-Unused for 120+ months. 31yr.-old wood structure. 26 sq. ft. Located at Glen Meadow Work Center. Offsite removal only. Reasons: Structural Damage - Extensive Deterioration

3

FS2104 FN Recreation Barn 57003 Road 223 North Fork CA 93643 Landholding Agency: USDA Property Number: 15202110010 Status: Unutilized Directions: Lat 37.23399768. Long-119.5057237. CN:1274.004381 Comments: Offsite removal only. 86 yr.-old, 1,288 sq. ft. structure. Vacant 60+ months. Poor condition, extensive repairs needed. Reasons: Structural Damage - Extensive Deterioration FS2503 North Fork Storage Shed 57003 Road 225 North Fork CA 93643 Landholding Agency: USDA Property Number: 15202110011 Status: Unutilized Directions: CN: 1275.001381 At Lat. 37.23493233. Long -119.5072653 Comments: Offsite removal only. 88 yr.-old, 1050 sq. ft. wood building. Poor condition, extensive repairs needed. Reasons: Structural Damage - Extensive Deterioration

FS2512 Trim Gas/Oil Ser. Shed 34849 Maxon Road Sanger CA 93657 Landholding Agency: USDA Property Number: 15202110012 Status: Unutilized Directions: Lat 36.91035162 Long -119.307089. CN: 1328.004381 Comments: Offsite removal only. 29 yr. old storage bldg. 128 sq. ft. Poor condition. Reasons: Structural Damage - Extensive Deterioration FS2636 Trimmer Storage Shed 34849 Maxon Road Sanger CA 93657 Landholding Agency: USDA Property Number: 15202110013 Status: Unutilized Directions: Lat 36.90841522 Long -119.3060051. CN: 1470.004381 Comments:

Offsite removal only. 35-yr. old, 104 sq. ft. storage bldg. Poor condition Reasons:

Structural Damage - Extensive Deterioration

FS2606 NF X-Powder Storage
57003 Road 225
North Fork CA 93643
Landholding Agency: USDA
Property Number: 15202110014
Status: Unutilized
Directions:
Lat 37.2357554 Long -119.5061491. CN: 1277.004381
Comments:
Offsite removal only. 86 yr. old, 432 sq. ft. wood structure. Poor condition, extensive repairs needed.
Reasons:
Structural Damage - Extensive Deterioration
FS28022 Deadwood Radio Vault
See Directions
North Fork CA
Landholding Agency: USDA
Property Number: 15202110015
Status: Unutilized
Directions:
CN:2776.004381. Located at Lat 37.313640, -119.685935
Comments:

Offsite removal only. Remote forest area. 34yr.-old, 120 sq. ft. concrete cinder block structure. Vacant and unused for a long time. Poor condition.

# Reasons:

Isolated area. Other - Remote area. Structural Damage - Extensive Deterioration

FS1022 Dinkey RS Residence 53635 Dinkey Creek Road Shaver Lake CA 93664 Landholding Agency: USDA Property Number: 15202110016 Status: Unutilized Directions: CN: 1142.00438. Located at Dinkey Ranger Station, Lat 37.06517477 Long -119.1562761. Comments: Offsite removal only. Vacant 15+ yrs. badly damaged from fallen tree. 88 yr. old 832 sq. ft. wood structure. Reasons: Isolated area. Other - Remote Location. Structural Damage - Extensive Deterioration FS1023 Dinkey RS Culture Res. 5.3635 Dinkey Creek Road Shaver Lake CA 93664 Landholding Agency: USDA Property Number: 15202110017 Status: Unutilized Directions: CN: 1143.004381. Lat 37.06561393 Long -119.1558034. Dinkey Ranger Station. Comments: Offsite removal only. 86 y. old, 1023 sq. ft. wood structure. Vacant 60+ months. Poor condition.

Reasons:

Isolated area. Other - Remote location. Structural Damage - Extensive Deterioration

FS28017 Jackass Shower House See Directions Shaver Lake CA 93664 Landholding Agency: USDA Property Number: 15202110018 Status: Unutilized Directions: CN: 2553.004381. Located at Jackass Station; Lat 37.28433316 Long -118.9668633 Comments: Offsite removal only. Vacant for an extensive period, poor condition. 29 yr. old, 233 sq. ft. wood structure. Reasons:

Other - Remote location. Isolated area. Structural Damage - Extensive Deterioration

FS2202 Dinkey RS Warehouse 53635 Dinkey Creek Road Shaver Lake CA 93664 Landholding Agency: USDA Property Number: 15202110019 Status: Unutilized Directions: CN: 1408.00438. Located at Dinkey Ranger Station, Lat 37.065362 Long -119.155894.

Comments:

Offsite removal only. 86 yr. old, 709 sq. ft. metal structure. Vacant for a long period of time. Poor condition.

Reasons:

Other - Remote location. Isolated area

FS1903 High Sierra Supply Shed See Directions Mono Springs CA 93642 Landholding Agency: USDA Property Number: 15202110020 Status: Excess Directions: Located at High Sierra Ranger Station off of Kaiser Pass Road. Lat 37.3141919 Long -119.0408313. Elevation 7300'. CN: 1078.004381 Comments: Offsite removal only. 53 yr.-old, 100 sq. ft. wood structure located in isolated, high elevation area. Poor condition, extensive deterioration.

Reasons:

Inaccessible. Isolated area. Structural Damage - Extensive Deterioration

# INDIANA

NIKE C47 Launcher Area CR 700N Hobart IN 46342 Landholding Agency: GSA Property Number: 54202110003 Status: Surplus GSA Number: I-G-IN-522AA Comments:

In extreme disrepair due to decades of deferred maintenance, extensive vandalism, and fire damage. Some walls at risk of collapse.

Reasons:

Structural Damage - Extensive Deterioration

#### UNSUITABLE PROPERTIES BUILDING MONTANA

RML ARMCO-1 903 S 4th Street Hamilton MT 59840 Landholding Agency: HHS Property Number: 57202110002 Status: Unutilized Comments:

Comments: Offsite removal only. 59 yr. old steel frame/slab on grade, 2,049 sq. ft. structure. Not easily converted to other purposes from existing. Survey for lead, asbestos and mercury underway.

Reasons:

Other - Size, building materials. National Security Concerns

RML ARMCO-2 903 S. 4th Street Hamilton MT 59840 Landholding Agency: HHS Property Number: 57202110003 Status: Unutilized Directions: (80901-00-ARM2)

mmonto

Comments:

Offsite removal only. Located on secure campus. 59-yr-old steel frame/slab on grade, 2, 048 sq. ft. Survey for lead, asbestos and mercury currently underway.

Reasons:

Other - Unsuitable for offsite removal-construct

#### UNSUITABLE PROPERTIES BUILDING NEW YORK

Bldg. 902LM B/902LM 59 John Hopkins St. Upton NY 11973 Landholding Agency: DOE Property Number: 41202110003 Status: Excess Directions: Offsite removal only.

#### Comments:

Offsite removal only. 41 yr. old modular wood framed textured 111 siding with a single ply asphalt roofing system. 5,065 Sq. Ft. 25-yrs. beyond expected life, poor condition.

Reasons:

Structural Damage - Extensive Deterioration. National Security Concerns

#### OREGON

Bldg. #2875 See Directions Rhododendron OR 97037 Landholding Agency: USDA Property Number: 15202110021 Status: Excess Directions: HR, RADIO BLDG, CLEAR LAKE BUTTE (1896.004901). LAT: 45°09.387'

LONG -121°43.116'

Comments:

Offsite removal only. 37 yr. old, 48 sq. ft. fiberglass structure. Exterior is compromised, interior frame and floor failing.

Reasons:

Inaccessible. Isolated area. Structural Damage - Extensive Deterioration. Other - Accessible by high clearance vehicles

## **UNSUITABLE PROPERTIES** BUILDING OREGON

```
Bldg. 5929
See Directions
Lakeview OR 97360
Landholding Agency: USDA
Property Number: 15202110022
Status: Excess
Directions:
       MP 8, OR HWY 140; 2 mi. south on FSR 3615; 10 mi. on FSR 3915; 1 mi. on FSR
       4011 to site access rd. 12662 (Willow Creek Campground). (1481.004681)
Comments:
```

Offsite removal only, 51 yr.-old, 20 sq. ft. service toilet. Exceeds life of building. Toilet used for human waste-possible health risks.

Reasons:

Structural Damage - Extensive Deterioration. Isolated area

Bldg. 5998 See Directions Lakeview OR 97360 Landholding Agency: USDA Property Number: 15202110023 Status: Excess

Directions:

MP 8, OR HWY 140; 2 mi. south on FSR 3615; 10 mi. on FSR 3915; 1 mi. on FSR 4011 to site access rd. 12662 (Willow Creek Campground) (1555.004681)

Comments:

Offsite removal only. 51 yr.-old, 20 sq. ft. service toilet. Exceeds service life. Remote location. Possible health concern due to human waste disposal.

Reasons:

Isolated area. Structural Damage - Extensive Deterioration

## UNSUITABLE PROPERTIES BUILDING SOUTH CAROLINA

South Tibwin Dwelling 9241 North Highway 17 McClennanville SC 29458 Landholding Agency: USDA Property Number: 15202110024 Status: Unutilized Directions:

The dwelling is located behind a locked gate. Unauthorized vehicle access is prohibited behind the gate.

Comments:

Offsite removal only. 36yr.-old 1,760 sq. ft. 2 floor residential dwelling. Vacant approx. 8 years. Complete disrepair. Structurally unsound. Roof leaks, interior black mold.

Reasons:

Isolated area. Documented Deficiencies-Contamination. Structural Damage - Extensive Deterioration