

INTERPRETATIVE BULLETIN E-3-76
EGRESS WINDOWS - 3280.404

Integral rolled-in screens are not permitted in egress windows.