



Real Estate Assessment Center Request for Technical Review of a Physical Inspection Score

Inspection Number <u>44444</u>	Project ID Number <u>8000000</u>
Inspection Date <u>July 15, 2000</u>	Address of Property <u>123 Main Street</u>
Project/Property Name <u>Main Street Apartments</u>	City, State <u>Chattanooga, TN</u>
Date of Request <u>July 31, 2000</u>	Contact Name <u>Jane Smith</u>

ISSUE # 1

Location (Inspectable Area)	Building Number	Unit Number
Dwelling Unit	4	48B

Documentation Type:



Item and Deficiency/Observation

Bathroom Cabinets – Damaged/Missing

Reason for Request

The bathroom cabinets are present and functioning properly. There was no damage at the time of the inspection.

Additional Comments

Picture #2 is date-stamped the day of the inspection, and shows no sign of damage.

ISSUE #

Location (Inspectable Area)	Building Number	Unit Number

Documentation Type:



Item and Deficiency/Observation

Reason for Review

Additional Comments

ISSUE #

Location (Inspectable Area)	Building Number	Unit Number

Documentation Type:



Item and Deficiency/Observation

Reason for Review

Additional Comments