for September 6, 2019

(NOTE: Please access the 'Landholding Agency Contact Spreadsheet' located in the 'RESOURCES' menu (on the right hand side) under the 'TITLE V SUITABLE LISTING MAP' page, for additional questions regarding properties listed.)

SUITABLE / AVAILABLE PROPERTIES BUILDING ARIZONA

USDA/FS Payson District Office

Payson Ranger District, Tonto National Forest

Payson AZ 85541

Landholding Agency: Agriculture Property Number: 15201930089

Status: Excess Comments:

Payson District Office, I Web #043009 RPUID:1084.002601; Off-site removal only; 45+ yrs. old; 4,152 sq. ft.; district office; ACM & LBP present; office is open to the public during office hours, but the compound is closed to the public; contact Agriculture for more information.

CALIFORNIA

USDA/FS Boulder Oaks

Campground, CN:1747.003621 Boulder Oaks Campground

Campo CA 91906

Landholding Agency: Agriculture Property Number: 15201930082

Status: Excess Comments:

8986-T02 Vault Toilet Building; Off-site removal only; 51+ yrs. old; 144 sq. ft.; restrooms; poor condition; ACM and LBP present; contact Agriculture for more

information.

for September 6, 2019

(NOTE: Please access the 'Landholding Agency Contact Spreadsheet' located in the 'RESOURCES' menu (on the right hand side) under the 'TITLE V SUITABLE LISTING MAP' page, for additional questions regarding properties listed.)

SUITABLE / AVAILABLE PROPERTIES BUILDING CALIFORNIA

USDA/FS Blue Jay Campground

CN: 1018.003621 Blue Jay Campground Lake Elsinore CA 92530

Landholding Agency: Agriculture Property Number: 15201930084

Status: Excess Comments:

23177-T02 Vault Toilet Building; Off-site removal only; 51+ yrs. old; 158 sq. ft.; restrooms; poor condition; ACM & LBP present; accessibility will need to be scheduled during business hours M-F 8-4:30pm, contact Agriculture for more information.

USDA/FS Blue Jay Campground

CN: 1019.003621 Blue Jay Campground Lake Elsinore CA 92530

Landholding Agency: Agriculture Property Number: 15201930086

Status: Excess Comments:

23177-T03 Vault Toilet Building; Off-site removal only; 51+ yrs. old; 168 sq. ft.; restrooms; poor condition; ACM & LBP present; accessibility will need to be scheduled during business hours M-F 8-4:30pm, contact Agriculture for more information.

for September 6, 2019

(NOTE: Please access the 'Landholding Agency Contact Spreadsheet' located in the 'RESOURCES' menu (on the right hand side) under the 'TITLE V SUITABLE LISTING MAP' page, for additional questions regarding properties listed.)

SUITABLE / AVAILABLE PROPERTIES BUILDING CALIFORNIA

USDA/FS Blue Jay Campground

CN: 1022.003621 Blue Jay Campground Lake Elsinore CA 92530

Landholding Agency: Agriculture Property Number: 15201930087

Status: Excess Comments:

23177-T06 Vault Toilet Building; Off-site removal only; 51+ yrs. old; 88 sq. ft.; restrooms; poor condition; ACM & LBP present; accessibility will need to be scheduled during business hours M-F 8-4:30pm, contact Agriculture for more information.

USDA/FS Boulder Oaks

Campground, CN:14142.003621 Boulder Oaks Campground

Campo CA 91906

Landholding Agency: Agriculture Property Number: 15201930088

Status: Excess Comments:

8986-U01 Pumphouse; Off-site removal only; 33+ yrs. old; 25 sq. ft.; pump house; poor condition; LBP present; prior approval needed to gain access; contact Agriculture for more information.

for September 6, 2019

(NOTE: Please access the 'Landholding Agency Contact Spreadsheet' located in the 'RESOURCES' menu (on the right hand side) under the 'TITLE V SUITABLE LISTING MAP' page, for additional questions regarding properties listed.)

SUITABLE / AVAILABLE PROPERTIES BUILDING OREGON

USDA/FS Dale Heliport Radio

Building, Hwy 395

Dale OR 97856

Landholding Agency: Agriculture Property Number: 15201930081

Status: Excess Comments:

Building ID #2821 (2169.009091); Off-site removal only; 38+ yrs. old; 48 sq. ft.; communication; 168+ mos. vacant; poor condition; severe rodent infestation; prior

approval needed to gain access; contact Agriculture for more information.

LAND

CALIFORNIA

USDA/FS Boulder Oaks

Campground, CN:1746.003621 Boulder Oaks Campground

Campo CA 91906

Landholding Agency: Agriculture Property Number: 15201930083

Status: Excess Comments:

8986-T01 Vault Toilet Building; Off-site removal only; 51+ yrs. old; 144 sq. ft.; restrooms; poor condition; ACM and LPB present; contact Agriculture for more

information.

for September 6, 2019

(NOTE: Please access the 'Landholding Agency Contact Spreadsheet' located in the 'RESOURCES' menu (on the right hand side) under the '<u>TITLE V SUITABLE LISTING MAP</u>' page, for additional questions regarding properties listed.)

UNSUITABLE PROPERTIES BUILDING COLORADO

USDA/FS Sunnyside Fish Brick

Toilet

Leadville Ranger District

Twin Lakes CO

Landholding Agency: Agriculture Property Number: 15201930090

Status: Excess Comments:

RPUID: #4359.001621 INFRA #9190; Extensive deterioration; severely dilapidated; significant waste build up that has caused severe deterioration.

Reasons:

Extensive deterioration

NEW MEXICO

Los Alamos National Laboratory

16-0374

Los Alamos NM 87545

Landholding Agency: Energy Property Number: 41201930001

Status: Excess Comments:

Public access denied and no alternative method to gain access without

compromising national security.

Reasons:

for September 6, 2019

(NOTE: Please access the 'Landholding Agency Contact Spreadsheet' located in the 'RESOURCES' menu (on the right hand side) under the 'TITLE V SUITABLE LISTING MAP' page, for additional questions regarding properties listed.)

UNSUITABLE PROPERTIES BUILDING NEW YORK

2 Buildings

Brookhaven National Laboratory

Upton NY 11973

Landholding Agency: Energy Property Number: 41201930004

Status: Excess Comments:

0901AM (Modular) of building 0901A; Building 0919J (PTR Rect. House #3);

Public access denied and no alternative method to gain access without

compromising national security.

Reasons:

Secured Area

2 Buildings

Brookhaven National Laboratory

Upton NY 11973

Landholding Agency: Energy Property Number: 41201930005

Status: Unutilized

Comments:

Building 0728M (Modular Offices); Building 0919I (Proton House G18); Public access denied and no alternative method to gain access without compromising national security.

Reasons:

for September 6, 2019

(NOTE: Please access the 'Landholding Agency Contact Spreadsheet' located in the 'RESOURCES' menu (on the right hand side) under the 'TITLE V SUITABLE LISTING MAP' page, for additional questions regarding properties listed.)

UNSUITABLE PROPERTIES BUILDING NEW YORK

2 Buildings

Brookhaven National Laboratory

Upton NY 11973

Landholding Agency: Energy Property Number: 41201930006

Status: Excess Comments:

0703M (Modular) of building 0703 & Building 0919H (PTR Rect. House #1);

Public access denied and no alternative method to gain access without

compromising national security.

Reasons:

Secured Area

2 Buildings

Brookhaven National Laboratory

Upton NY 11973

Landholding Agency: Energy Property Number: 41201930007

Status: Excess Comments:

Modular 0510M of building 0510, GARS Research Operations Office; Building 0919G (G-2 R&D Refrigerator Room); Public access denied and no alternative method to gain access without compromising national security.

Reasons:

for September 6, 2019

(NOTE: Please access the 'Landholding Agency Contact Spreadsheet' located in the 'RESOURCES' menu (on the right hand side) under the 'TITLE V SUITABLE LISTING MAP' page, for additional questions regarding properties listed.)

UNSUITABLE PROPERTIES BUILDING OKLAHOMA

Great Salt Plains HC 65, Box 120 Cherokee OK 73728

Landholding Agency: COE

Property Number: 31201930008

Status: Unutilized

Comments:

Highway 38 (Leased) GRSALT-43869; Extensive deterioration; building has

deteriorated and is beyond use.

Reasons:

Extensive deterioration

Sardis Lake

Mathies Park/ HC 60 Box 175

Clayton OK 74365

Landholding Agency: COE Property Number: 31201930009

Status: Excess Comments:

Sardis-42777; Extensive deterioration; building has deteriorated and is beyond use.

Reasons:

Extensive deterioration

for September 6, 2019

(NOTE: Please access the 'Landholding Agency Contact Spreadsheet' located in the 'RESOURCES' menu (on the right hand side) under the 'TITLE V SUITABLE LISTING MAP' page, for additional questions regarding properties listed.)

UNSUITABLE PROPERTIES BUILDING OREGON

USDA/FS Blue Springs Toilet

Near Blue Springs, approx. 40 road miles

La Grande OR 97850

Landholding Agency: Agriculture Property Number: 15201930080

Status: Unutilized

Comments:

Installation 07673 00#1034 (51297010263); Extensive deterioration; structurally

unsound; roof collapsing.

Reasons:

Extensive deterioration

TENNESSEE

9819 Maintenance Storage Bldg. Y-12 National Security Complex

Oak Ridge TN 37830

Landholding Agency: Energy Property Number: 41201930002

Status: Excess Comments:

Public access denied and no alternative method to gain access without

compromising national security.

Reasons:

for September 6, 2019

(NOTE: Please access the 'Landholding Agency Contact Spreadsheet' located in the 'RESOURCES' menu (on the right hand side) under the 'TITLE V SUITABLE LISTING MAP' page, for additional questions regarding properties listed.)

UNSUITABLE PROPERTIES BUILDING TEXAS

Building 11-020SS

Pantex Plant US Hwy. 60 at FM 2373

Carson County TX

Landholding Agency: Energy Property Number: 41201930003

Status: Unutilized

Comments:

Public access denied and no alternative method to gain access without

compromising national security.

Reasons:

Secured Area

LAND

SOUTH CAROLINA

Hilton Head Survey Tower

Hilton Head Island

Adjacent to 52 Canvaback Rd.

Hilton Head SC 29928

Landholding Agency: GSA

Property Number: 54201930005

Status: Surplus

GSA Number: 4-A-SC-0609AA

Comments:

Landholding Agency: Corp of Engineers; Disposal Agency: GSA; Property is inaccessible because it is landlocked and can only be reached by crossing private

property and there is no established right or means of entry.

Reasons:

Not accessible by road