04/01/2021

## TITLE V, FEDERAL SURPLUS PROPERTY PROGRAM FEDERAL REGISTER REPORT FOR 04/02/2021

## SUITABLE / AVAILABLE PROPERTIES BUILDING INDIANA

Soil Erosion Lab 317-8

See Directions

Lafvette IN

Landholding Agency: USDA-ARS Property Number: 14202110005

Status: Excess Directions:

20131 National Soil Erosion Research Lab; ARS Inventory No 363600B011; RPUID 03.55342. 40.470051 N 86.988926 W.

#### Comments:

Offsite removal only. 42 yr. old, 1520 sq. ft. warehouse. Agency permission to access. General bldg. repairs, maintenance. Contact Agency for more information.

## UNSUITABLE PROPERTIES BUILDING COLORADO

Old Wood Toilet See Directions Salida CO

Landholding Agency: USDA-FS Property Number: 13202110068

Status: Excess Directions:

Salida Ranger District; RPUID #4456.001621; Infra #9246. From Salida Rd office drive 0.1 mi to Hwy 50, turn L, then drive E for 18.3 miles then turn R on CR 6. then drive 4 miles to campground. Salida Ranger District RPUID 4456.001621

## Comments:

Off-site removal only, remote location. 55+ yrs. old; 48 sq. ft. wood restroom; poor condition; not ADA accessible.

## Reasons:

## UNSUITABLE PROPERTIES BUILDING

## COLORADO

Lakewood Campground Wood Toilet Lakeview CG, Loop D County Rd. 24

Leadville CO 81251

Landholding Agency: USDA-FS Property Number: 13202110070

Status: Excess Directions:

Leadville Ranger District; RPUID #4331.001621; Infra #9163

## Comments:

Off-site removal only. 41 yr. old; 102 sq. ft. wood restroom in poor, decrepit condition.

## Reasons:

Other – Toilet. Structural Damage - Extensive Deterioration

Lost Park Campground Wood Toilet

See Directions

Fairplay CO

Landholding Agency: USDA-FS Property Number: 13202110071

Status: Excess Directions:

South Park Ranger District; RPUID #4510.006121; Infra #9860. From Fairplay take Hwy 285 N towards Denver, approx. 1-mile N of Jefferson, turn right onto Park CO road. 56, stay on CR 56 until road ends at CG, approx. 37 miles.

## Comments:

Off-site removal only. 65 yr. old 56 sq. ft. outhouse in poor, decrepit condition.

#### Reasons:

Manitou Lake Park Ground Wood Toilet

32048 Hwy 67 North

Colorado Springs CO 80863

Landholding Agency: USDA-FS Property Number: 13202110072

Status: Excess Directions:

Pikes Peak Ranger District; RPUID #4385.991621; Infra #9734

Comments:

Off-site removal only. 39 yr. old 88 sq. ft. wood restroom in poor, decrepit condition.

Reasons:

Other – Toilet. Structural Damage - Extensive Deterioration

South Meadows Campground Wood Toilet

29931 Highway 67 North

Colorado Springs CO 80863

Landholding Agency: USDA-FS

Property Number: 13202110073

Status: Excess Directions:

Pikes Peak Ranger District; RPUID #4403.001621; Infra #9752

Comments:

Off-site removal only. 61 yr. 54 sq. ft. wood restroom in poor, decrepit

condition.

Reasons:

Springer Gulch Campground Wood Toilet

See Directions

Fairplay CO

Landholding Agency: USDA-FS Property Number: 13202110074

Status: Excess Directions:

South Park Ranger district, Springer Gulch campground. From Fairplay take Hwy 285 S to Hwy 9. Stay on CR 96 into 11 Mile drive. RPUID: 4516.001621

## Comments:

Off-site removal only. 59 yr. old 56 sq. ft. outhouse in poor, decrepit condition.

## Reasons:

Other – Toilet. Structural Damage - Extensive Deterioration

Timberline Campground SST Original Toilet

See Directions

Colorado Springs CO 80433 Landholding Agency: USDA-FS Property Number: 13202110075

Status: Excess Directions:

South Platte Ranger District; RPUID #12598.010465 National Forest System Rd 125 off Park County Rte. 125 off Park County Route 58 from US Hwy 285. Timberline CG SST ORIG.

#### Comments:

Off-site removal only; 30 yrs. old; 42 sq. ft.; single toilet. exterior wall damage; contains human waste. Bldg. backed into.

## Reasons:

Coledale Old Wood Toilet

See Directions

Salida CO

Landholding Agency: USDA-FS Property Number: 13202110078

Status: Excess Directions:

Salida Ranger District; Infra #9247. Coaldale CG. From Salida Rd office drive, 0.1 mile to Hwy 50, turn left, then drive E for 18.3 miles, then turn right on CR 6, then drive 4 miles to campground.

## Comments:

Off-site removal only. 55 yrs. old; 48 sq. ft. wood restroom in poor condition.

## Reasons:

Other – Toilet. Structural Damage - Extensive Deterioration

Lakewood Campground Wood Toilet

See Directions

Leadville CO 81251

Landholding Agency: USDA-FS Property Number: 13202110080

Status: Excess Directions:

Leadville Ranger District; RPUID #4434.001621; Infra #9165 Lakeview CG, Loop F, County Rd. 24.

## Comments:

Off-site removal only. 41 yrs. old 102 sq. ft. wood restroom. In poor condition, decrepit.

## Reasons:

Lost Park Campground Old Wood Toilet

See Directions

Fairplay CO 80433

Landholding Agency: USDA-FS Property Number: 13202110081

Status: Excess Directions:

From Fairplay take Hwy 285 N towards Denver, approx. 1-mile N of Jefferson, turn right onto Park Co Rd. 56, stay on CR 56 until road ends at CG approx. 37 miles. South Park Ranger District; RPUID

#4509.001621: Infra #9859

## Comments:

Off-site removal only. 55 yr. old 56 sq. ft. outhouse. Poor condition.

## Reasons:

Other – Toilet. Structural Damage - Extensive Deterioration

Manitou Lake Campground Wood Toilet

32048 Highway 67 North

Colorado Springs CO 80863

Landholding Agency: USDA-FS Property Number: 13202110082

Status: Excess Directions:

Pikes Peak Ranger District; RPUID #4385.001621.

## Comments:

Off-site removal only. 39 yrs. old 88 sq. ft. wood restroom in poor condition.

#### Reasons:

South Meadows Campground Wood Toilet

29931 Hwy 67 North

Colorado Springs CO 80863

Landholding Agency: USDA-FS Property Number: 13202110083

Status: Excess Directions:

Pikes Peak Ranger District; RPUID #5338.001621; Infra #9769

Comments:

Off-site removal only. 61 yr. old 54 sq. ft. wood restroom in poor condition.

Reasons:

Other – Toilet. Structural Damage - Extensive Deterioration

Springer Gulch Old Wood Toilet

See Directions

Fairplay CO 80433

Landholding Agency: USDA-FS Property Number: 13202110084

Status: Excess Directions:

South Park Ranger District; RPUID #4517.001621. Springer Gulch Campground, from Fairplay take HWY 285 south to HWY 9. Turn left on HWY 9 and drive to HWY 24, turn left on HWY 24 and rive towards Lake George. At Lake George turn right on CR 96. Stay on CR 96 for 11 miles.

Comments:

Off-site removal only. 59 yr. old 56 sq. ft. outhouse in poor condition.

Reasons:

Timberline Campground Toilet

See Directions

Colorado Springs CO 80433 Landholding Agency: USDA-FS Property Number: 13202110085

Status: Excess Directions:

South Platte Ranger District. RPUID #4655.001621. Timberline Campground. Located on National Forest Road 125 off park County Rte. 58 form US Hwy 285

## Comments:

Off-site removal only. 30 yrs. old 42 sq. ft. vault toilet. Exterior wall damaged.

#### Reasons:

Other – Toilet. Structural Damage - Extensive Deterioration

Boot Leg Campground Old Wood Toilet

See Directions Salida CO 81201

Landholding Agency: USDA-FS Property Number: 13202110093

Status: Excess Directions:

Salida Ranger District; RPUID #4434.001621; Infra #9220. From Salida Rd. drive 0.1 mile to Hwy 50 then drive W for 5.5 miles then turn R on Hwy 50/285 drive 0.5 miles then turn right on Hwy 285 & drive N for 15.5 miles then turn left on CR 162, drive 6.8 miles to Chalk Creek TH, then hike 0.1 mile to campground

## Comments:

Off-site removal only. 57 yr.-old 25 sq. ft. wood restroom in decrepit, poor condition.

## Reasons:

Denny Creek TH Wood Toilet

See Directions

Salida CO

Landholding Agency: USDA-FS Property Number: 13202110095

Status: Excess Directions:

Salida Ranger District; RPUID #4472.001621; Infra #9262 From Salida Rd office drive 0.1 miles to Hwy 50 then drive W for 5.5 miles then turn R on Hwy 50/285, drive 0.5 then turn R on Hwy 285 & drive N for 29.5 mile then turn left on CR 306, drive 12 miles to trailhead.

## Comments:

Off-site removal only. 35 yr. old 80 sq. ft. wood restroom in poor condition; not ADA accessible.

## Reasons:

Other – Toilet. Structural Damage - Extensive Deterioration

Hall Valley Campground SST Traditional Toilet

See Directions

Conifer CO 80433

Landholding Agency: USDA-FS Property Number: 13202110096

Status: Excess Directions:

South Platte Ranger District; RPUID #4282.001621. Infra #9965. Located on Nation Forest System Rd. 120.28 off Park County Route 60 from US Hwy 285. In Handcart campground.

#### Comments:

Off-site removal only. 28 yr. old 42 sq. ft. traditional single toilet in poor condition, needs new roof.

## Reasons:

Handcart Campground SST Traditional

See Directions Conifer CO

Landholding Agency: USDA-FS Property Number: 13202110126

Status: Excess Directions:

RPUID #4272.001621; Infra # 9953; South Platte Ranger District. Located on National forest System Road 120.2A off Park County Route 60 from US Highway 285

## Comments:

Off-site removal only; 28+ yrs. old; 42 sq. ft.; restroom; poor condition needs new roof, siding, and door.

#### Reasons:

Other – Toilet. Structural Damage - Extensive Deterioration

Lake Isabel Park Ground SST Original

See Directions Canyon City CO

Landholding Agency: USDA-FS Property Number: 13202110127

Status: Excess Directions:

San Carlos RD; PUID #5003.001621; Infra #9364; From the Town of Rye Co travel West on Hwy 165 10.8 miles to intersection of National Forest Rd 371, turn right onto 371 and drive approx. 0.24 miles; San Carlos RD

#### Comments:

Off-site removal only; 28+ yrs. old; plastic/wooden; restroom; decrepit.

## Reasons:

Pines Point #2 Public Toilet

See Directions

Pines Point CO

Landholding Agency: USDA-FS Property Number: 13202110128

Status: Unutilized

Directions:

Infra 48119

(43.31.50.70N) (LONG86.06.57.45W)

## Comments:

Off-site removal only; 22+ yrs. old;57 sq. ft.; wood; toilet; very poor condition.

## Reasons:

Other – Toilet. Structural Damage - Extensive Deterioration

Ptarmigan Lake TH Wood Toilet

See Directions

Salida CO

Landholding Agency: USDA-FS Property Number: 13202110129

Status: Excess Directions:

Salida Ranger District; RPUID #4434.001621; Infra #9223; From Salida Rd. office Dr. 0.1 mile to Hwy 50 then drive W for 5.5 miles then turn right on Hwy 50/285, drive 0.5 miles then turn right on Hwy 285 & drive N for 29.5 miles then turn left on CR 306, drive 13.7 miles to trailhead

#### Comments:

Off-site removal only; 35+ yrs. old; 80 sq. ft.; wooden; restroom; poor condition; not ADA accessible

## Reasons:

Shirley Site CXT Toilet

See Directions

Salida CO

Landholding Agency: USDA-FS Property Number: 13202110130

Status: Excess Directions:

Salida Ranger District; RPUID #6177.001621; Infra #9266; From Salida Rd. office drive 0.1 miles to Hwy 50, turn right then drive W 5.5 miles then turn left Hwy 285 drive 5.1 miles then turn right on CR 200, drive 2.3 miles to trailhead

#### Comments:

Off-site removal; 23+ yrs. old; 82 sq. ft.; wooden; restroom; poor condition

## Reasons:

Other - Toilet. Structural Damage - Extensive Deterioration

Thunder Ridge CCC Campground Wood Toilet

See Directions

Colorado Springs CO

Landholding Agency: USDA-FS Property Number: 13202110131

Status: Excess Directions:

Pikes Peak Ranger District; RPUID #4407.001621; Infra #9756; From CO Springs, travel West on Hwy 24 for 17.4 miles to Baldwin St. in Woodland Park. Turn right, N on Baldwin which turns into Rampart Range Rd. Travel approx. 3 miles

## Comments:

Off-site removal only; 46+ yrs. old; 54 sq. ft. wood restroom in decrepit condition.

## Reasons:

Winfield TH Wood Toilet

See Directions Leadville CO

Landholding Agency: USDA-FS Property Number: 13202110132

Status: Excess Directions:

Leadville Ranger District; RPUID #4371.001621; Infra #9198; West on FRD 390 to town site of Winfield, then follow FRD 390 to the left for about 500 yards then turn left into the camping area

## Comments:

Off-site removal only. 30 yrs. old 48 sq. ft. wooden; restroom in decrepit condition.

## Reasons:

Structural Damage - Extensive Deterioration. Other - Toilet

Pines Point #1 Toilet

See Directions

Pines Point CO

Landholding Agency: USDA-FS Property Number: 13202110133

Status: Unutilized

Directions:

Infra 48118 (LAT43.31.50.70N) (LONG86.06.57.45W)

Comments:

Off-site removal only. Very poor condition. 22 yrs. old wood toilet. 57 sq. ft.

Reasons:

Grand Canyon Toilet 1

See Directions

Pomona IL

Landholding Agency: USDA-FS Property Number: 13202110116

Status: Excess Directions:

Mississippi Bluffs Ranger District - Grand Canyon Recreation Site;

RPUID #1154.007541 Grand Canyon (1232)

## Comments:

Off-site removal only; 28+ yrs. old; 155 sq. ft.; vault toilet; Poor condition, roof skylight leaking, interior wall damaged; contains human waste.

## Reasons:

Other - Vault Toilet. Structural Damage - Extensive Deterioration

Toilet/Indian Kitchen TH

See Directions

Vienna IL

Landholding Agency: USDA-FS Property Number: 13202110117

Status: Unutilized

Directions:

Hidden Springs Ranger District; 2001020010602

#1709

## Comments:

Off-site removal only; 46+ yrs.; old; 25 sq. ft.; vault toilet; poor conditions; floor has cracks; roof leaks; contain human waste.

## Reasons:

Toilet (#1284) See Directions Vienna IL

Landholding Agency: USDA-FS Property Number: 13202110118

Status: Excess Directions:

Hidden Springs Ranger District, Millstone Bluff Recreation Area;

RPUID #1487.007541

Toilet/Romtec

Comments:

Off-site removal only; 30+ yrs. Old; 40 sq. ft.; vault toilet; poor condition; contains human waste.

Reasons:

Toilet #1/Red Bud (#1197)

See Directions

Vienna IL

Landholding Agency: USDA-FS Property Number: 13202110119

Status: Excess Directions:

Hidden Springs Ranger District, Red Bud Campground, Bell Smith Springs Recreation Area; RPUID #1119.007541

## Comments:

Off-site removal only; 29+ yrs. old; 40 sq. ft.; vault toilet; poor condition, crack in the floor and walls.

#### Reasons:

Structural Damage - Extensive Deterioration. Other - Vault Toilet

Toilet #2/Red Bud (#1198)

See Directions

Vienna IL

Landholding Agency: USDA-FS Property Number: 13202110120

Status: Excess Directions:

Hidden Springs Ranger District, Red Bud Campground; RPUID #1120.007541

## Comments:

Off-site removal only; 29+ yrs. old; 40 sq. ft.; vault toilet; Interior and exterior wall cracked; contains human waste.

## Reasons:

Structural Damage - Extensive Deterioration. Other - Vault Toilet

Toilet/SST/Male/Female/RIMROCK

Hidden Springs Rd. Junction IL 62934

Landholding Agency: USDA-FS Property Number: 13202110121

Status: Excess Directions:

**Shawnee National Forest** 

Comments:

Off-site removal only; 31+ yrs. old; 127 sq. ft.; wood commercial toilet, shallow foundation; poor condition; crack in the floor, walls need holes repaired, roof needs replaced.

Reasons:

Other – Toilet. Structural Damage - Extensive Deterioration

## UNSUITABLE PROPERTIES BUILDING KANSAS

Park Ground SST Traditional Toilet

See Directions

Elkhart KS

Landholding Agency: USDA-FS Property Number: 13202110069

Status: Excess Directions:

Cimarron Ranger District; RPUID #5368.001621; Infra #9622. From Elkhart, KS-2 miles east on Hwy 56 to Hwy 27, turn N on Hwy 27, 9 miles to Forest Rd. 700.2 turn N on Forest Rd. 798, into Cottonwood Picnic Area go to the bulletin board on the right.

## Comments:

Off-site removal only. 27 yr. old 42 sq. ft. restroom in poor condition, decrepit.

Reasons:

Structural Damage - Extensive Deterioration. Other - Toilet

Cimmaron Restroom/Toilet

See Directions

Elkhart KS

Landholding Agency: USDA-FS Property Number: 13202110076

Status: Excess Directions:

Cimarron Ranger District; RPUID #5362.001621; Infra #9616. 2 miles E on Hwy 56 to Hwy 27, turn N on Hwy 27.9 miles to Forest Rd 700.2 turn E, 4 miles to Cimarron Recreation Area, turn N into Rec area, CG on the left. RPUID: 5362.001621

#### Comments:

Off-site removal only. 28 yr. old 42 sq. ft. restroom in poor condition.

## Reasons:

Structural Damage - Extensive Deterioration. Other - Toilet

Cimarron Orig. Bldg./Restroom

See Directions

Elkhart KS

Landholding Agency: USDA-FS Property Number: 13202110077

Status: Excess Directions:

Cimarron Ranger District. From Elkhart KS-2miles E on Hwy 56 to Hwy 27, turn N on Hey 27, 9 miles to Forest Rd, 700.2 turn E, 4 miles to Cimarron Recreation Area, turn N into Rec Area, CG on the left. RPUID 5363.001621.

#### Comments:

Off-site removal only. 28 yr. old 42 sq. ft. restroom in poor/decrepit condition.

## Reasons:

Cottonwood Campground Restroom

See Directions

Elkhart KS

Landholding Agency: USDA-FS Property Number: 13202110079

Status: Excess Directions:

Cimarron Ranger District; RPUID #5367.001621; Infra #9621. From Elkhart KS-2 miles E on Hwy 56 t 27, turn N on Hwy 27, 9 miles to Forest Road 700.2 turn N on Forest road 798, into Cottonwood Picnic Area

## Comments:

Off-site removal only. 42 yrs. old 42 sq. ft.; restroom. Poor condition, decrepit.

## Reasons:

Other – Toilet. Structural Damage - Extensive Deterioration

Cimarron Group Campground Toilet

See Directions

Elkhart KS

Landholding Agency: USDA-FS Property Number: 13202110086

Status: Excess Directions:

Cimarron Ranger District; RPUID #5366.001621. From Elkhart KS-2 miles E on Hwy. 56 to Hwy 27, turn N on Hwy. 27, 9 miles to Forest Rd. 700.2 turn east, 4 miles to Cimarron Recreation Area.

#### Comments:

Off-site removal only. 28 yr. old 42 sq. ft. restroom. Poor condition, decrepit.

## Reasons:

Structural Damage - Extensive Deterioration. Other - Toilet

Cimarron Group Toilet

See Directions

Elkhart KS

Landholding Agency: USDA-FS Property Number: 13202110087

Status: Excess Directions:

Cimarron Ranger District. RPUID #5365.001621. From Elkhart KS-2 miles E on Hwy. 56 to Hwy 27, turn N on Hwy. 27, 9 miles to Forest Rd. 700.2 turn east, 4 miles to Cimarron Recreation Area.

## Comments:

Off-site removal only. 28 yrs. old restroom in poor condition, decrepit.

## Reasons:

Other – Toilet. Floodway. Structural Damage - Extensive Deterioration

**Atwood Ponds Original Restroom** 

See Directions

Elkhart KS

Landholding Agency: USDA-FS Property Number: 13202110092

Status: Excess Directions:

Cimarron Ranger District; RPUID #5364.001621; Infra #9618. From Elkhart KS-2 miles E on Hwy 56 to Hwy 27, turn N on Hwy 27, 9 miles to Forest Rd. 700.2 turn E, 4 miles to Cimarron Recreation Area. Turn North into Rec. area and turn right to the fishing dock.

## Comments:

Off-site removal only. 28 yr. 42 sq. ft. restroom poor condition, decrepit. Reasons:

Conestoga TRHD SST Traditional

See Directions

Elkhart KS

Landholding Agency: USDA-FS Property Number: 13202110094

Status: Excess Directions:

Cimarron Ranger District; RPUID #5372.001621; Infra #9626 From Elkhart KS-8 miles E on Hwy 56 to County Rd 16 (Wilburton, KS), turn N on County Rd. 16, 6 miles to Forest Rd 600.1 turn E 3.5 miles, turn N Forest Rd. 615, 1.5 miles Conestoga Trail head on the left.

## Comments:

Off-site removal only. 26 yr. old 42 sq. ft. restroom in very poor condition.

## Reasons:

Other – Toilet. Structural Damage - Extensive Deterioration

## UNSUITABLE PROPERTIES BUILDING MICHIGAN

1858 Henry Lake Campground Toilet 1

See Directions

Marenisco MI 49968

Landholding Agency: USDA-FS Property Number: 13202110058

Status: Excess Directions:

Bldg. is located in a remote campground, Henry Lake Campground. Installation ID 07773 Site ID 00, RPUID - 1537.007461. 1858 Henry LK CMPGRD.

......

## Comments:

Off-site removal only. 49 yrs. old 26 sq. ft. wood vault toilet. Asbestos vent stack and possible lead- based paint.

## Reasons:

1730 Marion Toilet 3 Single

See Directions

Watersmeet MI 49969

Landholding Agency: USDA-FS Property Number: 13202110060

Status: Excess Directions:

Installation ID 07773 Site ID 00; RPUID - 1474.007461. 1730 Marion Lake Campground. Building is located in a remote campground.

## Comments:

Off-site removal only. Remote location. 49 yr. old 26 sq. ft. wood comer vault toilet. Asbestos vent stack, possible LBP.

## Reasons:

Other - Vault Toilet

Marion Lk Toilet #7 Double

See Directions

Watersmeet MI 49969

Landholding Agency: USDA-FS Property Number: 13202110061

Status: Excess Directions:

1738 Marion Lake campground. Installation ID 07773 Side ID 00; RPUID - 1478.007461. Building is located in a remote campground.

## Comments:

Off-site removal only in remote location. 49 yr. old 62 sq. ft. wood commercial double vault toilet. Asbestos vent stack and possible LBP.

## Reasons:

Marion Lake Campground Toilet #8

See Directions

Watersmeet MI

Landholding Agency: USDA-FS Property Number: 13202110062

Status: Excess Directions:

1740 Marion lake campground. Installation ID 07773 Site ID 00; RPUID - 1479.007461. Building is located in a remote campground.

## Comments:

Off-site removal only. Remote location. 49-yr. old 62 sq. ft. wood commercial vault toilet. Asbestos vent stack; possible LBP.

## Reasons:

Other - Vault Toilet

Marion Lake Campground Toilet #9

See Directions

Watersmeet MI

Landholding Agency: USDA-FS Property Number: 13202110063

Status: Excess Directions:

1742 Marion Lake Campground Building is located in a remote campground. Installation ID 07773 Site ID 00. RPUID: 1480.007461

## Comments:

Offsite removal only. 49 yr. old, wood commercial vault toilet, 62 sq. ft. Asbestos vent stack and possible Lead-Based Paint.

#### Reasons:

IMP LK Campground Single Toilet #2

See Directions

Watersmeet MI 49969

Landholding Agency: USDA-FS Property Number: 13202110064

Status: Excess Directions:

Located in a remote IMP Lake Campground

Comments:

Offsite removal only. 49 yr. old wood commercial vault toilet, 26 sq. ft. Asbestos vent pipe and possible Lead-Based Paint.

Reasons:

Other - Toilet

IMP Lake Campground Toilet #5 Single

See Directions

Watersmeet MI 49969

Landholding Agency: USDA-FS Property Number: 13202110065

Status: Excess Directions:

1752 IMP Lake Campground. RPUID: 1485.007461. Installation ID 07773 Site ID 00. Building is located in a remote campground.

Comments:

Offsite removal only. 49 yr. old wood commercial vault toilet. 26 sq. ft. Asbestos vent pipe, possible Lead Based Paint.

Reasons:

Other - Campground vault toilet

Moosehead LK Campground Toilet #1

See Directions

Marenisco MI 39947

Landholding Agency: USDA-FS Property Number: 13202110066

Status: Excess Directions:

1862 Moosehead Lake Campground; Installation ID 07773 Site ID 00; RPUID - 1539.007461

## Comments:

Off-site removal only.49+ yrs. old; 26 sq. ft.; vault toilet; asbestos vent stack; may contain Lead Based Paint.

## Reasons:

Other - Vault Toilet

1876 Pomeroy Lake Campground Toilet #1

See directions

Marenisco MI 49947

Landholding Agency: USDA-FS Property Number: 13202110067

Status: Excess Directions:

Pomeroy Lake Campground; Installation ID 07773; Site ID 00

Bessemer RD; RPUID - 1546.0074611876 Pomeroy Lake Campground

## Comments:

49+ yrs. old; 26 sq. ft.; wood comer; vault toilet; asbestos vent stack; may contain lead base paint.

#### Reasons:

**Buttercup Campground Public Toilet** 

See Directions

Glennie MI

Landholding Agency: USDA-FS Property Number: 13202110088

Status: Unutilized

Directions:

Infra no# 49691. Oscoda County, McKinley Rd. latitude 44 38.28.36n. Longitude -83.54.48.10w) Buttercup Campground.

Comments:

Off-site removal only. 22 yr. old 24 sq. ft. wood toilet. Very poor condition. No roof.

Reasons:

Other - Toilet. Structural Damage - Extensive Deterioration

West Gate 1 Toilet

See Directions

Glennie MI

Landholding Agency: USDA-FS Property Number: 13202110090

Status: Unutilized

Directions:

Westgate #1 Day Use. Infra 50147(LAT44.27.22.27N) (LONG83.46.00.23W)

Comments:

Off-site removal only. 25 yr. 54 sq. ft. wood toilet in very poor condition.

Reasons:

Structural Damage - Extensive Deterioration. Other - Toilet

West Gate Day Use Toilet

See Directions

Glennie MI

Landholding Agency: USDA-FS Property Number: 13202110091

Status: Unutilized

Directions:

Westgate Day use. Infra #50148. LAT44.27.22.27W.

LONG83.46.00.23W

Comments:

Off-site removal only. 25 yr. old 54 sq. ft. wood toilet in very poor condition.

Reasons:

Other – Toilet. Structural Damage - Extensive Deterioration

Toilet #3

1880 Pomeroy Lake Campground

Marenisco MI 49947

Landholding Agency: USDA-FS Property Number: 13202110098

Status: Excess Directions:

Installation ID 07773; RPUID - 1548.007461

Comments:

Off-site removal only; 49 yrs. old; 26 sq. ft.; vault toilet; Asbestos vent stack and may contain lead based paint.

Reasons:

Other - Vault Toilet

96113 Hunters Pit Toilet

8261 County 513 T Road

Rapid River MI 49878

Landholding Agency: USDA-FS Property Number: 13202110105

Status: Excess Directions:

Installation ID 07776; Site ID 00; RPUID - 1686.007671

Comments:

Off-site removal only; 31+ yrs. old; 109 sq. ft.; wood, shallow foundation; toilet; deteriorated conditions.

Reasons:

96116 Little Bay DE NOC Toilet

See Directions

Rapids River MI 49878

Landholding Agency: USDA-FS Property Number: 13202110106

Status: Excess Directions:

Installation ID 07776; Site ID 00; RPUID - 1449.007671.

2 miles East of Rapid River, then 6 miles South on County 513 T Road

## Comments:

Off-site removal only; 31 yrs. old; 109 sq. ft.; wood, shallow foundation; toilet; deteriorated conditions.

#### Reasons:

Other – Toilet. Structural Damage - Extensive Deterioration

96118 Little Bay DE NOC Toilet

See Directions

Rapid River MI 49878

Landholding Agency: USDA-FS Property Number: 13202110107

Status: Excess Directions:

Installation ID 07776; Site ID 00; RPUID - 1452.007671

2 miles East of Rapid River, then 6 miles South on County 513 T Road

## Comments:

Off-site removal only; 31+ yrs. old; 110 sq. ft.; wood; shallow foundation; toilet; deteriorated conditions.

## Reasons:

96120 Little Bay DE NOC Toilet

See Directions

Rapid River MI 49878

Landholding Agency: USDA-FS Property Number: 13202110108

Status: Excess Directions:

Installation ID 07776; Site ID 00; RPUID - 1453.007671

Comments:

Off-site removal only; 31+ yrs. old; 109 sq. ft.; wood; shallow foundation; toilet; deteriorated conditions.

Reasons:

Structural Damage - Extensive Deterioration. Other - Toilet

Bldg. Site 15 See Directions

Rapid River MI 49878

Landholding Agency: USDA-FS Property Number: 13202110109

Status: Excess Directions:

96122 Little Bay DE NOC Toilet

Installation ID 07776; Site ID 00; RPUID - 1450.007671

Comments:

Off-site removal only; 31+ yrs. old; 109 sq. ft.; wood, shallow foundation; toilet; deteriorated conditions.

Reasons:

Structural Damage - Extensive Deterioration. Other - Toilet

Bldg. Site 20

8261 County 513 T Road

Rapid River MI 49878

Landholding Agency: USDA-FS Property Number: 13202110110

Status: Excess Directions:

Installation ID 07776; Site ID 00; RPUID - 1451.007671?

96124 Little Bay DE NOC Toilet

2 miles East of Rapid River, then 6 miles South on County 513 T Road

## Comments:

Off-site removal only; 31+ yrs. old; 110 sq. ft.; wood, shallow foundation; toilet; deteriorated conditions.

#### Reasons:

Other – Toilet. Structural Damage - Extensive Deterioration

**Building Site 25** 

8261 County 513 T Road

Rapid River MI 49878

Landholding Agency: USDA-FS Property Number: 13202110111

Status: Excess Directions:

Installation ID 07776; Site ID 00; RPUID- 1454.007671

96126 Little Bay DE NOC Toilet?

2 miles East of Rapid River, then 6 miles South on County 513 T Road

## Comments:

Off-site removal only; 31+ yrs. old; 110 sq. ft.; wood; shallow foundation; toilet; deteriorated conditions.

## Reasons:

Building Site 33

8261 County 513 T Road

Rapid River MI 49878

Landholding Agency: USDA-FS Property Number: 13202110112

Status: Excess Directions:

96128 Little Bay DE NOC Toilet Installation ID 07776; Site ID 00

RPUID - 1455.007671?

## Comments:

Off-site removal only; 31+ yrs. old; 110 sq. ft.; wood; shallow foundation; toilet; deteriorated conditions.

## Reasons:

Structural Damage - Extensive Deterioration. Other - Toilet

## **SITE 15**

See Directions

Munising MI 49862

Landholding Agency: USDA-FS Property Number: 13202110113

Status: Excess Directions:

**BAY FURNACE TOILET BLDG 96326** 

## Comments:

Off-site removal only; 37+ yrs.; 52 sq. ft.; wood; shallow foundation; toilet; deteriorated conditions.

## Reasons:

Structural Damage - Extensive Deterioration. Other - Toilet

## UNSUITABLE PROPERTIES BUILDING MINNESOTA

Cascade Lake Boat Access Toilet

See Directions

Tofte MN

Landholding Agency: USDA-FS Property Number: 13202110104

Status: Excess Directions:

RPUID #2224.007601

NRM# 68809

Comments:

Off-site removal only; 46 yrs. old; 20 sq. ft.; vault toilet; leaking vault.

Reasons:

Structural Damage - Extensive Deterioration. Other - Vault Toilet

Sand Lake Boat Access Toilet

null

Ely MN

Landholding Agency: USDA-FS Property Number: 13202110122

Status: Excess Directions:

RPUID #2822.007601

Comments:

Off-site removal only; 49+ yrs. old; 20 sq. ft.; vault toilet; leaking vault.

Reasons:

Other - Vault Toilet. Structural Damage - Extensive Deterioration

N Arm Burntside Boat Access Toilet

Kawishiwi Road

Ely MN

Landholding Agency: USDA-FS Property Number: 13202110123

Status: Excess Directions:

RPUID #3018.007601

Comments:

Off-site removal only; 56+ yrs. old; 20 sq. ft.; vault toilet; leaking vault.

Reasons:

Structural Damage - Extensive Deterioration. Other - Vault Toilet

## UNSUITABLE PROPERTIES BUILDING MINNESOTA

One Pine Lake Boat Access Toilet

Kawishiwi Rd.

Ely MN

Landholding Agency: USDA-FS Property Number: 13202110124

Status: Excess Directions:

RPUID #3059.007601

Comments:

Off-site removal only; 56+ yrs. old; 20 sq. ft.; vault toilet; leaking vault.

Reasons:

Structural Damage - Extensive Deterioration. Other - Vault Toilet. Floodway

Vermilion Falls Toilet

See Directions

Ely MN

Landholding Agency: USDA-FS Property Number: 13202110125

Status: Excess Directions:

Vermilion Falls Picnic Area LaCroix Ranger District; RPUID #642010436

Comments:

Off-site removal only; 20+ yrs. old; 89 sq. ft.; vault toilet; leaking vault. Critical removal.

Reasons:

Floodway. Structural Damage - Extensive Deterioration. Other - Vault Toilet

# UNSUITABLE PROPERTIES BUILDING MISSOURI

Meadow Springs Campground Toilet

East McKinley Rd.

Mio MO

Landholding Agency: USDA-FS Property Number: 13202110089

Status: Underutilized

Directions:

Meadows Springs campground. Infra #50079. Latitude: 44.39.20.80N.

Longitude: 84.04.27.17W.

Comments:

Off-site removal only. 24 yr. old 24 sq. ft. wood toilet. Very poor condition.

Reasons:

Other – Toilet. Structural Damage - Extensive Deterioration

Mink Lake

See Directions

Grand Marais MO

Landholding Agency: USDA-FS Property Number: 13202110102

Status: Excess Directions:

Mink Lake Gunflint Ranger District; RPUID #655010436

Comments:

Off-site removal only. 21+ yr. old 72 sq. ft. toilet; leaking vault.

Reasons:

# UNSUITABLE PROPERTIES BUILDING MISSOURI

Loggers Lake Block Toilet

See Directions

Bunker MO

Landholding Agency: USDA-FS Property Number: 13202110103

Status: Underutilized

Directions:

Loggers Lake Campground. Located 8 miles south of Bunker, MO on

Dent County road 5650.?

171581010602?

## Comments:

Off-site removal only. Concrete block construction. Vault toilet. 14 yrs. old, 120 sq. ft. Building is a hazard.

## Reasons:

Other - Vault Toilet. Structural Damage - Extensive Deterioration

Marble Creek Toilet

See Directions

Fredericktown MO

Landholding Agency: USDA-FS Property Number: 13202110114

Status: Underutilized

Directions:

Marble Creek Campground NRM#52149?

Located on MO State Highway E in Madison County, Missouri.

## Comments:

Off-site removal only; 31+ yrs. old; 96 sq. ft.; vault toilet.

## Reasons:

## UNSUITABLE PROPERTIES BUILDING MISSOURI

McCormack Picnic Toilet #66 Confederate Ridge Road Doniphan MO 63935

Landholding Agency: USDA-FS Property Number: 13202110115

Status: Unutilized

Directions:

Eleven Point Ranger District

Comments:

Off-site removal only; 30+ yrs.; 98 sq. ft.; vaulted toilet; mold and rotis present, roof deteriorated and leaking, rodent damage.

Reasons:

Structural Damage - Extensive Deterioration. Other - Vault Toilet

## OHIO

ARD RING MILL VAULT TOILET

County Road 68

Brownsville OH 45767

Landholding Agency: USDA-FS Property Number: 13202110099

Status: Unutilized

Comments:

Off-site removal only; 26 yrs. old; 48 sq. ft.; Wood light, shallow foundation; vault toilet vacant 4 mos.; fair condition; property located in a floodway.

Reasons:

Floodway. Other - Vault Toilet

## UNSUITABLE PROPERTIES BUILDING OHIO

## ARD\_KINDERHOOK TOILET/VAULT

1 County Road 244 Newport OH 45768

Landholding Agency: USDA-FS Property Number: 13202110100

Status: Underutilized

Comments:

Off-site removal only; 23 yrs. old; 60 sq. ft.; Precast/JILT shallow foundation; vault toilet; fair condition; vacant 4 mos.

Reasons:

Other - Vault Toilet

## IR VESUVIUS FURNACE FLUSH TOILET

County Road 29 Kitts Hill OH 45659

Landholding Agency: USDA-FS Property Number: 13202110101

Status: Underutilized

Comments:

Off-site removal only. 84 yrs. old 320 sq. ft. Wood light, shallow foundation vault toilet; fair condition; vacant 4 mos.

Reasons: