

02/03/2022

TITLE V, FEDERAL SURPLUS PROPERTY PROGRAM
FEDERAL REGISTER REPORT FOR 02/04/2022

UNSUITABLE PROPERTIES
BUILDING
ARKANSAS

14012 OCCC Voc. Training
570 Job Corps Road
Royal AR
Landholding Agency: USDA-FS
Property Number: 13202210016
Status: Unutilized
Comments:

Offsite removal only. 40-yr-old 4,300 SF classroom-wood, stucco. Very poor cond.
Not maintained for approx. 20 yrs. Exterior and interior walls structurally
unsound. Asbestos present. Restricted access.

Reasons:

Structural Damage - Extensive Deterioration
Documented Deficiencies-
Contamination
Floodway

COLORADO

River Springs Range Storage
See Directions
Antonito CO
Landholding Agency: USDA-FS
Property Number: 13202210019
Status: Unutilized
Directions:

From Antonito CO, take State Highway 17 west from Antonito to River Springs
Administrative site, about 15 ½ miles.

Comments:

Offsite removal only. 35-yr-old, 12 SF wood frame with concrete floor building.
Foundation and floors are structurally unsound.

Reasons:

Structural Damage - Extensive Deterioration
Other - Remote location

UNSUITABLE PROPERTIES
BUILDING
COLORADO

River Springs Firepump Rack

See Directions

Antonito CO

Landholding Agency: USDA-FS

Property Number: 13202210020

Status: Excess

Directions:

From Antonito CO, take State Highway 17 west from Antonito to River Springs Administrative Site, about 15 ½ miles.

Comments:

Offsite removal only. 49-yr-old, wood frame structure. Used to hold a fire pump when not on a truck. Structurally unsound floor, roof, interior/exterior walls.

Reasons:

Structural Damage - Extensive Deterioration

MINNESOTA

Dark Lake Boat Access Toilet

See Directions

Chisholm MN

Landholding Agency: USDA-FS

Property Number: 13202210018

Status: Underutilized

Directions:

From Chisholm, MN head N on 3rd Avenue NW. Turn right on McNiven Rd. (MN66) for 8.3 miles. Turn left on Smith (CSAH 25) for 3/6 miles. Turn left on North Dark Lake Rd. (MN663) & travel 0.8 miles to boat access.

Comments:

Offsite removal only. 49-yr-old, 20 SF vault toilet enclosure. Deteriorated condition.

Reasons:

Structural Damage - Extensive Deterioration

Other - Vault Toilet

UNSUITABLE PROPERTIES
BUILDING
NEVADA

Security Police Operations
4455 Grissom Ave
Nellis AFB NV 89191
Landholding Agency: DoD-USAF
Property Number: 18202210007
Status: Underutilized
Directions:

RPUID: 496063. Located on secure military facility, restricted public access.

Comments:

Offsite removal only. 38-yr-old 1,500 SF wood frame & stucco building. Poor cond., in a state of disrepair and beyond the life expectancy, structurally unsound. Poss. asbestos and Lead Based Paint.

Reasons:

Structural Damage - Extensive Deterioration

OHIO

302 Energy Conversion Lab
21999 Brookpark Road
Brookpark OH 44135
Landholding Agency: NASA
Property Number: 71202210001
Status: Underutilized
Comments:

Offsite removal only. 60-yr-old, 30,826 SF research facility. Size of building makes moving unfeasible. Located on secure site, no public access.

Reasons:

Other - Size of structure
National Security Concerns
Structural Damage - Extensive Deterioration

UNSUITABLE PROPERTIES
BUILDING
OHIO

#310 Antenna Alignment Ctr.
21000 Brookpark Road
Brookpark OH 44135
Landholding Agency: NASA
Property Number: 71202210002
Status: Underutilized
Comments:

Offsite removal only. 51-yr-old antenna. Located on secure site, no public access.

Reasons:

Other - Structure type-antenna

#3131 B1 Pump/Shop Building
3597 Scheid Rd
Sandusky OH 44870
Landholding Agency: NASA
Property Number: 71202210003
Status: Unutilized
Comments:

Offsite removal only. 61-yr-old, 6,027 SF research structure with metal siding and roof. Bldg. would need to be dismantled to move. Located on secure facility, no public access.

Reasons:

Other - Structure type/size
National Security Concerns