

SUITABLE / AVAILABLE PROPERTIES

BUILDING

UTAH

Oaks Park CG 4041 CN2268.00269

FSR-10211 MP .1-Oaks Park CG

Vernal Co: Uintah UT 84078

Landholding Agency: USDA-FS

Property Number: 13202330001

Status: Excess

Directions:

40.74233935-109.62381552

Comments:

68+ yrs. old; precast concrete structure; 128 sq. ft.; comfort station/toilet; water and electric does'nt meet criteria.

Dowd Mtn Vault Toilet NRM 2079

18 Miles South East of Manila FSR 094, off of

Manila UT 84046

Landholding Agency: USDA-FS

Property Number: 13202330002

Status: Excess

Directions:

40.89716978-109.62608410

Comments:

57+ yrs. old; brick structure; 61 sq. ft.; comfort station toilet; meets the key physical criteria.

Paradise GS Romtec 5011 CN 313

FSR 10104 MP.18-Paradise GS Compound

Whiterocks County Uin UT 84078

Landholding Agency: USDA-FS

Property Number: 13202330003

Status: Excess

Comments:

33+ yrs. old; precast concrete structure; 40 sq. ft.; comfort station/toilet; water and electric does'nt meet criteria.

SUITABLE / AVAILABLE PROPERTIES

BUILDING

UTAH

Whiterocks 1st Toilet 4053 CN
MP .25 FSR 116-Whiterocks CG Road
Whiterocks UT 84085
Landholding Agency: USDA-FS
Property Number: 13202330004
Status: Excess
Directions:

40.61925772-109.9410660

Comments:

58+ yrs. old; romtec structure; 62 sq. ft.; comfort station/toilet; water and electric doesn't meet criteria.

Beaver Pond Byway Vault Toilet
25 Miles North of Maeser Utah off of Highway
Maeser UT 84078
Landholding Agency: USDA-FS
Property Number: 13202330006
Status: Excess
Directions:

40.72621349-109.46836213

Comments:

26+ yrs. old; precast concrete structure; 94 sq. ft.; comfort station/toilet; water and electric doesn't meet criteria..

Navajo Cliffs Toilet 3034 CN 1
FSR 218-W Sheep Creek Road Geological Lp 3240
Manila UT 84046
Landholding Agency: USDA-FS
Property Number: 13202330007
Status: Excess
Directions:

40.92890432-109.7238123

Comments:

57+ yrs. old; brick structure; 138 sq. ft.; comfort station/toilet; water and electric doesn't meet criteria.

SUITABLE / AVAILABLE PROPERTIES

BUILDING

UTAH

Colton Guard Station 5035 CN 8

Colton GS Compound-FSR 019

Maeser Co: Uintah UT 84078

Landholding Agency: USDA-FS

Property Number: 13202330008

Status: Excess

Directions:

lat 40.66731085 long-109.5195274

Comments:

24+ yrs. old; precast concrete structure; 40 sq. ft.; comfort station/toilet water and electric doesn't meet criteria.

Kaler Hollow Romtec

Toilet 5012 CN 3133.002691

FSR-10494 MP .01 Kaler Hollow CG FSR-1049

Maeser Co: Uintah UT 84078

Landholding Agency: USDA-FS

Property Number: 13202330009

Status: Excess

Directions:

40.702252,-109.615136

Comments:

21+ yrs. old; precast concrete structure; 40 sq. ft.; comfort station/toilet; water and electric doesn't meet criteria.

Paradise Park Romec Toilet

4050 CN 2277.002691

Whiterocks UT 84078

Landholding Agency: USDA-FS

Property Number: 13202330010

Status: Excess

Directions:

40.66677201-109.91450512

Comments:

30+ yrs. old; precast concrete structure; 40 sq. ft.; comfort station/toilet; water and electric doesn't meet criteria.

SUITABLE / AVAILABLE PROPERTIES

BUILDING

UTAH

Range Study Area 4095
CN 3097.002691
MP. 1 FSR 10217-Just off of Highway 191
Maeser Co: Uintah UT 84078
Landholding Agency: USDA-FS
Property Number: 13202330012
Status: Excess
Directions:
40.71514658-109.4751523

Comments:
26+ yrs. old; precast concrete structure; 128 sq. ft.; comfort station/toilet; water and electric does'nt meet criteria.

Strawberry Bay Boat Ramp Flush
Toilet NRM T1001-1 CN 1218.003401
Strawberry Bay Marina Boat Ramp Parking Lot,
Soilder Summit Co: Wasatch UT 84032
Landholding Agency: USDA-FS
Property Number: 13202330013
Status: Excess
Directions:
40.177515-111.155337

Comments:
40+ yrs. old; block structure; 438 sq. ft.; comfort station/toilet; fair condition.

Whiterocks 3rd Toilet 4055
CN 2282.002691
MP .5 FSR 116-Whiterocks CG Road
Whiterocks Co: Uintah UT 84085
Landholding Agency: USDA-FS
Property Number: 13202330014
Status: Excess
Directions:
40.61975312-109.94351208

Comments:
58+ yrs.old; brick structure; 62 sq. ft.; comfort station/toilet; water and electric doesn't meet criteria.

SUITABLE / AVAILABLE PROPERTIES
Summary for SUITABLE / AVAILABLE

Total number of = 12

UNSUITABLE PROPERTIES

BUILDING

ALABAMA

4319 Storage Building

Inside gated Redstone Arsenal off of Digney R

Marshall Space Flight Center

MSFC AL 35812

Landholding Agency: NASA

Property Number: 71202330001

Status: Unutilized

Reasons:

National Security Concerns

Documented Deficiencies-Contamination

Comments:

Located in a National Security Complex; no public access.

4537 Test Support Building

Inside gated East Test Area on Mariner Rd.,

Marshall Space Flight Center

MSFC AL 35812

Landholding Agency: NASA

Property Number: 71202330002

Status: Unutilized

Reasons:

National Security Concerns

Comments:

Located in a National Security Complex; no public access.

4550 Structural Dynamic Test F

Inside gated East Test Area on Saturn Rd.,

Marshall Space Flight Center

MSFC AL 35812

Landholding Agency: NASA

Property Number: 71202330003

Status: Unutilized

Reasons:

National Security Concerns

Comments:

UNSUITABLE PROPERTIES

BUILDING

ALABAMA

Located in a National Security Complex; no public access.

4551 Structural Dynamic Support
Inside gated East Test Area on Saturen Rd.,
Marshall Space Flight Center
MSFC AL 35812
Landholding Agency: NASA
Property Number: 71202330004
Status: Unutilized

Reasons:

National Security Concerns

Comments:

Located in a National Security Complex; no public access.

4553C Shed
Inside gated East Test Area off of Able Ave.
Marshall Space Flight Center
MSFC AL 35812
Landholding Agency: NASA
Property Number: 71202330005
Status: Unutilized

Reasons:

National Security Concerns

Comments:

Located in a National Security Complex; no public access.

4571 Impact Test Facility
Inside gated East Test Area on Mariner Rd.,
Marshall Space Flight Center
MSFC AL 35812
Landholding Agency: NASA
Property Number: 71202330006
Status: Unutilized

Reasons:

National Security Concerns

Comments:

Located in a National Security Complex; no public access.

UNSUITABLE PROPERTIES

BUILDING

ALABAMA

4572A Structural Strength Test
Inside gated East Test Area on Mariner Rd.,
Marshall Space Flight Center
MSFC AL 35812
Landholding Agency: NASA
Property Number: 71202330007
Status: Unutilized

Reasons:

National Security Concerns

Comments:

Located in a National Security Complex; no public access.

4574 Observation Bunker
Inside gated East Test Area off of Nimbus Ave
Marshall Space Flight Center
MSFC AL 35812
Landholding Agency: NASA
Property Number: 71202330008
Status: Unutilized

Reasons:

National Security Concerns

Comments:

Located in a National Security Complex; no public access.

4584 Test Support Building
Inside gated East Test Area on Saturn Rd.,
Marshall Space Flight Center
MSFC AL 35812
Landholding Agency: NASA
Property Number: 71202330009
Status: Unutilized

Reasons:

National Security Concerns

Comments:

Located in a National Security Complex; no public access.

4597 Fuel Ready Storage
Inside gated East Test Area
Marshall Space Flight Center
MSFC AL 35812

UNSUITABLE PROPERTIES

BUILDING

ALABAMA

Landholding Agency: NASA

Property Number: 71202330010

Status: Unutilized

Reasons:

National Security Concerns

Property containing flammable or explosive materials

Comments:

Located in a National Security Complex; no public access; fuel tank located on property.

CALIFORNIA

047 Aircraft Maintenance Hanga

600 Jagels Road

Ames Reseach Center/Moffett Federal Airfield

Moffett Field CA 94035

Landholding Agency: NASA

Property Number: 71202330011

Status: Unutilized

Reasons:

National Security Concerns

Comments:

Located in a National Security Complex; no public access.

ILLINOIS

Carlyle Lake CB561-8060

Carlyle Lake IL

Landholding Agency: USACE - BC

Property Number: 32202330001

Status: Underutilized

Directions:

GPS Coordinates: 38.65198 -89.26338, located in Coles Creek Recreation Area/Campground

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Building is in serious disrepair; in need of a foundation, roof and interior repairs.

UNSUITABLE PROPERTIES

BUILDING

ILLINOIS

Carlyle Lake CB561-11616

Carlyle Lake IL

Landholding Agency: USACE - BC

Property Number: 32202330002

Status: Underutilized

Directions:

GPS Coordinates: 38.65789 -89.25786, located in Coles Creek Recreation Area/Campground

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Building is in need of extensive disrepairs; in need of a foundation; doesn't meet key criteria.

32202330003

Carlyle Lake IL

Landholding Agency: USACE - BC

Property Number: 32202330003

Status: Underutilized

Directions:

GPS Coordinates: 38.6157 -89.31471, located in Dam East Recreation Area

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Building is in need of extensive repairs; in need of a foundation; doesn't meet key criteria.

Carlyle Lake CB561-8070

Carlyle Lake IL

Landholding Agency: USACE - BC

Property Number: 32202330004

Status: Underutilized

Directions:

GPS Coordinates: 38.66365 -89.25837, located in Coles Creek Recreation Area/Campground

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Building is in need of extensive repairs; in need of a foundation; doesn't meet key criteria.

UNSUITABLE PROPERTIES

BUILDING

ILLINOIS

Carlyle Lake CB561-8070

Carlyle Lake IL

Landholding Agency: USACE - BC

Property Number: 32202330005

Status: Underutilized

Directions:

GPS Coordinates: 38.66365 -89.25837, located in Coles Creek Recreation Area/Campground

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Building is in need of extensive repairs; in need of a foundation; doesn't meet key criteria.

Carlyle Lake CB561-7920

Carlyle Lake IL

Landholding Agency: USACE - BC

Property Number: 32202330006

Status: Underutilized

Directions:

GPS Coordinates: 38.69394 -89.23724, located in Boulder Recreation Area/Campground

Reasons:

Structural Damage - Extensive Deterioration

Comments:

Building in serious disrepair, it's in need of foundation repairs; building has passed its useful life.

UNSUITABLE PROPERTIES

BUILDING

TENNESSEE

9983-FC Office Space
Bear Creek Road
Y-12 National Security Complex
Oak Ridge TN 37830
Landholding Agency: DOE
Property Number: 41202330001
Status: Unutilized

Reasons:

National Security Concerns

Comments:

Located in National Security Complex; no public access.

UTAH

B.S. Boat Equipment Tower CN:2

Manila UT

Landholding Agency: USDA-FS

Property Number: 13202330005

Status: Excess

Directions:

Brandon Sprng Group Camp in Land Between the Lakes NRA. GPS Coordinagtes:
36.895986 N, -88.014650 W.

Reasons:

Structural Damage - Extensive Deterioration

Comments:

The structural poles are rotten and at rick of failure; sanitary facilities, water and electric power doesn't meet criteria.

Summary for UNSUITABLE PROPERTIES

Total number of = 19

SUMMARY OF ALL PROPERTIES

Suitable/Available = 12
Suitable/Unavailable = 0
Suitable/To Be = 0
** Suitable/ Undefined = 0
Total Suitable = 12
Total Unsuitable = 19
Total number of = 31
Properties = 0