

Health & Safety	2.1	2.3	Difference	2.1	2.3	Difference
	Inspection	Inspection		Inspection	Inspection	
Non-Life Threatening	Site			Building		
Actual	0	0	0	3	1	-2
% Inspected	NA	NA	NA	100%	100%	0%
Projected	0		0	3	1	-2
Life Threatening	Site			Building		
Actual	0	0	0	2	2	0
% Inspected	NA	NA	NA	100%	100%	0%
Projected	0	0	0	2	2	0
Smoke Detectors	Site			Building		
Actual	0	0	0	0	0	0
% Inspected	NA	NA	NA	100%	100%	0%
Projected	0	0	0	0	0	0

2.1 Inspection	2.3 Inspection	Difference	2.1 Inspection	2.3 Inspection	Difference
Unit			Total		
1	1	0	4	2	-2
1%	1%	0%	NA	NA	NA
115	115	0	118	116	-2
Unit			Total		
1	2	1	3	4	1
1%	1%	0%	NA	NA	NA
115	229	114	117	231	114
Unit			Total		
0	0	0	0	0	0
1%	1%	0%	NA	NA	NA
0	0	0	0	0	0