

**Three Oaks/Buskirk
North Charleston, SC 29420**

Health & Safety	2.1	2.3	Difference	2.1	2.3	Difference	2.1	2.3	Difference	2.1	2.3	Difference
	Inspection	Inspection		Inspection	Inspection		Inspection	Inspection		Inspection	Inspection	
Non-Life Threatening	Site			Building			Unit			Total		
Actual	1	2	1	4	3	-1	6	4	-2	11	9	-2
% Inspected	NA	NA	NA	96%	96%	0%	15%	15%	0%	NA	NA	NA
Projected	1	2	1	4	3	-1	39	26	-13	44	31	-13
Life Threatening	Site			Building			Unit			Total		
Actual	0	0	0	1	0	-1	0	1	1	1	1	0
% Inspected	NA	NA	NA	96%	96%	0%	15%	15%	0%	NA	NA	NA
Projected	0	0	0	1	0	-1	0	7	7	1	7	6
Smoke Detectors	Site			Building			Unit			Total		
Actual	0	0	0	0	0	0	2	1	-1	2	1	-1
% Inspected	NA	NA	NA	96%	100%	4%	15%	15%	0%	NA	NA	NA
Projected	0	0	0	0	0	0	13	7	-6	13	7	-6