

Spring Brook Courts**Moline, IL**

Inspections 92081 and 1092081

Inspectable Area	Possible Points	2.1	2.3	Difference (2.3-2.1)	2.1	2.3	Difference (2.3-2.1)	2.1	2.3	Difference (2.3-2.1)
		Inspection 1092081	Inspection 92081		Inspection 1092081	Inspection 92081		Inspection 1092081	Inspection 92081	
		Area Points			H & S Deductions			Net Score		
Site	19.5	7.7	15.8	8.1	0	0	0	7.7	15.8	8.1
Building Exterior	19.5	17.7	17.9	0.2	0	0	0	17.7	17.9	0.2
Building System	16.5	16.5	16.5	0	0	0	0	16.5	16.5	0
Common Areas	1.1	1	1	0	0	0	0	1	1	0
Dwelling Units	43.4	39.3	41.3	2	3.5	3.5	0	35.8	37.8	2.0
Total	100	82.2	92.5	10.3	3.5	3.5	0	79	89	10