

Hillside Heights/Spring Valley**Moline IL**

Inspections 92082 and 1092082

Inspectable Area	Possible Points	2.1	2.3	Difference (2.3-2.1)	2.1	2.3	Difference (2.3-2.1)	Inspection	2.3	Difference (2.3-2.1)
		Inspection 1092082	Inspection 92082		Inspection 1092082	Inspection 92082		1092082	Inspection 92082	
		Area Points			H & S Deductions			Net Score		
Site	16.9	0	10.5	10.5	0	0	0	0	10.5	10.5
Building Exterior	19.3	18.8	19.2	0.4	0	0	0	18.8	19.2	0.4
Building System	20.5	20.3	20.5	0.2	0	0	0	20.3	20.5	0.2
Common Areas	1.7	1.5	1.7	0.2	0	0	0	1.5	1.7	0.2
Dwelling Units	41.7	40.9	41.4	0.5	1.1	1	-0.1	39.8	40.4	0.6
Total	100	81.5	93.3	11.8	1.1	1	-0.1	80	92	12