

West Park 92106

Bremerton, WA

Inspections 92106 and 1092106

Inspectable Area	Possible Points	2.1	2.3	Difference (2.3-2.1)	2.1	2.3	Difference (2.3-2.1)	2.1	2.3	Difference (2.3-2.1)
		Inspection 1092106	Inspection 92106		Inspection 1092106	Inspection 92106		Inspection 1092106	Inspection 92106	
		Area Points			H & S Deductions			Net Score		
Site	20.3	0	3.7	3.7	0	3.7	3.7	0	0	0
Building Exterior	20.2	12.6	14.6	2	0	0	0	12.6	14.6	2
Building System	13.3	13.5	13	-0.5	0.1	0	-0.1	13.4	13	-0.4
Common Areas	2.3	1.6	1.8	0.2	0.1	0.1	0	1.5	1.7	0.2
Dwelling Units	43.9	35.5	37.1	1.6	6.8	6.2	-0.6	28.7	30.9	2.2
Total	100	63.2	70.2	7	7	10	3	56	60	3