

Common Areas	Bldg 95-Office	Doors - Damaged Surface (Holes/Paint/Rusting)	L1		<0.05	
Common Areas	Bldg 95	Walls - Needs Paint	L2		<0.05	
Building Exterior	Bldg 96	Roofs - Missing/Damaged Components from Downspout/Gutter		L1		<0.05
Building Exterior	Bldg 96	Walls - Missing Pieces/Holes/Spalling		L2		<0.05
Building Systems	Bldg 96	Fire Protection - Missing/Damaged/Expired Extinguishers (LT)		L3		<0.05
Common Areas	Bldg 96	Doors - Damaged Surface (Holes/Paint/Rusting)		L2		0.05
Common Areas	Bldg 96	Floors - Needs Paint		L2		<0.05
Common Areas	Bldg 96-Laundry Room	Walls - Needs Paint		L2		<0.05
Common Areas	Bldg 96-Lobby	Walls - Needs Paint		L2		<0.05
Building Exterior	Bldg 101	Foundations - Cracks/Gaps	L3	L2	0.8	0.43
Unit 108-H&S	Bldg 101	Hazards- Tripping (NLT)	L3			
Building Exterior	Bldg 105	Roofs - Missing/Damaged Components from Downspout	L1		<0.05	
Building Exterior	Bldg 106	Roofs - Missing/Damaged Components from Downspout/Gutter		L1		<0.05
Building Exterior	Bldg 123	Foundations - Cracks/Gaps	L1		0.1	
Building Exterior	Bldg 123	Roofs - Missing/Damaged Components from Downspout	L3		0.18	
Building Exterior	Bldg 124	Roofs - Missing/Damaged Components from Downspout/Gutter		L2		0.1
Building Exterior	Bldg 131	Windows - Damaged/Missing Screens	L1		<0.05	
Unit 101A-H&S	Bldg 133	Hazards- Tripping (NLT)		L3		
Building Exterior	Bldg 135	Foundations - Cracks/Gaps	L2		0.2	
Building Exterior	Bldg 135	Roofs - Missing/Damaged Components from Downspout	L1		<0.05	
Unit 117C	Bldg 135	Smoke Detector - Missing Inoperable	L3		<0.05	
Building Exterior	Bldg 136	Foundations - Cracks/Gaps		L2		0.43
Building Exterior	Bldg 136	Roofs - Missing/Damaged Components from Downspout/Gutter		L1		0.1
Unit 117C	Bldg 136	Smoke Detector - Missing Inoperable		L3		<0.05
Building Exterior	Bldg 137	Roofs - Missing/Damaged Components from Downspout	L3		0.36	
Building Exterior	Bldg 137	Walls - Missing Pieces/Holes/Spalling	L2		0.19	
Unit 127	Bldg 137	Bathroom - Plumbing - Leaking Faucet/Pipes	L1		0.19	
Unit 127	Bldg 137	Hot Water Heater - Gas Fired Unit - Missing/Misaligned C	L3		0.86	
Building Exterior	Bldg 139	Roofs - Missing/Damaged Components from Downspout/Gutter		L2		0.19
Building Exterior	Bldg 139	Walls - Missing Pieces/Holes/Spalling		L2		0.21
Unit 127	Bldg 139	Bathroom - Plumbing - Leaking Faucet/Pipes		L1		0.2
Building Exterior	Bldg 147	Foundations - Cracks/Gaps	L2		0.4	
Unit 5604	Bldg 147	Hot Water Heater - Gas Fired Unit - Missing/Misaligned C	L3		0.86	
Building Exterior	Bldg 149	Roofs - Missing/Damaged Components from Downspout	L1		<0.05	