Building Exterior	Bldg 190	Windows - Damaged/Missing Screens	L1		<0.05		
	Bldg 190	Floors - Needs Paint	L2		<0.05		
	Bldg 190	Walls - Needs Paint	L1		<0.05		
Building Exterior	Bldg 195	Roofs - Damaged Soffits/Fascia		L1		<0.05	
Building Exterior	Bldg 195	Walls - Missing Pieces/Holes/Spalling		L2		<0.05	
Common Areas	Bldg 195	Floors - Needs Paint		L2		<0.05	
Building Exterior	Bldg 203	Foundations - Cracks/Gaps	L1		0.1		
Building Exterior	Bldg 203	Roofs - Missing/Damaged Components from Downspout	L1		<0.05		
Unit 45B	Bldg 203	Doors - Missing Door	L1		0.1		
Building Exterior	Bldg 206	Roofs - Missing/Damaged Components from Downspout	/Gutter	L1		<0.05	
Unit 45B	Bldg 206	Doors - Missing Door		L1		0.1	
Building Exterior	Bldg 211	Foundations - Cracks/Gaps	L2		0.4		
Building Exterior	Bldg 211	Roofs - Missing/Damaged Components from Downspout	L1		0.09		
Building Exterior	Bldg 211	Walls - Missing Pieces/Holes/Spalling	L2		0.19		
Unit 68H	Bldg 211	Hot Water Heater - Gas Fired Unit - Missing/Misaligned (L3		0.86		
Unit 68H	Bldg 211	HVAC System - Inoperable	L3		1.29		
Unit 68H	Bldg 211	Kitchen - Range/Stove - Missing/Damaged/Inoperable	L3		0.58		
Unit 68H-H&S	Bldg 211	Hazards- Other (NLT)	L3				
Unit 68H-H&S	Bldg 211	Hazards- Tripping (NLT)	L3				
Building Exterior	Bldg 216	Foundations - Cracks/Gaps		L2		0.21	
Building Exterior	Bldg 216	Roofs - Missing/Damaged Components from Downspout	/Gutter	L1		<0.05	
Building Exterior	Bldg 216	Walls - Missing Pieces/Holes/Spalling		L2		0.1	
Unit 68H	Bldg 216	HVAC System - Inoperable		L3		1.32	
	Bldg 216	Kitchen - Range/Stove - Missing/Damaged/Inoperable		L3		0.59	
	Bldg 213	Roofs - Missing/Damaged Components from Downspout	/Gutter	L2		0.1	
	Bldg 213	Domestic Water- Leaking Central Water Supply		L3		0.35	
0 ,	Bldg 213	Sanitary System - Missing Drain/Cleanout/Manhole Cove	ers	L3		0.26	
Unti 68E	Bldg 213	Doors - Damaged Surface (Holes/Paint/Rusting)		L2		0.09	
Unti 68E	Bldg 213	Doors - Missing Door		L1		0.1	
	Bldg 218	Roofs - Missing/Damaged Components from Downspout		L1		0.1	
Building Systems		Domestic Water- Leaking Central Water Supply	L3		0.32		
	Bldg 218	Sanitary System - Missing Drain/Cleanout/Manhole Cove			0.24		
	Bldg 218	Doors - Damaged Surface (Holes/Paint/Rusting)	L3		0.17		
Unti 68E	Bldg 218	Doors - Missing Door	L1		0.1		