

West Park

92106

Bremerton, WA

Inspections 92106 and 1092106

Summary	2.1 Inspection 1092106	2.3 Inspection 92106	Difference									
Scores												
Possible Points												
Site	20.6	20.3	-0.3	0	3.7	3.7	0	3.7	3.7	0	0	0
Building Exterior	20.5	20.2	-0.3	12.6	14.6	2	0	0	0	12.6	14.6	2
Building System	13.8	13.3	-0.5	13.5	13	-0.5	0.1	0	-0.1	13.4	13	-0.4
Common Areas	2.3	2.3	0	1.6	1.8	0.2	0.1	0.1	0	1.5	1.7	0.2
Dwelling Units	42.8	43.9	1.1	35.5	37.1	1.6	6.8	6.2	-0.6	28.7	30.9	2.2
Total	100	100	0	55	70.2	15.2	7	10	3	56	60	4
Final Score	NA						NA			NA		